

VEHICLE FACTORS ATTACHMENT

2005 Freightliner Roadside CVSA Inspections

Greenville, AL

HWY21MH009

(5 pages)

						REPORT			tral 3.4
TXDPS COMMERCIAL VEHICLE ENFORCEMENT				NENT	Report Number: TX5YTH Inspection Date: 03/04/2 Start: 5:15 PM CT En Inspection Level: II - Wa HM Inspection Type: Not			2021 nd: 05:58 PM CT /alk-Around	
NNUR TRANS LL 752 MEMORIAL I DECATUR, GA 30 JSDOT#: 0214617 MC/MX#: 0074653 State#: 0838110	DRIVE SUIT 0032 74 F 39	E B Phone#: Fax#:			Driver: License# Date of E CoDriver License# Date of E	Sirth: 1 999 199 : :		_	tate: GA tate:
.ocation: US-0090 lighway: US-0090 County:		E CO. (472	-516	MilePost: 500 Origin: SALTI Destination: (ipper: MABE Bill of Lading A Cargo: GENE			
VEHICLE IDENTI	FICATION								
<u>Unit</u> <u>Type</u> <u>Make</u> <u>Yo</u> 1 TT FRHT 2 ST WANC		<u>Plate #</u> C815CN XKS933		equipment ID 6875 FA994825	<u>VIN</u> 6875 2475	<u>GVWR</u> <u>CVSA #</u> 52,000 65,000	<u>Ne</u>	w CVSA #	<u>005#</u>
Axle # 1 Right 2 1/2	WIEIN I S								
Axle # 1 Right 2 1/2 Left 1 Chamber C-24									
Axle # 1 Right 2 1/2 Left 1 Chamber C-24	Section 393.47E		Unit 1	OOS Citation #	<u>Verify</u> <u>Crash</u> N N	Violations Discove BRAKE OUT OF AI ROTO (FMCSR 393 SIDE	JUST	-	
Axle # 1 Right 2 1/2 Left 1 Chamber C-24 /IOLATIONS Vio Code	Section					BRAKE OUT OF AI ROTO (FMCSR 393	DJUST 3.47(e) ERATIN DJUST): AXLE 1 /E AUTON TERS (FMC	RIGHT
Axle #1Right2 1/2Left1ChamberC-24VIOLATIONSVio Code393.47E	<u>Section</u> 393.47E		1	N	N N	BRAKE OUT OF AI ROTO (FMCSR 393 SIDE DEFECTIVE/INOPE SLACK (BRAKE) A	DJUST 3.47(e) ERATIN DJUST RIGH ⁻ SCURE): AXLE 1 I VE AUTON TERS (FMC T SIDE	RIGHT ATIC :SR
Axle #1Right2 1/2Left1ChamberC-24VIOLATIONSVio Code393.47E393.53B	<u>Section</u> 393.47E 393.53B		1	N	N N	BRAKE OUT OF AI ROTO (FMCSR 393 SIDE DEFECTIVE/INOPE SLACK (BRAKE) A 393.53(b)): AXLE 1 INOPERABLE/OBS	ERATIN 3.47(e) ERATIN DJUST RIGHT SCURE ER K (FMC): AXLE 1 I VE AUTON FERS (FMC T SIDE D ID LAMF SR 396.5(I	RIGHT ATIC SR (FMCSR)):
Axle #1Right2 1/2Left1ChamberC-24VIOLATIONSVio Code393.47E393.53B393.9	<u>Section</u> 393.47E 393.53B 393.9	3	1 1 1	N N N	N N N N N N	BRAKE OUT OF AI ROTO (FMCSR 393 SIDE DEFECTIVE/INOPE SLACK (BRAKE) A 393.53(b)): AXLE 1 INOPERABLE/OBS 393.9): INOP CENT OIL/GREASE LEAK	DJUST 3.47(e) DJUST RIGH CURE ER (FMC CENT R INF): AXLE 1 I VE AUTOM TERS (FMC T SIDE D ID LAMF SR 396.5(I ER REAR LATED (FM	RIGHT ATIC SR (FMCSR)): LEAKING ICSR
Axle # 1 Right 2 1/2 Left 1 Chamber C-24 VIOLATIONS Vio Code 393.47E 393.53B 393.9 396.5B 393.75A3	<u>Section</u> 393.47E 393.53B 393.9 396.5B 393.75A 3	3	1 1 1 1	N N N	N N N N N N	BRAKE OUT OF AI ROTO (FMCSR 393 SIDE DEFECTIVE/INOPE SLACK (BRAKE) A 393.53(b)): AXLE 1 INOPERABLE/OBS 393.9): INOP CENT OIL/GREASE LEAM ENGINE OIL LEAK TIRE-FLAT / UNDE	DJUST 3.47(e) ERATIN DJUST RIGH CURE ER (FMC CENT ER INF 5 right): AXLE 1 I VE AUTOM TERS (FMC T SIDE D ID LAMF SR 396.5(I ER REAR LATED (FM	RIGHT ATIC SR (FMCSR)): LEAKING ICSR ide
Axle # 1 Right 2 1/2 Left 1 Chamber C-24 /IOLATIONS Vio Code 393.47E 393.53B 393.9 396.5B 393.75A3	<u>Section</u> 393.47E 393.53B 393.9 396.5B 393.75A 3	3	1 1 1 1	N N N	N N N N N N	BRAKE OUT OF AI ROTO (FMCSR 393 SIDE DEFECTIVE/INOPE SLACK (BRAKE) A 393.53(b)): AXLE 1 INOPERABLE/OBS 393.9): INOP CENT OIL/GREASE LEAK ENGINE OIL LEAK TIRE-FLAT / UNDE 393.75(a)(3)): axle	DJUST 3.47(e) ERATIN DJUST RIGH CURE ER (FMC CENT ER INF 5 right): AXLE 1 I VE AUTON TERS (FMC T SIDE D ID LAMF SR 396.5(I ER REAR LATED (FM t side outs	RIGHT ATIC SR (FMCSR)): LEAKING ICSR ide
Axle # 1 Right 2 1/2 Left 1 Chamber C-24 VIOLATIONS VIOLATIONS 393.47E 393.53B 393.9 396.5B 393.75A3 HazMat: No HM T Special Checks:	<u>Section</u> 393.47E 393.53B 393.9 396.5B 393.75A 3	3	1 1 1 1	N N N	N N N N N N	BRAKE OUT OF AI ROTO (FMCSR 393 SIDE DEFECTIVE/INOPE SLACK (BRAKE) A 393.53(b)): AXLE 1 INOPERABLE/OBS 393.9): INOP CENT OIL/GREASE LEAK ENGINE OIL LEAK TIRE-FLAT / UNDE 393.75(a)(3)): axle	DJUST 3.47(e) ERATIN DJUST RIGH CURE ER (FMC CENT ER INF 5 right): AXLE 1 I VE AUTON TERS (FMC T SIDE D ID LAMF SR 396.5(I ER REAR LATED (FM t side outs	RIGHT ATIC SR (FMCSR)): LEAKING ICSR ide
Right 2 1/2 Left 1 Chamber C-24 VIOLATIONS VIOLATIONS VIOCOde 393.47E 393.53B 393.9 396.5B 393.75A3 HazMat: No HM T Special Checks: Vehicle OOS Text Failure to return this report	Section 393.47E 393.53B 393.9 396.5B 393.75A Transported.	l certification ca	1 1 1 2	N N N Y	N N N N N N A N	BRAKE OUT OF AI ROTO (FMCSR 393 SIDE DEFECTIVE/INOPE SLACK (BRAKE) A 393.53(b)): AXLE 1 INOPERABLE/OBS 393.9): INOP CENT OIL/GREASE LEAK ENGINE OIL LEAK TIRE-FLAT / UNDE 393.75(a)(3)): axle	DJUST 3.47(e) ERATIN DJUST RIGH SCURE ER CURE ER CURE ER CURE ER CURE ER STIGH STIGH): AXLE 1 I VE AUTON TERS (FMC T SIDE D ID LAMF CR REAR LATED (FM t side outs Cargo T	RIGHT ATIC SR (FMCSR)): EAKING ICSR ide ank:

Report Prepared By:

Badge #: 11200

Copy Received By:

Χ_



Χ_

DRIVER/VEHICLE EXAMINATION	NREPORT Query Central 3.4
Tennessee Department of Safety Commercial Vehicle Division 1150 Foster Avenue Nashville, TN 37243 Phone: (615)743-4990 Fax: (615)253-2278	Report Number: TNTFBW000027 Inspection Date: 01/01/2021 Start: 3:41 PM CT End: 03:47 PM CT Inspection Level: III - DriverOnly HM Inspection Type: None
ANNUR TRANS LLCDriver:PO BOX 830304LicenseSTONE MOUNTAIN, GA 30032Date ofUSDOT#: 02146174Phone#: ConstantMC/MX#: 00746539Fax#:State#:Date of	e#: State: GA Birth: State: GA er: e#: State:
Location: WILSON PKWY/PULASKI HWYMilePost:SHighway: 64Origin: LAWRENCEBURG,County: LINCOLN, TNDestination: ELLENWOOD	-
UnitTypeMakeYearStatePlate #Equipment IDVIN1TRFRHT 2005GAC815CN68751FUJBBCG25LN962STUTIL2020INP840249ATL03200081UVVS2538M7317	
BRAKE ADJUSTMENTS: No Brake Measurements Required For Level 3	
VIOLATIONS	
Vio Code 392.2-SLLS2Section 392.2Unit DOOS NCitation # NVerify Crast N	h <u>Violations Discovered</u> State/Local Laws - Speeding 6-10 miles per hour over the speed limit.: 60/50
HazMat: No HM Transported.	Placard: No Cargo Tank:
Special Checks: Traffic Enforcement;	
CERTIFICATION of REPAIRMAN: I certify that the violations marked above have been satisfactorily repaired.	
Failure to return this report with the required certification can result in penalties up to \$1,000 per day for each day	y the violation continues, up to a total of \$10,000.
	: Date:
*** NOTE TO DRIVER: This report must be furnished to the motor carrier whose name is listed above.	
CARRIER CERTIFICATION: The undersigned certifies that all driver and vehicle violations on this report have be and HM Regulations insofar as they are applicable to motor carriers and drivers. This certification MUST BE SIGN address at the top of this form.	

____ Title:__

Signature Of Motor Carrier X:____



Copy Received By:

Χ_



_ Date:_

Χ_

	DRIVE	R/VEHICLE	EXAMINA	TION RE	EPORT	Query Central 3.4
South Carolina State Tran P. O. Box 1993 https://www.scdps.sc.gov Blythewood, SC 29016 Phone: (803)896-5500 Fax	/scstp		Report Number: SCY309000867 Inspection Date: 07/16/2020 Start: 1:45 PM ET End: 02:20 PM ET Inspection Level: III - DriverOnly HM Inspection Type: None			
ANNUR TRANS LLC 4752 MEMORIAL DRIVE SU DECATUR, GA 30032 USDOT#: 02146174 MC/MX#: 00746539 State#:	IITE B Phone#: (404)8: Fax#: (888)60		Li Da Co Li	river: cense#: ate of Birt oDriver: cense#: ate of Birt		State: GA State:
Location: I-85 NB ROADSII Highway: County: CHEROKEE, SC	DE		LLENWOOD	,GA	per: KROGER Bill of Lading: 15 VA Cargo: GENERAL	
VEHICLE IDENTIFICATIO	N					
UnitTypeMakeYearState1TTFRHT2005GA2STWANC2020TN	<u>Plate #</u> C815CN 053595T	Equipment ID 6875 63640R	<u>VIN</u> 1FUJBBCG28 1JJV532B5L		<u>GVWR</u> <u>CVSA # N</u> 52,000 68,000	lew CVSA # OOS#
BRAKE ADJUSTMENTS: No Brake Measurements Required For Level 3						
VIOLATIONS						
Vio CodeSection392.2LV392.2	n <u>Unit</u> D	N WA063		<u>Crash</u> N	Violations Discovered Lane Restriction violation only allowed to travel in construction on I 85.	n: Travelling in lane 2,
396.17C 396.17	7(c) 1	N WA063	332 N	Ν	Operating a CMV withou inspection: Annual inspe expired June 2020.	
HazMat: No HM Transported	l.				Placard: No	Cargo Tank:
Special Checks: Traffic Enforcement;						
CARRIER CERTIFICATION: The unde Carrier Safety and Hazardous Material F RETURNED WITHIN 15 days to the: So Signature Of Motor Carrier X:	Regulations insofar as they uth Carolina State Transpo	are applicable to m ort Police, P.O. Box Title:	otor carriers and di 1993, Blythewood,	rivers. This ce South Carolin	rtification MUST BE SIGNED by	

Signature Of Motor Carrier X:______ Title:______

___ Date:____

Report Prepared By:



Copy Received By:

Χ_

Page 1 of 2

Χ_

DRIVER/VEHICLE EXAMINATION REPORT

South Carolina State Transport Police P. O. Box 1993 https://www.scdps.sc.gov/scstp Blythewood, SC 29016 Phone: (803)896-5500 Fax: (803)896-5526

ANNUR TRANS LLC 4752 MEMORIAL DRIVE SUITE B DECATUR, GA 30032 USDOT#: 02146174 MC/MX#: 00746539 State#: Phone#: (404)826-3001 Fax#: (888)608-1388 EPORIQuery Central 3.4Report Number:SCY309000867Inspection Date:07/16/2020Start:1:45 PM ET End:Inspection Level:III - DriverOnlyHM Inspection Type:None

Driver:	
License#:	State: GA
Date of Birth:	
CoDriver:	
License#:	State:
Date of Birth:	

Inspection Notes

Driver had copies of Annual Inspection paperwork, but not for vehicle that was being operated at the time of the inspection.

Special Studies No Special Study Data Recorded

Report Prepared By:



Copy Received By:

Page 2 of 2

ti lopaloa by:

Х

146174 SC SC 309000867

X