## DEPARTMENT OF HOMELAND SECURITY

U.S. Coast Guard

OMB No: 1625-0001 Exp. Date: 07/31/2022

REPORT of MARINE CASUALTY			/ING CASUALTY	, or OCS-RELA	TED CASUALTY		
1. Vessel or Facility Name HAFNIA AMESSI	2. Vessel Official 9719745			3. Vessel Flag Singapore			
		i, Vessel Gross Tons		6. Vessel Propulsion Type			
4. Vessel Length 184.06 Feet Meters	23,676						
7. Vessel or Facility Type Chemical Tanker	8. Vessel or Facil	lity Service or (	Occupation				
9. 9a. Arrangement: 9b. Number of V		9c. Maximum S	Size of Tow/Tow-Boat(s):	9d. Did one or more of the	barges in the tow cause or		
FOR Pushing Ahead Empty		Length feet		sustain damage in the marine casualty?  Yes No			
ONLY Towing Astern Loaded Total		Width		(If Yes complete and attach one or more CG-2692A forms to this report)			
Section II - Reason for Submitting this Report (Check all that apply)							
10. The above vessel was involved in a Marine C  1. Unintended grounding or an unintended strike 2. Intended grounding or intended strike of a bioriteria in 3 through 8 below 3. Loss of main propulsion, primary steering, of 4. Occurrence materially and adversely affected 5. Loss of life 6. Injury that requires professional medical trecommercial service, that renders the individual 7. Occurrence causing property damage in exion 8. Occurrence involving significant harm to the 11. The above facility or vessel was involved in a 1. Loss of life 2. Diving-related injury to any person causing a 3. Diving-related injury to any person requiring 12. The above facility or vessel was involved in an 1. Death 2. Injury to 5 or more persons in a single incide 3. Injury causing any person to be incapacitate 4. OCS Facility only - Damage affecting the us 5. OCS Facility only - Damage to the facility exits the strike of the secility exits of the secility exits of the facility exits of the faci	ke of (allision with) a bridge that created a had bridge that created a had bridge that created a had bridge that created compared the vessel's seawork atment (treatment beyond the perform his or crease of \$75,000 environment.  Commercial Diving incapacitation for more in hospitalization for more in OCS Facility Casulant bed for more than 72 hospitalizes of primary life performents of primary life.	oridge azard to navige ponent or contri thiness or fitne ond first aid) air r her routine du  Casualty inv e than 72 hours are than 24 hou ualty Resultin	tition, the environment or the second system that reduces the mass for service or route and, if the person is engaged or titles and the second system (46 CFR 197.484):  The second system of the seco	employed on board a vessel			
6. OCS Facility only - Damage to a floating OC	S facility exceeding \$	25,000					
Section	n III - Associated P	arties Inform	nation (Fill all fields that	apply)			
13. Name of Owner	Telepho	one	14. Name of Operator or M	Manager	Telephone		
Sea 342 Leasing Co. Limited,			Suntech Ship Mar	nagement			
Address 27/F Three Exchange Square	Email a	**************************************	Address #2-24 Nordic Eu	ropean Center,	Email address		
8 Connaught Place, Central Hong Kong	china.c		<ol> <li>International Park, Singapore</li> </ol>		marine@suntech -maritime.com		
15. Name of Master or Person-In-Charge (Last, First, M	fiddle) Telepho	Control of the Contro	16. Name of Agent (Last,		Telephone		
Sheikh, Sahanawaz			Moran Shipping A	Agencies, Inc.			
Address Please refer to Block 14	suntech	-@	Address 1 Diamond Causev Savannah, Georgi		Email address  @moranshipp ing.com		
17. Name of Dive Supervisor (Last, First, Middle)	Telepho	one	18. Name of Pilot (Last, Fi	rst, Middle)	Telephone		
Address	Email ad	ddress	Address		Email address		
	Section	IV - Casual	ty Information				
19. Date/Time (local) of Occurrence 14 Jan. 2024 / 1019 hours	20. Location-Name of Body of Water or Waterway: Latitude:  Cooper River, Pier Bravo  Longitude:  River Mile Marker:  OR						
21. Property Damage Estimated Damage Cost(s) to:	perty Damage Estimated Damage Cost(s) to:  Describe the Extent of Property Damage  Minor departs of Property Damage						
Vessel: \$UNK Cargo: \$ Minor damage to end of Pier Bravo, Joint Base Charleston, as vessel's starboard side grazed dolphin/pier.							
22. Status of Involved Persons (If there are 1 or more injure							
Total Number of Persons: On Board the Vessel: 24 Injured: 0 Dead: 0 Missing: 0							

A CONTRACTOR OF THE PROPERTY O	Section IV - Casualty	Information (continued)				
Section IV - Casualty Information (continued)  23. Was This Casualty a Serious Marine Incident (SMI) as Defined in 46 CFR 4.03-2?						
Yes No Not at this Time, But is Likely	to Become an SMI (If Ye	s or Is Likely to Become an SMI complete/attach one or mo				
24a. Is there any evidence of alcohol or drug use by or intoxicat involved in the casualty?	. Is there any evidence of alcohol or drug use by or intoxication of individuals directly blved in the casualty?  24b. Did any individual directly involved in a casualty refuse to submit to, or cooperate in, the administration of a timely chemical test, when directed by a law enforcement officer or the marine employer?					
Yes No (If Yes, identify those individuals for been obtained and specify the methevidence in block 24c)		Yes No (If Yes, note the individual(	s) who refused in block 24c)			
24c. Individuals with evidence of drug or alcohol use, evidence 25c) NA	of intoxication, or who refu	sed to submit/cooperate in a timely chemical test (if more s	space is needed, continue in block			
24d. Is there evidence that alcohol use contributed to thi	s casualty?					
Yes X No. (If Yes, discuss in block 25b)						
25. Nature and Circumstance of the Casualty:						
25a. Activity or Operation Being Conducted at the Time of the Casualty: The vessel was transiting downriver in the Cooper River under pilotage.						
25b. Description of the Casualty (casualty events and the conditions and actions that were believed to be causal factors as well as any hazards created as a result of the casualty. Attach additional sheets if necessary):  On downriver approach to Pier Bravo, the pilot ordered Port 20 on the rudder when coming around channel marker 72, but the ship did not turn to port. The Pilot ordered hard-to-port, engine half ahead. The rudder turned, but there was no rate of turn. The pilot ordered full-to-port. The rudder turned, but the ship continued on a straight course in the direction of Pier Bravo. Pilot ordered engine stop and tug boat to push from starboard bow. With tug's assistance, ship's course turned to port slightly just before vessel grazed dolphin/end of Pier Bravo. We confirmed no pollution or injuries, contacted the Coast Guard, and proceeded to Columbus Street Terminal without further incident.						
25c. Any other comments, including with respect to use of or need for emergency response equipment: NA						
	Section V - Perso	n Making this Report MT HAFNIA AMESSI				
24. Name (PRINT) (Last, First, Middle) Sheikh, Sahanawaz	25. Signature:		26. Date 19 January 2024			
27. Title Master	28. Address Aboard the M/1	HAFNIA AMESSI	Maria de la companio			
29. Telephone No.	30. Email		8-0-1			
2 C000		@suntech-fleet.com				