

Mechanical Fitting Failures for Jan 01, 2014 through Jan 31, 2024 for South Jackson

Map Record Number	Leak Number	Address	Leak Found Date	Leak Grade Found	Highest Leak Grade	Facility	Facility Involved	Leak Repair Date	Origin	Pipe Type	Threat	Coating Type	City	State	Leak Repair Comments	PSP Reading (Millivolt)
1	LEAK846209	5136 GERTRUDE DR JACKSON	12/12/2023	1	1	DIST	SERVICE	12/12/2023	FITTING	STEEL	NATURAL FORCES	HOT COATED	JACKSON	MS	Mechanical Fitting At Riser Leaking. Squeezed And Night Capped Service. Wrote Up To Be Killed.	-900
2	LEAK814329	5052 LURLINE DR JACKSON	3/23/2015	1	1	DIST	SERVICE	3/23/2015	FITTING	STEEL	EQUIPMENT	HOT COATED	JACKSON	MS	Abandon Old Tap & Removed The Riser.Installed Weld Tee With Efv,Inserted 1/2 Cts Pipe To Replace The 1" Stl S/L Due To A Leaking Dresser.Set New Ris	-1030
3	LEAK814159	5063 LURLINE DR JACKSON	3/14/2015	1	1	DIST	SERVICE	3/14/2015	FITTING	STEEL	EQUIPMENT	HOT COATED	JACKSON	MS	Abandon Old Tap & Removed The Riser.Installed Weld Tee With Efv,Inserted 1/2 Cts To Replace The 1" Stl S/L Due A Leaking 1" Dresser.Set New Riser &	-1030
4	LEAK812033	1914 RAYMOND RD JACKSON	10/21/2014	1	1	DIST	SERVICE	10/21/2014	COUPLING	STEEL	EQUIPMENT	HOT COATED	JACKSON	MS	Found 64' Of Isolated Steel . We Also Found For 22' The Service Was Only 3" Deep . Found Leak On The Compression Riser Ell . Open Cut For 22 ' Used Th	-400
5	LEAK817886	3291 BEINVILLE DR JACKSON	1/13/2016	1	1	DIST	SERVICE	1/13/2016	FITTING	STEEL	NATURAL FORCES	HOT COATED	JACKSON	MS	The 3/4" Mechanical Fitting Was Leaking I Replaced The Ser From The Main To The Riser.	-1020
6	LEAK812780	1144 VERBENA ST JACKSON	12/30/2014	1	1	DIST	SERVICE	12/30/2014	COUPLING	STEEL	EQUIPMENT	HOT COATED	JACKSON	MS	Found Leak On A Compression Coupling . Kill The Service At The Tap . Lremove Valve From Riser . For Locate Propose / Soap Wrap And Back Fill	-1140
7	LEAK846731	3078 FLEETWOOD DR JACKSON	1/26/2024	1	1	DIST	SERVICE	1/26/2024	FITTING	STEEL	NATURAL FORCES	MILL WRAP	JACKSON	MS	Grade 1 Leak On Tie In Tigheten Steal To Plastic Dresser Service Is To Be Replaced	-860
8	LEAK818190	3065 SUNCREST DR JACKSON	2/17/2016	1	1	DIST	SERVICE	2/17/2016	FITTING	STEEL	EQUIPMENT	HOT COATED	JACKSON	MS	Lk. On Mech. Fitt Weld .75 Efv Service Tee On 2" Mian Kill Old Tap Shut Off Plug & Cap Seal Around Inseted Pipe Had To Bust Driveway To Access Main	-1200
9	LEAK810703	1004 BROOKLEY STREET JACKSON	4/28/2014	1	1	DIST	SERVICE	4/28/2014	COUPLING	STEEL	EQUIPMENT	HOT COATED	JACKSON	MS	Found Bubbles In The Ditch At The Tie In . Service Has Not Been Active For Several Years . Killed At The Tap . Soap Wrap Backfill	-1200
10	LEAK811614	2375 MCDOWELL RD JACKSON	9/12/2014	1	1	DIST	MAIN	9/12/2014	COUPLING	STEEL	EXCAVATION	HOT COATED	JACKSON	MS	Foun D The Main Pulled Out Close The Valve , Cutout And Install Roll 2 2" Weld Ells .Install Anodes . Soap Wrap And Backfill	-600
11	LEAK825611	3021 MCDOWELL RD EXT JACKSON	1/18/2018	1	1	DIST	SERVICE	1/18/2018	COUPLING	STEEL	EQUIPMENT	HOT COATED	JACKSON	MS	C#0296094 Mpl Replaced Svc	-920
12	LEAK829861	1509 WOODY DR JACKSON	1/17/2019	1	1	DIST	SERVICE	1/17/2019	FITTING	STEEL	NATURAL FORCES	HOT COATED	JACKSON	MS	Cwo# 070.389103 Lk On Mech. Fitt. On Riser Inset Weld .75 Efv Ser Tee On 2" Mian Kill Old Tap Shut Off Tap Weld Cap On Outlet Of Tap	-1850
13	LEAK813682	0000 COOPER RD JACKSON	2/11/2015	1	1	DIST	MAIN	2/11/2015	FITTING	STEEL	EQUIPMENT	HOT COATED	JACKSON	MS	Three Bolt Coupling Was Leaking On 2" Main , Weld 2" Punkin On Main Encapsulation The Three Bolt Couplong Had To Bust Street To Access The Mai	-1100
14	LEAK846837	1471 WOODY DR JACKSON	1/31/2024	1	1	DIST	SERVICE	1/31/2024	COUPLING	STEEL	EQUIPMENT	HOT COATED	JACKSON	MS	Tightened 1" Dresser. Rr	-980
15	LEAK821412	1663 W MCDOWELL RD JACKSON	1/5/2017	1	1	DIST	SERVICE	1/5/2017	COUPLING	STEEL	EQUIPMENT	HOT COATED	JACKSON	MS	Found Leak On Service Killed Behind Curd With Marker And Wire Per Dg . Co # 0282069 14040 Mcdonald	-850
16	LEAK809956	375 LEA CIR JACKSON	1/31/2014	1	1	DIST	MAIN	4/17/2014	COUPLING	STEEL	NATURAL FORCES	MILL WRAP	JACKSON	MS	Found Leak On 2"Mech. Dresser Repair With 2" Stl Weld Split Sleeve	-940
17	LEAK828786	1748 SOUTHAVEN CIR JACKSON	10/17/2018	1	1	DIST	SERVICE	10/17/2018	FITTING	STEEL	EQUIPMENT	HOT COATED	JACKSON	MS	Cwo. 0389854 Lk On Mech Fitt . Kill At Tap Shut Off , Weld .75 Cap On Outlet Of Tap On Ser On 2" Main	-1100
18	LEAK846786	1760 WOOD GLEN RD JACKSON	1/29/2024	1	1	DIST	SERVICE	1/29/2024	COUPLING	STEEL	EQUIPMENT	HOT COATED	JACKSON	MS	Tightened Dresser On 3/4" Steel Service. Rr	-940
19	LEAK845554	1754 WOOD GLEN DR. JACKSON	11/15/2023	1	1	DIST	SERVICE	11/15/2023	FITTING	STEEL	NATURAL FORCES	HOT COATED	JACKSON	MS	.75" Service Pulled From Mechanical Fitting On 4" Main. Welded On Two 4" Short Stops And Dropped Stops And Killed Service.	-1070
20	LEAK818447	3041 3041 MEADOW FOREST DR JACKSON	3/17/2016	1	1	DIST	SERVICE	3/17/2016	FITTING	STEEL	EQUIPMENT	HOT COATED	JACKSON	MS	Lk. On Mech. Fitt . Weld .75 Servcie Tee On 2" Main . Kill Old Tap Shut Off Plug & Cap , Install New Riser & Meterbar Waxwrap & Backfill	-910
21	LEAK817512	2958 MEADOW FOREST DR JACKSON	11/20/2015	1	1	DIST	SERVICE	11/20/2015	FITTING	STEEL	NATURAL FORCES	HOT COATED	JACKSON	MS	Killed 30 Feet Of 1" Steel Service Line At Tap Due To Leaking Mechanical Fitting.	-990
22	LEAK818238	323 MCDOWELL PARK CIR JACKSON	2/24/2016	1	1	DIST	SERVICE	2/24/2016	FITTING	STEEL	NATURAL FORCES	HOT COATED	JACKSON	MS	Mech Fitting On Tee Was Leakin...Retired 72' Of 1" Stl S/L At Main...Removed Riser... Main Is 36" Deep	-960
23	LEAK828787	412 MCDOWELL PARK CIR JACKSON	10/18/2018	1	1	DIST	SERVICE	10/18/2018	COUPLING	STEEL	EQUIPMENT	MILL WRAP	JACKSON	MS	C#0282709 Leak On Riser Killed At Tap Inserted New Service Tested Left Ok	-980
24	LEAK819459	3025 LAKEWOOD DR JACKSON	6/30/2016	1	1	DIST	SERVICE	6/30/2016	FITTING	STEEL	NATURAL FORCES	HOT COATED	JACKSON	MS	Inserted 93 Feet Of 1/2" Cts Due To Leaking Mechanical Fitting On Service Line.	-960
25	LEAK813881	2936 LAKEWOOD DR JACKSON	2/26/2015	1	1	DIST	SERVICE	2/26/2015	FITTING	STEEL	NATURAL FORCES	HOT COATED	JACKSON	MS	Inserted 55 Feet Of Cts Pipe Due To Leaking Mechanical Fitting On Service Line.	-970
26	LEAK822659	3146 LAKEWOOD DR JACKSON	4/6/2017	1	1	DIST	SERVICE	4/6/2017	COUPLING	STEEL	EQUIPMENT	HOT COATED	JACKSON	MS	Found Compression Coupling Leaking At The Tap. Insert Service,Meter Bar ,Tee , Bond Wire. Mcdonald 14040 05 02 2017	-940

27	LEAK826180	3068 LAKEWOOD DR JACKSON	3/6/2018	1	1	DIST	SERVICE	3/6/2018	FITTING	STEEL	EQUIPMENT	HOT COATED	JACKSON	MS	Cwo# 0420034 Lk On Mech Fitt Weld .75 Efv Ser Tee On 2" Main Kill Old Tap Shut Off Weld Cap On Outlet Of Tap On 2" Stl Main	-957
28	LEAK834491	1621 WOOD GLEN DR JACKSON	8/19/2020	1	1	DIST	SERVICE	8/19/2020	COUPLING	STEEL	NATURAL FORCES	HOT COATED	JACKSON	MS	Replaced Service	-1300
29	LEAK846736	1341 RAYMOND RD JACKSON	1/26/2024	1	1	DIST	SERVICE	1/26/2024	FITTING	STEEL	NATURAL FORCES	HOT COATED	JACKSON	MS	Tightened Mechanical Fitting At Bottom Of Riser And Backing Nut On The Valve On Riser. Service Wrote Up To Be Killed. Pinned Service To Main No Leaks.	-930
30	LEAK826239	1816 FLOWERS DR JACKSON	3/13/2018	1	1	DIST	SERVICE	3/13/2018	COUPLING	STEEL	EQUIPMENT	HOT COATED	JACKSON	MS	Miller Crew Found The Tie End Leaking On A Compression Coupling. Inserted The S/L Weld New Tap Tee Meter Bar Riser 14040 Mcdonald 03 19 18	-1020
31	LEAK825695	2741 W BENWOOD DR JACKSON	1/19/2018	1	1	DIST	SERVICE	1/19/2018	COUPLING	STEEL	EQUIPMENT	HOT COATED	JACKSON	MS	C#0246806 Mpl Replaced Svc	-1020
32	LEAK822615	2733 W BENWOOD DR JACKSON	4/3/2017	1	1	DIST	SERVICE	4/3/2017	COUPLING	STEEL	EQUIPMENT	HOT COATED	JACKSON	MS	C#0315426 Mpl Replaced Svc	-1100
33	LEAK845843	1546 MARIA DR JACKSON	11/28/2023	1	1	DIST	SERVICE	11/28/2023	FITTING	STEEL	NATURAL FORCES	HOT COATED	JACKSON	MS	Grade 1 Leak On Service Tighten The Dresser On The Riseer	-1210
34	LEAK845850	1527 MARIA DR JACKSON	11/28/2023	1	1	DIST	SERVICE	11/28/2023	FITTING	STEEL	NATURAL FORCES	HOT COATED	JACKSON	MS	Grade 1 Leak On Service Tighten Up Dress Had Small Fizz Leak	-1250
35	LEAK828377	1424 BRINOY DR JACKSON	9/13/2018	1	1	DIST	SERVICE	9/13/2018	FITTING	STEEL	EQUIPMENT	MILL WRAP	JACKSON	MS	Killed 103' Of 1"Stl Service At Tap Due To Leake Inserted 103' Of 1/2 Cts And Wire Tested Left Ok	-980
36	LEAK835890	1518 WOOD GLEN DR JACKSON	3/3/2021	1	1	DIST	SERVICE	3/3/2021	FITTING	STEEL	EQUIPMENT	MILL WRAP	JACKSON	MS	Miller Repaired Service On Co# 0700509656	-1100
37	LEAK818899	936 WOODY DR JACKSON	5/5/2016	1	1	DIST	SERVICE	5/5/2016	COUPLING	STEEL	EQUIPMENT	HOT COATED	JACKSON	MS	Retired 42 Ft Of 1" Steel Service On A Grade 1 Leak On Riser. Vacant Service	-1000
38	LEAK818897	928 WOODY DR JACKSON	5/5/2016	1	1	DIST	SERVICE	5/5/2016	COUPLING	STEEL	EQUIPMENT	HOT COATED	JACKSON	MS	Retired 40 Ft Of 1" Steel Service On A Grade 1 Leak. Vacant Service.	-1000
39	LEAK812635	3264 ROSEMARY AVE. JACKSON	12/11/2014	1	1	DIST	SERVICE	12/11/2014	FITTING	STEEL	NATURAL FORCES	HOT COATED	JACKSON	MS	Inserted 108 Feet Of Cts Pipe Due To Leaking Mechanical Fitting On Service Line.	-990
40	LEAK811319	1377 MCDOWELL RD JACKSON	8/4/2014	1	1	DIST	SERVICE	8/4/2014	COUPLING	STEEL	EQUIPMENT	HOT COATED	JACKSON	MS	We Found The Riser Compression Ell Leaking . Replace The Service . Meter Bar . Bond Wire At The End Of The Serice Line . Weld New Tap Soap Wrap And Ba	-930
41	LEAK824905	3354 CHARLESTON DR. JACKSON	10/27/2017	1	1	DIST	SERVICE	10/27/2017	FITTING	STEEL	EQUIPMENT	HOT COATED	JACKSON	MS	Cwo.418988 Lk On Mech Fitt At Riser . Weld .75 Efv Ser Tee On 2" Stl Main Kill Old Tap Shut Off & Weld Cap On Outlet . Install 17# Anode On Main	-850
42	LEAK811398	3215 CHARLESTON DR JACKSON	8/13/2014	1	1	DIST	SERVICE	8/13/2014	FITTING	STEEL	EQUIPMENT	HOT COATED	JACKSON	MS	Leak On Mechancial Fitt . Weld .75 Efv Service Tee On 2" Main Kill Old Tap Shut Off Plug & Cap Seal Aroind Inseted Pipe Waxwrap & Backfill	-1000
43	LEAK817378	1139 DARDANELLE DR JACKSON	11/10/2015	1	1	DIST	SERVICE	11/10/2015	FITTING	STEEL	NATURAL FORCES	HOT COATED	JACKSON	MS	Inserted 123 Feet Of Cts Pipe Due To Leaking Mechanical Fitting On Service Line.	-1500
44	LEAK824008	3183 BILGRAY DR JACKSON	8/15/2017	1	1	DIST	SERVICE	8/15/2017	COUPLING	STEEL	EQUIPMENT	MILL WRAP	JACKSON	MS	C#0419185 Shut Svc Tee Off And Encapsulated Installed New Tee With Efv Svc Line Riser And Meter Bar Tested Left Ok	-920
45	LEAK845929	1107 SHALIMAR DR JACKSON	11/30/2023	1	1	DIST	SERVICE	11/30/2023	FITTING	STEEL	NATURAL FORCES	HOT COATED	JACKSON	MS	.75" Dresser Leaking At Tie In. Temp Repaired With Two .75" X .5" Cts Steel To Plastic Mechanical Fittings. Service Wrote Up To Be Replaced.	-950
46	LEAK824854	2024 SHADY LANE DR JACKSON	10/24/2017	1	1	DIST	SERVICE	10/24/2017	COUPLING	STEEL	EQUIPMENT	HOT COATED	JACKSON	MS	Miller Crew Inserted The Service. Weld Tee. Meter Bar ,Riser 10 24 17. Mcdonald 11 01 2017 14040	-1400
47	LEAK812474	2085 SHADY LANE DR JACKSON	11/28/2014	1	1	DIST	SERVICE	11/28/2014	FITTING	STEEL	EQUIPMENT	HOT COATED	JACKSON	MS	Gas Migrating Into Sewer.Leaking At Service Tap.Found A Dresser Ell Leaking,Vacant Riser No Meter.Resident All Electric,Retired The Srvce At The Main	-900
48	LEAK827983	1795 SHADY LANE DR JACKSON	8/7/2018	1	1	DIST	MAIN	8/7/2018	COUPLING	STEEL	EQUIPMENT	HOT COATED	JACKSON	MS	C#0417946 Miller Replaced Section Of Main And Valve	-1100
49	LEAK818000	3346 RICKAY DR JACKSON	1/26/2016	1	1	DIST	SERVICE	1/26/2016	FITTING	STEEL	NATURAL FORCES	HOT COATED	JACKSON	MS	Inserted 105 Feet Of Cts Pipe Due To Leaking Mechanical Fitting On Service Line.	-980
50	LEAK822643	3244 RICKAY DR JACKSON	4/5/2017	1	1	DIST	SERVICE	4/5/2017	COUPLING	STEEL	EQUIPMENT	HOT COATED	JACKSON	MS	C#0068947. Killed Svc At Tap. Welded New Svc Tee With Efv Inserted With New Riser And Meter Bar. Tested Left Ok	-1000
51	LEAK813817	495 WOODY DR JACKSON	2/20/2015	1	1	DIST	SERVICE	2/20/2015	FITTING	STEEL	EQUIPMENT	HOT COATED	JACKSON	MS	Leak On Mechancial Fitt At Riser . Weld .75 Efv Service Tee On 2" Main . Kill Old Tap Shut Off Plug & Cap . Seal Around Inserted Pipe Waxwrap & B	-1000
52	LEAK813177	3154 MONTICELLO DR JACKSON	1/21/2015	1	1	DIST	SERVICE	1/21/2015	FITTING	STEEL	NATURAL FORCES	HOT COATED	JACKSON	MS	Inserted 94 Feet Of Cts Pipe Due To Leaking Mechanical Fitting.	-1000
53	LEAK813175	3136 MONTICELLO DR JACKSON	1/21/2015	1	1	DIST	SERVICE	1/21/2015	FITTING	STEEL	NATURAL FORCES	HOT COATED	JACKSON	MS	Inserted 131 Feet Of Cts Pipe Due To Leaking Mechanical Fitting.	-1040
54	LEAK818309	2603 BROOKWOOD DR JACKSON	3/2/2016	1	1	DIST	SERVICE	3/2/2016	FITTING	STEEL	NATURAL FORCES	HOT COATED	JACKSON	MS	Inserted 65 Feet Of Cts Pipe Due To Leaking Mechanical Fitting On Service Line.	-1040

55	LEAK817487	3123 WHITTEN RD JACKSON	11/13/2015	1	1	DIST	MAIN	11/13/2015	FITTING	STEEL	NATURAL FORCES	HOT COATED	JACKSON	MS	Welded On 2" Tdw Fitting, Stopped Off And Killed 149 Feet Of 2" Steel Main Due To Leaking Three Bolt Mechanical Fitting.	-980
56	LEAK828489	1711 GIBRALTER DR JACKSON	9/21/2018	1	1	DIST	SERVICE	9/21/2018	FITTING	STEEL	EQUIPMENT	HOT COATED	JACKSON	MS	Cwo # 389841 Lk On Mech Fitt At Riser Ser Was Already Insert Tie With Mech Fitt At The Riser & Tie With Mech Fitt At The Tap Weild On Efv Tee & Rise	-1100
57	LEAK812027	1631 GIBRALTER DR JACKSON	10/21/2014	1	1	DIST	SERVICE	10/21/2014	FITTING	STEEL	EQUIPMENT	HOT COATED	JACKSON	MS	Leak On Mechancail Fitt At Riser , Weld .75 Efv Servie Tee On 2" Main . Kil L Old Tap Shut Off & Seal Aroiund Inserted Pipe New Meter Bar & Ano	-1000
58	LEAK816561	1777 CHESWOOD DR JACKSON	9/18/2015	1	1	DIST	SERVICE	9/18/2015	COUPLING	STEEL	EQUIPMENT	MILL WRAP	JACKSON	MS	Repair Made By Insertion Miller P/L 1/28/16 C0069284	-1300
59	LEAK819989	0000 ELLIS AVE JACKSON	8/25/2016	1	1	DIST	SERVICE	8/25/2016	FITTING	STEEL	EQUIPMENT	HOT COATED	JACKSON	MS	Lk On Mech. Fitt At Riser , Kill At Tap Shut Off Plug & Cap & Seal Dead Pipe Yes , Waxwrap & Backfill	-1200
60	LEAK815616	1945 BELVEDERE DR JACKSON	7/2/2015	1	1	DIST	SERVICE	7/2/2015	COUPLING	STEEL	EQUIPMENT	HOT COATED	JACKSON	MS	Found Compression Coupling Leaking At The Tie In . Replace The Service . Install Meter Bar Bond Wire Weld New Tee . Soap Wrap And Backfill	-1020
61	LEAK821991	235 COOPER RD JACKSON	2/6/2017	1	1	DIST	SERVICE	2/6/2017	FITTING	STEEL	EQUIPMENT	HOT COATED	JACKSON	MS	C# 0248837 Mpl Installed 154' Of Svc	-1200
62	LEAK846357	665 RAYMOND RD JACKSON	12/17/2023	1	1	DIST	MAIN	12/17/2023	FITTING	STEEL	EQUIPMENT	HOT COATED	JACKSON	MS	Cwo# 0700758435 Lk# 846357 G-1 Miller Pipe Line Encapsulate Fitting	-1100
63	LEAK812208	2526 PADEN ST JACKSON	11/4/2014	1	1	DIST	SERVICE	11/4/2014	FITTING	STEEL	EQUIPMENT	HOT COATED	JACKSON	MS	Abandon Old Tap & Removed The Riser, Installed Weld Tee- W- Efv. Inserted 1/2 Cts Pipe To Replace The 1" Stl S/L Due To Dresser Eil Leak At The Riser. Set	-1560
64	LEAK811973	2144 PADEN ST JACKSON	10/16/2014	1	1	DIST	SERVICE	10/16/2014	FITTING	STEEL	NATURAL FORCES	HOT COATED	JACKSON	MS	Inserted 65 Feet Of Cts Pipe Due To Leaking Mechanical Fitting At Riser.	-980
65	LEAK820000	2112 PADEN ST JACKSON	8/26/2016	1	1	DIST	SERVICE	8/26/2016	FITTING	STEEL	NATURAL FORCES	HOT COATED	JACKSON	MS	Mech Fitting On Riser Was Leaking...Inserted 1' Stl S/L Wtih .50" Cts P.E. S/L And Installed New Tee, Riser, And Meterbar Main Is 36" Deep	-980
66	LEAK818475	3845 NICHOLS BLVD JACKSON	3/21/2016	1	1	DIST	SERVICE	3/21/2016	FITTING	STEEL	NATURAL FORCES	HOT COATED	JACKSON	MS	Inserted 87 Feet Of Cts Pipe Due To Leaking Mechanical Fitting On Service Line.	-1160
67	LEAK824657	2267 ALTA WOODS TERR JACKSON	10/6/2017	1	1	DIST	SERVICE	10/6/2017	FITTING	STEEL	EQUIPMENT	HOT COATED	JACKSON	MS	Cwo# 418973 Lk On Mech Fitt Kill At Tap Shut Off & Weld Cap On Outlet On 2" Stl Main	-1100
68	LEAK823725	1918 BLVD ALTA WOODS BLVD JACKSON	7/19/2017	1	1	DIST	SERVICE	7/19/2017	COUPLING	STEEL	EQUIPMENT	MILL WRAP	JACKSON	MS	D. Taylor Inserted 66' 1/2" Pe Ser Due To Leak Co#0419616	-980
69	LEAK820269	2542 CORONET PL JACKSON	9/19/2016	1	1	DIST	SERVICE	9/19/2016	COUPLING	STEEL	EQUIPMENT	MILL WRAP	JACKSON	MS	D. Taylor Killed 128' 1" Stl Service At Tap To Remave Leak Co#0282017	-1290
70	LEAK815945	448 W MCDOWELL RD JACKSON	8/5/2015	1	1	DIST	MAIN	8/5/2015	COUPLING	STEEL	EQUIPMENT	MILL WRAP	JACKSON	MS	Mpl Line Removed 2 2" Cplgs And Replaced A Valve And Enc. A Valve Co#0075961	-1020
71	LEAK820030	540 MOCKING BIRD LN JACKSON	8/30/2016	1	1	DIST	SERVICE	8/30/2016	FITTING	STEEL	EQUIPMENT	HOT COATED	JACKSON	MS	Lk On Mech Fitt . Weld .75 Efv Ser. Tee On 2" Kill Old Tap Squeeze Off Tap Weld Punkin Over Tap Inst New Riser & Meterbar Waxwrap & Backfill	-1000
72	LEAK824619	507 CUMMINGS ST JACKSON	10/4/2017	1	1	DIST	SERVICE	10/4/2017	FITTING	STEEL	EQUIPMENT	HOT COATED	JACKSON	MS	Cwo 418997 Lk On Mech Fitt At Riser Kill At Tap Shut Off Weld Cap On Outlet Of Tee On 2" Stl Main Waxwrap & Backfill	-1100
73	LEAK813770	404 MCDOWELL RD JACKSON	2/17/2015	1	1	DIST	SERVICE	2/17/2015	FITTING	STEEL	EQUIPMENT	HOT COATED	JACKSON	MS	Leak On Mechancail Fitt At Riser Kill At Tap Shut Off Plug & Cap . Seal Dead Pipe Yes Bust Street To Get To Main Waxwrap & Backfill . Pin Hole No	-1300
74	LEAK809824	417 CUMMINS JACKSON	1/13/2014	1	1	DIST	SERVICE	1/13/2014	FITTING	STEEL	NATURAL FORCES	HOT COATED	JACKSON	MS	Killed 45 Feet Of 1" Steel Pipe At Tap Due To Leaking Mechanical Fitting . The Leak At Tap Was At 1832 Kenmore Dr. Instead Of 1829.	-1010
75	LEAK828573	513 MERIGOLD DR JACKSON	10/1/2018	1	1	DIST	SERVICE	10/1/2018	FITTING	STEEL	EQUIPMENT	HOT COATED	JACKSON	MS	Cwo# 0389845 Lk On Mech Fitt Weld .75 Efv Ser Tee On Main Insert Kill Old Tap Weld Cap On Outlet On Cap On 2" Main	-1100
76	LEAK810527	338 COLONIAL DR JACKSON	4/3/2014	1	1	DIST	SERVICE	4/3/2014	FITTING	STEEL	EQUIPMENT	BARE	JACKSON	MS	Leak On Mechancail Fit At The Riser , Weld .75 Efv Service Te On 2.5 Main , Kill Old Tap Shut Off Plug & Cap Wawrap & Backfill	-1100
77	LEAK821446	115 N.W. PINECREST CIR JACKSON	1/8/2017	1	1	DIST	SERVICE	1/8/2017	FITTING	STEEL	EQUIPMENT	HOT COATED	JACKSON	MS	C.W.O #68711 Lk On Mech Fitt . Weld .75 Efv Tee On 2" Mian . Kill Old Tap Weld On Two Tdw Fitt To Stop Off Kill Tap , Installl Marker Ball Under Tdw	-1100
78	LEAK817395	2033 WILL O WISP WAY JACKSON	11/10/2015	1	1	DIST	SERVICE	11/10/2015	COUPLING	STEEL	EQUIPMENT	HOT COATED	JACKSON	MS	Found Compression Coupling On The Main Cut Out And Replace 5 Of Two Stl . Killed The Service . Soap Warp And Backfill	-900
79	LEAK846780	1936 WILLOW WAY JACKSON	1/29/2024	1	1	DIST	MAIN	1/29/2024	COUPLING	STEEL	EQUIPMENT	MILL WRAP	JACKSON	MS	Kevin Moncrief Miller, Replaced 15ft Of Main, Rb	-1010
80	LEAK820016	1825 EAST DR JACKSON	8/29/2016	1	1	DIST	SERVICE	8/29/2016	COUPLING	STEEL	EQUIPMENT	HOT COATED	JACKSON	MS	Leak On Dresser Eil At Riser. Killed Service To Repair Leak. House Has Been Vacant Longer Than 3 Years	-980
81	LEAK829983	2976 N. TERRY RD. JACKSON	2/1/2019	1	1	DIST	SERVICE	2/1/2019	COUPLING	STEEL	EQUIPMENT	MILL WRAP	JACKSON	MS	Miller Co# 0511347	-1100
82	LEAK825547	2357 OAKHURST DR JACKSON	1/10/2018	1	1	DIST	SERVICE	1/10/2018	COUPLING	STEEL	EQUIPMENT	HOT COATED	JACKSON	MS	C#0246802 Mpl Replaced Svc	-1100

83	LEAK820014	1803 WALTHAM ST JACKSON	8/29/2016	1	1	DIST	SERVICE	8/29/2016	FITTING	STEEL	EQUIPMENT	HOT COATED	JACKSON	MS	Lk On Mech Fitt At Riser Bust Street Kill At Tap Shut Off Plug & Cap Seal Dead Pipe Yes Waxwrap & Backfill	-1000
84	LEAK835512	111 E MCDOWELL RD JACKSON	1/1/2021	1	1	DIST	SERVICE	1/1/2021	FITTING	STEEL	EQUIPMENT	MILL WRAP	JACKSON	MS	Miller Abandon Service On Co# 0700509801	-1200
85	LEAK820035	245 MARLA AVE JACKSON	8/30/2016	1	1	DIST	SERVICE	8/30/2016	COUPLING	STEEL	EQUIPMENT	MILL WRAP	JACKSON	MS	Mpl Inserted 108' 1/2" Pe Service Dur To Leak On Comp. Coupling Co#0280066	-1020
86	LEAK820032	214 SHADY CIR JACKSON	8/30/2016	1	1	DIST	SERVICE	8/30/2016	COUPLING	STEEL	EQUIPMENT	MILL WRAP	JACKSON	MS	Mpl Inserted 124' 1/2" Service Due To Leak On Comp. Coupling Co#0280067	-1000
87	LEAK812338	215 CARMEL AVE JACKSON	11/18/2014	1	1	DIST	SERVICE	11/18/2014	FITTING	STEEL	NATURAL FORCES	HOT COATED	JACKSON	MS	Inserted 138 Feet Of Cts Pipe Due To Leaking Mechanical Fitting At Riser.	-940
88	LEAK819642	0000 INTERSECTION OF GREENWOOD AVE AND MCDOWELL RD JACKSON	7/23/2016	1	1	DIST	MAIN	7/23/2016	COUPLING	STEEL	EQUIPMENT	HOT COATED	JACKSON	MS	Miller Pipe Line Cut And Replaced 35' Of 6" Stl. Test The 6" Replacement At 150lb'S For 1 Hour. Tap. Stop Cut And Cap. Rebuild Tie In To Greenwood	-1000