

SURVIVAL FACTORS ATTACHMENT

The Woodlands Fire Department Reports


(BFIR and CAD)

Spring, Texas

HWY21MH007

(36 pages)


A SA416 TX DD 17 17 Incident Date 5	YYYY 2021 7 0004476 000 Change Change NFIRS-1 Basic
	SPRING TX 77389 - State ZIP Code
C Incident Type ☐ 131 ☐ Passenger vehicle fire Incident Type ☐ Aid Given or Received ☐ None ☐ Mutual aid received ☐ Auto. aid received ☐ Their FDID Their State ☐ Auto. aid given ☐ Auto. aid given ☐ Their Incident Number	E1 Dates and Times Month Day Year Hour Min
Actions Taken Extinguishment by [11] [fire service personnel] Primary Action Taken (1) [24] [Recover body] Additional Action Taken (2) Additional Action Taken (3)	G1 Resources G2 Estimated Dollar Losses and Values Check this box and skip this block if an Apparatus or Personnel Module is used. Apparatus Personnel Suppression
Completed Modules ▼ Fire-2 □ Structure Fire-3 □ Civilian Fire Cas4 ▼ Fire Service Cas5 □ EMS-6 □ HazMat-7 □ Wildland Fire-8 ▼ Apparatus-9 ▼ Personnel-10 □ Arson-11 □ Unknown	1
Property Use None Structures 131 Church, place of worship 161 Restaurant or cafeteria 162 Bar/Tavern or nightclub 213 Elementary school, kindergarten 215 High school, junior high 241 College, adult education 311 Nursing home 331 Hospital Outside 124 Playground or park 655 Crops or orchard 669 Forest (timberland)	341 ☐ Clinic, clinic-type infirmary 342 ☐ Doctor/Dentist office 361 ☐ Prison or jail, not juvenile 419 ☐ 1- or 2-family dwelling 429 ☐ Multifamily dwelling 439 ☐ Rooming/Boarding house 449 ☐ Commercial hotel or motel 459 ☐ Residential, board and care 459 ☐ Residential, board and care 464 ☐ Dormitory/Barracks 519 ☐ Food and beverage sales 936 ☑ Vacant lot 938 ☐ Graded/Cared for plot of land 946 ☐ Lake, river, stream 951 ☐ Railroad right-of-way 953 ☐ Clinic, clinic-type infirmary 539 ☐ Household goods, sales, repairs 579 ☐ Motor vehicle/boat sales/repairs 615 ☐ Electric-generating plant 629 ☐ Laboratory/Science laboratory 700 ☐ Manufacturing plant 819 ☐ Livestock/Poultry storage (barn) 882 ☐ Non-residential parking garage 891 ☐ Construction site 984 ☐ Industrial plant yard 984 ☐ Industrial plant yard




Roald Hoppel - TK108 April 20,2021 21:18:55

ON 04/17/2021 @ 21:28, TK108 WAS DISPATCHED TO 22 HAMMOCK DUNES PLACE FOR A REPORTED CAR FIRE, WITH OTHER UNITS ALREADY ENROUTE. AT 21:33 TK108 HAD FIRECOM NOTIFY CARLTON WOODS SECURITY THAT TWFD UNITS WOULD BE USING THE BRANSON WAY ENTRANCE. E107 ARRIVED ON LOCATION AND WENT OUT WITH ONE VEHICLE IN THE WOODS. FULLY INVOLVED. AT 21:36 TK108 ARRIVED ON LOCATION AND ESTABLISHED HAMMOCK DUNES INCIDENT COMMAND. TK108 OFFICER DID A FACE-TO-FACE PASS-ON WITH THE ACTING E107 OFFICER. THE VEHICLE WAS A SHORT DISTANCE FROM THE DRY CONCRETE ROAD AND HAD IMPACTED A TREE FRONTALLY AND REMAINED FULLY INVOLVED. THE REAR DRIVER SIDE TIRE WAS VISIBLE AND INDICATED THE VEHICLE TO BE A TESLA THAT HAD BEEN TRAVELING FROM EAST TO WEST ON HAMMOCK DUNES PLACE, THE ROAD DEAD ENDS TO THE EAST. TK108'S FIREFIGHTERS JOINED E107'S FIRE ATTACK. TK108'S DRIVER ASSISTED E107'S DRIVER WITH PUMP OPERATIONS AND SECURING A SUPPLY LINE. AT 21:39 BC102 ASSUMED HAMMOCK DUNES COMMAND FROM TK108 OFFICER, IN A FACE-TO-FACE PASS-ON. AT 21:40 THE MAJORITY OF THE FIRE HAD BEEN KNOCKED DOWN AND IT BECAME EVIDENT THAT THE VEHICLE WAS OCCUPIED. THERE WAS ONE OCCUPANT IN THE FRONT PASSENGER SEAT AREA AND ANOTHER IN THE REAR DRIVER SIDE AREA. THE PLACEMENT OF THE OCCUPANTS RAISED IMMEDIATE CONCERNS THAT THERE MIGHT BE MORE OCCUPANTS AND A SEARCH WAS STARTED IN THE HEAVILY WOODED AREA OF THE CRASH AND AROUND THE POND USING MULTIPLE FIREFIGHTE

✓ More remarks? Check this box and attach Supplemental Forms (NFIRS-1S) as necessary.






E 3	Supplemental Special Local Option	Studies					NFIRS-1S Supplemental
1	Special Special Study ID# Study Value	Special Study ID#	Special Study Value	3 Special Study ID#	Special Study Value	Special Study ID#	Special Study Value
5	Special Special Study ID# Study Value	Special Study ID#	Special Study Value	7 Special Study ID#	Special Study Value	Special Study ID#	Special Study Value
L	Remarks: Local Option						

R USING THERMAL CAMERAS. CONSTABLE OFFICERS FROM PCT. 4 MADE CONTACT WITH FAMILY MEMBERS OF THE OCCUPANTS OF THE VEHICLE AND CONFIRMED THAT THERE WERE TWO OCCUPANTS IN THE VEHICLE SO THE SEARCH WAS DISCONTINUED. TK108 OFFICER ASSISTED MCHD M24 ON SCENE WITH TWO DISTRAUGHT FEMALE FAMILY MEMBERS OF THE OCCUPANTS IN THE VEHICLE. M24 ASSISTED THEM WITH NOTIFYING MORE FAMILY MEMBERS WHO WERE REQUESTED TO COME TO THE SCENE. TK108 OFFICER AT THAT POINT WENT TO THE ROADBLOCK AT THE BEGINNING OF HAMMOCK DUNES PLACE TO AWAIT THE ARRIVAL OF THOSE FAMILY MEMBERS. CCEMS M512 ARRIVED ON LOCATION FOR A CARDIAC PATIENT ON HAMMOCK DUNES PLACE AND TK108 OFFICER ASSISTED THEM NAVIGATE THE SCENE. M512 DETERMINED THIS WAS THE SAME PATIENT M24 HAD CHECKED OUT EARLIER AND THEY HAD BEEN CALLED TO THE SCENE BY PCT.4 BUT THERE WAS NO MEDICAL EMERGENCY. TK108 OFFICER WAS NO LONGER NEEDED TO ESCORT FAMILY AS THEY HAD FOUND ANOTHER WAY IN. BACK AT THE SCENE OF THE CRASH LATENT HEAT HAD REIGNITED THE FIRE IN THE VEHICLE AND FIRE SUPPRESSION HAD RESUMED, DURING WHICH TK108'S DRIVER HAD BEEN INJURED BY A FIRE HOSE. THE SPARE AIR SUPPLY AT THIS POINT HAD BECOME CRITICALLY LOW AND BC102 DECIDED TO BRING THE INJURED FIREFIGHTER TO WOODLAND MEMORIAL ER WEST AND DROP OFF THE EMPTY AIR CYLINDERS AT STATION 5 FOR REFILLING. AT 23:57 TK108 OFFICER ASSUMED COMMAND FROM BC102. AT THIS POINT A BLITZFIRE WAS DEPLOYED TO COOL THE VEHICLE AND A 1.75" ATTACK LINE AND A BOOSTER LINE FROM E107 WERE ALL BEING USED TO KEEP THE INCIDENT IN CHECK. PCT. 4 DEPUTY SINGLETON NOTIFIED COMMAND THAT HARRIS COUNTY HAZMAT WOULD BE NEEDED TO DECONTAMINATE THE VICTIMS, THE UNITS WOULD TAKE ABOUT AN HOUR TO ARRIVE, THE WOODLANDS FIRE DEPARTMENT HAZMAT TEAM THAT WAS ALREADY ENROUTE WAS DISREGARDED. AT 01:18 HARRIS COUNTY HAZMAT ARRIVED ON LOCATION AND COMMAND NOTIFIED THEM OF THE SITUATION AT HAND UP TO THAT TIME. IT WAS DETERMINED THAT SUFFICIENT COOLING HAD OCCURRED TO ATTEMPT TO REMOVE THE VICTIMS, AND ALL ATTACK LINES WERE SHUT DOWN. CREWS FROM E107 AND TK108 WOULD REMOVE THE DOORS FROM THE VEHICLE TO GAIN BETTER ACCESS FOR PATIENT REMOVAL. IT WAS THEN DECIDED THAT E107 AND TK108 WOULD ALSO ASSIST HARRIS COUNTY MEDICAL PERSONNEL WITH PATIENT REMOVAL FROM THE VEHICLE. DURING THIS OPERATION SEVERAL EXPOSURES OCCURRED OF FIRE DEPARTMENT PERSONNEL BY BODY FLUIDS FROM ONE OF THE VICTIMS. BOTH VICTIMS WERE SUCCESSFULLY EXTRICATED FROM THE VEHICLE AND TURNED OVER TO THE MEDICAL EXAMINER. THE CREWS CONTAMINATED WERE DECONTAMINATED BY MCHD M24 AND BC102 WAS NOTIFIED OF THE SITUATION. TWO HARRIS COUNTY MEDICAL EXAMINERS PERSONNEL ALSO RECEIVED MINOR LACERATIONS TO THE HAND REQUIRING THE ASSISTANCE OF M24. TK108 ASSISTED E107 WITH ROLLING ALL THEIR HOSE AND DOING A ON SCENE GROSS DECONTAMINATION OF ALL BUNKER GEAR TO RETURN BOTH UNITS TO SERVICE. AT 04:26 HAMMOCK DUNES COMMAND WAS TERMINATED AND THE SCENE WAS LEFT WITH E107. TK108 RETURNED TO SERVICE.


Roald Hoppel
April 20,2021 21:58:00



E 3	Supplemental Local Option	Special Studies								NFIRS-1S Supplementa	ıl
1	Special Spe Study ID# Stud		Special Study ID#	Special Study Value	3	Special Study ID#	Special Study Value	4	Special Study ID#	Special Study Value	
5	Special Spe Study ID# Study		Special Study ID#	Special Study Value	7	Special Study ID#	Special Study Value	8	Special Study ID#	Special Study Value	
L	Remarks: Local Option										

TK108 narrative by Lt. Hoppel

ON 04/17/2021 @ 21:28, TK108 WAS DISPATCHED TO 22 HAMMOCK DUNES PLACE FOR A REPORTED CAR FIRE, WITH OTHER UNITS ALREADY ENROUTE. AT 21:33 TK108 HAD FIRECOM NOTIFY CARLTON WOODS SECURITY THAT TWFD UNITS WOULD BE USING THE BRANSON WAY ENTRANCE. E107 ARRIVED ON LOCATION AND WENT OUT WITH ONE VEHICLE IN THE WOODS, FULLY INVOLVED. AT 21:36 TK108 ARRIVED ON LOCATION AND ESTABLISHED HAMMOCK DUNES INCIDENT COMMAND. TK108 OFFICER DID A FACE-TO-FACE PASS-ON WITH THE ACTING E107 OFFICER. THE VEHICLE WAS A SHORT DISTANCE FROM THE DRY CONCRETE ROAD AND HAD IMPACTED A TREE FRONTALLY AND REMAINED FULLY INVOLVED. THE REAR DRIVER SIDE TIRE WAS VISIBLE AND INDICATED THE VEHICLE TO BE A TESLA THAT HAD BEEN TRAVELING FROM EAST TO WEST ON HAMMOCK DUNES PLACE, THE ROAD DEAD ENDS TO THE EAST. TK108'S FIREFIGHTERS JOINED E107'S FIRE ATTACK. TK108'S DRIVER ASSISTED E107'S DRIVER WITH PUMP OPERATIONS AND SECURING A SUPPLY LINE. AT 21:39 BC102 ASSUMED HAMMOCK DUNES COMMAND FROM TK108 OFFICER, IN A FACE-TO-FACE PASS-ON. AT 21:40 THE MAJORITY OF THE FIRE HAD BEEN KNOCKED DOWN AND IT BECAME EVIDENT THAT THE VEHICLE WAS OCCUPIED. THERE WAS ONE OCCUPANT IN THE FRONT PASSENGER SEAT AREA AND ANOTHER IN THE REAR DRIVER SIDE AREA. THE PLACEMENT OF THE OCCUPANTS RAISED IMMEDIATE CONCERNS THAT THERE MIGHT BE MORE OCCUPANTS AND A SEARCH WAS STARTED IN THE HEAVILY WOODED AREA OF THE CRASH AND AROUND THE POND USING MULTIPLE FIREFIGHTER USING THERMAL CAMERAS. CONSTABLE OFFICERS FROM PCT. 4 MADE CONTACT WITH FAMILY MEMBERS OF THE OCCUPANTS OF THE VEHICLE AND CONFIRMED THAT THERE WERE TWO OCCUPANTS IN THE VEHICLE SO THE SEARCH WAS DISCONTINUED. TK108 OFFICER ASSISTED MCHD M24 ON SCENE WITH TWO DISTRAUGHT FEMALE FAMILY MEMBERS OF THE OCCUPANTS IN THE VEHICLE. M24 ASSISTED THEM WITH NOTIFYING MORE FAMILY MEMBERS WHO WERE REQUESTED TO COME TO THE SCENE. TK108 OFFICER AT THAT POINT WENT TO THE ROADBLOCK AT THE BEGINNING OF HAMMOCK DUNES PLACE TO AWAIT THE ARRIVAL OF THOSE FAMILY MEMBERS. CCEMS M512 ARRIVED ON LOCATION FOR A CARDIAC PATIENT ON HAMMOCK DUNES PLACE AND TK108 OFFICER ASSISTED THEM NAVIGATE THE SCENE. M512 DETERMINED THIS WAS THE SAME PATIENT M24 HAD CHECKED OUT EARLIER AND THEY HAD BEEN CALLED TO THE SCENE BY PCT.4 BUT THERE WAS NO MEDICAL EMERGENCY. TK108 OFFICER WAS NO LONGER NEEDED TO ESCORT FAMILY AS THEY HAD FOUND ANOTHER WAY IN. BACK AT THE SCENE OF THE CRASH LATENT HEAT HAD REIGNITED THE FIRE IN THE VEHICLE AND FIRE SUPPRESSION HAD RESUMED, DURING WHICH TK108'S DRIVER HAD BEEN INJURED BY A FIRE HOSE. THE SPARE AIR SUPPLY AT THIS POINT HAD BECOME CRITICALLY LOW AND BC102 DECIDED TO BRING THE INJURED FIREFIGHTER TO WOODLAND MEMORIAL ER WEST AND DROP OFF THE EMPTY AIR CYLINDERS AT STATION 5 FOR REFILLING. AT 23:57 TK108 OFFICER ASSUMED COMMAND FROM BC102. AT THIS POINT A BLITZFIRE WAS DEPLOYED TO COOL THE VEHICLE AND A 1.75" ATTACK LINE AND A BOOSTER LINE FROM E107 WERE ALL BEING USED TO KEEP THE INCIDENT IN CHECK. PCT. 4 DEPUTY SINGLETON NOTIFIED COMMAND THAT HARRIS COUNTY HAZMAT WOULD BE NEEDED TO DECONTAMINATE THE VICTIMS, THE UNITS WOULD TAKE ABOUT AN HOUR




E 3	Supplemental Special Studies	s							NFIRS-1S Supplemental
1	Special Special Study ID# Study Value	Special Study ID#	Special Study Value	3	Special Study ID#	Special Study Value	4	Special Study ID#	Special Study Value
5	Special Special Study ID# Study Value	Special Study ID#	Special Study Value	7	Special Study ID#	Special Study Value	8	Special Study ID#	Special Study Value
L	Remarks: Local Option								

TO ARRIVE, THE WOODLANDS FIRE DEPARTMENT HAZMAT TEAM THAT WAS ALREADY ENROUTE WAS DISREGARDED. AT 01:18 HARRIS COUNTY HAZMAT ARRIVED ON LOCATION AND COMMAND NOTIFIED THEM OF THE SITUATION AT HAND UP TO THAT TIME. IT WAS DETERMINED THAT SUFFICIENT COOLING HAD OCCURRED TO ATTEMPT TO REMOVE THE VICTIMS, AND ALL ATTACK LINES WERE SHUT DOWN. CREWS FROM E107 AND TK108 WOULD REMOVE THE DOORS FROM THE VEHICLE TO GAIN BETTER ACCESS FOR PATIENT REMOVAL. IT WAS THEN DECIDED THAT E107 AND TK108 WOULD ALSO ASSIST HARRIS COUNTY MEDICAL EXAMINER PERSONNEL WITH PATIENT REMOVAL FROM THE VEHICLE. DURING THIS OPERATION SEVERAL EXPOSURES OCCURRED OF FIRE DEPARTMENT PERSONNEL BY BODY FLUIDS FROM ONE OF THE VICTIMS. BOTH VICTIMS WERE SUCCESSFULLY EXTRICATED FROM THE VEHICLE AND TURNED OVER TO THE MEDICAL EXAMINER. THE CREWS CONTAMINATED WERE DECONTAMINATED BY MCHD M24 AND BC102 WAS NOTIFIED OF THE SITUATION. TWO HARRIS COUNTY MEDICAL EXAMINERS PERSONNEL ALSO RECEIVED MINOR LACERATIONS TO THE HAND REQUIRING THE ASSISTANCE OF M24. TK108 ASSISTED E107 WITH ROLLING ALL THEIR HOSE AND DOING A ON SCENE GROSS DECONTAMINATION OF ALL BUNKER GEAR TO RETURN BOTH UNITS TO SERVICE. AT 04:26 HAMMOCK DUNES COMMAND WAS TERMINATED AND THE SCENE WAS LEFT WITH E107. TK108 RETURNED TO SERVICE.

Please refer to the individual Unit narratives for more information.

Russell Rice - BC102 April 20,2021 22:13:06


Battalion 102 (BC102) arrived on location. BC102 met with Tk108 officer who had established initial incident command for a face to face briefing and transfer of command. Initial fire attack was being performed and additional manpower were searching in the surrounding woods with thermal cameras for any additional occupants. It was quickly determined that the vehicle had two occupants that were deceased, and our fire attack tactics were modified to protect the scene for potential investigations by law enforcement. BC102 canceled R101 due to the lack of need for the additional manpower or specialized equipment they carry. While the vehicle was involved in heavy fire it was difficult to determine what make and manufacturer the vehicle was. After the main body of fire was knocked down we could determine that the vehicle was a Tesla electric vehicle. The only way we were able to determine this due to the extent of damage from the fire was to identify the companies logo on the left rear wheel center cap. Still having fire coming from the battery area crews initially applied Dry Chem extinguisher with a little success. The dry chem would smother the flames, however they would shortly reignite due to level of heat still in the battery system. BC102 contacted WFD Hazardous Materials response team via phone for consult



E 3	Supplemental Special Studies	s							NFIRS-1S Supplemental
1	Special Special Study ID# Study Value	Special Study ID#	Special Study Value	3	Special Study ID#	Special Study Value	4	Special Study ID#	Special Study Value
5	Special Special Study ID# Study Value	Special Study ID#	Special Study Value	7	Special Study ID#	Special Study Value	8	Special Study ID#	Special Study Value
L	Remarks: Local Option								

ation on special needs or techniques to handle this type of fire. While they were researching BC102 used the cell phone to look up recommendations from Tesla.com. Tesla's site specifically stated for fire fighting operations the only recommendation was copious amounts of water to extinguish but more importantly cool the battery area. E107 had established a water supply with a five inch supply to a nearby hydrant. Crew continued to used an 1 ¾ handline to cool the battery tray and hit hot spots as they flared up. Harris County Fire Marshals office arrived on scene and took charge of the investigation portion of the incident while fire department continued fire suppression. Precinct 4 constables officers arrived on scene and set up a perimeter and taped off the area. Shortly after their arrival a family member of one of the victims was located and told police that two males were in the vehicle. This concluded our searching for any other victims and resources were redirected for fire suppression. Water was applied as per Tesla instructions to keep the battery compartment cool. There were many small sections that would reignite and those were extinguished as the became apparent. At some point while adding an additional line, Tk108 driver was injured by the hose. Command was advised of the injury, and our supply of 30 minute SCBA cylinders was running low. BC102 made the decision to transfer command to Tk108 officer in order to take the injured firefighter to Memorial Herman the Woodlands West for treatment, and to fill bottles at WFD station five, which has a cascade unit located there. At 23:57:56 BC102 transferred command and took bottles to refill at WFD station 5 then took the Firefighter to ER, once FF was at the ER BC102 went back to retrieve cylinders and deliver transferred to the scene. BC102 arrived back at the scene and stayed with TK108 officer who was in command. Anticipating the injured FF's discharge from the hospital, and for scene continuity, command was not formally transferred from TK108 officer. During this time it was determined that the vehicle was safe enough to allow the medical examiners office to access the victims for removal. At 02:56:39 BC102 was notified that injured personnel was getting discharged by ER so BC102 cleared the scene enroute to pickup FF. While enroute to hospital BC102 was notified by command that three members had an exposure to body fluids. Via cell phone they were advised to decontaminate on scene with Medic 24 and then upon returning to station complete an exposure report. BC102 also reminded command to assure that personnel on scene need to follow all exposure protection measures with appropriate PPE. BC102 picked up Firefighter from the ER and then delivered him to his assigned station so he could gather his belongings to return home until further evaluation from an orthopedic doctor could be performed. At approximately 03:45 BC102 left WFD station 8 and returned to service.

Russell Rice Battalion 102



E 3	Supplemen Local Option	ntal Special Studies	s									NFIRS-1 Suppleme	
1	Special Study ID#	Special Study Value		Special Study Value	T	3	Special Study ID#	Special Study Value	J	4	Special Study ID#	Special Study Value	Т
5	Special Study ID#	Special Study Value		Special Study Value	T	7	Special Study ID#	Special Study Value	J	8	Special Study ID#	Special Study Value	J

Remarks:

For additional information please refer to additional agencies incident reports. Reference the following incident numbers.

TWFD & MCHD # 21-02692

HCFMO # 2104-00055


HCP4 # 2104-02102

HCME # ML21-1741 and ML21-1742

Bryan Crivelli - E107 April 20,2021 22:44:16

E-107 OFFICER

E-107 WAS INITIALLY DISPATCHED TO A SMALL OUTSIDE FIRE, ADDRESS #22 HAMMOCK DUNES PL. AFTER GOING ENROUTE BUT PRIOR TO LEAVING FIRE STATION PROPERTY FIRECOM NOTIFIED E-107 THAT THE CALL WAS BEING UPGRADED TO AN MVA WITH VEHICLE FIRE. E-107'S OFFICER MADE THE DECISION TO USE THE MAIN ENTERANCE INTO THE CARLTON WOODS SUBDIVISON AS THE ACCESS POINT. READING THROUGH THE CALL NOTES PROVIDED BY FIRECOM ON THE MDT, E-107 ROUTED TO #46 THORNBLADE CIR. BELIEVING THIS WOULD GIVE THE BEST ACCESS POINT TO THE VEHICLE. E-107 WENT ON LOCATION AT #46 THORNBLADE CIR. AND COULD SEE HEAVY FIRE IN THE WOODS BUT WOULD NOT BE ABLE TO ACCESS THE FIRE DUE TO THE DISTANCE. E-107 RELAYED TO FIRECOM AND THE OTHER INCOMING UNITS THAT #22 HAMMOCK DUNES WOULD BE A BETTER ACCESS POINT. E-107 WENT ON LOCATION AT #22 HAMMOCK DUNES AND FOUND A SINGLE VEHICLE IN THE WOODS HEAVILY INVOLVED IN FIRE. E-107 CREW USED A 1 3/4" BUMPER LINE TO INITIATE FIRE ATTACK. IT WAS NOTED THAT THE SINGLE VEHICLE WAS SITTING UPRIGHT WITH HEAVY FRONT END DAMAGE FROM IMPACT WITH A LARGE TREE. T-108 WENT ON LOCATION AND ASSUMED COMMAND. A FACE TO FACE TRANSFER TOOK PLACE BETWEEN E-107 OFFICER AND COMMAND. T-108 CREW ASSISTED E-107 CREW WITH FIRE CONTAINMENT. E-107 FIREFIGHTER RELAYED TO THE E-107 OFFICER THAT 2 DECEASED VICTIMS WERE FOUND TO BE INSIDE THE VEHICLE, IDENTIFIED DURING THE FIRE EXTINGUISHMENT PROCESS. E-107 OFFICER USED A THERMAL IMAGER AND A FLASHLIGHT AND BEGUN TO SEARCH THE THICK WOODS ON FOOT AROUND THE VEHICLE FOR POSSIBLE INJURED VICTIMS BUT NONE WERE LOCATED. E-107 OFFICER DID FIND A LARGE DEBRIS FIELD APPROX 10 YARDS AWAY IN FRONT OF THE VEHICLE. COMMAND RELAYED TO FIRE PERSONNEL THAT THE VEHICLE WAS A "TESLA" ALL ELECTRIC VEHICLE WITH A LARGE BATTERY BANK. E-107 DRIVER ESTABLISHED A WATER SUPPLY FROM A NEARBY FIRE HYDRANT. THE VEHICLE WAS LIFT



E 3	Supplemental Special Studies Local Option		NFIRS-1S Supplemental
1	Special Study ID# Study Value 2	Special Special Study ID# Study Value Study ID#	Special Study Value
5	Special Special Study ID# Study Value	Special Special Study ID# Study Value Study ID# Special Study ID# Study ID# Study ID# Study ID# Study ID#	Special Study Value
L	Remarks: Local Option		
ED	AND CRIBBED USING THE	HYDRAULIC SPREADERS TO GAIN ACCESS UNDER THE VEH	ICLE WHERE

THE BATTERY BANK WAS LOCATED. AN ADDITIONAL 3" HOSELINE WITH A BLITZFIRE NOZZLE AND REDLINE WERE DEPLOYED TO HELP EXTINGUISH AND COOL THE VEHICLE. E-107 ALSO ASSISTED THE FAMILY OF THE VICTIMS WITH PERSONAL NEEDS. E-107 AND T-108 CREWS ASSISTED THE HARRIS COUNTY MEDICAL EXAMINER WITH REMOVING THE REMAINS OF THE DECEASED VICTIMS. THE FIRST VICTIM WAS LOCATED IN THE FRONT PASSENGER SEAT, SITTING UP, FACING FORWARD, HEAD SLUMPED FORWARD WITH THE VICTIMS FEET CROSSED IN FRONT OF THE SEAT. THE SECOND VICTIM WAS LOCATED BEHIND THE DRIVERS SEAT FACING FORWARD SLUMPED DOWN IN THE SEAT WITH THE HANDS UP IN A DEFENSIVE POSTURE ALSO WITH THE FEET CROSSED. DURING THE REMOVAL PROCESS 3 FIREFIGHTERS WERE EXPOSED TO HUMAN BLOOD FROM THE VICTIMS. FIRE CREWS DID HAVE TO REMOVE THE BACK PASSENGER DRIVER SIDE DOOR USING THE HYDRAULIC SPREADERS AND CUTTERS TO ACCESS ONE OF THE VICTIMS. AFTER THE VICTIMS WERE REMOVED AND CARE OF THE REMAINS WERE TRANSFERED TO THE MEDICAL EXAMINER, FIRE PERSONAL ON SCENE WERE GROSS DECONED USING SOAP AND WATER. E-107 REMAINED ON LOCATION AFTER COMMAND WAS TERMINATED FOR LIGHTING AND SAFTEY WHILE THE VEHICLE WAS REMOVED FROM THE WOODS AND PLACED ON A FLAT BED TOW TRUCK. E-107 WENT BACK IN SERVICE AND THE SCENE WAS LEFT WITH HARRIS COUNTY PT. 4 CONSTABLES AND HARRIS COUNTY FIRE MARSHAL OFFICE.

	7YY 021 7 0004476 000 Exposure	Delete NFIRS-2 Fire
B Property Details B1	or Products None commerci or material Enter up to three codes. Check one box for each code entered. L	if there were any significant amounts of al. industrial, energy, or agricultural products als on the property, whether or not they became involved. On-Site Materials Storage Use 1
D Ignition D1 80 Vehicle area, other Area of fire origin	E1 Cause of Ignition	Check all applicable boxes None 1
F1 Equipment Involved in Ignition None If equipment was not involved, skip to Section G. Equipment Involved Brand Implication Model Implication Serial # Implication Year Implication Year Implication Involved in Ignition Involved, skip to Section G.	F2 · ·	factor (2)
H1 Mobile Property Involved None 1 Not involved in ignition, but burned 2 Involved in ignition, but did not burn 3 Involved in ignition and burned Mobile property model TX License Plate Number Structure fire? Please be sure to complete the Structure		Local Use Pre-Fire Plan Available Some of the information presented in this report may be based upon reports from other agencies: Arson report attached Police report attached Coroner report attached Other reports attached NFIRS-2 Revision 01/01/05

A		21 7 000447	76 000 Delete NFIRS-4 Civilian Fire Casualty
В	Injured Person UNK First Name N		Female C Casualty Number 001 Casualty Number
D	OR OR Date of Birth Day Year 3 Am. Ind 4 Asian 5 Native Pacific 0 Other, r U Undeter 1 His	F Affiliation 1 Civilian 2 EMS, n 3 Police 0 Other slander nultiracial mined Date of Injury	ot fire department 1
I	Cause of Injury 1	ne Contributing to Injury	r drug Contributing factor (2)
L	1	cation at Time of Incident In area of origin and not involved Not in area of origin and not involved Not in area of origin, but involved In area of origin and involved Other location Undetermined neral Location at Time of Injury area of fire origin building, but not in area tside, but not in area determined	M3 Story at Start of Incident Complete ONLY if injury occurred INSIDE Story at start of incident Below grade M4 Story Where Injury Occurred Story where injury occurred, if Below grade M5 Specific Location at Time of Injury Complete ONLY if casualty NOT in area of origin Specific location at time of injury
N	Primary Apparent Symptom 11 Smoke only, asphyxiation 11 Burns and smoke inhalation 12 Burns only 21 Cut, laceration 33 Strain or sprain 96 Shock 98 Pain only Look up a code only if the symptom is NOT found above	Primary Area of Body Injured Head Neck and shoulder Thorax Abdomen Spine Upper extremities Lower extremities Internal Multiple body parts	P Disposition Transported to emergency care facility Remarks Local option Age approximate. See HCME Inc. # ML21-1741

Α	SA416 TX DM DD 1. State State Incident Date	7 2021	7 Station	000447	Exposure	□Delete Civilian Fire Casualty
В	Injured Person First Name	[[.ast Name	☆ Gender 1 ☑Male 2 [Female Suffix	C Casualty Number
D	OR OR OR Date of Birth Month Day Year	Asian Native Hawa Pacific Islan Other, multir Undetermine Ethnicity Hispanic	Alaska Native iian, Other der racial ed	3 Police 0 Other G Date and Time	ot fire department	H Severity 🕁 1 Minor 2 Moderate 3 Severe 4 Life threatening 5 Death U Undetermined
Cause of Injury						
L	1	M ₂ Genera In area 2 In build	ot in area of original ther location indetermined at Location at of fire original ding, but not in a	nd not involved gin and not involved gin, but involved and involved Time of Injury Skip to Section N	M3 Story at Start of I Complete ONLY if injury occur Story at start of incident M4 Story Where Injury Story where injury occurred, if different from M3 M5 Specific Location Complete ONLY if casualty Specific location at time of in	Below grade Ty Occurred Below grade Below grade Below grade The at Time of Injury NOT in area of origin
N	Primary Apparent Symptom 11 Smoke only, asphyxiation 11 Burns and smoke inhalation 12 Burns only 21 Cut, laceration 33 Strain or sprain 96 Shock 98 Pain only Look up a code only if the symptom is NOT found about the	ove	1	extremities r extremities	☐Transported to	emergency care facility al option tmate. Reference 1-1742

7 7 -	

K ₁	Did protective equipment fail and Please complete the remainder of this form		14 and 1.5m3 1.5m3 14 and 10 5 and 11 5 1.7m	Yes No	Y □ N □	Equipment Sequence Number	ш	NFIRS-5 Fire Service Casualty
(i)	B			1				
K_2	Protective Equipment Item			K ₃		ctive Equipm		
Hea	d or Face Protection	Coat, Shir	t, or Trousers	11	☐ Bui	one box to indicate	the main proble	m that occurred.
11 12	☐ Helmet ☐ Full face protector		Protective coat Protective trousers	12	☐ Me	Ited		
13	☐ Partial face protector		Uniform shirt	21	□ Fra	ctured, crack	ed or broke	en
14 15	☐ Goggles/eye protection☐ Hood		Uniform T-shirt Uniform trousers	200			04 01 21010	
16	☐ Ear protector	26	Uniform coat or jacket	22	Pui			
17 10	☐ Neck protector☐ Other	28 🔲	Coveralls Apron or gown	23	☐ Scr			
	Account Objection	20 📙	Other	24	∐ Kno	ocked off		
31	ots or Shoes Multiple Head of the steel of	baseplate	and steel toes	25	☐ Cut	or ripped		
32	☐ Knee length boots with steel	toes only		31	☐ Tra	pped steam o	or hazardou	s gas
33 34	☐ 3/4 length boots with steel to							
35 36	☐ Safety shoes with steel base	Boots without steel baseplate and steel toes Safety shoes with steel baseplate and steel toes					onto equipr	nent item
37 38	☐ Safety shoes with steel toes of Non-safety shoes		41	☐ Fai	led under imp	oact		
30 Other				42	☐ Fac	e piece or ho	se detache	d
	spiratory Protection		43	☐ Ext	nalation valve	inoperative	e or damaged	
41 42	☐ SCBA (demand) open circuit☐ SCBA (positive pressure) open			44	☐ Hai	ness detache	ed or separa	ated
43 44	☐ SCBA closed circuit ☐ Not self-contained			45	□ Red	gulator failed	to operate	
45	Cartridge respirator						58	
46 40	☐ Dust or particle mask☐ Other			46	_ =	gulator dama		
1000	nd Protection			47	☐ Pro	blem with ad	missions va	alve
51	☐ Firefighter gloves with wristle	ets		48	☐ Ala	rm failed to o	perate	
52 53		istlets		49	☐ Ala	rm damaged	by contact	
54	☐ HazMat gloves			51	☐ Su	oply cylinder	or valve fail	led to operate
55 50	☐ Medical gloves ☐ Other			52	☐ Su	oply cylinder/	valve dama	ged by contact
Spe	ecial Equipment			53	☐ Su	oply cylinder-	-insufficier	nt air/oxygen
61 62	,			94	Did	not fit prope	rly	
63	☐ Totally encapsulated, reusab			95	☐ Not	properly ser	viced or sto	ored prior to use
64 65				96	☐ Not	used for des	igned purp	ose
66	Partially encapsulated, dispo			97	□ Not	used as reco	ommended	by manufacturer
67 68					_			•
69	☐ Brush suit			00		ner equipmen	t problem	
71 72		reathing ar	oparatus (SCUBA)	UU		determined		
73	Life preserver	를 즐겁게 된다. 즐겁게 살아보는 이 보다 보다 보다 보고 보고 있는데 보다 보다 보다 되었다. 그런데 나는데 보다 그래요 그래요 보다 되었다. 그래요 보다 보다 되었다. 그래요 보다 그래요				시 하 것은 1.400 전 시간	facturer, Mo	odel and Serial
74		(DAGG)	Was the failure of more	K ₄	Num	iber		
75 76		than one item of protective				Manufacturer		
77						1		ì
78	Fire shelter or tent		additional page of this			Model		
79			form for each piece of					1
70	,	failed equipment.			Serial Number	NEW	20 E Povision 05/04/02	

A SA416 TX		7 Lion Inciden	1727-12222	4476	<u></u> =		FIRS-10 ersonnel
B Apparatus or Resources	Check if same date as Alarm dathe Basic Module (Block E1).	night is 0000 lite on Hour/Min	Sent	of ☆	Apparatus Use Check ONE box for ear apparatus to indicate it use at the incident.	ch List up to	ns Taken 4 actions for paratus and sonnel.
A- 1111	rrival 04 18 2021	0017	Sent	0	Suppressi EMS Other	on	
Personnel ☆ ID	Name	Rank or Grade	Attend	Action Taken	Action Taken	Action Taken	Action Taken
		21 20 1	Sent			-	-
AI AI		2128 2137 0256	Sent ☑	1	☐ Suppressi ☐ EMS ☑ Other	on 81	_
Personnel ద	Name	Rank or Grade	Attend	Action Taken	Action Taken	Action Taken	Action Taken
008108	Russell Rice		Ø				
Ar	rival 🛛 🗌 📗 📗	2128 2136 0426	Sent	4	Suppressi EMS Other	ion 81	
Personnel 🛱	Name	Rank or Grade	Attend	Action Taken	Action Taken	Action Taken	Action Taken
002193	Jesse Cox		Ø				
000328	Kameron DeLany		Ø	11	24	21	
008341	Roald Hoppel		Ø	81	21	31	
005509	Robert Mitchell		Ø				

A SA416 TX	MM DD YYYY 04 17 2021 L Incident Date Stat	7 Linciden	1727-12222	4476 00 Expos	<u> </u>		FIRS-10 ersonnel
B Apparatus or Resources	Check if same date as Alarm da the Basic Module (Block E1).	night is 0000 ate on Hour/Min	Sent X	of ☆	Apparatus Use Check ONE box for ea apparatus to indicate it use at the incident.	ch List up to	ns Taken 4 actions for paratus and sonnel.
A. I 11 I	rrival 🗹 🔲 📗 📗	2125 2136 0436	Sent	4	Suppressi	on	
Personnel ☆ ID	Name	Rank or Grade	Attend	Action Taken	Action Taken	Action Taken	Action Taken
006604	Justin Fryer		Q	11	12	23	24
009140	Bryan Crivelli		Ø	86	21	11	24
007342	Todd Gladish		Ø	11	46		
003861	Jonathan Tatum		Ø	11	24		
Ar Ar	spatch		Sent		Suppressi EMS Other	on	
Personnel ద	Name	Rank or Grade	Attend	Action Taken	Action Taken	Action Taken	Action Taken
Ar	spatch		Sent	ш	Suppressi EMS Other	ion	
Personnel ద	Name	Rank or Grade	Attend	Action Taken	Action Taken	Action Taken	Action Taken

	TX MM DD YYYY 2021 7 State Incident Date Station	□ 000447	Delete Change Exposure No Activity Signature No Activity Delete ESO-1 Non-NFIRS Fields Change Change No Activity Change Change
E1 Additional Inci	Month Day Year Hour Min	N Dispatch Notified	onth Day Year Hour Min
B Apparatus or Resources	Dates and Times Midnight is 0000 Month Day Year Hour/Min	5 ID	En Route L L L L L L L L L L L L L L L L L L L
1 ID E102	En Route 04 18 2021 0017 District 04 18 2021	6 ID	En Route L L L L L L L L L L L L L L L L L L L
2 ID BC102	En Route [04] [17] [2021] [2129] District [04] [18] [2021] []	7 ID	En Route L L L L L L L L L L L L L L L L L L L
3 ID TK108	En Route 04 17 2021 2129 District 04 18 2021	8 ID	En Route L L L L L L L L L L L L L L L L L L L
Type	En Route 04 17 2021 2126 District 04 18 2021	9 ID	En Route

Incident Detail Report

Data Source: **Data Warehouse**Incident Status: **Closed**Incident number: **21-026920** Map it
Case Numbers:

Incident Date: 04/17/2021 21:24:11 Report Generated: 04/26/2021 16:15:36

Incident Type: Vehicle Extrication Alarm Level: 1

Priority:Priority 1Problem:MVA - FireDeterminant:67B01RAgency:MCCAD

Base Response#:Jurisdiction:The Woodlands FDConfirmation#:Division:The Woodlands FDTaken By:Citron, NoahBattalion:The Woodlands FDResponse Area:10XHResponse Plan:10 Vehicle Extrication

Response Area:10XHResponse Plan:Disposition:AC - Assignment CompleteCommand Ch:

Cancel Reason: Primary TAC: FD4

Incident Status: Closed Secondary TAC:

Certification: Fire Delay Reason (if any):

Longitude: 95531404 Latitude: 30155024

Location Name: County: HARRIS

Address: 22 HAMMOCK DUNES PL Location Type:

Apartment: Cross Street: Dead End/THORNBLADE CIR

Building: Map Reference: 250K

City, State, Zip: SPRING TX 77389

Caller Name: VERIZON

Method Received: Call Back Phone:
Caller Type: 911 Caller Location:

Caller Address: Caller Location Phone:
Caller Building: 4974D3 Caller Apartment:

Caller Building: 4974D3 Caller Apartment:
Caller City, State, Zip: Caller County:

Description	Date	Time	User	Description	Time
Phone Pickup	04/17/2021	21:24:11			
1st Key Stroke	04/17/2021	21:24:11		Received to In Queue	00:01:05
In Waiting Queue	04/17/2021	21:25:16		Call Taking	00:03:15
Call Taking Complete	04/17/2021	21:27:26	Citron, Noah	In Queue to 1st Assign	00:00:02
1st Unit Assigned	04/17/2021	21:25:18		Call Received to 1st Assign	00:01:07
1st Unit Enroute	04/17/2021	21:26:43		Assigned to 1st Enroute	00:01:25.1
1st Unit Arrived	04/17/2021	21:36:00		Enroute to 1st Arrived	00:09:16.9
Closed	04/18/2021	04:36:45	Mobile1	Incident Duration	07:12:34

Primary At Delay Odm. Odm. Cancel Unit Flag Assigned Disposition Enroute Staged Arrived Patient Avail Complete Enroute Arrived Reason

E107	N	21:25:18	AC - Assignment Complete	21:26:43	21:36:00	04:36:45
TK108	Y	21:28:25	AC - Assignment Complete	21:29:45	21:36:34	04:26:42
CCM512	2 N	21:28:25	AC - Assignment Complete	21:34:32		21:41:30
R101	N	21:28:25	AC - Assignment Complete	21:34:50		21:39:51
BC102	N	21:28:25	AC - Assignment Complete	21:29:31	21:37:14	02:56:43
D2	N	21:28:25	District Chief Assist - DC	21:29:42	21:54:20	22:47:01
M24	N	21:28:25	Dead On Arrival - DOA	21:29:20	21:37:39	03:20:57
CH10	N	21:47:46	AC - Assignment Complete	21:47:46	21:48:03	22:41:06
E102	N	00:17:00	AC - Assignment Complete	00:17:00		00:19:51

Unit Name

D2 Jaszkowiak, Brenna (435)

M24 Roach, Mark (106); Shannon, Emily (1309)

Notes	Туре	Priority
BEST ACCESS IS VIA THE CARLTON WOODS CREEKSIDE GATE. GATE ON		
CINDY ANN IS NOT ALWAYS STAFFED. GATE AT S BRANSON CREEK WAY	Region	High
IS UNABLE TO BE OPENED REMOTELY BUT DOES HAVE A KNOX BOX.		

No Pre-Scheduled Information

No Transports Information

No Transports Information

Date	Time	User	Type	Conf.	Comments
04/17/2021	21:24:11	Automatic by System	Response		[Geographic Area: 27 HAMMOCK DUNES PL] [High] [Access Codes] BEST ACCESS IS VIA THE CARLTON WOODS CREEKSIDE GATE. GATE ON CINDY ANN IS NOT ALWAYS STAFFED. GATE AT S BRANSON CREEK WAY IS UNABLE TO BE OPENED REMOTELY BUT DOES HAVE A KNOX BOX.
04/17/2021	21:24:46	W957	Response		[ProQA: Case Entry Complete] Problem Description: LOT ON FIRE Chief Complaint: 67, CCText: Outside Fire
04/17/2021	21:25:16	W957	Response		[ProQA Dispatch] Dispatch Level: 67B01 (SMALL OUTSIDE fire) Suffix: R (Residential) Response Text: B

Alloc (2nd pty). Callet Sales no hazmat pres.					[ProQA: Key Questions]
OA/17/2021 21:25:16 W957 Response South Larea Sout					> At loc (2nd pty).
2	04/17/2021	21:25:16	W957	Response	•
O4/17/2021 21:25:21 USDD					
PinQA: Key Questions					
No one trapped or in immed danger.	04/17/2021	21:25:21	USDD	Response	Dispatch Alert successful: Station(s); Radio(s) E107
NA					
September Sept	04/17/2021	21:25:54	W057	Desnonse	> N/A
No inj. FIRE IN THE WOODS - DID HEAR A BOOM PRIOR TO NOTICING THE FIRE — APPROX 20FT WIDE 25-30 FT TALL 281-35-8631	04/11/2021	21.25.54	VV331	Response	
OA/17/2021 21:26:25 W935 Response					
281-357-8631	0.4.47.1000.4	04.00.05	14005	5	
Od/17/2021 21:26:46 Automatic by System	04/17/2021	21:26:25	W935	Response	
CREEKSIDE GATE GATE ON CINDY ANN IS NOT ALWAYS STAFFED GATE AT S BRANSON CREEK WAY IS UNABLE TO BE OPENED REMOTELY BUT DOES HAVE A KNOX BOX.					
STAFFED GATE AT S BRANSON CREEK WAY IS UNABLE TO BE OPENED REMOTELY BUT DOES HAVE A KNOX BOX.	04/17/2021	21:26:46		Response	
O4/17/2021 21:27:10 W957 Response CP IS AT THE DISPATCHED ADDRESS, STATES THERE IS A FIRE IN THE VACANT LOT ACROSS THE STREET, POSS THREAT TO HOUSES IN THE AREA ADDRESS CHANGED TO NEAREST ADDRESS ON THAT SIDE OF THE STREET — POSSIBLY FROM THE BACK YARD OF 46 THORNBILADE CIR.			System		STAFFED. GATE AT S BRANSON CREEK WAY IS UNABLE TO
04/17/2021 21:27:10 W957 Response					
ADDRESS CHANGED TO NEAREST ADDRESS ON THAT SIDE OF THE STREET — POSSIBLY FROM THE BACK YARD OF 46 THORNBLADE CIR (Notification) [MCCAD]-Problem changed from Outside - Small Fire to MVA - Fire by MCCAD	04/17/2021	21:27:10	W957	Response	
04/17/2021 21:27:34 W935 Response OF THE STREET — POSSIBLY FROM THE BACK YARD OF 46 THORNBLADE CIR 04/17/2021 21:28:14 W935 Response Response (Notification) [MCCAD]-Problem changed from Outside - Small Fire to MVA - Fire by MCCAD 04/17/2021 21:28:20 CPSERVICE Response Closest Level 1-3 Trauma Center to 22 HAMMOCK DUNES PL: 1: Memorial Hermann Woodlands Level - II - ETA: 00:14:03 1: Memorial Hermann Woodlands Level - II - ETA: 00:15:56 3: Cornore - HCAHH Level - II - ETA: 00:12:04 04/17/2021 21:28:30 USDD Response 04/17/2021 21:28:30 USDD Response 04/17/2021 21:28:36 W935 Response CALLING CREEK SIDE 04/17/2021 21:28:40 W957 Response ADDITIONAL CALL STATES CAR CRASHED INTO A TREE AND EXPLODED 04/17/2021 21:30:53 W957 Response Information Acknowledged - FIRE 04/17/2021 21:31:03 W938 Response FIRE IS NOW SPREADING INTO THE TREE LINES 04/17/2021 21:33:01 W935 Response CALLER ADV 04/17/2021 21:33:02 W935 R					
THORNBLADE CIR Notification] [MCCAD]-Problem changed from Outside - Small Fire to MVA - Fire by MCCAD Closest Level - II - ETA: 00:14:03	04/17/2021	21:27:34	W935	Response	
10 11 12 12 12 12 12 12				·	THORNBLADE CIR
Closest Level 1-3 Trauma Center to 22 HAMMOCK DUNES PL: 1: Memorial Hermann Woodlands Level - II - ETA: 00:14:03 2: Tomball - HCAHH Level - III - ETA: 00:15:56 3: Conroe - HCAHH Level - III - ETA: 00:21:04 4: Northwest - HCAHH Level - III - ETA: 00:23:04 5: Kingwood - HCAHH Level - III - ETA: 00:23:04 5: Kingwood - HCAHH Level III - ETA: 00:29:48 Dispatch Alert successful: Station(s); Radio(s) TK108,R101,BC102,D2,M24 Response CALLIING CREEK SIDE ADDITIONAL CALL STATES CAR CRASHED INTO A TREE AND EXPLODED CP STATES VS VS TREE, EXPLODED, UNABLE TO TELL IF ANYONE IS INSIDE THE VEH O4/17/2021 21:31:03 W938 Response Information Acknowledged - FIRE O4/17/2021 21:33:01 W938 Response FIRE IS NOW SPREADING INTO THE TREE LINES O4/17/2021 21:33:01 W935 Response CALLER ADV O4/17/2021 21:33:29 W935 Response CALLER ADV O4/17/2021 21:33:29 W935 Response CALLER ADV O4/17/2021 21:35:29 W938 Response GATE IS OPEN O4/17/2021 21:35:29 W938 Response Information Acknowledged Unable to MAKE LOCATION GOING TO HAMMOCK DUNES O4/17/2021 21:36:02 W938 Response CALLING CARLTON CREEKSIDE O4/17/2021 21:36:02 W938 Response CALLING CARLTON CREEKSIDE O4/17/2021 21:36:02 W938 Response Information Acknowledged Unable to MAKE LOCATION GOING TO HAMMOCK DUNES O4/17/2021 21:36:02 W938 Response VEH IN THE WOODS FULLY INVOLVED O4/17/2021 21:36:57 W935 Response MANY WERE RELATED — FIRECOM RECEIVED AT LEAST 5	04/17/2021	21:28:14	W935	Response	
04/17/2021 21:28:20 CPSERVICE Response 2: Tomball - HCAHH Level - III - ETA: 00:21:04					
3: Conroe - HCAHH Level - II - ETA: 00:21:04 4: Northwest - HCAHH Level - II - ETA: 00:23:04 5: Kingwood - HCAHH Level - II - ETA: 00:23:04 5: Kingwood - HCAHH Level II - ETA: 00:23:04 5: Kingwood - HCAHH Level II - ETA: 00:23:04 5: Kingwood - HCAHH Level II - ETA: 00:23:04 604/17/2021 21:28:30 USDD Response Dispatch Alert successful: Station(s); Radio(s) TK108,R101,BC102,D2,M24 CALLIING CREEK SIDE 04/17/2021 21:38:40 W957 Response ADDITIONAL CALL STATES CAR CRASHED INTO A TREE AND EXPLODED CP STATES VS VS TREE, EXPLODED, UNABLE TO TELL IF ANYONE IS INSIDE THE VEH 04/17/2021 21:31:03 W938 Response Information Acknowledged - FIRE 04/17/2021 21:33:00 W938 Response FIRE IS NOW SPREADING INTO THE TREE LINES 04/17/2021 21:33:01 W935 Response CALLER ADV 04/17/2021 21:33:29 W935 Response CALLING CARLTON CREEKSIDE 04/17/2021 21:33:29 W957 Response GATE IS OPEN 04/17/2021 21:36:02 W938 Response GATE IS OPEN 04/17/2021 21:36:02 W938 Response I VEH IN THE WOODS FULLY INVOLVED 04/17/2021 21:36:46 W938 Response "**TK108 EST HAMMOCK DUNES CMMD*** 04/17/2021 21:36:57 W935 Response MANY WERE RELATED — FIRECOM RECEIVED AT LEAST 5				_	
5: Kingwood - HCAHH Level II - ETA: 00:29:48	04/17/2021	21:28:20	CPSERVICE	Response	3: Conroe - HCAHH Level - II - ETA: 00:21:04
04/17/2021 21:28:30 USDD Response Dispatch Alert successful: Station(s); Radio(s) TK108,R101,BC102,D2,M24 04/17/2021 21:28:36 W935 Response CALLIING CREEK SIDE 04/17/2021 21:28:40 W957 Response ADDITIONAL CALL STATES CAR CRASHED INTO A TREE AND EXPLODED 04/17/2021 21:30:53 W957 Response CP STATES VS VS TREE, EXPLODED, UNABLE TO TELL IF ANYONE IS INSIDE THE VEH 04/17/2021 21:31:03 W938 Response Information Acknowledged - FIRE 04/17/2021 21:33:00 W935 Response FIRE IS NOW SPREADING INTO THE TREE LINES 04/17/2021 21:33:00 W938 Response NOTIFY SECURITY FIRE IS COMING THRU THE BRANSON WAY 04/17/2021 21:33:01 W935 Response CALLER ADV 04/17/2021 21:33:29 W935 Response CALLING CARLTON CREEKSIDE 04/17/2021 21:36:40 W935 Response GATE IS OPEN 04/17/2021 21:35:29 W938 Response E107 WENT TO THORNBLADE UNABLE TO MAKE LOCATION GOING TO HAMMOCK DUNES 04/17/2021 21:					
04/17/2021 21:28:36 W935 Response CALLIING CREEK SIDE 04/17/2021 21:28:40 W957 Response ADDITIONAL CALL STATES CAR CRASHED INTO A TREE AND EXPLODED 04/17/2021 21:30:53 W957 Response CP STATES VS VS TREE, EXPLODED, UNABLE TO TELL IF ANYONE IS INSIDE THE VEH 04/17/2021 21:31:03 W938 Response Information Acknowledged - FIRE 04/17/2021 21:32:03 W935 Response FIRE IS NOW SPREADING INTO THE TREE LINES 04/17/2021 21:33:00 W938 Response NOTIFY SECURITY FIRE IS COMING THRU THE BRANSON WAY 04/17/2021 21:33:01 W935 Response CALLER ADV 04/17/2021 21:33:29 W935 Response CALLING CARLTON CREEKSIDE 04/17/2021 21:34:10 W935 Response PCT 4 RESPONDING 04/17/2021 21:35:29 W938 Response GATE IS OPEN 04/17/2021 21:36:02 W938 Response 1 VEH IN THE WOODS FULLY INVOLVED 04/17/2021 21:36:46 W938 Response ***TK108 EST HAMMOCK	04/47/2024	21:20:20	HEDD	Dosponso	
04/17/2021 21:28:40 W957 Response ADDITIONAL CALL STATES CAR CRASHED INTO A TREE AND EXPLODED 04/17/2021 21:30:53 W957 Response CP STATES VS VS TREE, EXPLODED, UNABLE TO TELL IF ANYONE IS INSIDE THE VEH 04/17/2021 21:31:03 W938 Response Information Acknowledged - FIRE 04/17/2021 21:33:00 W935 Response FIRE IS NOW SPREADING INTO THE TREE LINES 04/17/2021 21:33:00 W938 Response NOTIFY SECURITY FIRE IS COMING THRU THE BRANSON WAY 04/17/2021 21:33:01 W935 Response CALLER ADV 04/17/2021 21:33:29 W935 Response CALLING CARLTON CREEKSIDE 04/17/2021 21:33:29 W935 Response PCT 4 RESPONDING 04/17/2021 21:35:29 W938 Response GATE IS OPEN 04/17/2021 21:36:02 W938 Response 1 VEH IN THE WOODS FULLY INVOLVED 04/17/2021 21:36:46 W938 Response ***TK108 EST HAMMOCK DUNES CMMD*** 04/17/2021 21:36:57 W935 Response MANY W					
04/17/2021 21:28:40 W957 Response EXPLODED 04/17/2021 21:30:53 W957 Response CP STATES VS VS TREE, EXPLODED, UNABLE TO TELL IF ANYONE IS INSIDE THE VEH 04/17/2021 21:31:03 W938 Response Information Acknowledged - FIRE 04/17/2021 21:32:03 W935 Response FIRE IS NOW SPREADING INTO THE TREE LINES 04/17/2021 21:33:00 W938 Response NOTIFY SECURITY FIRE IS COMING THRU THE BRANSON WAY 04/17/2021 21:33:01 W935 Response CALLER ADV 04/17/2021 21:33:29 W935 Response CALLING CARLTON CREEKSIDE 04/17/2021 21:33:29 W957 Response PCT 4 RESPONDING 04/17/2021 21:35:29 W935 Response GATE IS OPEN 04/17/2021 21:35:29 W938 Response I VEH IN THE WOODS FULLY INVOLVED 04/17/2021 21:36:46 W938 Response ***TK108 EST HAMMOCK DUNES CMMD*** 04/17/2021 21:36:57 W935 Response MANY WERE RELATED — FIRECOM RECEIVED AT LEAST 5	04/17/2021	21:28:36	W935	Response	
04/17/2021 21:30:33 W937 Response ANYONE IS INSIDE THE VEH 04/17/2021 21:31:03 W938 Response Information Acknowledged - FIRE 04/17/2021 21:32:03 W935 Response FIRE IS NOW SPREADING INTO THE TREE LINES 04/17/2021 21:33:00 W938 Response NOTIFY SECURITY FIRE IS COMING THRU THE BRANSON WAY 04/17/2021 21:33:01 W935 Response CALLER ADV 04/17/2021 21:33:29 W935 Response CALLING CARLTON CREEKSIDE 04/17/2021 21:33:29 W957 Response PCT 4 RESPONDING 04/17/2021 21:34:10 W935 Response GATE IS OPEN 04/17/2021 21:35:29 W938 Response E107 WENT TO THORNBLADE UNABLE TO MAKE LOCATION GOING TO HAMMOCK DUNES 04/17/2021 21:36:02 W938 Response 1 VEH IN THE WOODS FULLY INVOLVED 04/17/2021 21:36:46 W938 Response ****TK108 EST HAMMOCK DUNES CMMD****	04/17/2021	21:28:40	W957	Response	
04/17/2021 21:31:03 W938 Response Information Acknowledged - FIRE 04/17/2021 21:32:03 W935 Response FIRE IS NOW SPREADING INTO THE TREE LINES 04/17/2021 21:33:00 W938 Response NOTIFY SECURITY FIRE IS COMING THRU THE BRANSON WAY 04/17/2021 21:33:01 W935 Response CALLER ADV 04/17/2021 21:33:29 W935 Response CALLING CARLTON CREEKSIDE 04/17/2021 21:33:29 W957 Response PCT 4 RESPONDING 04/17/2021 21:34:10 W935 Response GATE IS OPEN 04/17/2021 21:35:29 W938 Response E107 WENT TO THORNBLADE UNABLE TO MAKE LOCATION GOING TO HAMMOCK DUNES 04/17/2021 21:36:02 W938 Response 1 VEH IN THE WOODS FULLY INVOLVED 04/17/2021 21:36:46 W938 Response ***TK108 EST HAMMOCK DUNES CMMD****	04/17/2021	21:30:53	W957	Response	· · · · · · · · · · · · · · · · · · ·
04/17/2021 21:32:03 W935 Response FIRE IS NOW SPREADING INTO THE TREE LINES 04/17/2021 21:33:00 W938 Response NOTIFY SECURITY FIRE IS COMING THRU THE BRANSON WAY 04/17/2021 21:33:01 W935 Response CALLER ADV 04/17/2021 21:33:29 W935 Response CALLING CARLTON CREEKSIDE 04/17/2021 21:33:29 W957 Response PCT 4 RESPONDING 04/17/2021 21:34:10 W935 Response GATE IS OPEN 04/17/2021 21:35:29 W938 Response E107 WENT TO THORNBLADE UNABLE TO MAKE LOCATION GOING TO HAMMOCK DUNES 04/17/2021 21:36:02 W938 Response 1 VEH IN THE WOODS FULLY INVOLVED 04/17/2021 21:36:46 W938 Response ***TK108 EST HAMMOCK DUNES CMMD****	04/17/2021	21:31:03	W938	Response	
04/17/2021 21:33:00 W938 Response WAY 04/17/2021 21:33:01 W935 Response CALLER ADV 04/17/2021 21:33:29 W935 Response CALLING CARLTON CREEKSIDE 04/17/2021 21:33:29 W957 Response PCT 4 RESPONDING 04/17/2021 21:34:10 W935 Response GATE IS OPEN 04/17/2021 21:35:29 W938 Response E107 WENT TO THORNBLADE UNABLE TO MAKE LOCATION GOING TO HAMMOCK DUNES 04/17/2021 21:36:02 W938 Response 1 VEH IN THE WOODS FULLY INVOLVED 04/17/2021 21:36:46 W938 Response ***TK108 EST HAMMOCK DUNES CMMD**** *MULTIPLE QUEUED CALLS WITH MCSO UNKNOWN HOW MANY WERE RELATED FIRECOM RECEIVED AT LEAST 5				•	_
04/17/2021 21:33:01 W935 Response CALLER ADV 04/17/2021 21:33:29 W935 Response CALLING CARLTON CREEKSIDE 04/17/2021 21:33:29 W957 Response PCT 4 RESPONDING 04/17/2021 21:34:10 W935 Response GATE IS OPEN 04/17/2021 21:35:29 W938 Response E107 WENT TO THORNBLADE UNABLE TO MAKE LOCATION GOING TO HAMMOCK DUNES 04/17/2021 21:36:02 W938 Response 1 VEH IN THE WOODS FULLY INVOLVED 04/17/2021 21:36:46 W938 Response ***TK108 EST HAMMOCK DUNES CMMD***	04/17/2021	21:33:00	W938	Response	
04/17/2021 21:33:29 W957 Response PCT 4 RESPONDING 04/17/2021 21:34:10 W935 Response GATE IS OPEN 04/17/2021 21:35:29 W938 Response E107 WENT TO THORNBLADE UNABLE TO MAKE LOCATION GOING TO HAMMOCK DUNES 04/17/2021 21:36:02 W938 Response 1 VEH IN THE WOODS FULLY INVOLVED 04/17/2021 21:36:46 W938 Response ***TK108 EST HAMMOCK DUNES CMMD***	04/17/2021	21:33:01	W935	Response	
04/17/2021 21:34:10 W935 Response GATE IS OPEN 04/17/2021 21:35:29 W938 Response E107 WENT TO THORNBLADE UNABLE TO MAKE LOCATION GOING TO HAMMOCK DUNES 04/17/2021 21:36:02 W938 Response 1 VEH IN THE WOODS FULLY INVOLVED 04/17/2021 21:36:46 W938 Response ***TK108 EST HAMMOCK DUNES CMMD***	04/17/2021	21:33:29	W935	Response	CALLING CARLTON CREEKSIDE
04/17/2021 21:35:29 W938 Response E107 WENT TO THORNBLADE UNABLE TO MAKE LOCATION GOING TO HAMMOCK DUNES 04/17/2021 21:36:02 W938 Response 1 VEH IN THE WOODS FULLY INVOLVED 04/17/2021 21:36:46 W938 Response ***TK108 EST HAMMOCK DUNES CMMD***	04/17/2021	21:33:29	W957	Response	PCT 4 RESPONDING
04/17/2021 21:35:29 W938 Response GOING TO HAMMOCK DUNES 04/17/2021 21:36:02 W938 Response 1 VEH IN THE WOODS FULLY INVOLVED 04/17/2021 21:36:46 W938 Response ***TK108 EST HAMMOCK DUNES CMMD*** *MULTIPLE QUEUED CALLS WITH MCSO UNKNOWN HOW 04/17/2021 21:36:57 W935 Response MANY WERE RELATED FIRECOM RECEIVED AT LEAST 5	04/17/2021	21:34:10	W935	Response	GATE IS OPEN
04/17/2021 21:36:46 W938 Response ***TK108 EST HAMMOCK DUNES CMMD***	04/17/2021	21:35:29	W938	Response	
*MULTIPLE QUEUED CALLS WITH MCSO UNKNOWN HOW 04/17/2021 21:36:57 W935 Response MANY WERE RELATED FIRECOM RECEIVED AT LEAST 5	04/17/2021	21:36:02	W938	Response	1 VEH IN THE WOODS FULLY INVOLVED
04/17/2021 21:36:57 W935 Response MANY WERE RELATED FIRECOM RECEIVED AT LEAST 5	04/17/2021	21:36:46	W938	Response	
	04/17/2021	21:36:57	W935	Response	MANY WERE RELATED FIRECOM RECEIVED AT LEAST 5

04/17/2021 21:37:13	W935	Response	SOME CALLERS TRANSFERRED MULTIPLE OUTSIDE AGENCIES	TIMES FROM
04/17/2021 21:38:46	W957	Response	CYPRESS CREEK D51 RESPONDING	
04/17/2021 21:39:19	W938	Response	***BC102 ASSUMING CMMD***	
04/17/2021 21:39:46	W938	Response	POSSIBLY CODE 4, R101 CAN DISREGARD	
04/17/2021 21:39:48	W935	Response	CALLING CYCREEK	
04/17/2021 21:40:03		Response	FIRE IS BEING KNOCKED DOWN	
04/17/2021 21:40:43		Response	D2 CAN BE DOWNGRADED	
04/17/2021 21:41:24		Response	DISREGARD M512	
04/17/2021 21:46:25		Response	CREEKSIDE ADV TO OPEN BRANSON	
04/17/2021 21:47:40		Response	TRAINEE ANSWERED AT GUARDSHACK AD' REACH OUT TO THE OTHER GUARD WHO W SCENE	
04/17/2021 21:48:08	W957	Response	HCFM HAS 3 FM'S RESPONDING AND WILL A CONTACT BC102 ON HIS CELL	ATTAEMP TO
04/17/2021 21:49:01	W938	Response	M24 2 CODE 4'S	
04/17/2021 21:50:32	W938	Response	D2 WAITING ON GATE TO BE OPENED BACK NOTIFIED SECURITY TO REOPEN GATE	(UP, FIRECOM
04/17/2021 23:37:08	W957	Response	SENT PEER SUPPORT NOTIFICATION	
04/17/2021 23:42:15	W938	Response	LE ON SCENE IS REQ MEDIC FOLLOW THEN STATION TO PERFORM A FIELD SOBRIETY THE ROADWAY	
04/17/2021 23:46:25	W938	Response	DISREGARD LAST NOTE WAS MEANT FOR A	ANOTHER CALL
04/17/2021 23:57:56	W938	Response	TK108 ASSUMING CMMD	
04/18/2021 01:18:19	W938	Response	HARRIS CTY HAZMAT ON LOCATION	
04/18/2021 02:56:39	W938	Response	BC102 CLEAR THE SCENE, SCENE LEFT WI	TH TK108 E107
04/18/2021 04:26:22	W938	Response	CMMD TERMINATED	
04/18/2021 04:26:37	W938	Response	LEAVING SCENE WITH E107	
		·		
Date Time	Locatio	n/Address		User
04/17/2021 21:26:4	6 / 27 Han	nmock Dunes Pl		LL
Date Time	Change	ed from Priority	Reason	User
04/17/2021 21:28:1	_	-	PTC - Patient Condition	LL
Date Time	User	Change to Alar	m	
04/17/2021 21:25:1	8 AD	1		
04/17/2021 21:28:2	5 LL	1		
Date Time	Radio Ac	tivity Location	n Log Entry	User
04/17/2021 21:24:11	Ra	pidSOS	Location found 30.15445/-95.5310	9 RSOSSERVICE
04/17/2021 21:25:16		II/ALI atistics	INT Insert:Apr 17 2021 21:24:10 / INT SendNP:Apr 17 2021 21:24:10 / WS RecvNP:Apr 17 2021 21:24:10 / WS Process:Apr 17 2021 21:25:16	W957
04/17/2021 21:25:16	Pri	cident mary TAC cannel	Primary TAC Channel FD2 has been added.	W957
04/17/2021 21:25:17		oblem 27 Hamr ture PI	nock Dunes Incident problem nature changed from <blank> to Outside - Small Fire</blank>	W957
04/17/2021 21:25:17	Pro	oQA 27 Hamr Pl	nock Dunes ProQA determinant sent	W957

04/17/2021 21:25:18	Automatic Dispatch		Automatic Dispatch Successful for DYNAMIC-10 Still - Alarm level 1	AUTODISPATCH
04/17/2021 21:25:18 E	•	27 Hammock Dunes Pl		AUTODISPATCH
04/17/2021 21:25:21 E	107 Station Alert		USDD has sent the following message: E107 successfully ACK'd incident <incidentnumber> from <terminalid></terminalid></incidentnumber>	USDD
04/17/2021 21:25:41	UserAction		User clicked Exit/Save	W938
04/17/2021 21:26:31	UserAction		User clicked Exit/Save	W935
04/17/2021 21:26:33	Incident Late	<u> </u>	Active incident marked as late	
04/17/2021 21:26:38	UserAction		User clicked Reconfigure	W954
04/17/2021 21:26:39	Reconfigure		The following unit(s) is (are)	W954
04/11/2021 21.20.00	Response		recommended for assignment: E107 (00:03:43)	VV00+
04/17/2021 21:26:43 E	107 Enroute	27 Hammock Dunes Pl	Responding From = KUYKENDAHL RD\LECRONE DR.	E107
04/17/2021 21:26:59	UserAction		User clicked Exit/Save	W938
04/17/2021 21:27:26	UserAction		User clicked Exit/Save	W957
04/17/2021 21:28:14 E	107 Change Unit Priority		Change Unit Priority from Priority 2 to Priority 1	W935
04/17/2021 21:28:14	Incident Priority Change		Incident priority changed from Priority 2 to Priority 1 due to PTC - Patient Condition	W935
04/17/2021 21:28:14	Problem Nature	22 HAMMOCK DUNES PL	Incident problem nature changed from <blank> to MVA - Fire</blank>	W935
04/17/2021 21:28:15	UserAction		User clicked Reconfigure	W935
04/17/2021 21:28:21	Reconfigure Response		The following unit(s) is (are) recommended for assignment: E107 (00:03:44),TK108 (00:06:49),CCM512 (00:08:38),R101 (00:15:37),BC102 (00:08:46),D2 (00:17:12),M24 (00:09:57)	W935
04/17/2021 21:28:25	Can't Send Resource		Resource Not Available: MSQ - MCHD Squad - C	W935
04/17/2021 21:28:25 D	2 Dispatched	22 HAMMOCK DUNES PL		W935
04/17/2021 21:28:25 C	CM512 Dispatched	22 HAMMOCK DUNES PL		W935
04/17/2021 21:28:25 M	24 Dispatched	22 HAMMOCK DUNES PL		W935
04/17/2021 21:28:25 B	C102 Dispatched	22 HAMMOCK DUNES PL		W935
04/17/2021 21:28:25 R	101 Dispatched	22 HAMMOCK DUNES PL		W935
04/17/2021 21:28:25 TI	K108 Dispatched	22 HAMMOCK DUNES PL		W935
04/17/2021 21:28:30 TI	K108 Station Alert		USDD has sent the following message: TK108,R101,BC102,D2,M24 successfully ACK'd incident <incidentnumber> from <terminalid></terminalid></incidentnumber>	USDD
04/17/2021 21:28:30 R	101 Station Alert		USDD has sent the following message: TK108,R101,BC102,D2,M24 successfully ACK'd incident	USDD

			<incidentnumber> from <terminalid></terminalid></incidentnumber>	
04/17/2021 21:28:30 BC102	Station Alert		USDD has sent the following message: TK108,R101,BC102,D2,M24 successfully ACK'd incident <incidentnumber> from</incidentnumber>	USDD
04/17/2021 21:28:30 D2	Station Alert		<terminalid> USDD has sent the following message: TK108,R101,BC102,D2,M24</terminalid>	USDD
			successfully ACK'd incident <incidentnumber> from <terminalid></terminalid></incidentnumber>	
04/17/2021 21:28:30 M24	Station Alert		USDD has sent the following message: TK108,R101,BC102,D2,M24 successfully ACK'd incident <incidentnumber> from <terminalid></terminalid></incidentnumber>	USDD
04/17/2021 21:28:53	Incident Primary TAC Channel		Primary TAC Channel has been modified from FD2 to FD4.	W954
04/17/2021 21:29:20 M24	Enroute	22 HAMMOCK DUNES PL	Responding From = ASHLANE WAY\THE WOODLANDS FIRE STATION 5.	M24
04/17/2021 21:29:22	Caution Note Info. Access		Caution Note Viewed	W935
04/17/2021 21:29:31 BC102	Enroute	22 HAMMOCK DUNES PL	Responding From = BAY BRANCH DR\KUYKENDAHL RD.	BC102
04/17/2021 21:29:40	Incident Late		Active incident marked as late	
04/17/2021 21:29:42 D2	Enroute	22 HAMMOCK DUNES PL	Responding From = HARPERS LANDING BLVD\S TRADE CENTER PKWY.	D2
04/17/2021 21:29:43	Incident Late		Active incident marked as late	
04/17/2021 21:29:45 TK108	Enroute	22 HAMMOCK DUNES PL	Responding From = GOSLING RD\GATEWOOD RESERVE LN.	TK108
04/17/2021 21:29:45	Incident Late		Active incident marked as late	
04/17/2021 21:30:12	UserAction		User clicked Exit/Save	1310
04/17/2021 21:30:50 E107	Route Deviation	KUYKENDAHL RD\CINDY ANN WAY	Unit E107 deviated from original driving directions route	E107
04/17/2021 21:31:02 E107	Unit Late at Scene		E107 did not go At Scene in expected ETA.	
04/17/2021 21:32:10	UserAction		User clicked Exit/Save	1109
04/17/2021 21:32:45	Caution Note Info. Access		Caution Note Viewed	W954
04/17/2021 21:32:56	UserAction		User clicked Exit/Save	W957
04/17/2021 21:32:59	Caution Note Info. Access		Caution Note Viewed	W954
04/17/2021 21:33:06	Caution Note Info. Access		Caution Note Viewed	W935
04/17/2021 21:33:08	Caution Note Info. Access		Caution Note Viewed	W938
04/17/2021 21:33:40	UserAction		User clicked Exit/Save	W957
04/17/2021 21:34:14	UserAction		User clicked Exit/Save	W935
04/17/2021 21:34:32 CCM51	2 Enroute	22 HAMMOCK DUNES PL	Responding From = CCEMS Sta 512.	W954
04/17/2021 21:34:33	Incident Late		Active incident marked as late	

04/17/2021 21:34:50 R101				
04/11/2021 21:34:30 1(101	Enroute	22 HAMMOCK DUNES PL	Responding From = GOSLING RD\FELLOWSHIP DR.	W954
04/17/2021 21:34:50	Incident Late		Active incident marked as late	
04/17/2021 21:36:00 E107	At Scene	22 HAMMOCK DUNES PL		W938
04/17/2021 21:36:34 TK108	At Scene	22 HAMMOCK DUNES PL		TK108
04/17/2021 21:36:45	UserAction		User clicked Exit/Save	W954
04/17/2021 21:37:01 E107	Primary Vehicle Status Change	22 HAMMOCK DUNES PL	Primary Vehicle Status removed.	W938
04/17/2021 21:37:01 TK108	Primary Vehicle Status Change	HAMMOCK DUNES PL\THORNBLADE CIR	Primary Vehicle Status set.	W938
04/17/2021 21:37:14	UserAction		User clicked Exit/Save	W935
04/17/2021 21:37:14 BC102	At Scene	22 HAMMOCK DUNES PL		BC102
04/17/2021 21:37:16 BC102	On Scene GeoFence alert	HAMMOCK DUNES PL\THORNBLADE CIR	Unit BC102 has gone At Scene while 0.04 Miles away from Incident 21-026920	USAPSERVICE
04/17/2021 21:37:39 M24	At Scene	22 HAMMOCK DUNES PL		M24
04/17/2021 21:37:40 M24	On Scene GeoFence alert	HAMMOCK DUNES PL\THORNBLADE CIR	Unit M24 has gone At Scene while 0.03 Miles away from Incident 21-026920	USAPSERVICE
04/17/2021 21:39:03 CCM512	2 Unit Late at Scene		CCM512 did not go At Scene in expected ETA.	
04/17/2021 21:39:03	Incident Late		Active incident marked as late	
04/17/2021 21:39:51 R101	Disposition	22 HAMMOCK DUNES PL	AC - Assignment Complete	W938
04/17/2021 21:39:51 R101 04/17/2021 21:39:51 R101	Disposition Available			W938 W938
		DUNES PL 22 HAMMOCK	AC - Assignment Complete Unit Cleared From Incident 21-	
04/17/2021 21:39:51 R101	Available Route Deviation	DUNES PL 22 HAMMOCK DUNES PL CREEKSIDE FOREST DR\CREEKSIDE FOREST DR TO CREEKSIDE GREEN	AC - Assignment Complete Unit Cleared From Incident 21- 026920 Unit D2 deviated from original	W938
04/17/2021 21:39:51 R101 04/17/2021 21:40:54 D2	Available Route Deviation	DUNES PL 22 HAMMOCK DUNES PL CREEKSIDE FOREST DR\CREEKSIDE FOREST DR TO CREEKSIDE GREEN DR RAMP 22 HAMMOCK	AC - Assignment Complete Unit Cleared From Incident 21- 026920 Unit D2 deviated from original driving directions route	W938 D2
04/17/2021 21:39:51 R101 04/17/2021 21:40:54 D2 04/17/2021 21:41:30 CCM512	Available Route Deviation	DUNES PL 22 HAMMOCK DUNES PL CREEKSIDE FOREST DR\CREEKSIDE FOREST DR TO CREEKSIDE GREEN DR RAMP 22 HAMMOCK DUNES PL 22 HAMMOCK	AC - Assignment Complete Unit Cleared From Incident 21- 026920 Unit D2 deviated from original driving directions route AC - Assignment Complete Unit Cleared From Incident 21-	W938 D2 W938
04/17/2021 21:39:51 R101 04/17/2021 21:40:54 D2 04/17/2021 21:41:30 CCM512 04/17/2021 21:41:30 CCM512	Available Route Deviation Disposition Available	DUNES PL 22 HAMMOCK DUNES PL CREEKSIDE FOREST DR\CREEKSIDE FOREST DR TO CREEKSIDE GREEN DR RAMP 22 HAMMOCK DUNES PL 22 HAMMOCK	AC - Assignment Complete Unit Cleared From Incident 21- 026920 Unit D2 deviated from original driving directions route AC - Assignment Complete Unit Cleared From Incident 21- 026920	W938 D2 W938 W938
04/17/2021 21:39:51 R101 04/17/2021 21:40:54 D2 04/17/2021 21:41:30 CCM512 04/17/2021 21:41:30 CCM512 04/17/2021 21:45:52	Available Route Deviation Disposition Available UserAction	DUNES PL 22 HAMMOCK DUNES PL CREEKSIDE FOREST DR\CREEKSIDE FOREST DR TO CREEKSIDE GREEN DR RAMP 22 HAMMOCK DUNES PL 22 HAMMOCK	AC - Assignment Complete Unit Cleared From Incident 21- 026920 Unit D2 deviated from original driving directions route AC - Assignment Complete Unit Cleared From Incident 21- 026920 User clicked Exit/Save	W938 D2 W938 W938 W938 W954
04/17/2021 21:39:51 R101 04/17/2021 21:40:54 D2 04/17/2021 21:41:30 CCM512 04/17/2021 21:41:30 CCM512 04/17/2021 21:45:52 04/17/2021 21:45:55	Available Route Deviation Disposition Available UserAction UserAction Unit Late at	DUNES PL 22 HAMMOCK DUNES PL CREEKSIDE FOREST DR\CREEKSIDE FOREST DR TO CREEKSIDE GREEN DR RAMP 22 HAMMOCK DUNES PL 22 HAMMOCK	AC - Assignment Complete Unit Cleared From Incident 21-026920 Unit D2 deviated from original driving directions route AC - Assignment Complete Unit Cleared From Incident 21-026920 User clicked Exit/Save User clicked Exit/Save D2 did not go At Scene in expected	W938 D2 W938 W938 W938 W954
04/17/2021 21:39:51 R101 04/17/2021 21:40:54 D2 04/17/2021 21:41:30 CCM512 04/17/2021 21:41:30 CCM512 04/17/2021 21:45:52 04/17/2021 21:45:55 04/17/2021 21:47:37 D2	Available Route Deviation Disposition Available UserAction UserAction Unit Late at Scene	DUNES PL 22 HAMMOCK DUNES PL CREEKSIDE FOREST DR\CREEKSIDE FOREST DR TO CREEKSIDE GREEN DR RAMP 22 HAMMOCK DUNES PL 22 HAMMOCK	AC - Assignment Complete Unit Cleared From Incident 21-026920 Unit D2 deviated from original driving directions route AC - Assignment Complete Unit Cleared From Incident 21-026920 User clicked Exit/Save User clicked Exit/Save D2 did not go At Scene in expected ETA.	W938 D2 W938 W938 W938 W954
04/17/2021 21:39:51 R101 04/17/2021 21:40:54 D2 04/17/2021 21:41:30 CCM512 04/17/2021 21:41:30 CCM512 04/17/2021 21:45:52 04/17/2021 21:45:55 04/17/2021 21:47:37 D2	Available Route Deviation Disposition Available UserAction UserAction Unit Late at Scene Incident Late	DUNES PL 22 HAMMOCK DUNES PL CREEKSIDE FOREST DR\CREEKSIDE FOREST DR TO CREEKSIDE GREEN DR RAMP 22 HAMMOCK DUNES PL 22 HAMMOCK DUNES PL	AC - Assignment Complete Unit Cleared From Incident 21- 026920 Unit D2 deviated from original driving directions route AC - Assignment Complete Unit Cleared From Incident 21- 026920 User clicked Exit/Save User clicked Exit/Save D2 did not go At Scene in expected ETA. Active incident marked as late Responding From = HAMMOCK DUNES PL\THORNBLADE CIR.	W938 D2 W938 W938 W938 W954 W957
04/17/2021 21:39:51 R101 04/17/2021 21:40:54 D2 04/17/2021 21:41:30 CCM512 04/17/2021 21:41:30 CCM512 04/17/2021 21:45:52 04/17/2021 21:45:55 04/17/2021 21:47:37 D2 04/17/2021 21:47:37 04/17/2021 21:47:46 CH10	Available Route Deviation Disposition Available UserAction UserAction Unit Late at Scene Incident Late Dispatched	DUNES PL 22 HAMMOCK DUNES PL CREEKSIDE FOREST DR\CREEKSIDE FOREST DR TO CREEKSIDE GREEN DR RAMP 22 HAMMOCK DUNES PL 22 HAMMOCK DUNES PL 22 HAMMOCK DUNES PL 22 HAMMOCK DUNES PL	AC - Assignment Complete Unit Cleared From Incident 21-026920 Unit D2 deviated from original driving directions route AC - Assignment Complete Unit Cleared From Incident 21-026920 User clicked Exit/Save User clicked Exit/Save D2 did not go At Scene in expected ETA. Active incident marked as late Responding From = HAMMOCK	W938 D2 W938 W938 W938 W954 W957
04/17/2021 21:39:51 R101 04/17/2021 21:40:54 D2 04/17/2021 21:41:30 CCM512 04/17/2021 21:41:30 CCM512 04/17/2021 21:45:52 04/17/2021 21:45:55 04/17/2021 21:47:37 D2 04/17/2021 21:47:37 04/17/2021 21:47:46 CH10 04/17/2021 21:47:46 CH10	Available Route Deviation Disposition Available UserAction UserAction Unit Late at Scene Incident Late Dispatched Enroute	DUNES PL 22 HAMMOCK DUNES PL CREEKSIDE FOREST DR\CREEKSIDE FOREST DR TO CREEKSIDE GREEN DR RAMP 22 HAMMOCK DUNES PL 22 HAMMOCK DUNES PL 22 HAMMOCK DUNES PL 22 HAMMOCK DUNES PL	AC - Assignment Complete Unit Cleared From Incident 21- 026920 Unit D2 deviated from original driving directions route AC - Assignment Complete Unit Cleared From Incident 21- 026920 User clicked Exit/Save User clicked Exit/Save D2 did not go At Scene in expected ETA. Active incident marked as late Responding From = HAMMOCK DUNES PL\THORNBLADE CIR.	W938 D2 W938 W938 W938 W954 W957

04/17/2021 21:48:03 CH10	On Scene GeoFence alert	HAMMOCK DUNES PL\THORNBLADE CIR	Unit CH10 has gone At Scene while 0.06 Miles away from Incident 21-026920	USAPSERVICE
04/17/2021 21:48:21	UserAction		User clicked Exit/Save	W957
04/17/2021 21:49:57	UserAction		User clicked Exit/Save	1312
04/17/2021 21:54:20 D2	At Scene	22 HAMMOCK DUNES PL		D2
04/17/2021 21:54:21 D2	On Scene GeoFence alert	THORNBLADE CIR\HAMMOCK DUNES PL	Unit D2 has gone At Scene while 0.15 Miles away from Incident 21-026920	USAPSERVICE
04/17/2021 22:01:00	Incident Late		Active incident marked as late	
04/17/2021 22:01:09	UserAction		User clicked Exit/Save	W957
04/17/2021 22:05:51	UserAction		User clicked Exit/Save	W957
04/17/2021 22:06:14	UserAction		User clicked Exit/Save	W954
04/17/2021 22:14:28	UserAction		User clicked Exit/Save	W935
04/17/2021 22:35:56	UserAction		User clicked Exit/Save	W935
04/17/2021 22:41:06 CH10	Disposition	22 HAMMOCK DUNES PL	AC - Assignment Complete	10
04/17/2021 22:41:06 CH10	Available	22 HAMMOCK DUNES PL	Unit Cleared From Incident 21- 026920	10
04/17/2021 22:47:01 D2	Disposition	22 HAMMOCK DUNES PL	District Chief Assist - DC	W938
04/17/2021 22:47:01 D2	Available	22 HAMMOCK DUNES PL	Unit Cleared From Incident 21- 026920	W938
04/17/2021 22:47:31	UserAction		User clicked Exit/Save	1150
04/17/2021 22:47:57	UserAction		User clicked Exit/Save	1109
04/17/2021 22:48:11	UserAction		User clicked Exit/Save	1150
04/17/2021 22:51:18	UserAction		User clicked Exit/Save	1310
04/17/2021 22:52:25	UserAction		User clicked Exit/Save	W938
04/17/2021 23:22:42	UserAction		User clicked Exit/Save	W954
04/17/2021 23:37:09	UserAction		User clicked Exit/Save	W957
04/18/2021 00:17:00 E102	Dispatched	22 HAMMOCK DUNES PL		E102
04/18/2021 00:17:00 E102	Enroute	22 HAMMOCK DUNES PL	Responding From = GOSLING RD\UNNAMED.	E102
04/18/2021 00:17:01	Incident Late		Active incident marked as late	
04/18/2021 00:19:51 E102	Disposition	22 HAMMOCK	AC - Assignment Complete	E102
	·	DUNES PL	,	
04/18/2021 00:19:51 E102	Available	22 HAMMOCK DUNES PL	Unit Cleared From Incident 21- 026920	E102
04/18/2021 00:38:43	UserAction		User clicked Exit/Save	W938
04/18/2021 01:06:45	UserAction		User clicked Exit/Save	1109
04/18/2021 01:13:19	UserAction		User clicked Exit/Save	W935
04/18/2021 01:19:34	UserAction		User clicked Exit/Save	W957
04/18/2021 01:42:24	UserAction		User clicked Exit/Save	1110
04/18/2021 02:35:31	UserAction		User clicked Exit/Save	W938
04/18/2021 02:41:53	UserAction		User clicked Exit/Save	1110
04/18/2021 02:52:16	UserAction		User clicked Exit/Save	1110
04/18/2021 02:56:43 BC102	Disposition	22 HAMMOCK DUNES PL	AC - Assignment Complete	W938
04/18/2021 02:56:43 BC102	Available	22 HAMMOCK DUNES PL	Unit Cleared From Incident 21- 026920	W938
04/18/2021 02:56:46	UserAction		User clicked Exit/Save	W938
04/18/2021 02:57:09	UserAction		User clicked Exit/Save	1109
	555 (011011			• •

04/18/2021 03:03:44	UserAction		User clicked Exit/Save	W957
04/18/2021 03:03:52	UserAction		User clicked Exit/Save	W957
04/18/2021 03:14:04	UserAction		User clicked Exit/Save	1109
04/18/2021 03:20:09 M24	Depart	HAMMOCK DUNES	Unit M24 has moved 0.08 Miles	USAPSERVICE
04/10/2021 00:20:00 M24	Scene GeoFence alert	PL\THORNBLADE CIR	away from Incident 21-026920 while At Scene	SOM SERVICE
04/18/2021 03:20:57 M24	Disposition	22 HAMMOCK DUNES PL	Dead On Arrival - DOA	1109
04/18/2021 03:20:57 M24	Available	22 HAMMOCK DUNES PL	Unit Cleared From Incident 21- 026920	1109
04/18/2021 03:21:55	UserAction		User clicked Exit/Save	1110
04/18/2021 03:42:06	UserAction		User clicked Exit/Save	1110
04/18/2021 03:42:49	Caution Note Info. Access)	Caution Note Viewed	W935
04/18/2021 03:43:11	Caution Note Info. Access)	Caution Note Viewed	W954
04/18/2021 03:55:16	UserAction		User clicked Exit/Save	W954
04/18/2021 04:00:43	Caution Note Info. Access	•	Caution Note Viewed	W935
04/18/2021 04:03:21	UserAction		User clicked Exit/Save	W935
04/18/2021 04:24:06 TK108	Depart Scene GeoFence alert	HAMMOCK DUNES PL\THORNBLADE CIR	Unit TK108 has moved 0.05 Miles away from Incident 21-026920 while At Scene	USAPSERVICE
04/18/2021 04:26:42 TK108	Disposition	22 HAMMOCK DUNES PL	AC - Assignment Complete	W938
04/18/2021 04:26:42 TK108	Available	22 HAMMOCK DUNES PL	Unit Cleared From Incident 21- 026920	W938
04/18/2021 04:34:33 E107	Depart Scene GeoFence alert	HAMMOCK DUNES PL\THORNBLADE CIR	Unit E107 has moved 0.04 Miles away from Incident 21-026920 while At Scene	USAPSERVICE
04/18/2021 04:35:57 E107	Depart Scene GeoFence alert	HAMMOCK DUNES PL\THORNBLADE CIR	Unit E107 has moved 0.1 Miles away from Incident 21-026920 while At Scene	USAPSERVICE
04/18/2021 04:36:45 E107	Disposition	22 HAMMOCK DUNES PL	AC - Assignment Complete	E107
04/18/2021 04:36:45 E107	Available	22 HAMMOCK DUNES PL	Unit Cleared From Incident 21- 026920	E107
04/18/2021 04:36:46	Incident Timer Clear	22 HAMMOCK DUNES PL	Incident Late Timer cleared for 21-026920	Mobile1
04/18/2021 04:36:46 E107	Response Closed	22 HAMMOCK DUNES PL	Response Disposition: AC - Assignment Complete	E107
04/18/2021 04:38:49	UserAction		User clicked Exit/Save	W938
04/18/2021 04:47:17	UserAction		User clicked Exit/Save	W954
04/18/2021 07:58:01	UserAction		User clicked Exit/Save	887
04/18/2021 11:43:30	UserAction		User clicked Exit/Save	W923
04/18/2021 11:44:48	UserAction		User clicked Exit/Save	W951
04/18/2021 18:33:55	UserAction		User clicked Exit/Save	W935
04/18/2021 18:34:59	UserAction		User clicked Exit/Save	W935
04/19/2021 05:09:24	UserAction		User clicked Exit/Save	W935
04/19/2021 08:18:58	UserAction		User clicked Exit/Save	W949
04/19/2021 08:22:07	UserAction		User clicked Exit/Save	W949

04/19/2021 08:39:33	Caution Note Info. Access	Caution Note Viewed	W949
04/19/2021 08:40:03	UserAction	User clicked Exit/Save	W949
04/19/2021 16:00:51	Caution Note Info. Access	Caution Note Viewed	W949
04/19/2021 16:02:31	UserAction	User clicked Exit/Save	W949
04/19/2021 20:34:29	UserAction	User clicked Exit/Save	W927
04/25/2021 01:28:43	UserAction	User clicked Exit/Save	1311

Date	Time	Field	Changed From	Changed To	Reason	Table	Workstati on	User
04/17/2 021	21:24 :11	Call_Back_Phone		(713) 303- 9869	(Response Viewer)	Response_Master_I ncident	DISCON- D402	W957
04/17/2 021	21:24 :11	Address	(Blank)	30°09'16.7 8"N / 095°31'52. 25"W	New Entry	Response_Master_I ncident	DISCON- D402	W957
04/17/2 021	21:24 :11	Jurisdiction		The Woodland s FD	(Response Viewer)	Response_Master_I ncident	DISCON- D402	W957
04/17/2 021	21:24 :11	Division		The Woodland s FD	(Response Viewer)	Response_Master_I ncident	DISCON- D402	W957
04/17/2 021	21:24 :11	Battalion		The Woodland s FD	(Response Viewer)	Response_Master_I ncident	DISCON- D402	W957
04/17/2 021	21:24 :11	Response_Area		10XH	(Response Viewer)	Response_Master_I ncident	DISCON- D402	W957
04/17/2 021	21:24 :11	ResponsePlanType	0	0	(Response Viewer)	Response_Master_I ncident	DISCON- D402	W957
04/17/2 021	21:24 :11	Address	30°09'16.7 8"N / 095°31'52. 25"W	HAMMOC	Entry Selected/Re turned from GeoLocator	Response_Master_I ncident	DISCON- D402	W957
04/17/2 021	21:24 :11	City		SPRING	Updated City	Response_Master_I ncident	DISCON- D402	W957
04/17/2 021	21:24 :11	Latitude	0	30154662	Entry Selected/Re turned from GeoLocator	Response_Master_I ncident	DISCON- D402	W957
04/17/2 021	21:24 :11	Longitude	0	95531180	Entry Selected/Re turned from GeoLocator	Response_Master_I ncident	DISCON- D402	W957
04/17/2 021	21:24 :11	Agency Name		MCCAD	(Response Viewer)	Incident	DISCON- D402	W957
04/17/2 021	21:24 :11	Call Back Phone			(Response Viewer)	Incident	DISCON- D402	W957
04/17/2 021	21:24 :19	Pro Qa Case Number Fire		437438	(Response Viewer)	Incident	DISCON- D402	W957
04/17/2 021	21:24 :46	Caller Name		VERIZON	(Response Viewer)	Incident	DISCON- D402	W957
04/17/2 021	21:25 :16	Problem		Outside - Small Fire	(Response Viewer)	Response_Master_I ncident	DISCON- D402	W957
04/17/2 021	21:25 :16	Primary TAC Channel		FD2	(Response Viewer)	Incident	DISCON- D402	W957
04/17/2 021	21:25 :17	Response_Time_Cri teria	00:00:00	00:11:59	Updated by ProQA	Response_Master_I ncident	DISCON- D402	W957

04/17/2 021	21:25 :17	Priority_Number	0	2	Updated by ProQA	Response_Master_I ncident	DISCON- D402	W957
04/17/2 021	21:25 :17	Priority_Description		Priority 2	Updated by ProQA	Response_Master_I ncident	DISCON- D402	W957
04/17/2 021	21:25 :17	Certification_Level		Fire	Updated by ProQA	Response_Master_I ncident	DISCON- D402	W957
04/17/2 021	21:25 :17	Determinant		67B01R	(Response Viewer)	Response_Master_I ncident	DISCON- D402	W957
04/17/2 021	21:25 :17	EMD_Used	0	1	(Response Viewer)	Response_Master_I ncident	DISCON- D402	W957
04/17/2 021	21:25 :17	CIS_Used	0	null	(Response Viewer)	Response_Master_I ncident	DISCON- D402	W957
04/17/2 021	21:25 :18	Pickup_Map_Info		250K		Response_Transpor ts	DISCON- D402	W957
04/17/2 021	21:25 :18	Map_Info		250K		Response_Master_I ncident	DISCON- D402	W957
04/17/2 021	21:25 :18	Caller_Building		4974D3	Polygon Lookup	Response_Master_I ncident	DISCON- D402	W957
04/17/2 021	21:25 :21	Unread Comment	False	True	(Response Viewer)	Incident	SERVERV M260	SERVERVM26 0MSOS
04/17/2 021	21:26 :39	CIS_Used	0	null	(Response Viewer)	Response_Master_I ncident	DISCON- D402	W957
04/17/2 021	21:26 :39	Pro QA Termination State Code		С	(Response Viewer)	Incident	DISCON- D402	W957
04/17/2 021	21:26 :39	ProQATerminationS tateCode		С	(Response Viewer)	Incident	DISCON- D402	W957
04/17/2 021	21:26 :45	Address	27 Hammock Dunes PI	22 Hammock Dunes Pl	Address Change	Response_Master_I ncident	DISCON- D404	W935
04/17/2 021	21:26 :46	Address	27 Hammock Dunes Pl	22 HAMMOC K DUNES PL	(Response Viewer)	Response_Master_I ncident	DISCON- D404	W935
04/17/2 021	21:26 :46	Latitude	30154662	30155024	(Response Viewer)	Response_Master_I ncident	DISCON- D404	W935
04/17/2 021	21:26 :46	Longitude	95531180	95531404	(Response Viewer)	Response_Master_I ncident	DISCON- D404	W935
04/17/2 021	21:26 :46	Street_Id	640364	640356	(Response Viewer)	Response_Master_I ncident	DISCON- D404	W935
04/17/2 021	21:26 :46	Address	22 Hammock Dunes Pl	22 HAMMOC K DUNES PL	Change Verified	Response_Master_I ncident	DISCON- D404	W935
04/17/2 021	21:26 :47	Pickup_Map_Info		250K		Response_Transpor ts	DISCON- D404	W935
04/17/2 021	21:26 :47	Map_Info	250K	250K		Response_Master_I ncident	DISCON- D404	W935
04/17/2 021	21:26 :47	Caller_Building	4974D3	4974D3	Polygon Lookup	Response_Master_I ncident	DISCON- D404	W935
04/17/2 021	21:28 :14	Current_UnitRespPr iorityDesc	E107: Priority 2	Priority 1	PTC - Patient Condition	Response_Vehicles _Assigned	DISCON- D404	W935
04/17/2 021	21:28 :14	Response_Time_Cri teria	00:11:59	00:09:59	(Response Viewer)	Response_Master_I ncident	DISCON- D404	W935
04/17/2 021	21:28 :14	Problem	Outside - Small Fire	MVA - Fire	(Response Viewer)	Response_Master_I ncident	DISCON- D404	W935

04/17/2 21:28 RespReconfigState 021 :14	0	1	Response reconfigure needed	Response_Master_I ncident	DISCON- D404	W935
04/17/2 21:28 Response_Plan 021 :14	10 Still	10 Vehicle Extrication	(Response Viewer)	Response_Master_I ncident	DISCON- D404	W935
04/17/2 21:28 DispatchLevel 021 :14	Default	Normal Operation s EMS	(Response Viewer)	Response_Master_I ncident	DISCON- D404	W935
04/17/2 21:28 Priority_Description 021 :14	Priority 2	Priority 1	PTC - Patient Condition	Response_Master_I ncident	DISCON- D404	W935
04/17/2 21:28 Priority_Number 021 :14	2	1	PTC - Patient Condition	Response_Master_I ncident	DISCON- D404	W935
04/17/2 21:28 Incident_Type 021 :14	Still	Vehicle Extrication	(Response Viewer)	Response_Master_I ncident	DISCON- D404	W935
04/17/2 21:28 CIS_Used 021 :22	0	null	(Response Viewer)	Response_Master_I ncident	DISCON- D402	W957
04/17/2 21:28 Primary_TAC_Chan 021 :53 nel	FD2	FD4	(Response Viewer)	Response_Master_I ncident	DISCON- D401	W954
04/17/2 21:49 Date_Time 021 :12		Apr 17 2021 21:49:12	Dead on Scene	Response_User_Ti meStamps	DISCON- D403	W938

 Description
 Date
 Time
 User

 Dead on Scene
 04/17/2021
 21:49:12
 W938

No Custom Data Fields

No Attachment



#21-026920 CAR FIRE @ 22 HAMMOCK DUNES PLACE

ON 04/17/2021 @ 21:28, TK108 WAS DISPATCHED TO 22 HAMMOCK DUNES PLACE FOR A REPORTED CAR FIRE, WITH OTHER UNITS ALREADY ENROUTE. AT 21:33 TK108 HAD FIRECOM NOTIFY CARLTON WOODS SECURITY THAT TWFD UNITS WOULD BE USING THE BRANSON WAY ENTRANCE. E107 ARRIVED ON LOCATION AND WENT OUT WITH ONE VEHICLE IN THE WOODS, FULLY INVOLVED. AT 21:36 TK108 ARRIVED ON LOCATION AND ESTABLISHED HAMMOCK DUNES INCIDENT COMMAND. TK108 OFFICER DID A FACE-TO-FACE PASS-ON WITH THE ACTING E107 OFFICER. THE VEHICLE WAS A SHORT DISTANCE FROM THE DRY CONCRETE ROAD AND HAD IMPACTED A TREE FRONTALLY AND REMAINED FULLY INVOLVED. THE REAR DRIVER SIDE TIRE WAS VISIBLE AND INDICATED THE VEHICLE TO BE A TESLA THAT HAD BEEN TRAVELING FROM EAST TO WEST ON HAMMOCK DUNES PLACE, THE ROAD DEAD ENDS TO THE EAST. TK108'S FIREFIGHTERS JOINED E107'S FIRE ATTACK. TK108'S DRIVER ASSISTED E107'S DRIVER WITH PUMP OPERATIONS AND SECURING A SUPPLY LINE. AT 21:39 BC102 ASSUMED HAMMOCK DUNES COMMAND FROM TK108 OFFICER, IN A FACE-TO-FACE PASS-ON. AT 21:40 THE MAJORITY OF THE FIRE HAD BEEN KNOCKED DOWN AND IT BECAME EVIDENT THAT THE VEHICLE WAS OCCUPIED. THERE WAS ONE OCCUPANT IN THE FRONT PASSENGER SEAT AREA AND ANOTHER IN THE REAR DRIVER SIDE AREA. THE PLACEMENT OF THE OCCUPANTS RAISED IMMEDIATE CONCERNS THAT THERE MIGHT BE MORE OCCUPANTS AND A SEARCH WAS STARTED IN THE HEAVILY WOODED AREA OF THE CRASH AND AROUND THE POND USING MULTIPLE FIREFIGHTER USING THERMAL CAMERAS. CONSTABLE OFFICERS FROM PCT. 4 MADE CONTACT WITH FAMILY MEMBERS OF THE OCCUPANTS OF THE VEHICLE AND CONFIRMED THAT THERE WERE TWO OCCUPANTS IN THE VEHICLE SO THE SEARCH WAS DISCONTINUED. TK108 OFFICER ASSISTED MCHD M24 ON SCENE WITH TWO DISTRAUGHT FEMALE FAMILY MEMBERS OF THE OCCUPANTS IN THE VEHICLE. M24 ASSISTED THEM WITH NOTIFYING MORE FAMILY MEMBERS WHO WERE REQUESTED TO COME TO THE SCENE. TK108 OFFICER AT THAT POINT WENT TO THE ROADBLOCK AT THE BEGINNING OF HAMMOCK DUNES PLACE TO AWAIT THE ARRIVAL OF THOSE FAMILY MEMBERS. CCEMS M512 ARRIVED ON LOCATION FOR A CARDIAC PATIENT ON HAMMOCK DUNES PLACE AND TK108 OFFICER ASSISTED THEM NAVIGATE THE SCENE. M512 DETERMINED THIS WAS THE SAME PATIENT M24 HAD CHECKED OUT EARLIER AND THEY HAD BEEN CALLED TO THE SCENE BY PCT.4 BUT THERE WAS NO MEDICAL EMERGENCY. TK108 OFFICER WAS NO LONGER NEEDED TO ESCORT FAMILY AS THEY HAD FOUND ANOTHER WAY IN. BACK AT THE SCENE OF THE CRASH LATENT HEAT HAD REIGNITED THE FIRE IN THE VEHICLE AND FIRE SUPPRESSION HAD RESUMED, DURING WHICH TK108'S DRIVER HAD BEEN INJURED BY A FIRE HOSE. THE SPARE AIR SUPPLY AT THIS POINT HAD BECOME CRITICALLY LOW AND BC102 DECIDED TO BRING THE INJURED FIREFIGHTER TO WOODLAND MEMORIAL ER WEST AND DROP OFF THE EMPTY AIR CYLINDERS AT STATION 5 FOR REFILLING. AT 23:57 TK108 OFFICER ASSUMED COMMAND FROM BC102. AT THIS POINT A BLITZFIRE WAS DEPLOYED TO COOL THE VEHICLE AND A 1.75" ATTACK LINE AND A BOOSTER LINE FROM E107 WERE ALL BEING USED TO KEEP THE INCIDENT IN CHECK. PCT. 4 DEPUTY SINGLETON NOTIFIED COMMAND THAT HARRIS COUNTY HAZMAT WOULD BE NEEDED TO DECONTAMINATE THE VICTIMS, THE UNITS WOULD TAKE ABOUT AN HOUR TO ARRIVE, THE WOODLANDS FIRE DEPARTMENT HAZMAT TEAM THAT WAS ALREADY ENROUTE WAS DISREGARDED. AT 01:18 HARRIS COUNTY HAZMAT ARRIVED ON LOCATION AND COMMAND NOTIFIED THEM OF THE SITUATION AT HAND UP TO THAT TIME. IT WAS DETERMINED THAT SUFFICIENT COOLING HAD OCCURRED TO ATTEMPT TO REMOVE THE VICTIMS, AND ALL ATTACK LINES WERE SHUT DOWN. CREWS FROM E107 AND TK108 WOULD REMOVE THE DOORS FROM THE VEHICLE TO GAIN BETTER ACCESS FOR PATIENT REMOVAL. IT WAS THEN DECIDED THAT E107 AND TK108 WOULD ALSO ASSIST HARRIS COUNTY MEDICAL PERSONNEL WITH PATIENT REMOVAL FROM THE VEHICLE. DURING THIS OPERATION SEVERAL EXPOSURES OCCURRED OF FIRE DEPARTMENT PERSONNEL BY BODY FLUIDS FROM ONE OF THE VICTIMS. BOTH VICTIMS WERE SUCCESSFULLY EXTRICATED FROM THE VEHICLE AND TURNED OVER TO THE MEDICAL EXAMINER. THE CREWS CONTAMINATED WERE DECONTAMINATED BY MCHD M24 AND BC102 WAS NOTIFIED OF THE SITUATION. TWO HARRIS COUNTY MEDICAL EXAMINERS PERSONNEL ALSO RECEIVED MINOR LACERATIONS TO THE HAND REQUIRING THE ASSISTANCE OF M24. TK108 ASSISTED E107 WITH ROLLING ALL THEIR HOSE AND DOING A ON SCENE GROSS DECONTAMINATION OF ALL BUNKER GEAR TO RETURN BOTH UNITS TO SERVICE. AT 04:26 HAMMOCK DUNES COMMAND WAS TERMINATED AND THE SCENE WAS LEFT WITH E107. TK108 RETURNED TO SERVICE.