

Recap of ground incident of DA-50 registration OE-DSD

This document will recap the event that occurred on June 13th 2023 involving a DA-50 registration OE-DSD a visiting aircraft from Austria. This occurred at [REDACTED] Wagener SC, 29164 on my private airstrip.

At approximately 10:30 I completed my preflight and planned a flight departing to the east from my airstrip. I started the takeoff and all seemed normal until just before rotation, I felt a large wind gust and decided to abort the take off with now a sudden change in wind speed and direction, as I was decelerating the abort took me off the end of my airstrip going through a fence and the aircraft came to rest upright just beyond the end of my runway. No injuries and minor damage to a fence located on edge of my property.



Sayyu Dantata
FAA Private Pilot Certificate [REDACTED]