



Vehicle Attachment – Van ACM Results

Andrews, TX

HWY22MH006

(4 pages)

From: [Kawamoto Gerald](#)
To: [Cantrell Jerome](#)
Cc: [Babcock Christopher](#)
Subject: HWY22MH006 (Andrews, Texas) Electronic Device Email Report
Date: Friday, August 5, 2022 9:48:48 AM
Attachments: [IMG_3961.jpg](#)
[IMG_3962.jpg](#)
[IMG_3969.jpg](#)

Email Report Instructions:

The narrative and attachments from this email report may be used in other reports at the discretion of the IIC. This email, including attachments (if applicable), should also be placed in the docket by the IIC.

Email Report:

The Vehicle Recorder Division received an unidentified airbag control module (S/N: unknown). The device sustained fire damage (IMG_3961.jpg, IMG_3962.jpg) rendering it inoperable. An internal examination revealed the internal components sustained extensive heat damage (IMG_3969.jpg), thus, no data were recovered.

Prepared by:


Gerald Kawamoto, Recorder Specialist NTSB RE-40



Photograph 1: The damage to the bottom of the ACM from the van



Photograph 2: The damage to the top of the ACM from the van



Photograph 3: The damaged ACM chip board