

Communication Summary

October 22, 2020

Information from: Mr. Nick Shepler, Rolls Royce



Summary & Factual Information: Mr. Shepler was asked if he could advise what effect a Pc Line leak would have on engine operation. He in part, reported: A leak in the pneumatic line can cause the engine control system to go into a sub-idle fuel flow condition and subsequent power loss.

I can attest that the above summary is correct to the best of my knowledge:

Edward F. Malinowski
National Transportation Safety Board
Air Safety Investigator