



**Photo 1 – Supplied view of the jackscrew in the trim system.**



**Photo 2 - Supplied view of the jackscrew in the trim system.**



**Photo 3 - Supplied view of the jackscrew with about 8 threads showing. Trim indicator is in the takeoff position.**



**Photo 4 - Supplied view of the trim indicator in the takeoff position. The jackscrew has about 8 threads showing.**





**Photo 5 - Supplied view of the jackscrew with about 13 threads showing.**



**Photo 6 - Supplied view of the jackscrew at full extension.**



**Photo 7 - Supplied view of the trim indicator in the full up position. The jack screw is at its full extension.**





**Photo 8 - View of the jackscrew on N602TF at the accident site.**