



Photo 1 – Supplied view of the accident airplane on a runway. The landing gear are not extended and the propellers exhibit tip damage.



Photo 2 - Supplied view of the fuselage belly. A skin panel is detached from its damaged ribs and stringers.