

SURVIVAL FACTORS ATTACHMENT

Hempstead Fire Department Brief Field Incident

Report

Monaville, TX

HWY22FH002

(3 pages)

Waller Harris ESD 200

Station: 11

Location:

Holik Rd and 1887 Hempstead TX 77445

Holik Road

Lat/Long: N 29° 57′ 0.28″ W 96° 3′ 55.4″

Zone:

Monaville - Monaville

Location Type: **2 - Intersection**Cross Street, Directions or National Grid:

Holik Road

Incident Type:

322 - Motor vehicle accident with injuries

EMSID: FDID: **XC601**

Incident #: **2021-562462**Exposure ID: **63049199**Incident Date: **12/17/2021**

Report Completed by:	Conner , Mitchell	ID: Date	e: 12/17/2021
Report Reviewed by:	Gibson , Timothy W	ID: 10196	Date: 01/05/2022
Report Printed by:	Gibson, Timothy W	ID: 10196	Date: 1/5/2022 Time: 11:00

Aid Given or Received:	None	Primary action	taken: 81 - Incident command			
Additional actions:	dditional actions: 31 - Provide first aid & check for injuries , 52 - Forcible entry					
Total # of apparatus on o	all:	2	Total # of personnel on call:	3		

Special Studies

COVID 19 was a factor in this incident. No, COVID 19 was not a factor.

NARRATIVE (1)

Narrative Title: n/a

Narrative Author: Conner, Mitchell

Narrative Date: 12/17/2021 17:16:28

Narrative Apparatus ID: E12

Narrative:

E-12 was dispatched to an MVC with Med 1 and S-1, and responded emergency traffic from the station. Upon arrival on school bus was found off the road sitting upright with heavy damage. The bus appeared to have lost control, and rolled at least twice. E-12 established command. EMS 1 had EMS command. E-12 secured the vehicle while medics began patient care. E-12 cut battery cables, and made sure the bus had breaks locked. E-12 assisted packaging the patient's, and extricating them from the bus. E-12 secured the roadway to allow air medical to land. E-12 remained on location to control traffic. One of E-12 crew members had an exposure, and it was documented and recorded. DPS advised they no longer needed traffic control. Command was terminated, and E-12 returned to service.

APPARATUS				
Unit	E12	Unit	B12	
Туре:	Engine	Type:	Brush truck	
Use:	Suppression	Use:	Suppression	
Response Mode:	Lights and Sirens	Response Mode:	Lights and Sirens	
# of People	2	# of People	1	
Alarm	12 /17/2021 12:16:16	Alarm	12 /17/2021 12:17:00	
Dispatched	12 /17/2021 12:16:16	Dispatched	12 /17/2021 12:17:02	
Enroute	12 /17/2021 12:16:20	Enroute	12 /17/2021 12:18:00	
Arrived	12 /17/2021 12:25:00	Arrived	12 /17/2021 12:27:30	
Cancelled	/ / : :	Cancelled	/ / : :	
Cleared Scene	12 /17/2021 13:27:06	Cleared Scene	12 /17/2021 13:27:26	
In Quarters	/ / : :	In Quarters	/ / : :	
In Service	/ / : :	In Service	/ / : :	
Number Of People not on apparatus: 0				

CUSTOM FIELDS FORM

Did you verify the FDID Number on BASIC 1 for your Department? ESD 200 XC601 Monaville XC501 Mt. Zion XC201 Pattison XC406 Prairie View XC403 Tri-County XC104 Waller XC405

Yes

PERSONNEL ON CALLNamePersonnel RankRole(s)ApparatusArcher, MalloryDuty Crew FirefighterE12Conner, MitchellDuty Crew FirefighterE12Pahl, BenjaminVolunteerB12

Member Making Report (Duty Crew Firefighter Mitchell Conner):				
Incident Reviewer (Chief Timothy W Gibson):				