

Nabtesco 出張工事報告書

SERVICE REPORT

検印 (Checked)

運報 No. Service Work Request No.	1-16066	原受注先 Original Customer		補償判定 (GUARANTEE)		
エンジン型式 Engine Type	DU 7RTA6Z	本工事受注先 Client of This Work	NABTESCO SINGAPORE	有償 (OUT)	無償 (IN)	一部有償 (Partly OUT)
ENGINE	☒ SUL ☐ B&W ☐ UE ☐ PC ☐ MAN ☐ OTHER					

船主 (OWNER)		日時 (DATE)	2006 SEP 9 ~
船名 (SHIP NAME)	AFRAMAX RIVER	工事場所 (PLACE)	HOUSTON USA
造船所 (SHIP YARD)	IMABARU	HULL No.	8009
		就航年月日 (DELIVERY)	2002/SEP
装置名 (SYSTEMS TYPE)	GOV (HCB302/EAL-300B)	図番 (DWG.NO.)	74H58116-00

サービス項目 (SERVICE ITEM)	状況 (SYMPTOMS)
☐ 海上運転 (SEATRIAL) ☐ 陸上運転 (SHOPTRIAL)	
☐ 点検 (INSPECTION) ☐ オーバーホール (OVERHAUL)	
☐ 修理 (REPAIR) ☐ 改造 (MODIFICATION)	
☐ 調査 (INVESTIGATION) ☐ その他 (OTHER)	

工事内容及び結果 (WORKS AND RESULTS)	後送品 (有無) / 残工事 (有無) Goods To Be Sent Later (Exist/Not Exist) Remained Work (Exist/Not Exist)
日時	
DISPATCHED 1 ENGINEER FROM JAPAN TO HOUSTON FOR GOVERNOR INVESTIGATION ON AFRAMAX RIVER	
FOUND GOVERNOR ACTUATOR SYSTEM ENCOUNTERED ABNORMALITY MOMENTARILY BUT WAS LATER WAS FOUND RECOVERED TO NORMAL OPERATION.	
TO AVOID THE RE-OCCURRENCE OF THIS TROUBLE, AS A PRECAUTIONARY MEASURE, RECOMMED FOR BELOW PARTS TO BE RENEWED THIS TIME	
GOVERNOR ACTUATOR EAL-300B-L51 P/N 72793526-53 P C B UCA-601-01 P/N 73748383-01	

年月日 (DATE)	出港 (Depart.)	作業時間 (WORKING TIME)	帰任 (Return)	記号 (Remark)	サービスの御用命、お問合せは下記へ
SEP-9-2016	08:00	TRAVEL	18:30	X1 STAY	ナブテスコ株式会社 電話番号 (078)967-1404 To the users of Nabtesco production, we are always ready to answer swiftly about your requests and inquiry for after-sale services on Nabtesco production all times in Japan. Please contact Nabtesco Service Section Phone NO. 81-78-887-1404
SEP-10		08:30-20:30		X1 STAY	
SEP-11		WAITING		X1 STAY	
SEP-12		08:30-18:30		X1 STAY	
SEP-13		WAITING		X1 STAY	
SEP-14		09:30-18:00		X1 STAY	

上記の通り相違ないことを証明する
(I certify that contents mentioned above is correct.)

Nabtesco ナブテスコ株式会社

社名:
(Company Name)署名:
(SIGNED)

M.T. AFRAMAX RIVER
[REDACTED]
CHIEF ENGINEER

工事施工者:
(ENGINEER)

Qualified ID No.

Nabtesco

出張工事報告書 Z
SERVICE REPORT

検印 (Checked)

工事内容及び結果 (WORKS AND RESULTS)

後送品 (有無) / 残工事 (有無)

日時

AFRAMAX RIVER (IMABARI 8009)

Goods To Be Sent Later (Exist/Not Exist)
Remained Work (Exist/Not Exist)

RECEIVED RECOMMENDED ITEMS SUPPLIED BY
MAKER (NABTESCO) AND PROCEED TO RENEW THESE
PARTS.

CARRIED OUT RE-CALIBRATION OF GOVERNOR ACTUATOR
POSITION F.B AND SYSTEM FINE TUNING

CARRIED OUT GOVERNOR SIMULATION TEST. CONFIRMED
NORMAL FUNCTION.

CARRIED OUT ACTUAL TEST
MULTIPLE ENGINE START (AHEAD / ASTERN). CONFIRMED
GOOD OPERATION (SUBJECT TO ACTUAL CONDITION)

CONFIRMED GOVERNOR SYSTEM IS IN NORMAL CONDITION.

TRAVEL BACK RETURN TO JAPAN

	年月日 (DATE)	出発 (Depart)	作業時間 (WORKING TIME)	帰任 (Return)	記事 (Remark)	
作業時間 HOURS WORKED	SEP-15 2016		09:30 ~ 21:00		X1 STAY	サービスの御用命、お問合せ は下記へ ナブテスコ株式会社 電話番号 (078) 967-1404 To the users of Nabtesco production, we are always ready to answer swiftly about your requests and inquiry for after-sale services on Nabtesco production all time in Japan. Please contact Nabtesco Service Section Phone NO +81-78-967-1404
	SEP-16		08:30 ~		X1 STAY	
			~			
			~			
			~			

上記の通り相違ないことを証明する
(I certify that contents mentioned above is correct.)

Nabtesco ナブテスコ株式会社

社名:
(Company Name)
署名:
(SIGNED)

M.T. AFRAMAX RIVER

CHEF ENGINEER

工事施工者:
(ENGINEER)