



VEHICLE FACTORS ATTACHMENT

Freightliner Maintenance Records

Louisville, NY

HWY23FH005

(22 pages)



Repair Order 0241-234620

Unit #: 381074
My Unit #:
Mileage: 122,191

Unit Type: 26FT SAD MEDIUM VAN
Make: 2021 FREIGHTLINER M2
VIN: 3ALACWFC1MDMS3297
In-Service: 10/01/2020

RO Date: 02/02/2022
Repair Loc: 0241-10 HARTFORD SOUTH
Owning Loc: 0335-10 PROVIDENCE

Customer: 62397200 AERO GLOBAL LOGISTICS LLC

042 COOLING SYSTEM		DVIR Number	Description	Part#	Qty/Hrs
Complaint:	UNIT HAS A COOLANT LEAK CONCERN		Labor		0.8
Cause:	HOLE IN UPPER RADIATOR HOSE		HOSE-CLNT,UPR,M2-106,ISB,...	05-33586-000	1.0
Correction:	REPLACE UPPER RADIATOR HOSE				
Notes:	DRAIN AND RECLAIM COOLANT; REPLACE RADIATOR HOSE; REPLACE CLAMPS AS NEEDED; REFILL SYSTEM AND CHECK FOR LEAKS				
Tech or Vendor:	[JK]				

019 PREVENTIVE MAINTENANCE		DVIR Number	Description	Part#	Qty/Hrs
Complaint:	SCHEDULED PM		Labor		2.5
Cause:	PREVENTIVE MAINTENANCE				
Correction:	COMPLETE FED - TRUCK / TRACTOR, FEDERAL ANNUAL INSPECTION - FHWA				
Notes:	THIS PM INSPECTION STEPS COVERS D.O.T 396.17				
Tech or Vendor:	[DC]				

027 TRANSMISSION - AUTOMATIC		DVIR Number	Description	Part#	Qty/Hrs
Complaint:	PREVENTIVE MAINTENANCE / REPLACE FILTER		Labor		0.4
Cause:	SCHEDULED MAINTENANCE		FILTER,ELEMENT,FILTER	HF35296	1.0
Correction:	COMPLETE AEF - AUTO TRANS EXTERNAL FILTER (ALLISON 1000/2000 SERIES), REPLACE				
Notes:	REPLACE AUTO TRANS EXTERNAL FILTER (ALLISON 1000/2000 SERIES) - TOP OFF FLUID AS REQUIRED.				
Tech or Vendor:	[DC]				

043 EXHAUST SYSTEM		DVIR Number	Description	Part#	Qty/Hrs
Complaint:	COMPLETE CDP - CUMMINS DELTA P PORT / ORIFICE (ISB ENGINE ONLY), CLEAN		Labor		0.5
Cause:	SCHEDULED MAINTENANCE				
Correction:	COMPLETE CDP - CUMMINS DELTA P PORT / ORIFICE (ISB ENGINE ONLY), CLEAN				
Notes:	CLEAN DELTA P PORT AND ORIFICE				
Tech or Vendor:	[DC]				

019 PREVENTIVE MAINTENANCE		DVIR Number	Description	Part#	Qty/Hrs
Complaint:	SCHEDULED PM		Labor		0.5
Cause:	PREVENTIVE MAINTENANCE				
Correction:	COMPLETE LG1 - LIFT GATE, MAINTENANCE INSPECTION				
Notes:	PERFORM MULTIPOINT INSPECTION (INCLUDES ELECTRICAL, HYDRAULIC, STRUCTURAL); GREASE COMPONENT AS NEEDED; DOCUMENT ADDITIONAL REPAIRS NEEDED				
Tech or Vendor:	[DC]				



Repair Order 0241-234620

Unit #: 381074
My Unit #:
Mileage: 122,191

Unit Type: 26FT SAD MEDIUM VAN
Make: 2021 FREIGHTLINER M2
VIN: 3ALACWFC1MDMS3297
In-Service: 10/01/2020

RO Date: 02/02/2022
Repair Loc: 0241-10 HARTFORD SOUTH
Owning Loc: 0335-10 PROVIDENCE

Customer: 62397200 AERO GLOBAL LOGISTICS LLC

045 POWER PLANT		DVIR Number	Description	Part#	Qty/Hrs
Complaint:	SCHEDULED PM WET STEPS		FILTER, FUEL SPIN-ON	FF63054NN	1.0
Cause:	PREVENTIVE MAINTENANCE		PENSKE-A OIL ANALYSIS KIT	AOKT0068349012	1.0
Correction:	TRUCK / TRACTOR, FLUID CHANGE		FILTER,OIL,FULL FLOW	FG LF3970	1.0

027 TRANSMISSION - AUTOMATIC		DVIR Number	Description	Part#	Qty/Hrs
Complaint:	TRANSMISSION - AUTOM AUTOMATIC TRANSMISSION - WILL NOT GO INTO GEAR	null	Labor		2.4
Cause:	REPLACE CABLE WITH ONE FROM A TOTALED UNIT				
Correction:	ADJUST SHIFT CABLE OR ROD				
Tech or Vendor:	[JK]				

041 AIR INTAKE SYSTEM		DVIR Number	Description	Part#	Qty/Hrs
Complaint:	DUE PM		Labor		0.5
Cause:	DUE		FILTER,ELEMENT,AIR FILTER	AF26154	1.0
Correction:	COMPLETE AF - AIR FILTER, MAIN ENGINE (INCLUDES BOTH ON M2S), REPLACE				
Notes:	CHECK AIR FILTER FOR RESTRICTION AND REPLACE AIR FILTER				
Tech or Vendor:	[DC]				

069 VEHICLE CLEAN UP/ DETAILING		DVIR Number	Description	Part#	Qty/Hrs
Complaint:	PM WASH		Labor		0.7
Cause:	NEEDED				
Correction:	STEAM CLEAN TO ASSIST WITH DIAGNOSITICS AND/OR FOR VEHICLE APPEARANCE				
Notes:	PRESSURE WASH TO ASSIST WITH DIAGNOSIS SUCH AS FLUID LEAKS OR FOR PURPOSES OF VEHICLE APPEARANCE.				
Tech or Vendor:	[DC]				

003 INSTRUMENTS, GAUGES, WARNING & SHUTDOWN DEVICES, & METERS		DVIR Number	Description	Part#	Qty/Hrs
Complaint:	METER OR MILEAGE READING REQUIRED		Labor		0.2
Cause:	MISSING METER OR MILEAGE READING				
Correction:	LOCATE UNIT, MOVE TO WORK LOCATION, RECORD ALL CURRENT METER READING(S) ONTO RO, TO UPDATE THE UNIT				
Notes:	RETRIEVE THE UNIT, OBTAIN CORRECT MILEAGE/KILOMETER AND/OR APU/REEFER HOUR READING(S) AND RECORD ONTO THE RO PRIOR TO STARTING THE JOB TO ENSURE PROPER PM(S) BEING PERFORMED				
Tech or Vendor:	[DC]				



Repair Order 0241-234620

Unit #: 381074
My Unit #:
Mileage: 122,191

Unit Type: 26FT SAD MEDIUM VAN
Make: 2021 FREIGHTLINER M2
VIN: 3ALACWFC1MDMS3297
In-Service: 10/01/2020

RO Date: 02/02/2022
Repair Loc: 0241-10 HARTFORD
SOUTH

Customer: 62397200 AERO GLOBAL LOGISTICS LLC

Owning Loc: 0335-10 PROVIDENCE

027 TRANSMISSION - AUTOMATIC		DVIR Number	Description	Part#	Qty/Hrs
Complaint:	TRANSMISSION OIL DIP STICK		Labor		0.3
Cause:	BROKEN		DIPSTICK,TUBE	A07-22451-000	1.0
Correction:	REPLACE TRANSMISSION OIL LEVEL DIP STICK				
Tech or Vendor:	[JK]				
002 CAB & SHEET METAL		DVIR Number	Description	Part#	Qty/Hrs
Complaint:	WIPER BLADE IS NOT FUNCTIONING PROPERLY		Labor		0.4
Cause:	BLADE SURFACE NOT WORKING CORRECTLY.		IMPERIAL 22""PREMIUM BLAD	360022-7	2.0
Correction:	REPLACE WINDSHIELD WIPER BLADE				
Tech or Vendor:	[DC]				
053 EXPENDABLES		DVIR Number	Description	Part#	Qty/Hrs
Complaint:	DRIVER SIDE MUD FLAP		Labor		0.7
Cause:	MISSING		FLAP,MUD	GT2436C	1.0
Correction:	REPLACE MUD FLAP				
Tech or Vendor:	[DC]				
002 CAB & SHEET METAL		DVIR Number	Description	Part#	Qty/Hrs
Complaint:	ISSUE OR CONCERN WITH THE GRILLE ASSEMBLY		Labor		1.3
Cause:	NEEDED		GRILLE-HOOD MTD,MIC,106	A17-21024-007	1.0
Correction:	REPLACE GRILLE				
Notes:	REMOVE ALL HARDWARE AS NEEDED; REMOVE GRILLE ASSEMBLY AND REPLACE WITH NEW; CHECK FOR PROPER ALIGNMENT AND FIT				
Tech or Vendor:	[JK]				
013 BRAKES		DVIR Number	Description	Part#	Qty/Hrs
Complaint:	RIGHT SIDE REAR BRAKE CHAMBER		Labor		2.0
Cause:	LEAKING AIR		3030LS PBK KIT	NT3030ELSKIT	1.0
Correction:	REPLACE BRAKE CHAMBER DIAPHRAGM				
Tech or Vendor:	[JK]				
072 REAR DOOR		DVIR Number	Description	Part#	Qty/Hrs
Complaint:	REAR DOOR HINGE		Labor		0.9
Cause:	BROKEN		BRACKET,CLOSURE	6943	1.0
Correction:	REPLACE REAR DOOR HINGE		ROLLER	N/A	1.0
Notes:	REMOVE AND REPLACE REAR DOOR HINGE; LUBRICATE AS NEEDED FOR PROPER OPERATION				
Tech or Vendor:	[DC]				



Repair Order 0241-234620

Unit #: 381074
My Unit #:
Mileage: 122,191

Unit Type: 26FT SAD MEDIUM VAN
Make: 2021 FREIGHTLINER M2
VIN: 3ALACWFC1MDMS3297
In-Service: 10/01/2020

RO Date: 02/02/2022
Repair Loc: 0241-10 HARTFORD
SOUTH
Owning Loc: 0335-10 PROVIDENCE

Customer: 62397200 AERO GLOBAL LOGISTICS LLC

068 HIKING		DVIR Number	Description	Part#	Qty/Hrs
Complaint:	HIKE		Labor		0.3
Cause:	MOVE ON YARD TRANSMISSION PROBLEM				
Correction:	VEHICLE HIKE/HIKING				
Tech or Vendor:	[DC]				



Repair Order 0335-247735

Unit #: 381074
My Unit #:
Mileage: 154,807

Unit Type: 26FT SAD MEDIUM VAN
Make: 2021 FREIGHTLINER M2
VIN: 3ALACWFC1MDMS3297
In-Service: 10/01/2020

RO Date: 09/08/2022
Repair Loc: 0335-10 PROVIDENCE
Owning Loc: 0335-10 PROVIDENCE

Customer: RENTAL RENTAL

017 REAR TIRES		DVIR Number	Description	Part#	Qty/Hrs
Complaint:	INSPECT / ADJUST TIRE AIR PRESSURE ALL POSITIONS		Labor		0.2
Cause:	INSPECT / ADJUST TIRE AIR PRESSURE ALL POSITIONS				
Correction:	INSPECT / ADJUST TIRE AIR PRESSURE ALL POSITIONS				
Notes:	INSPECT TIRES FOR SAFETY; CHECK INFLATION PRESSURES AND ADJUST AS NEEDED				
Tech or Vendor:	[JONATHAN]				



Vehicle Work Summary for AERO GLOBAL LOGISTICS LLC

Unit #: 381074
My Unit #:
Mileage: 156,070

Unit Type: 26FT SAD MEDIUM VAN
Make: 2021 FREIGHTLINER M2
VIN: 3ALACWFC1MDMS3297

RO: 0335-248764
Date In: 10/13/2022
Date Out: 10/24/2022

Repairs Made:

061 ACCIDENT/INCIDENT		DVIR Number	Description	Part#	Quantity
Complaint:	ALIGN STEERING WHEEL				
Cause:	ACCIDENT DAMAGE				
Correction:	ALIGN STEERING WHEEL				
Notes:	ADJUST STEERING WHEEL POSITION TO CENTER WITH FRONT WHEELS				
Tech or Vendor:	[JONATHAN]				
036 SUPPLEMENTAL INFORMATION DEVICES		DVIR Number	Description	Part#	Quantity
Complaint:	ABS/TRACTION LIGHT ON		NUT,HX FLNG MTRC,M6X1.0,C...	910112 006001	1.0
Cause:	FRONT RADAR GONE		RADAR-SEN- COVER	WAB4008782000	1.0
Correction:	REPAIR - WIRING HARNESS - MAIN, RADAR COLLISION MITIGATION SYSTEM		ASSY-BRKT,RDR FWD,M2 106,...	A66-07840-000	1.0
Notes:	CHECK FOR CODES FOR FRONT RADAR SYSTEM AND RADAR MISSING AND WIRING BROKEN OFF REPLACED WITH NEW RADAR AND WIRING HARNESS AND REPIN WIRES AND PROGRAM RADAR AND ESC MODULE		RADAR-OGP1 ECR2-ACT M2 50...	WAB 400 871 574 0	1.0
Tech or Vendor:	[DAVID],[JONATHAN]		TERMINAL	963729-1	8.0

Serviced with Pride by the Penske Team
We Value Your Business - Questions? Please Call (401) 463-5478

CHECK-IN FOR SERVICE VISITS FASTER FROM THE COMFORT OF YOUR VEHICLE USING THE PENSKE DRIVER™ APP

Download today from the Apple App Store and Google Play.
Get started. Your activation code is PBWF69

Use your phone's camera to scan





Outside Repair Order 0551-6878319-1

Unit #: 381074
My Unit #:
Mileage: 121,693

Unit Type: 26FT SAD MEDIUM VAN
Make: 2021 FREIGHTLINER M2
VIN: 3ALACWFC1MDMS3297
In-Service: 10/01/2020

RO Date: 01/27/2022
Repair Loc: 0551- 24/7 ROADSIDE ASSISTANCE
Owning Loc: 0335-10 PROVIDENCE

Customer: 62397200 AERO GLOBAL LOGISTICS L

Vendor: NORTHEAST TOWING & TRANSP	Estimated Cost: \$ [REDACTED]00	Invoice #: 2223755	PCard: NO
Address:	Invoice Cost: \$ [REDACTED].00	Invoice Date: 01/27/2022	

027 TRANSMISSION - AUTOMATIC	DVIR Number	Description	Part#	Qty/Hrs
------------------------------	-------------	-------------	-------	---------

Complaint: Automatic transmission - will not go into gear
Cause: TRANS CABLE FAILURE
Correction: TOW TO DESTINATION - TRANSMISSION - AUTOMATIC
Tech or Vendor: [OTR Dept.]



Repair Order 0705-305500

Unit #: 381074
My Unit #:
Mileage: 121,311

Unit Type: 26FT SAD MEDIUM VAN
Make: 2021 FREIGHTLINER M2
VIN: 3ALACWFC1MDMS3297
In-Service: 10/01/2020

RO Date: 01/24/2022
Repair Loc: 0705-10 FRANKLIN
Owning Loc: 0335-10 PROVIDENCE

Customer: 62397200 AERO GLOBAL LOGISTICS LLC

042 COOLING SYSTEM

Complaint: CHECK COOLANT LOW, ENG LIGHT COMES ON
Cause: UPPER RADIATOR HOSE CLAMP DEFECTIVE
Correction: REPLACE CLAMP - HOSE, COOLING SYSTEM/RADIATOR
Notes: REPLACE COOLANT HOSE CLAMP; ADD FLUID AS NEEDED; CHECK FOR LEAKS
Tech or Vendor: [JORDAN]

DVIR Number

Description

Part#

Qty/Hrs

Labor		0.9
RADIATOR HOSE CLAMP	5005	1.0
ELC - NITRATE-FREE PRE-DI...	ELC5050	2.0



Repair Order 0705-308888

Unit #: 381074
My Unit #:
Mileage: 129,076

Unit Type: 26FT SAD MEDIUM VAN
Make: 2021 FREIGHTLINER M2
VIN: 3ALACWFC1MDMS3297
In-Service: 10/01/2020

RO Date: 05/23/2022
Repair Loc: 0705-10 FRANKLIN
Owning Loc: 0335-10 PROVIDENCE

Customer: 62397200 AERO GLOBAL LOGISTICS LLC

032 CRANKING SYSTEM

		DVIR Number	Description	Part#	Qty/Hrs
Complaint:	CRANKING SYSTEM TRUCK WON'T START - ENGINE WILL NOT TURN OVER	null	Labor		1.0
Cause:	BOX LIGHTS LEFT ON				
Correction:	JUMP START MAIN ENGINE				
Tech or Vendor:	[ANDREW]				



Repair Order 5157-122154

Unit #: 381074
My Unit #:
Mileage: 152,723

Unit Type: 26FT SAD MEDIUM VAN
Make: 2021 FREIGHTLINER M2
VIN: 3ALACWFC1MDMS3297
In-Service: 10/01/2020

RO Date: 08/25/2022
Repair Loc: 5157-10 BANGOR
Owning Loc: 0335-10 PROVIDENCE

Customer: 62397200 AERO GLOBAL LOGISTICS LLC

053 EXPENDABLES		DVIR Number	Description	Part#	Qty/Hrs
Complaint:	NEED MUD FLAP		Labor		0.6
Cause:	MISSING		SPLASH GUARD-RUBBER,24IN ...	KRC 062430	1.0
Correction:	REPLACE MUD FLAP				
Notes:	DRILL MOUNTING HOLES AS NEEDED, REPLACE MUD FLAP(S)				
Tech or Vendor:	[RYAN]				

003 INSTRUMENTS, GAUGES, WARNING & SHUTDOWN DEVICES, & METERS		DVIR Number	Description	Part#	Qty/Hrs
Complaint:	ABS LIGHT		Labor		0.9
Cause:	COULD NOT CONNECT WITH ABS MODULE-NEED TO RESCHEDULE				
Correction:	INSPECT GAUGES & WARNING DEVICES ELECTRICAL POWERED EQUIP.				
Tech or Vendor:	[TIM]				



Repair Order 6028-158512

Unit #: 381074
My Unit #:
Mileage: 167,020

Unit Type: 26FT SAD MEDIUM VAN
Make: 2021 FREIGHTLINER M2
VIN: 3ALACWFC1MDMS3297
In-Service: 10/01/2020

RO Date: 12/05/2022
Repair Loc: 6028-10 UTICA
Owning Loc: 0335-10 PROVIDENCE

Customer: RENTAL RENTAL

019 PREVENTIVE MAINTENANCE		DVIR Number	Description	Part#	Qty/Hrs
Complaint:	SCHEDULED PM		Labor		2.3
Cause:	PREVENTIVE MAINTENANCE				
Correction:	COMPLETE FED - TRUCK / TRACTOR, FEDERAL ANNUAL INSPECTION - FHWA				
Notes:	THIS PM INSPECTION STEPS COVERS D.O.T 396.17				
Tech or Vendor:	[JOSH]				

019 PREVENTIVE MAINTENANCE		DVIR Number	Description	Part#	Qty/Hrs
Complaint:	SCHEDULED PM		Labor		0.4
Cause:	PREVENTIVE MAINTENANCE				
Correction:	COMPLETE LG1 - LIFT GATE, MAINTENANCE INSPECTION				
Notes:	PERFORM MULTIPOINT INSPECTION (INCLUDES ELECTRICAL, HYDRAULIC, STRUCTURAL); GREASE COMPONENT AS NEEDED; DOCUMENT ADDITIONAL REPAIRS NEEDED				
Tech or Vendor:	[RYAN],JOSH				

045 POWER PLANT		DVIR Number	Description	Part#	Qty/Hrs
Complaint:	SCHEDULED PM WET STEPS		FILTER, FUEL SPIN- ON	FF63054NN	1.0
Cause:	PREVENTIVE MAINTENANCE		PENSKE-A OIL ANALYSIS KIT	AOKT0072783044	1.0
Correction:	TRUCK / TRACTOR, FLUID CHANGE		LUBE FILTER	LF3970	1.0
Tech or Vendor:					

067 WASH		DVIR Number	Description	Part#	Qty/Hrs
Complaint:	WASH FOR PM		Labor		0.6
Cause:	PM				
Correction:	WASH - TRUCK / VAN / CAR				
Notes:	WASH VEHICLE				
Tech or Vendor:	[JOSH]				

056 RADIO		DVIR Number	Description	Part#	Qty/Hrs
Complaint:	ANTENNA ON DRIVERS MIRROR IS LOOSE		Labor		0.3
Cause:	WEAR FROM MOVING AROUND				
Correction:	REPAIR ANTENNA LEAD WIRE ASSEMBLY-LEFT				
Tech or Vendor:	[RYAN]				



Repair Order 6028-158512

Unit #: 381074
My Unit #:
Mileage: 167,020

Unit Type: 26FT SAD MEDIUM VAN
Make: 2021 FREIGHTLINER M2
VIN: 3ALACWFC1MDMS3297
In-Service: 10/01/2020

RO Date: 12/05/2022
Repair Loc: 6028-10 UTICA
Owning Loc: 0335-10 PROVIDENCE

Customer: RENTAL RENTAL

042 COOLING SYSTEM

Complaint: COOLANT HOSE ON TOP OF RESERVOIR THAT GOES TO TOP OF RADIATOR IS LEAKING
Cause: HOLE IN THE COOLANT HOSE
Correction: REPLACE CLAMP - HOSE, COOLING SYSTEM/RADIATOR
Notes: REPLACE COOLANT HOSE CLAMP; ADD FLUID AS NEEDED; CHECK FOR LEAKS
Tech or Vendor: [RYAN],[JOSH]

DVIR Number	Description	Part#	Qty/Hrs
	Labor		1.7
	ROTELLA ELC NITRITE FREE ...	550041811	1.0

072 REAR DOOR

Complaint: ROLLER OR REAR DOOR IS BUSTED
Cause: BROKEN HINGE
Correction: ADJUST OR REPAIR REAR DOOR LINKAGE
Notes: ADJUST OR REPAIR REAR DOOR LINKAGE
Tech or Vendor: [RYAN]

DVIR Number	Description	Part#	Qty/Hrs
	Labor		0.2



Outside Repair Order 6028-158706

Unit #: 381074
My Unit #:
Mileage: 167,502

Unit Type: 26FT SAD MEDIUM VAN
Make: 2021 FREIGHTLINER M2
VIN: 3ALACWFC1MDMS3297
In-Service: 10/01/2020

RO Date: 12/14/2022
Repair Loc: 6028-10 UTICA
Owning Loc: 0335-10 PROVIDENCE

Customer: 62397200 AERO GLOBAL LOGISTICS LLC

Vendor: CLINTON COLLISION	Estimated Cost: \$ [REDACTED].00	Invoice #: 27700	PCard: YES
Address: MCBRIDE AVE. CLINTON NY 13323	Invoice Cost: [REDACTED]0	Invoice Date: 12/14/2022	

061 ACCIDENT/INCIDENT	DVIR Number	Description	Part#	Qty/Hrs
-----------------------	-------------	-------------	-------	---------

Complaint: INCIDENT
Cause: DEER DAMAGED
Correction: REPLACE / REPAIR ACCIDENT / INCIDENT DAMAGE
Notes: REPLACE / REPAIR ACCIDENT/INCIDENT DAMAGE
Tech or Vendor:



Repair Order 6073-164698

Unit #: 381074
My Unit #:
Mileage: 146,740

Unit Type: 26FT SAD MEDIUM VAN
Make: 2021 FREIGHTLINER M2
VIN: 3ALACWFC1MDMS3297
In-Service: 10/01/2020

RO Date: 07/27/2022
Repair Loc: 6073-10 NORTON
Owning Loc: 0335-10 PROVIDENCE

Customer: 62397200 AERO GLOBAL LOGISTICS LLC

019 PREVENTIVE MAINTENANCE		DVIR Number	Description	Part#	Qty/Hrs
Complaint:	SCHEDULED PM	8371213	Labor		3.2
Cause:	PREVENTIVE MAINTENANCE				
Correction:	COMPLETE FED - TRUCK / TRACTOR, FEDERAL ANNUAL INSPECTION - FHWA				
Notes:	THIS PM INSPECTION STEPS COVERS D.O.T 396.17				
Tech or Vendor:	[MOOSE]				

042 COOLING SYSTEM		DVIR Number	Description	Part#	Qty/Hrs
Complaint:	COMPLETE CS - COOLANT SAMPLE & CHANGE POWER STEERING FILTER IF APPLICABLE		Labor		0.3
Cause:	SCHEDULED MAINTENANCE		HYDRAULIC, REPLACES FREIG...	HF35387	1.0
Correction:	COMPLETE CS - COOLANT SAMPLE & CHANGE POWER STEERING FILTER IF APPLICABLE		PENSKE-C1 COOLANT KIT	ACKT0015982026	1.0
Notes:	COOLING SYSTEM AND POWER STEERING INSPECTION; TAKE COOLANT SAMPLE; CHANGE POWER STEERING FILTER				
Tech or Vendor:	[DAVE],MOOSE				

045 POWER PLANT		DVIR Number	Description	Part#	Qty/Hrs
Complaint:	COMPLETE CVF - CRANKCASE VENTILATION FILTER /COALESCING FILTER / BREATHER, INSPECTION / REPLACE		Labor		1.0
Cause:	SCHEDULED MAINTENANCE		CCV	CV54003	1.0
Correction:	COMPLETE CVF - CRANKCASE VENTILATION FILTER /COALESCING FILTER / BREATHER, INSPECTION / REPLACE				
Notes:	REMOVE CRANKCASE / COALESCING FILTER HOUSING / COVER; CLEAN OR CHANGE FILTER WITH NEW, AS NEEDED; REINSTALL HOUSING / COVER. REMOVE DPF DOSER NOZZLE (CUMMINS ONLY); CLEAN NOZZLE TIP AND REINSTALL.				
Tech or Vendor:	[DAVE],MOOSE				

019 PREVENTIVE MAINTENANCE		DVIR Number	Description	Part#	Qty/Hrs
Complaint:	SCHEDULED PM		Labor		0.2
Cause:	PREVENTIVE MAINTENANCE				
Correction:	COMPLETE LG1 - LIFT GATE, MAINTENANCE INSPECTION				
Notes:	PERFORM MULTIPOINT INSPECTION (INCLUDES ELECTRICAL, HYDRAULIC, STRUCTURAL); GREASE COMPONENT AS NEEDED; DOCUMENT ADDITIONAL REPAIRS NEEDED				
Tech or Vendor:	[MOOSE]				



Repair Order 6073-164698

Unit #: 381074
My Unit #:
Mileage: 146,740

Unit Type: 26FT SAD MEDIUM VAN
Make: 2021 FREIGHTLINER M2
VIN: 3ALACWFC1MDMS3297
In-Service: 10/01/2020

RO Date: 07/27/2022
Repair Loc: 6073-10 NORTON
Owning Loc: 0335-10 PROVIDENCE

Customer: 62397200 AERO GLOBAL LOGISTICS LLC

014 FRAME COMPONENTS		DVIR Number	Description	Part#	Qty/Hrs
Complaint:	SCHEDULED PM / First time Penske service applying treatment		Labor		1.4
Cause:	SCHEDULED MAINTENANCE				
Correction:	COMPLETE UCF - UNDER CARRIAGE CORROSION TREATMENT PRODUCT, APPLY				
Notes:	PREP WASH UNIT FOR TREATMENT; ALLOW UNIT TO SET FOR 20 MIN; APPLY CORROSION TREATMENT ELEMENT (KROWN KL73) TO UNIT.				
Tech or Vendor:	[KAEDYN]				

045 POWER PLANT		DVIR Number	Description	Part#	Qty/Hrs
Complaint:	SCHEDULED PM WET STEPS		FILTER, FUEL SPIN- ON	FF63054NN	1.0
Cause:	PREVENTIVE MAINTENANCE		FILTER-LUBE OIL	LF3970	1.0
Correction:	TRUCK / TRACTOR, FLUID CHANGE		PENSKE-A OIL ANALYSIS KIT	AOKT0072644014	1.0
Tech or Vendor:					

045 POWER PLANT		DVIR Number	Description	Part#	Qty/Hrs
Complaint:	NEEDS ECM UPDATE		Labor		0.9
Cause:	NEEDED CALIBRATION UPDATE				
Correction:	UPDATE ECM SOFTWARE - CUMMINS				
Tech or Vendor:	[DAVE]				

042 COOLING SYSTEM		DVIR Number	Description	Part#	Qty/Hrs
Complaint:	COOLANT LEVEL LOW		Labor		3.7
Cause:	LEAKING COOLANT		HOSE CLAMPCONST TORQUE	72370	2.0
Correction:	REPLACE TUBE / PIPE / HOSE WATER PUMP		FORMED-HOSE, M2106, AWD, ...	05-33332-000	1.0
Notes:	DRAIN AND RECLAIM COOLANT; REPLACE WATER PUMP HOSE; REPLACE CLAMPS AS NEEDED; REFILL SYSTEM AND CHECK FOR LEAKS				
Tech or Vendor:	[DAVE],[DIEGO],[MOOSE]				

061 ACCIDENT/INCIDENT		DVIR Number	Description	Part#	Qty/Hrs
Complaint:	REPLACE R/S HUB CAP STEER		Labor		0.9
Cause:	INCIDENT DAMAGED HIT CURB BROKE CAP		HUBCAP, WHEEL, 3.500 ID 6...	CR1612	1.0
Correction:	REPLACE / REPAIR ACCIDENT / INCIDENT DAMAGE		SPIRAX S6 AXRME75W90_1*55...	550026918	1.0
Notes:	REPLACE / REPAIR ACCIDENT/INCIDENT DAMAGE				
Tech or Vendor:	[JAMES1]				



Repair Order 6073-164698

Unit #: 381074
My Unit #:
Mileage: 146,740

Unit Type: 26FT SAD MEDIUM VAN
Make: 2021 FREIGHTLINER M2
VIN: 3ALACWFC1MDMS3297
In-Service: 10/01/2020

RO Date: 07/27/2022
Repair Loc: 6073-10 NORTON
Owning Loc: 0335-10 PROVIDENCE

Customer: 62397200 AERO GLOBAL LOGISTICS LLC

034 LIGHTING SYSTEM		DVIR Number	Description	Part#	Qty/Hrs
Complaint:	LOW BEAM NOT WORKING PROPERLY		Labor		0.3
Cause:	BLOWN BULB		9006XSLLO BEAM CAP	81598-7	1.0
Correction:	REPLACE HEADLIGHT-LEFT				
Notes:	REPLACE DEFECTIVE HEADLIGHT; VERIFY OPERATION				
Tech or Vendor:	[MOOSE]				

053 EXPENDABLES		DVIR Number	Description	Part#	Qty/Hrs
Complaint:	DRIVER SIDE MUD FLAP CONCERN		Labor		0.8
Cause:	TORN OFF		FLAP MUD 1/4X24X30 PLN BL...	KR062430F100	1.0
Correction:	REPLACE MUD FLAP				
Tech or Vendor:	[MOOSE]				

061 ACCIDENT/INCIDENT		DVIR Number	Description	Part#	Qty/Hrs
Complaint:	ABS LIGHT ON		Labor		0.9
Cause:	FRONT BUMPER SENSOR IS MISSING DUE TO DAMAGE AND WIRES WERE CUT. SEE ATTACHED				
Correction:	CALIBRATE - MERITOR/WABCO ELECTRONIC CONTROL UNIT (ECU) - ANTILOCK BRAKES				
Tech or Vendor:	[DAVE]				

036 SUPPLEMENTAL INFORMATION DEVICES		DVIR Number	Description	Part#	Qty/Hrs
Complaint:	ELD INTERNAL DASH DECAL NEEDS REPLACED		Labor		0.3
Cause:	MISSING				
Correction:	REPLACE/INSTALL- DECAL - ELD				
Tech or Vendor:	[MOOSE]				

072 REAR DOOR		DVIR Number	Description	Part#	Qty/Hrs
Complaint:	REAR DOOR ROLLER INOPERATIVE		Labor		0.5
Cause:	LOOSE/BROKEN				
Correction:	REPLACE REAR DOOR ROLLER				
Notes:	REPLACE REAR DOOR ROLLER(S) WITH NEW; LUBRICATE AS NEEDED; CHECK DOOR FOR PROPER OPERATION				
Tech or Vendor:	[MOOSE]				

013 BRAKES		DVIR Number	Description	Part#	Qty/Hrs
Complaint:	ISSUE OR CONCERN WITH A BRAKE CHAMBER ASSEMBLY		Labor		1.4
Cause:	LOOSENED CAGING BOLT RATTLING				
Correction:	REPAIR BRAKE CHAMBER - SPRING AND SERVICE INCL. ROD, CLAMP, DIAPHRAGM				
Tech or Vendor:	[DAVE],[MOOSE]				



Repair Order 6073-164698

Unit #: 381074
My Unit #:
Mileage: 146,740

Unit Type: 26FT SAD MEDIUM VAN
Make: 2021 FREIGHTLINER M2
VIN: 3ALACWFC1MDMS3297
In-Service: 10/01/2020

RO Date: 07/27/2022
Repair Loc: 6073-10 NORTON
Owning Loc: 0335-10 PROVIDENCE

Customer: 62397200 AERO GLOBAL LOGISTICS LLC

072 REAR DOOR		DVIR Number	Description	Part#	Qty/Hrs
Complaint:	REAR DOOR PULL-DOWN		Labor		0.7
Cause:	FRAYED/TORN		DOOR PULLSTRAP	913824-3	1.0
Correction:	REPLACE REAR DOOR STRAP				
Tech or Vendor:	[MOOSE]				
061 ACCIDENT/INCIDENT		DVIR Number	Description	Part#	Qty/Hrs
Complaint:	NEEDS ALL RIGHT SIDE STEER AXLE WHEEL STUDS		Labor		2.3
Cause:	DAMAGED		STUD,WHEEL	CM 107477	10.0
Correction:	REPLACE FRONT AXLE WHEEL STUDS		NUT-FLANGE,M22-1.5,1.06,3...	OKA WNM2227TIXY	6.0
Notes:	RAISE FRONT AXLE; REMOVE WHEEL; REMOVE AND REPLACE WHEEL STUD(S) WITH NEW; REINSTALL WHEEL; TORQUE LUG NUTS TO SPEC		NUT	OKA WNM2227TIXY	3.0
Tech or Vendor:	[DAVE]		NUT	OKA WNM2227TIXY	1.0
042 COOLING SYSTEM		DVIR Number	Description	Part#	Qty/Hrs
Complaint:	RADIATOR DRAIN SNAPPED		Labor		2.1
Cause:	PREVIOUSLY OVERTIGHTNED		DRAIN,QUICK CONNECT	PH FEM25224MMB02	1.0
Correction:	REPAIR RADIATOR		ROTELLA ELC NITRITE FREE ...	550041811	5.0
Tech or Vendor:	[DAVE],[DIEGO]				



Repair Order 6073-174778

Unit #: 381074
My Unit #:
Mileage: 146,740

Unit Type: 26FT SAD MEDIUM VAN
Make: 2021 FREIGHTLINER M2
VIN: 3ALACWFC1MDMS3297
In-Service: 10/01/2020

RO Date: 07/29/2022
Repair Loc: 6073-10 NORTON
Owning Loc: 0335-10 PROVIDENCE

Customer: RENTAL RENTAL

016 FRONT TIRES		DVIR Number	Description	Part#	Qty/Hrs
Complaint:	NEEDS STEER TIRES		Labor		0.9
Cause:	RIGHT SIDE IS AT 5/32 AND LEFT AT 8/32		11R22.5 R268	248817	1.0
Correction:	REPLACE STEER / FRONT TIRE(S)-BOTH		Steer/8-32nds/A	Tire Credit	1.0
Notes:	INSPECT FRONT END AND STEERING AS NEEDED; REMOVE STEER TIRE(S) AND REPLACE WITH NEW; TORQUE LUGS TO SPEC; PERFORM RADIAL RUN-OUT		248817	Wheel	1.0
			Usable Steel	Wheel Credit	1.0
Tech or Vendor:	[DAVE]		11R22.5 R268	248817	1.0
			Steer/5-32nds/A	Tire Credit	1.0
			248817	Wheel	1.0
			Non-Std/Other/None	Wheel Credit	1.0



Repair Order 6073-174851

Unit #: 381074
My Unit #:
Mileage: 146,740

Unit Type: 26FT SAD MEDIUM VAN
Make: 2021 FREIGHTLINER M2
VIN: 3ALACWFC1MDMS3297
In-Service: 10/01/2020

RO Date: 08/01/2022
Repair Loc: 6073-10 NORTON
Owning Loc: 0335-10 PROVIDENCE

Customer: 62397200 AERO GLOBAL LOGISTICS LLC

017 REAR TIRES		DVIR Number	Description	Part#	Qty/Hrs
Complaint:	NEEDS DRIVE TIRE		Labor		0.7
Cause:	RIGHT OUTER TIRE HAS SIDE WALL DAMAGE		USED TIRE	22.5R/	1.0
Correction:	REPLACE DRIVE TIRE(S)-2ND AXLE RIGHT OUTER		Scrap/Unusable/13-32nds	Tire Credit	1.0
Notes:	REMOVE TIRE(S); REPLACE AS NEEDED; TORQUE LUGS TO SPEC		22.5R/	Wheel	1.0
Tech or Vendor:	[DAVE]		Usable Steel	Wheel Credit	1.0



Repair Order 6073-175579

Unit #: 381074
My Unit #:
Mileage:

Unit Type: 26FT SAD MEDIUM VAN
Make: 2021 FREIGHTLINER M2
VIN: 3ALACWFC1MDMS3297
In-Service: 10/01/2020

RO Date: 07/28/2022
Repair Loc: 6073-10 NORTON
Owning Loc: 0335-10 PROVIDENCE

Customer: 62397200 AERO GLOBAL LOGISTICS LLC

016 FRONT TIRES

Complaint: TIRE CHARGEBACK
Cause: CASING ADJUSTMENT
Correction: TIRE CHARGEBACK RO ORIGINATING FROM :6073-174778
Tech or Vendor:

DVIR Number

Description

Part#

Qty/Hrs

USED TIRE R22.5 (8/32nds)	22.5R/(T)	1.0
---------------------------	-----------	-----



Outside Repair Order 6259-1612

Unit #: 381074
My Unit #:
Mileage: 167,502

Unit Type: 26FT SAD MEDIUM VAN
Make: 2021 FREIGHTLINER M2
VIN: 3ALACWFC1MDMS3297
In-Service: 10/01/2020

RO Date: 01/05/2023
Repair Loc: 6259-10 PTCR
ROCHESTER
Owning Loc: 0335-10 PROVIDENCE

Customer: 62397200 AERO GLOBAL LOGISTICS LLC

PTCR: PTCR ROCHESTER Address: 333 COLFAX ST ROCHESTER NY 14606	Estimated Cost: \$0.00	PTCR PO #: 6259101612
--	-------------------------------	------------------------------

061 ACCIDENT/INCIDENT	DVIR Number	Description	Part#	Qty/Hrs
Complaint: INCIDENT				
Cause:				
Correction: REPLACE / REPAIR ACCIDENT / INCIDENT DAMAGE				
Notes: REPLACE / REPAIR ACCIDENT/INCIDENT DAMAGE				
Tech or Vendor: SUMMIT				