

AIRFRAME LOG

Page No. _____

DA1 05-27-2021
Complete Aviation Management LLC.

>RK

N9126P Serial# 24-4605 S/N 24-4605 Tach 3348.2 ATT 3348.2

Performed Annual inspection IAW FAR Part 43, Appendix D. Performed all routine maintenance. Installed new ELT battery P/N 0141823 S/N 21180027 ELT unit function tested satisfactorily per FAR 91.207. Battery due 03-2028. Installed new air filter P/N BA3. Serviced brake reservoir with MIL5606. Install 10 new spark plugs. P/N UREM38E. Installed new landing gear bungees P/N 8097 IAW AD77-13-21. Replaced missing #5 valve cover screw. Serviced brake reservoir with MIL5606. Removed shimmy damper, installed Dampener service kit ADS-7551-107 IAW STC SA10594SC, serviced and reinstalled shimmy Dampener. See submitted for 337 for details. Installed new aileron static wick. Replaced beacon and RH NAV light bulbs. Applied corrosion throughout entire aircraft. Installed overhauled LH and RH magnetos P/N 6350 S/NJ-04370 and 6393 S/N J-05184.

C/W the following AD's: 75-12-06 Fin spar, 77-13-21 (a) per SL782A next due Tach 4348.2 (b) by installation of new bungees P/N 8097 next due 3848 or 06/01/2024, 79-20-10 Aileron nose ribs, 94-13-10 Stabilator torque tube 76-07-12 Ignition switch. Checked AD's for compliance through 2021-10. See attached AD List for details.

Test run aircraft, all systems working satisfactorily at this time.

Maintenance Release: This airframe has been repaired and inspected in accordance with current maintenance rules of the Federal Aviation Regulations, was found airworthy and is approved for Return to service.

Dirk Buchheit 

SUB-TOTALS this page
TOTALS—Carry forward to next page

AIRFRAME LOG

DATE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
------	-----------------------	---------------------------	------------------------------	---

05-14-20
Complete Aviation Management LLC.

N9126P Serial# 24-4605 S/N 24-4605 Tach 3280.73 ATT 3280.7

Performed Annual inspection IAW FAR Part 43, Appendix D. Performed all routine maintenance. ELT unit function tested satisfactorily per FAR 91.207. Battery due 03-2021. Installed new air filter P/N BA3. Serviced brake reservoir with MIL5606. Install one new spark plug. P/N UREM38E. Adjusted and trimmed nose landing gear door. Install new air intake scoop receptacles. P/N 212-12ND. Installed new LH & RH brake adcl clamps. Installed new main landing gear door actuator rod ends. P/N CA452-860A. Fabricate and install new LH and RH instrument panel overlay using 0.09 2024T3 aluminum. Install new navigation light bulb on LH wing tip. P/N 11-01964 Service nose strut with N2. Install new air filter. P/N BA-3

C/W the following AD's: 75-12-06 Fin spar, 79-20-10 Aileron nose ribs, 94-13-10 Stabilator torque tube. Checked AD's for compliance through 2020-08. See attached AD List for details.

Test run aircraft, all systems working satisfactorily at this time.

Maintenance Release: This airframe has been repaired and inspected in accordance with current maintenance rules of the Federal Aviation Regulations, was found airworthy and is approved for Return to service.

Dirk Buchheit [Redacted Signature]

Date: 5/13/2021 Tach: 3344.3
Replaced nose tire with new Goodyear Flight Special 600X6 and Leak guard tube. Cleaned and packed nose wheel bearings.
Signed: [Redacted Signature]
A&P: [Redacted Signature]
For: Martin Aircraft Services, LLC

				SUB-TOTALS this page
				TOTALS—Carry forward to next page