


~~670~~

Detector 276.3 gave us a critical alarm axle 299 North rail.
We stopped to check with temp stick. After talking with
dispatcher and wayside desk, we were told to take train to
Riverside at track speed to set car in the house track on
the siding. ~~Train~~ Train went into emergency while approaching
Kumis. Head end stopped at mile post V 262.0. We were
~~originally~~ originally going to set car in siding at North Fork but
were not sure we could shove back up the hill at Faggi.
Detector at Mile post V 266.6 gave a no defect reading.

J. D. Gammons



VISION STATEMENT

BE THE SAFEST, MOST
CUSTOMER-FOCUSED AND
SUCCESSFUL TRANSPORTATION
COMPANY IN THE WORLD