

INSPECTION REPORT

Inspector's Name DePietro, Gregory J.		Inspector's Signature			Inspector's ID No. [REDACTED]	Report No. 114	Date yy mm dd 2020 10 15						
Railroad/Company Name & Address HOUSATONIC RR CO., INC. Canaan CT				R/C R	Division SYSTEM	RR/Co. Representative (Receipt Acknowledged) Name Phillip Bailey Title Trainmaster Email Signature _____							
From: City CANAAN		Codes 0100	Destination City & County			Codes	From Latitude						
State CT		09	City				From Longitude						
County LITCHFIELD		C005	County				To Latitude						
Mile Post: From To		Inspection Point HEADQUARTERS					To Longitude						
Activity Code:	RWP												
Units:	1												
Sub Units:	4												
Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
1										N	N	0	
Description - [** Comment to Railroad/Company **] In the course of assisting the Inspector In Charge (IIC) with FE-2020-14 investigation I reviewed and received copies of HRRC records of qualification for the 4 roadway workers present at the incident. The records obtained were for the following: Roadway Worker Protection (RWP), Northeast Operating Rules Advisory Committee (NORAC), and Physical Characteristics. The records were provided to the FRA IIC and remain in his possession at this time.													
Seal Applied		Seal Removed			Hazard Class			UN/NA ID					
Violation Recommended				<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		Latitude:			Longitude:				
Written Notification to FRA of Remedial Action is:				<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional		Railroad Action Code		Date(mm/dd/yyyy):		[REDACTED]		Comments on back?	