



DAILY RECORD OF FACILITY OPERATION

PAGE NO.

1 of 1

DATE

03-22-09

LOCATION	IDENTIFICATION	TYPE FACILITY	OPERATING POSITION	CHECKED BY 
PRESCOTT VALLEY, AZ	PRC	FSS HUB	WS	MANAGER C.S. HATHEWAY 

UTC	REMARKS
0700	D. DOROW ON. CFPL. FOR OUTAGES, SEE EQUIPMENT LOG. FGSB NUW.
0716	WCLC.
E 0912	THERMOSTAT IN THE SOUTH-EAST QUADRANT IS CONTINUOUSLY CYCLING FROM ZERO TO NINETY-NINE DEGREES. SEEMS TO HAVE NO AFFECT ON TEMPERATURE IN BUILDING.
1320	C. HOLLIMAN ON.
1330	WCLC.
1525	J. SCOVELL ON.
1815	C. HOLLIMAN ON.
1934	NOCC CALLED FOR THE RELEASE OF JLI EFAS FREQS. I REQUESTED THAT JLI NOT BE RELEASED DUE TO WX CONCERNS. I WAS ADVISED THAT THE FLOOR BOSS OF POCC SAYS THAT IT, JLI, IS ATACHED TO A RCAG SITE SO, "THEY WERE TAKING IT." I ADVD THAT I WAS NOT IN AGREEMENT, BUT , JLI RLSD TILL 2330. SV
2/23/09 Q 2059	RICK GRIFFITH, AP MANAGER BTM REPORTS AN ACFT CRASH VCNTY RY 33 IN CEMETARY. SAYS ACFT BURNED BEYOND RECOGNITION. NO TAIL NUMBER. RESCUE ACTIVITY REPORTED. ZLC REPORTS NO TRAFIC IN THE AREA. GTF AOR HAS NO FP ACTIVITY. FBO FONE 406-490-1643.
2123	CALLSIGN ACFT ACCIDENT AT BTM N128CM, TYPE PC12, AT LEAST SEVENTEEN FATAL ATTM PER ROC. ADVD JJ/CH TMU.
2149	O.JONES ON ABV NOTED.
2341	JLI EFAS FREQ RTS. TY
0023	J. CUMMINGS ON.
0130	WCLC.
0505	C HOLLIMAN ON.
0559	SEA C-SITE CLSD.
0659	COB.

I CERTIFY that all entries above are correct; that scheduled operations have been accomplished, except as noted, and all abnormal occurrences and conditions have been recorded.

