



Photo 1 – View of the substantial damage sustained to the left-wing lift struts (courtesy of the Federal Aviation Administration).



Photo 2 – View of the substantial damage sustained to the vertical stabilizer and the rudder (courtesy of the Federal Aviation Administration).



Photo 3 – View of the cockpit (courtesy of the Federal Aviation Administration).