From:
 To:

 Subject:
 Re: CEN22LA148 (N85855) - Additional Question

 Date:
 Thursday, April 7, 2022 2:29:40 PM

[CAUTION] This email originated from outside of the organization Do not click any links or open attachments unless you recognize the sender and know the content is safe

Sorry I missed that. No there was nothing at all wrong with the plane.

Thanks!

Jearmy McCubbins

New docks, dock re-pair

Re-foam, dock additions

"The bitterness of poor quality lingers long after the sweetness of the cheap price is forgotten!"

From: Hodges Michael

Sent: Thursday, April 7, 2022 8:36 AM

To: Jearmy McCubbins

Subject: CEN22LA148 (N8585S) - Additional Question

Good morning sir,

I have a quick question about the NTSB Form 6120.1 that you just submitted – on page 10, the one question was left blank:

1224
Hours
Cycles Time Since This Part
Inspected/Overhaule

Was there anything mechanically wrong with the airframe or engine during the accident flight?

Thank you again.

Mike

Mike J. Hodges, MS, CHP Air Safety Investigator National Transportation Safety Board

4760 Oakland Street, Suite 500 Denver, Colorado 80239-2793

Cellular/SMS:

Facsimile:

Response Operations Center (24/7): 1-844-373-9922 Work Hours: Monday-Friday, 0900-1730 Mountain Time

"We always need to prepare ourselves for handling the unexpected." – Neil A. Armstrong

CONFIDENTIALITY NOTICE - THIS E-MAIL TRANSMISSION MAY CONTAIN INFORMATION THAT IS PRIVILEGED, CONFIDENTIAL, PROPRIETARY, SUBJECT TO COPYRIGHT, AND/OR EXEMPT FROM DISCLOSURE UNDER APPLICABLE LAW. IT IS FOR THE USE OF INTENDED RECIPIENTS ONLY. If you are not an intended recipient of this message, please notify the original sender immediately by forwarding what you received and then delete all copies of the correspondence and attachments from your computer system. Any use, distribution, or disclosure of this message by unintended recipients is not authorized and may be unlawful.