

ATTACHMENT 3

AIRWORTHINESS GROUP FACTUAL REPORT

NTSB No. DCA20LA100

Auxiliary Servocylinder Assembly Serial No. 644 Authorized Release Certificates, Last Overhaul (September 2017) and Repair (August 2019) (2 pages)

1. Approving Civil Aviation Authority: Country		2.				3. Form Tracking No.			
Transport Canada		AUTHORIZED RELEASE CERTIFICATE				= 5.1.2.5.3			
		FORM ONE				C 16980			
4. Organization name and address JB Helicopter Accessory Service Limited, 6258-202 Street, L Tel: 604-533-427				Langley, BC, V2Y 1N2 CANADA 75 Fax: 604-533-6611		w/O 25941			
6. Item	7. Description	8. Part No.	9. Qty	10.Serial Batch No.	11. S	atus/work			
1	Aux Servo	S6165-61500-061	1	644		Overhauled			
12. Remarks: Assembly Overhauled in accordance with Manual No. Sikorsky SA4045-83 , Rev 22. Dated Nov 30, 2005									
Assembly Overhauled I.A.W. Mfgs.									
T.S.N. 34184.2									
T.S.O. 0.0									
13a. Certifi	es that the items identified above were	manufactured in conformity to:	14a						
Approved design data and are in condition for safe operation.			X CAR 571,10 Maintenance Release.						
Non-approved design data specified in block 12.			Other regulations specified in block 12						
				Certifies that unless otherwise specified in block 12, the work identified in block 11 and described in block 12, has been performed in compliance with the Canadian Aviation Regulations.					
13b. Signa	ture	13c. Approved Organization Number	14b. Signatur	e	_	14c. Approved Organization Number			
N/A		N/A	70000			5-HAS / AMO # 2-90			
13d. Name		13e. Date (dd/mmm/yyyy)	14d. Name			14e. Date (dd/mmm/yyyy)			
N/A		N/A	John Boyko			01 September 2017			

(Previously form 24-0078)

Important: See notes

Installer Responsibilities

This certificate does not constitute authority to install.

Installers working in accordance with the national regulations of a country other than that specified in Block 1 must ensure that their regulations recognize certifications from the country specified.

Statements in blocks 13a or 14a do not constitute installation certification. In all cases, the technical record for the aircraft must contain an installation certification issued in accordance with the applicable national regulations before the aircraft may be flown.

1. Approvir	ng Civil Aviation Authority: Country	2.	3 Form Trac	rking No						
1	Fransport Canada	AUTHORIZED RELEASE CERTIFICATE				3. Form Tracking No.				
		FORM ONE				C 17911				
Organization name and address				5. Work		er/contract/invoice				
JB Helicopter Accessory Service Limited , 6258-202 Street, Langle Tel: 604-533-4275				N2 CANADA		W/O 26954				
6. Item	7. Description	8. Part No.	9 QTY	10.Serial Batch No.	11. Statu	s/work				
1	Aux Servo	S6165-61500-061	1	644		Repaired				
12. Remarks: Assembly Repaired in accordance with Manual No. Sikorsky 4045-83 Rev 22 Nov 30, 2010										
Assembly Repaired I.A.W. Mfgs. Specs										
Yaw piston seals where replaced and a complete functional check was carried out										
T.S.N. 34691.7 T.S.O. 507.5										
13a. Certifies that the items identified above were manufactured in conformity to:			14a.							
L	Approved design data and are in		X CAR 571.10 Maintenance Release.							
Non-approved design deta specified in block 12.			Other regulations specified in block 12							
				Certifies that unless otherwise specified in block 12, the work identified in block 11 and described in block 12, has been performed in compliance with the Canadian Aviation Regulations.						
13b. Signa	ture	13c. Approved Organization Number	14b. Signature		14	c. Approved Organization Number				
	N/A	N/A	a			AMO # 2-90				
13d. Name N/A		13e. Date (dd/mmm/yyyy)	14d. Name		14	e. Date (dd/mmm/yyy				
		N/A	2	John Boyko		01 August 2019				

Previously form 24-0078)

Important: See notes

Installer Responsibilities

This certificate does not constitute authority to install.

Installers working in accordance with the national regulations of a country other than that specified in Block 1 must ensure that their regulations recognize certifications from the country specified.

Statements in blocks 13a or 14a do not constitute installation certification. In all cases, the technical record for the aircraft must contain an installation certification issued in accordance with the applicable national regulations before the aircraft may be flown.