

Area Weather Reports

April 4, 2022, 1250 EDT

ERA22LA179

Somerset Airport (SMQ), Somerville, New Jersey; 6nm NW of the accident site:

12:53 PM: KSMQ 041653Z AUTO 31011G17KT 10SM FEW049 11/M02 A3000
RMK AO2 SLP159 T01111017

Linden Airport (LDJ), Linden, New Jersey; 17 nm E of the accident site:

12:55 PM: KLDJ 041655Z AUTO 35009KT CLR 11/M03 A2999 RMK AO2
T01121027 PWINO

Trenton Mercer Airport (TTN), Trenton, New Jersey; 18 nm SW of the accident site:

11:53 PM: KTTN 041553Z 35007KT 10SM BKN042 09/M01 A3003 RMK AO2
SLP163 T00891006

12:53 PM: KTTN 041653Z 29006KT 10SM BKN045 09/M01 A3002 RMK AO2
SLP161 T00941011