

HIGHWAY FACTORS GROUP CHAIRMAN'S FACTUAL REPORT

Highway Attachment – Paved Shoulder Width Measurements Along Eastbound SR-12 Near Crash Location

Bryce Canyon City, Utah

HWY19MH012

(5 pages)

| Location Number | Milepost | Station | Shoulder Width | Description | |
|-----------------|----------|---------|----------------|-----------------|--|
| 1 | 10.384 | 0+00 | 11 in | Rest Area Sign | |
| 2 | 10.389 | 0+25 | 11 in | N 200 | |
| 3 | 10.393 | 0+50 | 11 in | | |
| 4 | 10.398 | 0+75 | 9 in | | |
| 5 | 10.403 | 1+00 | 10 in | | |
| 6 | 10.408 | 1+25 | 7 in | | |
| 7 | 10.412 | 1+50 | 7 in | | |
| 8 | 10.417 | 1+75 | 8 in | Delineator Post | |
| 9 | 10.422 | 2+00 | 7 in | | |
| 10 | 10.427 | 2+25 | 8 in | | |
| 11 | 10.431 | 2+50 | 9 in | | |
| 12 | 10.436 | 2+75 | 12 in | | |

Physical measurements were taken every 10 steps (approximately 25 feet) through the measured location





