

HIGHWAY FACTORS GROUP CHAIRMAN'S FACTUAL REPORT

Highway Attachment – Existing Sign Inventory Eastbound SR-12 MP 7.5 – 10.5

Bryce Canyon City, Utah

HWY19MH012

(6 pages)

Existing Sign Inventory Eastbound SR-12 MP 7.5 - 10.5

NTSB Attachment - Page 2

6) Signage plans for SR-12, approximately 3 miles preceding the crash in eastbound direction





SR-12 Signs EB 7.5-10.5

Description	Direction	Location	Sign Code	Size	Color	Condition
SPEED LIMIT 65	EB	7.608	R2-1	24 x 30	Black on White	GOOD
Marker, MILE 8	EB	7.991	D10-1	10 x 18	White on Green	GOOD
NO PASSING ZONE	EB	8.538	W14-3	40 x 34	Black on Yellow	GOOD
NO PASSING ZONE	WB	8.828	W14-3	40 x 34	Black on Yellow	GOOD
Marker, MILE 9	EB	8.993	D10-1	10 x 18	White on Green	GOOD
SUMMIT 7777 FT	EB	9.144	GS-3A	36 x 24	White on Green	GOOD
Symbol, Trailer Camping (Trailer)	EB	9.526	D9-3A	24 x 24	White on Blue	FAIR
Symbol, Pedestrian Crossing (Man Walking) & Plaque, NEXT 1/2 MILES,	EB	9.685	W11-2	36 x 36	Black on Yellow	GOOD
REST AREA AHEAD REST ROOMS	EB	9.842	D5-1A	96 x ?	White on Blue	FAIR
Marker, MILE 10	EB	10.000	D10-2	10 x 27	White on Green	GOOD
REST AREA (TO THE LEFT)	EB	10.384	D5-2	96 x ?	White on Blue	GOOD