

NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety Washington, D.C. 20594

May 31, 2017

Attachment 8 - American Airlines Flight Attendant Briefing

OPERATIONAL FACTORS/HUMAN PERFORMANCE

DCA17FA021



7.1.10 Flight Attendant / Purser Briefing

Reference: IOSA FLT 1.3.9

- A. The FA 1/A-FA/Purser will be the primary liaison between the Captain and the flight attendants and will promptly inform the Captain of all on-board cabin emergencies, irregular issues, passenger concerns and cabin discrepancies.
- B. Prior to gate departure, the Captain will give the FA 1/A-FA/Purser the flight plan F/A briefing message and personally discuss the following items as applicable:
 - 1. number of flight attendants on board
 - 2. any anticipated enroute delays
 - short-taxi situations and safety demo considerations (if applicable)
 - 4. preflight turbulence briefing:
 - a) include weather and turbulence forecast along the route of flight, the expected intensity and duration of forecast turbulence, plus notification procedures and required action in the event of a significant unexpected turbulence encounter.
 - b) Brief service may be suspended at the flight attendants' discretion if the conditions in the cabin warrant.
 - c) If possible, a call should be made to the flightdeck to report the cabin situation, including any injuries.
 - d) If not seated at a jumpseat with an interphone, remain seated to avoid injury until instructed to resume duties by the Captain.
 - e) Once cleared to resume duties, call the flightdeck to report any injuries or abnormalities.
 - 5. appropriate security items (see 15.1.7 Crew Security Briefing).
 - 6. brief flightdeck access procedures and codes
 - 7. cabin or galley write-ups or deferrals in the AML (logbook).
 - 8. A life vest or floating seat cushion demonstration is required on all flights. If the onboard video monitors are inop or not installed, a manual demonstration must be accomplished.

Note

Allow adequate time for the manual briefing along with the complete safety demo briefing.

- 9. Gen. Decs/Customs Immigration forms (if required)
- 10. coordination of flightdeck crew meal service, if applicable
- 11. address the importance of minimizing noise and activity around the crew rest areas
- on North Atlantic flights routed north of 66° north over Greenland, request the FA 1/A-FA/Purser review the FA Safety Manual information concerning "66N Supplemental O₂ Unit"
- 13. any other unusual or pertinent issues relevant to the flight