



MEMORANDUM

Timothy N. Sorensen
Aviation Accident Investigator
Central Region

Date: December 2, 2019

NTSB Accident Number: CEN20FA022 – Chamberlain, South Dakota

Narrative:

An autopsy of the pilot was performed at Sanford Health Pathology Clinic (Sioux Falls, South Dakota) under authority of the Brule County Coroner (South Dakota). The pilot's cause of death was blunt force injuries sustained in the accident.

----- End of entries -----