

## MEMORANDUM FOR RECORD

Aaron Sauer Sr. Air Safety Investigator Central Region

Date: 07/26/21 NTSB Accident Number: CEN21FA199

An autopsy of the pilot was performed by the Office of the Medical Examiner, Corpus Christi, Texas, which listed the cause of death as multiple blunt force injuries. The manner of death is accident.