

## MEMORANDUM FOR RECORD

Aaron Sauer Sr. Air Safety Investigator Central Region

Date: 03/29/23

**NTSB Accident Number: CEN23LA093** 

An autopsy of the pilot was performed by the Marion County Coroner's Office, Indianapolis, Indiana, which listed the cause of death as blunt force trauma. The manner of death was suicide.