



History Details For Locomotive - BNSF 9251 Aug 22, 2021 to Aug 24, 2021

BNSF 9251 | HP Actual/Available 4300 0000 | FLY 0.00 | Laid Up Status LUTR

Shopping and Servicing Details Field Repairs

| Location | Arrival Reason | Work Level Description | Comments | Arrived | Released | | |
|-----------------------------------|-----------------------------------|------------------------------------------|----------|------------------|------------------|------------------|------|
| > ALLINE (ALLIANCE, NE)(02937408) | OCR | Service | | 8/23/21 20:41:08 | 8/23/21 21:40 23 | | |
| ∨ ALLINE (ALLIANCE, NE)(02910494) | M368 | Service | | 8/20/21 10:17:54 | 8/23/21 11:40:37 | | |
| History Work Plan History | | | | | | | |
| > 200002458754 | MOD | 116S-Snyder Fuel Neck Adjustment 116S- S | REG | 0/1 | Deferred | | |
| > 200002458979 | SHDF | Battery Audit BP07-388 SD70ACe and SD70M | REG | 45/117 | Completed | | |
| > 200002459066 | SHDF | Exhaust Inspection & Re-Torque BP01-142 | REG | 81/105 | Completed | | |
| > 200002458748 | NSP | BNSF 9251 Locomotive Outshop Supervisor | REG | 1/70 | Completed | | |
| ∨ 200002458750 | NSP | BNSF 9251 Wheel Sheet Maintenance Wheel | REG | 2/2 | Completed | | |
| Op No. | Description | Start Date | Tasks | Track & Spot | Duration | Status | Mate |
| > 0010 | Initial Wheel Sheet REG | 08/22/2021 | 1/1 | 0020-20 | 01 H 00 M | Completed | |
| > 0020 | Final Wheel Sheet REG | 08/23/2021 | 1/1 | WB21-21 | 00 H 37 M | Completed | |
| > 200002459034 | SHDF | Slip Ring and Brush Inspection BP07-377 | REG | 31/31 | Completed | | |
| > 200002459123 | SHDF | PC04-009 BP01-189 Inspection of Cooling | REG | 12/12 | Completed | | |
| ∨ 200002458746 | NSP | BNSF 9251 AFM Insp AFM Inspection | REG | 2/2 | Completed | | |
| Op No. | Description | Start Date | Tasks | Track & Spot | Duration | Status | Mate |
| > 0010 | AFM Calibration REG | 08/22/2021 | 2/2 | 0020-20 | 00 H 30 M | Completed | |
| > 200002459053 | SHDF | Outbound Quality Inspection BP11-022 BNS | REG | 10/10 | Completed | | |
| > 200002459065 | SHDF | Hot Squeeze BP04-001 HOT ENGINE SQUEEZE | REG | 46/86 | Completed | | |
| ∨ 200002458747 | NSP | BNSF 9251 Hand Brake Insp Hand Bra | REG | 1/1 | Completed | | |
| Op No. | Description | Start Date | Tasks | Track & Spot | Duration | Status | Mate |
| > 0010 | Perform Hand Brake Inspection REG | 08/22/2021 | 1/1 | 0020-20 | 00 H 30 M | Completed | |
| ∨ 200002458749 | NSP | BNSF 9251 FRQ Inspection FRQ with ERI | REG | 9/9 | Completed | | |
| Op No. | Description | Start Date | Tasks | Track & Spot | Duration | Status | Mate |
| > 0010 | Federal Inspection tems REG | 08/22/2021 | 7/7 | 0020-20 | 03 H 30 M | Completed | |
| > 0020 | Level 1 Air Test REG | 08/22/2021 | 1/1 | 0020-20 | 01 H 00 M | Completed | |
| > 0030 | Event Recorder Test REG | 08/22/2021 | 1/1 | 0020-20 | 01 H 00 M | Completed | |
| > 200002458752 | MOD | 107S - PTC GPS Firmware Update 107S - PT | REG | 1/1 | Completed | | |
| > 200002459033 | SHDF | Inspect / Replace Crankcase Felt Seal | REG | 1/1 | Completed | | |
| > 200002458753 | MOD | 114S - LXA Software Upgrade Ver 610 114S | REG | 1/1 | Completed | | |
| > 200002458751 | NSP | BNSF 9251 General Maintenance General Ma | REG | 266/266 | Completed | | |
| > 200002468152 | SHDF | BNSF 9251 L4R4 Out of tolerance Wheel Wo | REG | 1/1 | Completed | | |
| > 200002468153 | SHDF | BNSF 9251 L5R5 Out of tolerance Wheel Wo | REG | 1/1 | Completed | | |
| > 200002468151 | SHDF | FRONT Coupler Height | REG | 1/1 | Completed | | |
| > 200002469182 | SHDF | Need to replace unloader valves | REG | 1/1 | Completed | | |
| > 200002458654 | SHDF | UNSC Defects | REG | 9/9 | Completed | | |



History Details For Locomotive - BNSF 9251 Aug 22, 2021 to Aug 24, 2021

BNSF 9251 | HP Actual/Available 4300 0000 | FLY 0.00 | Laid Up Status LUTR

Shopping and Servicing Details Field Repairs

| Location | Arrival Reason | Work Level Description | Comments | Arrived | Released | | | |
|-----------------------------------|-----------------------------------|----------------------------------------------|------------------------------------------|------------------|------------------|-----------|-----------|---|
| > ALLINE (ALLIANCE, NE)(02937408) | OCR | Service | | 8/23/21 20:41:08 | 8/23/21 21:40 23 | | | |
| ∨ ALLINE (ALLIANCE, NE)(02910494) | M368 | Service | | 8/20/21 10:17:54 | 8/23/21 11:40:37 | | | |
| History | Work Plan History | | | | | | | |
| > 200002458754 | MOD | 116S-Snyder Fuel Neck Adjustment 116S- S | REG | 0/1 | Deferred | | | |
| > 200002458979 | SHDF | Battery Audit BP07-388 SD70ACe and SD70M | REG | 45/117 | Completed | | | |
| > 200002459066 | SHDF | Exhaust Inspection & Re-Torque BP01-142 | REG | 81/105 | Completed | | | |
| > 200002458748 | NSP | BNSF 9251 Locomotive Outshop Supervisor | REG | 1/70 | Completed | | | |
| > 200002458750 | NSP | BNSF 9251 Wheel Sheet Maintenance Wheel | REG | 2/2 | Completed | | | |
| > 200002459034 | SHDF | Slip Ring and Brush Inspection BP07-377 | REG | 31/31 | Completed | | | |
| > 200002459123 | SHDF | PC04-009 BP01-189 Inspection of Cooling | REG | 12/12 | Completed | | | |
| > 200002458746 | NSP | BNSF 9251 AFM Insp AFM Inspection | REG | 2/2 | Completed | | | |
| > 200002459053 | SHDF | Outbound Quality Inspection BP11-022 BNS | REG | 10/10 | Completed | | | |
| > 200002459065 | SHDF | Hot Squeeze BP04-001 HOT ENGINE SQUEEZE | REG | 46/86 | Completed | | | |
| > 200002458747 | NSP | BNSF 9251 Hand Brake Insp Hand Bra | REG | 1/1 | Completed | | | |
| > 200002458749 | NSP | BNSF 9251 FRQ Inspection FRQ with ERI | REG | 9/9 | Completed | | | |
| > 200002458752 | MOD | 107S - PTC GPS Firmware Update 107S - PT | REG | 1/1 | Completed | | | |
| > 200002459033 | SHDF | Inspect / Replace Crankcase Felt Seal | REG | 1/1 | Completed | | | |
| > 200002458753 | MOD | 114S - LXA Software Upgrade Ver 610 114S | REG | 1/1 | Completed | | | |
| ∨ 200002458751 | NSP | BNSF 9251 General Maintenance General Ma | REG | 266/266 | Completed | | | |
| > | Op No. | Description | Start Date | Tasks | Track & Spot | Duration | Status | M |
| > | 0010 | Safety Precautions REG | 08/22/2021 | 4/4 | 0020-20 | 00 H 25 M | Completed | |
| > | 0020 | Cab/Carbody Inspections REG | 08/22/2021 | 29/29 | 0020-20 | 01 H 06 M | Completed | |
| > | 0030 | Traction Motor REG | 08/22/2021 | 23/23 | 0020-20 | 00 H 30 M | Completed | |
| > | 0040 | In Shop Electrical Checks - Bottoms REG | 08/22/2021 | 5/5 | 0020-20 | 00 H 30 M | Completed | |
| > | 0050 | In Shop Electrical Checks - Tops REG | 08/22/2021 | 17/17 | 0020-20 | 03 H 38 M | Completed | |
| > | 0060 | Complete Before Downloading Event Record REG | 08/22/2021 | 4/4 | 0020-20 | 01 H 00 M | Completed | |
| > | 0070 | In Shop Machinist Checks REG | 08/22/2021 | 31/31 | 0020-20 | 04 H 05 M | Completed | |
| > | 0080 | In Shop Air System Checks REG | 08/22/2021 | 12/12 | 0020-20 | 02 H 26 M | Completed | |
| > | 0090 | Filters/Gaskets REG | 08/22/2021 | 16/16 | 0020-20 | 04 H 00 M | Completed | |
| > | 0100 | In Shop Pipefitter REG | 08/22/2021 | 11/11 | 0020-20 | 04 H 15 M | Completed | |
| > | 0110 | In Shop Laborer REG | 08/23/2021 | 5/5 | 0020-20 | 00 H 00 M | Completed | |
| > | 0120 | Outbound Electrical Checks REG | 08/22/2021 | 25/25 | 0020-20 | 01 H 00 M | Completed | |
| > | 0130 | Outbound Machinist Checks REG | 08/22/2021 | 21/21 | 0020-20 | 03 H 00 M | Completed | |
| > | 0140 | Outbound Load Test Values REG | 08/22/2021 | 29/29 | 0020-20 | 01 H 45 M | Completed | |
| > | 0150 | Outbound Pipefitter REG | 08/22/2021 | 2/2 | 0020-20 | 00 H 30 M | Completed | |
| > | 0160 | DB Stall Test REG | 08/22/2021 | 16/16 | 0020-20 | 00 H 30 M | Completed | |
| > | 0170 | PTC M368 Inspection REG | 08/22/2021 | 16/16 | 0020-20 | 00 H 30 M | Completed | |
| > | 200002468152 | SHDF | BNSF 9251 L4R4 Out of tolerance Wheel Wo | REG | 1/1 | Completed | | |
| > | 200002468153 | SHDF | BNSF 9251 L5R5 Out of tolerance Wheel Wo | REG | 1/1 | Completed | | |
| > | 200002468151 | SHDF | FRONT Coupler Height | REG | 1/1 | Completed | | |
| > | 200002469182 | SHDF | Need to replace unloader valves | REG | 1/1 | Completed | | |

Loco Defects for BNSF 9251

From 10/30/2021 12:00:00 AM thru 11/24/2021 12:00:00 AM

Note: Blanks in Rprs column indicates an open defect
 Actn: 1=Replaced 2=Repaired 3=Adjusted 4=No defect found 5=Duplicate 6=Reduced

| Defect Date | Lvl | DEFJ C | Loco Init | Loco No | City | Defect | Defective Item | Rprs | Actn | Rpr City | Rpr Date |
|-------------|-----|--------|-----------|---------|-----------|-------------|--------------------|------|------|----------|-----------|
| 11/14/2021 | 1 | F021 | BNSF | 9251 | GATEWAY | | Derailed | | | | |
| 11/9/2021 | 9 | F004 | BNSF | 9251 | GUERNSEY | | | | | | |
| 11/4/2021 | 9 | F014 | BNSF | 9251 | ARBOR | | Incorrect Reading | 2 | | LINCOLN | 11/7/2021 |
| 11/4/2021 | 2 | F014 | BNSF | 9251 | ARBOR | Out of Fuel | Empty | 6 | | ARBOR | 11/4/2021 |
| 11/2/2021 | 8 | F016 | BNSF | 9251 | AMTMCCPAS | | Electrical Failure | 2 | | LINCOLN | 11/7/2021 |