

Blake P. Buchanan

Conductor West Quincy

We was traveling Westbound on train CBAM MAS 800A  
Lead Locomotive BNSF 9251 when we noticed a  
Barge was nosed up over the rail around up 186.  
We couldn't tell that it was fouling the track until  
the last couple of seconds before impact. Our Lead  
Locomotive struck the ~~front~~ front of the Boat causing  
our Engines to Derail where they tipped over onto the sides  
and derailed multiple cars behind us. We rang up  
911 on the radio to inform the Dispatcher what  
had happened and location. After that we tried  
to find a way out of the locomotive. All Exits  
were blocked, so we had to climb up and out ~~of~~ of  
the conductor's window on top. We then called  
Dispatcher and trainmaster on the phone to  
give them more information.

11-14-21