


TABLE



FRA-Required Signals

Show / Hide



Signal	Value
Wheel Speed	0.0 mph
Throttle Pos	Idle
BC Pres	72.0 psi
BP Pres	63.0 psi
Rear Pres	62.0 psi
Horn On	Off
Reversor Pos	Forward
Tractive Effort	0 kibf
DB Handle Pos	0 %
AB Mode	Lead Cutin Freight
Distance Traveled Increment	0 ft

Chat with an Expert









