

National Transportation Safety Board

Office of Highway Safety

Washington, DC 20594



HWY23FH012

HUMAN PERFORMANCE FACTORS

Group Chair's Factual Report - Supplemental

TABLE OF CONTENTS

A. Crash Information	3
B. Human Performance Factors Group	3
C. Crash Summary	3
D. Errata to the Human Performance Factual Report	3

A. CRASH INFORMATION

Location: State Highway 33/22 in the vicinity of Northwoods Drive, near Excelsior,
Sauk County, Wisconsin
Date: May 12, 2023
Time: 7:20 a.m. Central Daylight Time

B. HUMAN PERFORMANCE FACTORS GROUP

Group Chair Dennis Collins
National Transportation Safety Board
Washington, D.C.

C. CRASH SUMMARY

For a summary of the crash, refer to the *Crash Information and Summary Report*, which can be found in the NTSB docket for this investigation.

D. ERRATA TO THE HUMAN PERFORMANCE FACTUAL REPORT

Page 7, first line of Section 1.7

Reads as: "Following the crash, with the consent of his parents, a blood sample was taken from the pickup driver at 8:39 a.m."

Should read as: "Following the crash, with the consent of his parents, a blood sample was taken from the pickup driver at 9:13 a.m."

Page 14, first line of Section 2.7

Reads as: "Following the crash, the bus driver consented to a blood draw. A blood sample was taken from him at 9:13 a.m."

Should read as: "Following the crash, the bus driver consented to a blood draw. A blood sample was taken from him at 8:39 a.m."

Submitted by:

Dennis J. Collins
Senior Accident Investigator (Human Performance)