

Citation Product Support
The Cessna Aircraft Company
Post Office Box [redacted] Wichita, Kansas [redacted]
Telefax: [redacted] Phone: [redacted]

CESCOM

Aircraft Flight Log

CSNA-1024-A



A/C Serial No. 560-6026		A/C Unit No. 6026		A/C Registration No. N56012		Operator Of Aircraft Brook Haven Properties				Maintenance Base 488-Swf-ME2									
Date July 20 21	Flight		No. of Persons Aboard	Distance Nautical Miles	Flight Duration Hrs. This	Accumulated Total Time								Landing This Flight	Accumulated Total			Discrepancy Sheet Number	Crew Pilot / Copilot
	From	To				Aircraft	Engine No. 1		Engine No. 2		APU		Freon		Eng. 1 Cycles	Eng. 2 Cycles	APU Events		
Accumulated Totals Brought Forward						2563	8	2563	8	2563	8	1081	2	1891	1891	1891	1383		
7/17/21	ME2-438	2		29	2566	7	2566	7	2566	7	1084	7	1	1892	1892	1892	1384	Maint/B102	
21-29	488-P81-438	4		54	2572	1	2572	1	2572	1	1086	1	2	1894	1894	1894	1386	B103	
						83	8	83	8	83	8	49	3	3	3	3	3		

VOR Receiver Operation Checked In Accordance With FAR 91.171					Comments		Specialized Cycles	
Date	Bearing Error		Place	Signature			Flight Log	
	VOR 1	VOR 2					Section	Page
							1	

Permanent Aircraft Record-File In Flight Log Section

*Refer to Engine Manufacturer For Definition Of Engine Cycle

Printed in U.S.A.

Citation Product Support
The Cessna Aircraft Company
Post Office Box [redacted] Wichita, Kansas
Telefax: [redacted] / Phone: [redacted]



Aircraft Flight Log CSNA-1024-A



A/C Serial No.		A/C Unit No.		A/C Registration No.		Operator Of Aircraft		Maintenance Base														
S60-6026		6026		N560AR		Brook Haven Properties		488-SWF-ME2														
Date Feb 20 21	Flight		No of Persons Aboard	Distance Nautical Miles	Flight Duration Hrs. This	Accumulated Total Time										Landings This Flight	Accumulated Total				Discrepancy Sheet Number	Crew Pilot / Copilot
	From	To				Aircraft	Engine No. 1		Engine No. 2		APU		Freon		Landings		Eng. 1 Cycles	Eng. 2 Cycles	APU Events			
							Serial No.	Hours	Serial No.	Hours	Serial No.	Hours	Serial No.	Hours								
																				Hours		
Accumulated Totals Brought Forward						2471	8	2471	8	2471	8	1065	9	1836	1836	1836	1350					
4	488-BCT	488	4		53	2477	1	2477	1	2477	1	1065	9	2	1838	1838	1838	1350	C017			
6	488-BED-19	PWA-488	5		71	2484	2	2484	2	2484	2	1067	1	4	1842	1842	1842	1353	B088			
8-10	488-BED-PBI	OKC	6		65	2490	7	2490	7	2490	7	1067	7	3	1845	1845	1845	1355	B090			
11	OKC-BED	488	5		31	2493	8	2493	8	2493	8	1069	2	2	1847	1847	1847	1357	B089			
14	488-BCT	488	4		53	2499	1	2499	1	2499	1	1068	2	2	1849	1849	1849	1357	C018			
15-	488-BDL-BED	PBI-BED																				
15	PBI-BED	488	4		80	2507	1	2507	1	2507	1	1069	8	8	1857	1857	1857	1361	B092			
21	488-BED	RSW-488	5		61	2513	2	2513	2	2513	2	1070	9	3	1860	1860	1860	1363	B091			
24	488-BED	PBI-488	3		58	2519	0	2519	0	2519	0	1071	8	3	1863	1863	1863	1365	B093			
						47.2		472		472		59		27	27	27	15					

VOR Receiver Operation Checked In Accordance With FAR 91.171						Comments		Specialized Cycles		
Date	Bearing Error		Place	Signature				Flight Log		
	VOR 1	VOR 2						Section	Page	
2/4/21	±2	±2	HFD	[redacted]				1		