
NATIONAL TRANSPORTATION SAFETY BOARD Investigative Hearing Alaska Airlines Flight 1282 Boeing 737-9, N704AL

Left Mid Exit Door Plug Separation in Portland, OR January 5, 2024



Manufacturing Records and Human Performance - Attachment 1 NCR N1450292531 and NCO 145-8789-RSHK-1296-002NC

(20 Pages)

DCA24MA063

MANUFACTURING RECORDS AND HUMAN PERFORMANCE

Group Chair's Factual Report

Attachment 1 - NCR N1450292531 and NCO 145-8789-RSHK-1296-002NC

July 1, 2024

									BEN	SEC		N.											
ICR		Rev	Rec	ord-Su	b-Re	cord T	/pe			Initiate	d							Sho	р	ACC	/Pos/	WL	MF
1450292531		0	Rev	vork - Sł	hake					09/01/2	023							R38	F1	941/	1/UAE	3	
IES Company		ERP	Com	pany					lte	em ID						Ite	m De	escrip	tion				
45 JI/WBJ/FBJ-R	tn	NON	None	е																			
						NCR:	22T N	V14502															
lodel 37		Line 08789-	A/F 1D76			Right Left NONE	Multi Unit NO		BFE NO	Cust Sens NO		eck	Stock Chec NO				ASIT 0		SRL	Mai Mai		IPC	FT
ob ID				Relate	d Or	der						Opr/s	Step	Job Qt	y C	Disc Q	Qty						
				IP											1								
Physical Item Loo	cation	ST	ΓA		WL	•	E	BL		Other			Ser	ial ID				RMVD) From	n LN			
Supplier Code	Supplier	Name								Purchas	se Or	der N	lumb	er	Purcha	ise Oi	rder	Positi	on	R	eceip	ot	
01882	SPIRIT A	EROSYS	STEM	IS INC																			
upplier Originat	ion Date		Sup	plier No	onco	onforma	ince T	ype		Pu	rchas	se Co	ntrac	t		Cont	ract	Date	A	Autho	rize t	o Ship	,

Printed: 01/15/2024 19	27:54	Export Control:	COM	
NCR	Status			Page
N1450292531	Complete			1

 \geq

HEADER SECTION(Continued)

Corrective	Responsible Group	Current Task	Parent NCR	Current NCR	Child NCRs	Туре	Coverag
			No	Not A Child	None		

		PLANN	ING SUMMARY	SECTION				
Line A/P	ACC/Pos/WL	NC Order Id	Plan	Last Order	Rev	Status	Interim	Related Revs
8789-1D762	941/1/UAB	145-8789-RSHK-1296-002NC	0001	09/01/2023	11:14	Complete		0
		REVISI	ON 0 SECTION	Complete	`		·	
GNATURES	Task	Name		complete	Org	Phone	Date	9
	Initiation	XXXXXX			XXXXXX	xxxxxx	09/0)1/2023 11:14
Description: Defect Count ************************************	 Fastener Right C15 - Clincher C15 - Clincher AS RECEIVED FRITIS DAMAGED EXIT DOOR. MAR PER THE REQUINE Phone: XXXXXX 2023 11:14 Phone: XXXXXX 9 - Fastener Right C15 - Clincher C15 - Clincher C15 DAMAGED EXIT DOOR. MAR 	d OM SPIRIT********** C/T THE EDGE KED WITH ORANGE TAPE. SEE REMENTS OF EDGE COrg: XXXXXX 	Disposition	1				
Printed: 01/15/					Export Co	ntrol: COM		
NCR	Status							Page

2

N1450292531

Complete

REVISION 0 SECTION--Complete (Continued)

Disposition

Discrepancy Revision: 0 Phone: XXXXXXOrg: XXXXXX Date: 09/01/2023 11:14 Defect No: 3 STA: 727H WL: 254.862 BL: LBL69.249 Feature: F06 - Fastener Rivet Description: C15 - Clinched Defect Count: 1 IS: 1EA RIVET IS DAMAGED C/T THE EDGE FRAME - MID EXIT DOOR. MARKED WITH ORANGE TAPE. SEE ATTACHMENT. S/B: INSTALL PER THE REQUIREMENTS OF Name: XXXXXX Revision: 0 Phone: XXXXXX Org: XXXXXX Date: 09/01/2023 11:14 Defect No: 4 STA: 727H WL: 223.954 BL: LBL68.825 Feature: FO6 - Fastener Rivet Description: C15 - Clinched Defect Count: 0 S: 1EA RIVET IS DAMAGED C/T THE EDGE FRAME - MID EXIT DOOR. MARKED WITH ORANGE TAPE. SEE ATTACHMENT. S/B: INSTALL PER THE REQUIREMENTS OF Name: XXXXXX Revision: 0 Phone: XXXXXX Org: XXXXXX Date: 09/01/2023 11:14 _____ ____ Defect No: 5 STA: 727H WL: 224.1 BL: LBL68.932 Feature: F06 - Fastener Rivet Description: C15 - Clinched Defect Count: 0 IS: 1EA RIVET IS DAMAGED C/T THE EDGE FRAME - MID EXIT DOOR. MARKED WITH ORANGE TAPE. SEE ATTACHMENT. S/B: INSTALL PER THE REQUIREMENTS OF Name: XXXXXX Revision: 0 Phone: XXXXXX Org: XXXXXX

Printed: 01/15/2024 10:27:54

Printed: 01/15/2024 19	27:54	Export Control: COM	
NCR	Status	Page	е
N1450292531	Complete	3	

COM

REVISION 0 SECTION--Complete (Continued)

Discrepancy

Date: 09/01/2023 11:14

Disposition

COVERAG	Line	A/P	Туре	ACC/Pos/WL	NC Order ID	Plan	Last Order Rev	Status	Interim
	08789-10	0762	New	941/1/UAB	145-8789-RSHK-1296-002NC	0001	09/01/2023 11:14	Complete	Final

Printed: 01/15/2024 19:	27:54	Export Control: COM		
NCR	Status		Page	
N1450292531	Complete		4	LP

NON CONFORMANCE ORDER

ACC/	POS W	VRK	LINE/CVN		0	ORDER	ID		REV				ORDER TIT	LE		
941	1/1/UAI	В	8789/1D762		145-8789-F	RSHK-	1296-002NC		0			D	AMAGED RIV	VETS		
PROGR	RAM	LAS	T REVISION	EXF	י ר	/R P	ROD STAT	ORD	ER STAT	TUS		REL F	REC		ORDER S	SUB-TYPE
737		09	9/01/2023		COM NO	N	COMP	C	ompleted	k		IP			RS	ЭНК
	NCR				JOB/SE		COVERAGE					DISPOSIT	ION TYPE	N	CM REVI	SION
N145	502925	531										FINAL				
		Company	у			Area				Su	ıb-Area			Que	eue ID	
	145	5-JI/WBJ/FE	BJ-Rtn													
		STA				WL					BL			0	ther	
					Order	er Id:	145-8789-RSH	K-1296-	002NC							
					Cruci					~~~						
							OPERATIO									
			OPER	ATIONS WI	THOUT AN	N "*" IN	I THE OPERA	TION		N MA	Y BE WOF	RKED IN AI	NY ORDER.			
0											F		Shop			uality
· ·	10 C	Narrative Defect No							No	nks	No	ptions	Accepta	ince	ACC	eptance
		STA: 727H WL: 254.9											09/18/2023 Supl Short			
	E	3L: LBL66		tener Rive	et								Supi Short		ххххх	<
	I L	Descrinti	$on \cdot C15 =$	Clinchad											09/18/20	
	*		on: CTS = ount: 0 ***AS REC	EI VED FROI	M_SPI RI T'	*****	****								Sup Q S	
	F	FRAME - M	ID EXIT D		/		E TAPE. SEE	-					XXXXXX 09/19/2023			
		ATTACHMEN											Supl Accpt			
	S	S/B: INST	ALL PER T	HE REQUIR	EMENTS OF	F									XXXXXX 09/19/20	
	-		PLIER ACC												Sup Q A	
	X	XXXXXX 09	/06/2023	15: 12												
	h	KENUVED N	IOTED DAMA	GE FASIEN												
								rdor 1/c	W+Comr		05252/1	01/15/2024	1 19.24.48		FOV	
Date/Tir	me	01/18	5/2024 19:24	:48 By	y:XXXXXX	Х	0		sy+Camp	Jus. a	55525241	01/10/202	10.24.40		ECV	: COM
Date/Tir	me POS/WI		5/2024 19:24 CVN	•	y : XXXXXX der ID	X	0	Rev	-y+Camp	Jus. 3	55525241	01/10/202-	Order Title	e		H Page

2

Oper	Sten	Narrative				Linł	s	Exceptions	Shop Acceptance	Quality ceptance
	10	FASTENERS REMOVE SUF XXXXX 09, CONDITION APPLY SUPF XXXXX 09, NOTED RIVE IN CONCURF APPLY SUPF XXXXX 09, NOTED RIVE IN CONCURF REMOVE SUF XXXXX 09, Damaged ri and replac damaged ri and replac damaged ri and replac damaged ri APPLY SUPF XXXXX 09, Damaged ri and replac damaged ri and replac damaged ri APPLY SUPF XXXXX 09, Removed ri countersin . 1285" In concurn APPLY SUPF XXXXX 09, fasteners of damage. APPLY SUPF	PLIER ACC /06/2023 STILL EX PLIER ACC /08/2023 ET BUCKT/ RENCE WIT PLIER QU/ /08/2023 ET BUCKT/ RENCE WIT PLIER QU/ /11/2023 Vets are ced per & vet head PLIER ACC /11/2023 Vets are ced per & vet head PLIER SHO /18/2023 Vet per nks are of rence with PLIER QU/ /18/2023 have bee all hol	15:24 KIST. RIVETS WERE JUST PAIN CEPTANCE 16:26 ALL DAMAGE IS ACCEPTABLE AS TH SUPPLIER QA ALITY ACCEPTANCE 16:27 ALL DAMAGE IS ACCEPTABLE AS TH MECHANIC JALITY ACCEPTANCE 07:30 e not acceptable and need t bac5004-1. sec 11.2.2.c tallow compared to the second	ITED OVER. IS PER IS PER IS PER to be remo ks about screpancy. and round and round	oved oved a at	N	Exceptions No		
ACC	1	NL Line	CVN	Order ID		Rev	5. 55	JOLULTI 01/10/2020	Order Title	H Page
941	1/UA		1D762	145-8789-RSHK-1296-002NC	0		D RIV	VETS		N 2

Oper	Step	Narrative					Links	Exceptions	Shop Acceptance		Quality ceptance
10	10	XXXXXX 09/ Installed	rivet pe				No	No			
		XXXXXX 09/	19/2023	LITY ACCEPTANCE 15:11 H MECHANIC							
20	10	Descriptic Defect Cou IS: 1EA RI FRAME - MI ATTACHMENT S/B: INSTA 	2 429 06 - Fas on: C15 - int: 0 VET IS D EXIT D	DAMAGED C/T THE OOR. MARKED WITH ORANGE TA HE REQUIREMENTS OF EPTANCE 15: 12 GE FASTENERS AND INSTALLED AND DWG REQUIREMENTS CEPTANCE 15: 23 IST. RIVETS WERE JUST PAIN EPTANCE 16: 26 IL DAMAGE IS ACCEPTABLE AS H SUPPLIER QA LITY ACCEPTANCE	D NEW S. NTED OVER. S IS PER		No	No	XXXXXX 09/18/2023 Supl Short XXXXXX 09/19/2023 Supl Accpt	XXXXX 09/18/2 Sup Q S XXXXX 09/19/2 Sup Q /	023 Shrt X 023
Date/	Time	01/15/	2024 19:24	:48 By : XXXXXX	Orde	er Ke	ey+Campus:	99525241 01/15/20	24 19:24:48	EC	/: COM
ACC	POS/\	WL Line	CVN	Order ID	F	Rev			Order Title		H Page
941	1/UA	B 8789	1D762	145-8789-RSHK-1296-002NC	C)		RIVETS			N 3

Oper	Step	Narrative	Links	Exceptions	Shop Acceptance		uality eptance
20	10	IN CONCURRENCE WITH MECHANIC	No	No			
		REMOVE SUPPLIER QUALITY ACCEPTANCE XXXXXX 09/11/2023 07:29 Damaged rivets are not acceptable and need to be removed and replaced per talks about damaged rivet heads and it's a different discrepancy.					
		REMOVE SUPPLIER ACCEPTANCE XXXXXX 09/11/2023 07:29 Damaged rivets are not acceptable and need to be removed and replaced per talks about damaged rivet heads and it's a different discrepancy.					
		APPLY SUPPLIER SHORT STAMP XXXXXX 09/18/2023 15:36 Removed rivet per countersinks are clean, holes checked clean and round at .1285" In concurrence with spirit QA					
		APPLY SUPPLIER QUALITY SHORT STAMP XXXXXX 09/18/2023 15:57 fasteners have been removed. holes clean round and free of damage. all holes measure .1285"					
		APPLY SUPPLIER ACCEPTANCE XXXXXX 09/19/2023 15:05 Installed rivet per In concurrence with spirit QA					
		APPLY SUPPLIER QUALITY ACCEPTANCE XXXXXX 09/19/2023 15:12 IN CONCURRENCE WITH MECHANIC					
20	10	Defect No: 3	No				
30	10	STA: 727H WL: 254.862 BL: LBL69.249 Feature: F06 - Fastener Rivet Description: C15 - Clinched	No	No	XXXXXX 09/18/2023 Supl Short	XXXXXX 09/18/20	
		Defect Count: 1 IS: 1EA RIVET IS DAMAGED C/T THE EDGE FRAME - MID EXIT DOOR. MARKED WITH ORANGE TAPE. SEE			xxxxxx	Sup Q S	
Date/T	Time	01/15/2024 19:24:48 By : XXXXXX Order Ke	y+Campus:	99525241 01/15/202	24 19:24:48	ECV	: COM
CC	POS/V	WL Line CVN Order ID Rev			Order Title		H Page
941	1/UAI	B 8789 1D762 145-8789-RSHK-1296-002NC 0	DAMAGED I	RIVETS			N 4

Oper	Step	Narrative			Links	Exceptions	Shop Acceptance	Quality Acceptance
30		ATTACHMENT.	THE REQUIREMENTS OF BAC500	04-1	No	No	09/19/2023 Supl Accpt	XXXXXX 09/19/2023
		APPLY SUPPLIER AC XXXXXX 09/06/2023 REMOVED NOTED DAM FASTENERS PER		ED NEW				Sup Q Acpt
		REMOVE SUPPLIER A XXXXXX 09/06/2023 CONDITION STILL E		NTED OVER.				
		APPLY SUPPLIER AC XXXXXX 09/08/2023 NOTED RIVET BUCK	CCEPTANCE 3 16:26 TALL DAMAGE IS ACCEPTABLE #	AS IS PER				
		IN CONCURRENCE WI	I TH SUPPLIER QA					
		XXXXXX 09/08/2023	UALITY ACCEPTANCE 3 16:28 TAIL DAMAGE IS ACCEPTABLE A	AS IS PER				
		IN CONCURRENCE WI	I TH MECHANI C					
		XXXXXX 09/11/2023 Damaged rivets and replaced per	r <u>e not acceptable and need</u>	alks about	t k			
		REMOVE SUPPLIER A XXXXXX 09/11/2023 Damaged rivets ar and replaced per	ACCEPTANCE 3 07:29 r <u>e not acceptable and ne</u> ed	to be removed alks about	t			
		APPLY SUPPLIER SF XXXXXX 09/18/2023 Removed rivet per countersinks are	3 15:3 <u>6</u>	n and round at	t			
Date/T	Time	01/15/2024 19:	24:48 By : XXXXXX	Order Ke	ey+Campus:	99525241 01/15/20	24 19:24:48	ECV: COM
Duto, I	1	1						

Oper	Step	Narrative				Links	s Exceptions	Shop Acceptance		uality eptance
30	10	.1285" In concurr APPLY SUPF XXXXXX 09/ fasteners of damage. APPLY SUPF XXXXXX 09/ Installed In concurr APPLY SUPF XXXXXX 09/	PLIER QUA (18/2023 have bee all hol PLIER ACC (19/2023 rivet per rence wit PLIER QUA (19/2023	en removed. holes clean ro es measure .1285" CEPTANCE 15:05 er Entrange ch spirit QA ALITY ACCEPTANCE	ound and fro	No	No			
40	10	Descriptic Defect Cou IS: 1EA RI FRAME - MI ATTACHMENT S/B: INSTA APPLY SUPF XXXXX 09/ REMOVED NC FASTENERS REMOVE SUF XXXXX 09/ CONDITION APPLY SUPF XXXXX 09/	64 825 06 - Fas 015 - 015 - 0 EXIT E 0	DAMAGED C/T THE DOOR. MARKED WITH ORANGE T THE REQUIREMENTS OF CEPTANCE 15: 12 AGE FASTENERS AND INSTALLE AGE FASTENERS AND INSTALLE CEPTANCE 15: 23 KIST. RIVETS WERE JUST PAI CEPTANCE	APE. SEE	No	No	XXXXXX 09/18/2023 Supl Short XXXXXX 09/19/2023 Supl Accpt	XXXXXX 09/18/20 Sup Q S XXXXXX 09/19/20 Sup Q A	023 Shrt K 023
Date/1	Гime	01/15/	/2024 19:24	4:48 By : XXXXXX	Order	Key+Campus	: 99525241 01/15/2	024 19:24:48	ECV	: COM
ACC	POS/V	VL Line	CVN	Order ID	Re	ev		Order Title		H Page
941	1/UAI	3 8789	1D762	145-8789-RSHK-1296-002NC	0	DAMAGED	RIVETS			N 6

Oper	Step	Narrative	Links	Exceptions	Shop Acceptance	Quality Acceptance
40	10	IN CONCURRENCE WITH SUPPLIER QA	No	No		
		APPLY SUPPLIER QUALITY ACCEPTANCE XXXXXX 09/08/2023 16:30 NOTED RIVET BUCKTAIL DAMAGE IS ACCEPTABLE AS IS PER				
		IN CONCURRENCE WITH MECHANIC				
		REMOVE SUPPLIER QUALITY ACCEPTANCE XXXXXX 09/11/2023 07:28 Damaged rivets are not acceptable and need to be removed and replaced per talks about damaged rivet heads and it's a different discrepancy.				
		REMOVE SUPPLIER ACCEPTANCE XXXXXX 09/11/2023 07:28 Damaged rivets are not acceptable and need to be removed and replaced per talks about damaged rivet heads and it's a different discrepancy.				
		APPLY SUPPLIER SHORT STAMP XXXXXX 09/18/2023 15:36 Removed rivet per countersinks are clean, holes checked clean and round at .1285" In concurrence with spirit QA				
		APPLY SUPPLIER QUALITY SHORT STAMP XXXXXX 09/18/2023 15:57 fasteners have been removed. holes clean round and free of damage. all holes measure .1285"				
		APPLY SUPPLIER ACCEPTANCE XXXXXX 09/19/2023 15:05 Installed rivet per In concurrence with spirit QA				
		APPLY SUPPLIER QUALITY ACCEPTANCE XXXXXX 09/19/2023 15:12 IN CONCURRENCE WITH MECHANIC				

Date/	Time	01/15/	/2024 19:24	By: XXXXXX	Order K	ey+Campus: 99525241 01/15/2024 19:24:48	ECV:	COM
ACC	POS/WL	Line	CVN	Order ID	Rev	Order Title	F	l Page
941	1/UAB	8789	1D762	145-8789-RSHK-1296-002NC	0	DAMAGED RIVETS	N	1 7

Oper 50	10	Defect No: 5 STA: 727H WL: 224.1 BL: LBL68.932			No	Exceptions	Acceptance		eptance
Date/T	Fime	FRAME - MID EXIT ATTACHMENT. S/B: INSTALL PER APPLY SUPPLIER AG XXXXXX 09/06/2023 REMOVED NOTED DAM FASTENERS PER REMOVE SUPPLIER AG XXXXXX 09/06/2023 CONDITION STILL APPLY SUPPLIER AG XXXXXX 09/06/2023 CONDITION STILL APPLY SUPPLIER AG XXXXXX 09/08/2023 NOTED RIVET BUCK IN CONCURRENCE WI APPLY SUPPLIER OG XXXXXX 09/08/2023 NOTED RIVET BUCK IN CONCURRENCE WI REMOVE SUPPLIER OG XXXXXX 09/08/2023 NOTED RIVET BUCK IN CONCURRENCE WI REMOVE SUPPLIER OG XXXXXX 09/08/2023 NOTED RIVET BUCK IN CONCURRENCE WI REMOVE SUPPLIER OG XXXXXX 09/11/2023 Damaged rivets an and replaced per damaged rivet hea REMOVE SUPPLIER AG REMOVE SUPPLIER AG	- Clinched DAMAGED C/T THE DOOR. MARKED WITH OR THE REQUIREMENTS OF CCEPTANCE 3 15: 12 MAGE FASTENERS AND IN AND DWG REQUI ACCEPTANCE 3 15: 23 EXIST. RIVETS WERE JU CCEPTANCE 3 16: 26 TAIL DAMAGE IS ACCEPT TH SUPPLIER QA JALITY ACCEPTANCE 3 16: 30 TAIL DAMAGE IS ACCEPT TH MECHANIC UALITY ACCEPTANCE 3 07: 27 Te not acceptable and ads and it's a differ ACCEPTANCE	ABLE AS IS PER	ed	No	XXXXXX 09/18/2023 Supl Short XXXXXX 09/19/2023 Supl Accpt	XXXXXX 09/18/20. Sup Q SI XXXXXX 09/19/20. Sup Q Ad	23 hrt 23
	1	01/15/2024 19: <u>WL</u> Line CVN	24:48 By : XXXXXX Order ID	Rev		99525241 01/15/20	Order Title		H Page
941	1/UA		145-8789-RSHK-1296-0			DIVETS			N 8

Oper	Step	Narrative				Links	s Exceptions	Shop Acceptance	Quality Acceptance
50	10	XXXXXX 09/ Damaged ri and replac	ivets are	<u>e not acceptable and need to</u>	ks about	No	No		
		countersi n . 1285"	/18/2023 ivet per nks are c		and round	at			
		APPLY SUPP XXXXXX 09/ fasteners	PLIER QUA /18/2023 have bee	LITY SHORT STAMP	nd and fre	e			
		APPLY SUPP XXXXXX 09/ Installed In concurr	/19/2023 rivet pe	15: 05					
		XXXXXXX 09/	/19/2023	ALITY ACCEPTANCE 15:12 TH MECHANIC					
98	10	Assure all areas comm	foreign non to th	n objects are removed from v nis order.	work	No	No	XXXXXX 09/19/2023 Supl Accept	
		APPLY SUPP XXXXXX 09/ REMOVE SUP XXXXXX 09/ EIE	/06/2023 PPLIER AC	15: 13 CCEPTANCE				Supl Accpt	
		APPLY SUPP XXXXXX 09/ REMOVE SUP XXXXXX 09/ eie	/08/2023 PPLIER AC	16: 26 CCEPTANCE					
		APPLY SUPP XXXXXX 09/							
Date/T	īme	01/15/	5/2024 19:24	4:48 By : XXXXXX	Order	Key+Campus	: 99525241 01/15/2	024 19:24:48	ECV: COM
СС	POS/V	WL Line	CVN	Order ID	Rev	v		Order Title	H Page
941	1/UAE	B 8789	1D762	145-8789-RSHK-1296-002NC	0	DAMAGED	RIVETS		N 9

Oper	Step	Narrative			Links	Exceptions	A	Shop cceptance	Quality Acceptance
998	10				No	No			
999	10	Final Acceptance APPLY FINAL SUPPLIER ACCEPTANCE XXXXX 09/06/2023 15:13 REMOVE FINAL SUPPLIER ACCEPTANCE XXXXX 09/06/2023 15:22 CONDITION STILL EXIST. RIVETS WER APPLY FINAL SUPPLIER ACCEPTANCE XXXXX 09/10/2023 14:12 NOTED RIVET BUCKTAIL DAMAGE IS AC REMOVE FINAL SUPPLIER ACCEPTANCE XXXXX 09/11/2023 07:17 Acceptance was removed because a acceptance action removed APPLY FINAL SUPPLIER ACCEPTANCE XXXXX 09/19/2023 15:11	CCEPTABLE	AINTED OVER. AS IS PER	No	No	XXXX 09/19 Final	/2023	XXXXXX 09/19/2023 Final QA
		APPLY FINAL QUALITY ACCEPTANCE XXXXXX 09/19/2023 18:11 Final quality acceptance per AII prior inspection an supplier.							
			E	XCEPTION SECT	ION				(
Oper/	Step	Туре	Source	ID		Status	5	BEMSID/Nam	e
		24	EPD	N1450293199 CLEARED XXXXXX		XXXXXX			

145-8789-RGEN-RSHK-001NC

CLEARED

XXXXXX

EPD

NCO

A A A

BELOW WEB ATTACHMENTS WILL NOT BE PRINTED

ATTACHMENT TYPE

Attachment Graphics

GRAPHICS ID 8789_BAD_RIVETS **OPER/STEP**

Date	/Time	01/1	5/2024 19:24	4:48 By : XXXXXX	Ord	ler K	ey+Campus: 99525241 01/15/2024 19:24:48	ECV:	С	СОМ
ACC	POS/WL	Line	CVN	Order ID		Re	Order Title	Н	Ρ	Page
941	1/UAB	8789	1D762	145-8789-RSHK-1296-002NC		0	DAMAGED RIVETS	Ν	1	11

		ATTA	CHMENTS		
ATTACHMENT ID 20230901_111952.jpg	TASK ADDED	Rev 0	EXP CNTRL COM	ATTACH TYPE Graphic	
		000			

Date/	Time	01/15	/2024 19:24	4:48 By : XXXXXX Ord	der Key+Campus:	99525241 01/15/2024 19:24:48		
ACC	POS/WL	Line	CVN	Order ID		Order Title	Н	Page
941	1/UAB	8789	1D762	145-8789-RSHK-1296-002NC	DAMAGED RIVE	TS	Ν	12

			ACHMENTS		
ATTACHMENT ID	TASK ADDED	Rev 0	EXP CNTRL COM	ATTACH TYPE Graphic	
20230901_111959.jpg					

Date/	'Time	01/15	/2024 19:24	4:48 By : XXXXXX Ord	er Key+Campus:	99525241 01/15/2024 19:24:48		
ACC	POS/WL	Line	CVN	Order ID		Order Title	Н	Page
941	1/UAB	8789	1D762	145-8789-RSHK-1296-002NC	DAMAGED RIV	ETS	Ν	13

		ATTA	CHMENTS		
ATTACHMENT ID 20230901_112003.jpg	TASK ADDED	Rev 0	EXP CNTRL COM	ATTACH TYPE Graphic	

Date/Time		01/15/2024 19:24:48		4:48 By : XXXXXX Ord	ler Key+Campus:	99525241 01/15/2024 19:24:48		
ACC	POS/WL	Line	CVN	Order ID		Order Title	Н	Page
941	1/UAB	8789	1D762	145-8789-RSHK-1296-002NC	DAMAGED RIV	ETS	N	14

		ATTACHMENTS		
ATTACHMENT ID 20230901_112007.jpg	TASK ADDED	Rev EXP CNTRL 0 COM	ATTACH TYPE Graphic	
20230901_112007.jpg	PF HN			

Date/Time		01/15/2024 19:24:48		I:48 By : XXXXXX Orde	er Key+Campus: 99525241 01/15/2024 19:24:48			
ACC	POS/WL	Line	CVN	Order ID	Order Title	HPa	ge	
941	1/UAB	8789	1D762	145-8789-RSHK-1296-002NC	DAMAGED RIVETS	N 15		LP