
NATIONAL TRANSPORTATION SAFETY BOARD **Investigative Hearing**

Alaska Airlines Flight 1282 Boeing 737-9, N704AL Left Mid Exit Door Plug Separation in Portland, OR January 5, 2024



Manufacturing Records and Human Performance - Attachment 2 NCR N1450293199 and NCO 145-8789-RGEN-RSHK-001NC

(16 Pages)

DCA24MA063

MANUFACTURING RECORDS AND HUMAN PERFORMANCE

Group Chair's Factual Report

Attachment 2 - NCR N1450293199 and NCO 145-8789-RGEN-RSHK-001NC

July 1, 2024

NCR		Rev	Rece	ord-Su	b-Re	ecord Ty	/pe		ļ	Initiated	i					Shop	p	ACC/Posi	/WL	MR
N1450293199		0	Rew	ork - Ge	enera	al			(09/07/20	123					R38F	F1	941/1/UAE	В	
MES Company		ERP	Comp	pany					Item	n ID					Item De	 escrip	otion			_
145 JI/WBJ/FBJ-R	itn		None											ļ						
							22T N1													
Model		Line	A/P	•			Multi Unit	FAA	RFF			Stock Check	Tool Check	I/R	JASIT	,	SRL	Maint Manua	IPC	ET
		08789-1							NO			NO	NO	NO			SIL	Mana	11 5	FT
737		00100-	IDIOZ] L	NONL	INC	INC	INC	INC	INO	INO	INO	INC	INC					
Job ID				Related	d Or	der					Opr	r/Step Jo	ob Qty	Dis	sc Qty					
145-8789-RSHK-1	296-002NC			145-87	89-R	RSHK-12	<u> 1</u> 96-002	NC						1						
					1,411		- In						1.5							
Physical Item Loc	ation	51	TA		WL BL Other Serial ID RMV					RMVU	D From	LN								
Supplier Code	Supplier N	Name							F	urchas	e Order	Number	Pur	chase	e Order F	Positi	ion	Receip	.pt	
7 01882	SPIRIT AE	EROSY	STEM	IS INC																
	•																<u> </u>			
Supplier Origination Date Supplier N					onco	nforma	nce Ty	pe		Purc	chase Co	ontract		Со	ontract D	Jate	A	Authorize t	to Ship	p
																	No	10		

N1450293199

Complete

Corrective	Responsible Group	Current Task

Parent NCR	Current NCR	Child NCRs	Туре	Coverag
No	Not A Child	None		

		REVISION 0 SECTIONComplete			
SIGNATURES	Task	Name	Org	Phone	Date
	Initiation	xxxxxx	XXXXXX	xxxxxx	09/07/2023 13:34

Disposition

Discrepancy

Defect No: 1

STA: 0 WL: 0 BL: 0.0

Feature: UO6 - Unauthorized Description: W41 - Work

Defect Count: 0

SUPPLIER STAMPED ALL INSPECTION POINTS STATING REMOVED AND REPLACED RIVETS PER (RIVETS) RIVETS WERE NOT REPLACED AND WAS JUST PAINTED OVER THERE was NO ACCESS ON THE OTHER SIDE of the part to replace those rivets and no removals were made. See attachments

Name: XXXXXX

Revision: O Phone: XXXXXXOrg: XXXXXX

Date: 09/07/2023 13:34

COVERAG Plan Line A/P Type ACC/Pos/WL NC Order ID **Last Order Rev Status** Interim 145-8789-RGEN-RSHK-001NC 08789-1D762 New 941/1/UAB 0001 09/07/2023 13:34 Complete Final

 Printed:
 02/13/2024 15:26:50
 by XXXXXXXX, XXXXX
 Export Control:
 COM

 NCR
 Status
 Page

 N1450293199
 Complete
 2

WORK CO

		PLAN 0001 SECTION: UNAUTHORIZED REWORK		
Line A/P	ACC/Pos/WL	Details	Last Order Rev	Status
08789 - 1D762	941/1/UAB	NC Order ld: 145-8789-RGEN-RSHK-001NC	09/07/2023 13:34	Complete
		WORK WITH:		
		WORK TYPE:		
		RELATED REVS: 0		
Oper# Task/WC0	2 Narrative			

Oper#	Task/WCC	Narrative
010		Defect No: 1 STA: 0 WL: 0 BL: 0.0 Feature: U06 - Unauthorized Description: W41 - Work Defect Count: 0 SUPPLIER STAMPED ALL INSPECTION POINTS STATING REMOVED AND REPLACED RIVETS PER LIVETS WERE NOT REPLACED AND WAS JUST PAINTED OVER.THERE was NO ACCESS ON THE OTHER SIDE of the part to replace those rivets and no removals were made. See attachments
998		Assure all foreign objects are removed from work areas common to this order.
999		FINAL BUYOFF

		CODES SECTION		
Y	NCR Item ID	Item Description	Model Description	Serial ID
1			737	

MES Company
145 JI/WBJ/FBJ-Rtn

ERP Company
NON None

Shop	ACC/Pos/WL	Job ID	Job Qty	Operation No	Line A/P	Last Revised	J
R38F1	941/1/UAB	145-8789-RSHK-1296-002NC			08789 - 1D762	09/07/2023	T

Printed: 02/	13/2024 15	:26:50 by	XXXXXXX, XXXXX	Export Control:	COM	
NCR		Status				Page
N1450293199	9	Complete				3

REFERENCE ONL

CODES SECTION (continued)

N	lodel			Line	A/P	SRL	Maint	Manua	al	IPO		FTA		C	ust Sens
7	37			08789 -	1D762									N	lo
D	efect Numbe	er:	1				Summ				1 of 1 Inter	nal			
							Company - V								
	em Qty * Def	ects Per	Item = Defe	ect Count		MBU/	RC Date	of Mfg	3	Pape	r Form ID			Paper Forn	n Type
1	* 0 = 0									1					
C	ption				Module					Pr	oduct TBS	F	Proces	s TBS	Shop ID
															NO
STA WL						BL			Other					Removed	From Line
0 0						0.0									
Feature Description								Process Sub-Process							
U06 - Unauthorized W41 - Work															
<u>J</u>	ocation			Sub-	Location		Component					Sub-	Componen	t	
)															
Α	ir Transport	Associa	tion Code	'	Grief						Defect Unio	que 1	Defe	t Unique 2	Defect Unique
)															
						CAU	SE - Where D	efect	Was Pro	duce	k				
D	efect Supplic	er					Defect Item	ID				MBU/RC	Re	peat Failur	e I/R Failure
7	01882 - SPIR	IT AERO	SYSTEMS I	NC									NC)	NO
R	aw Material I	ltem			Option				Module					Date of I	Manufacturing
					•										•
N	lachine ID	Shop	Def	fect Job II	 D				Se	elf Ins	pection And	l Accepta	ance		
R38F1 145-8789-RSHK-1296-002NC												•			
Α	CC/Pos/WL		Operation				JOM		Р	roduc	t TBS			Process 1	rbs
	41/1/UAB														
_	, ,, ,, ,,														

NCR

N1450293199

Status

Complete

Page

PRODUCTION

CODES SECTION (continued)

Feature		Description	Process		Sub-Process	
U06 - Unau	thorized	W41 - Work				
Summary	Disposition			Defect Unique 1	Defect Unique 2	Defect Unique 3
		RESOLU	JTION			ı
CAR	Cause Group:	S11 - SM&P Supplier Manufacturing	Multi-	-Level Escapement	1	ı
	Root Cause:	U02 - Unauthorized Rework				1
	Resolution Group:		Multi-	-Level Escapement	2	
	Action Taken:					,

Printed: 02/13/2024 15	:26:50	by XXXXXXXX, XXXXX Export Control: COM		
NCR	Status		Page	
N1450293199	Complete		5	LP

NON CONFORMANCE ORDER

ACC/POS	WRK	LINE/CVN		ORI	DER ID		REV			(ORDER TI	TLE		
941/1/U	AB	8789/1D762	145-8789-RGEN-RSHK-001NC				0			UNAUTHORIZED REWORK				
PROGRAM	I	LAST REVISION	EXP I/R PROD STAT ORE			ORDE	DER STATUS REL REC			С	ORDER SUB-TYPE			
737 09/07/2023			COM	N	COMP	Co	mplete	ed	145-	8789-RSHK-1	296-002N	C RGEN		
NCR			JOB/	JOB/SERIAL COVERAGE					DISPOSITION TYPE			NCM REVISION		
N145029	N1450293199									FINAL				
Company				Ar	ea			Su	ıb-Area			Queue ID		
1	145-JI/WBJ/FBJ-Rtn													
	STA		WL						BL		Other			



Order Id:

145-8789-RGEN-RSHK-001NC

OPERATION SECTION

OPERATIONS WITHOUT AN "*" IN THE OPERATION COLUMN MAY BE WORKED IN ANY ORDER.

))o _l	per	Step	Narrative	Links	Exceptions	Shop Acceptance	Quality Acceptance
100)		Defect No: 1 STA: 0 WL: 0 BL: 0.0 Feature: U06 - Unauthorized Description: W41 - Work Defect Count: 0 SUPPLIER STAMPED ALL INSPECTION POINTS STATING REMOVED AND REPLACED RIVETS PER WERE NOT REPLACED AND WAS JUST PAINTED OVER. THERE was NO ACCESS ON THE OTHER SIDE of the part to replace those rivets and no removals were made. See attachments APPLY SUPPLIER ACCEPTANCE XXXXXX 09/10/2023 09: 11 SHOULD HAVE BEEN STAMPED IN THIS MANNER.	No	No	XXXXXX 09/19/2023 Supl Accpt	XXXXXX 09/19/2023 Sup Q Acpt

Date/	Time	01/10	/2024 09:45	5:50 By: XXXXXXXXX O	der K	ey+Campus: 99605292 01/10/2024 09:45:50 ECV	/ :	COM
ACC	POS/WL	Line	CVN	Order ID	Rev	Order Title	Н	Page
941	1/UAB	8789	1D762	145-8789-RGEN-RSHK-001NC	0	UNAUTHORIZED REWORK	N	1

OPERATION SECTION

		UPERATION SEC	TION	1	1	
Oper	Step	Narrative	Links	Exceptions	Shop Acceptance	Quality Acceptance
10	10	NOTED RIVET BUCKTAIL DAMAGE IS ACCEPTABLE AS IS PER BAC5004-1 SECTION 11.2.2(C)	No	No	·	·
		APPLY SUPPLIER QUALITY ACCEPTANCE XXXXXX 09/10/2023 09: 35 REMOVE SUPPLIER QUALITY ACCEPTANCE XXXXXX 09/11/2023 07: 20 Damaged rivets are not acceptable and need to be removed and replaced per talks about damaged rivet heads and it's a different discrepancy painting rivets and saying that it was removed and replaced is not acceptable				
		REMOVE SUPPLIER ACCEPTANCE XXXXXX 09/11/2023 07: 21 Damaged rivets are not acceptable and need to be removed and replaced per talks about damaged rivet heads and it's a different discrepancy painting rivets and saying that it was removed and replaced is not acceptable				
		APPLY SUPPLIER ACCEPTANCE XXXXXX 09/19/2023 15:06 Rivets have been removed and replaced per rework accomplished on NCR: N1450292531				L
		APPLY SUPPLIER QUALITY ACCEPTANCE XXXXXXX 09/19/2023 15:13 in concurrence with mechanic. Rivets have been removed and replaced per rework accomplished on NCR: N1450292531				
998	10	Assure all foreign objects are removed from work areas common to this order.	No	No	XXXXXX 09/19/2023 Supl Accpt	xxxxxx
		APPLY SUPPLIER ACCEPTANCE XXXXXX 09/10/2023 09: 11 REMOVE SUPPLIER ACCEPTANCE XXXXXX 09/11/2023 07: 17 Damaged rivets are not acceptable and need to be removed and replaced per				
		APPLY SUPPLIER ACCEPTANCE XXXXXXX 09/19/2023 15:07				
Date/	Time	01/10/2024 09:45:50 By: XXXXXXXXXX Order Key+0	Campus:	99605292 01/10/2024	4 09:45:50	ECV: COM

Date/ i	ime	01/10/	2024 09.45	0.50 By . AAAAAAAAA	idei K	ey+Campus. 99605292 01/10/2024 09.45.50	CV.	COM
ACC	POS/WL	Line	CVN	Order ID	Rev	Order Title	Н	Page
941	1/UAB	8789	1D762	145-8789-RGEN-RSHK-001NC	0	UNAUTHORIZED REWORK	N	2

OPERATION SECTION

	Narrative	Links	Exceptions	Shop Acceptance	Quality Acceptance
10		No	No		
10	Final Acceptance APPLY FINAL SUPPLIER ACCEPTANCE XXXXXX 09/10/2023 09: 11 APPLY FINAL QUALITY ACCEPTANCE	No	No	XXXXXX 09/19/2023 Final Supl	XXXXXX 09/19/2023
	XXXXXX 09/10/2023 15:19 REMOVE FINAL QUALITY ACCEPTANCE XXXXXX 09/11/2023 07:16 Damaged rivets are not acceptable and need to be removed and replaced per				Final QA
	REMOVE FINAL SUPPLIER ACCEPTANCE XXXXXX 09/11/2023 07:17 Damaged rivets are not acceptable and need to be removed and replaced per				
	APPLY FINAL SUPPLIER ACCEPTANCE XXXXXX 09/19/2023 15:07 Rivets removed and replaced, now are per requirements				
	APPLY FINAL QUALITY ACCEPTANCE XXXXXX 09/19/2023 18:11 Final quality acceptance per All prior inspection and work performed by supplier.				
	10	Final Acceptance APPLY FINAL SUPPLIER ACCEPTANCE XXXXXX 09/10/2023 09:11 APPLY FINAL QUALITY ACCEPTANCE XXXXXX 09/10/2023 15:19 REMOVE FINAL QUALITY ACCEPTANCE XXXXXX 09/11/2023 07:16 Damaged rivets are not acceptable and need to be removed and replaced per REMOVE FINAL SUPPLIER ACCEPTANCE XXXXXX 09/11/2023 07:17 Damaged rivets are not acceptable and need to be removed and replaced per APPLY FINAL SUPPLIER ACCEPTANCE XXXXXX 09/19/2023 15:07 Rivets removed and replaced, now are per requirements APPLY FINAL QUALITY ACCEPTANCE XXXXXX 09/19/2023 18:11 Final quality acceptance per . All prior inspection and work performed by	Final Acceptance APPLY FINAL SUPPLIER ACCEPTANCE XXXXXX 09/10/2023 09: 11 APPLY FINAL QUALITY ACCEPTANCE XXXXXX 09/10/2023 15: 19 REMOVE FINAL QUALITY ACCEPTANCE XXXXXX 09/11/2023 07: 16 Damaged rivets are not acceptable and need to be removed and replaced per REMOVE FINAL SUPPLIER ACCEPTANCE XXXXXX 09/11/2023 07: 17 Damaged rivets are not acceptable and need to be removed and replaced per APPLY FINAL SUPPLIER ACCEPTANCE XXXXXX 09/19/2023 15: 07 Rivets removed and replaced, now are per requirements APPLY FINAL QUALITY ACCEPTANCE XXXXXX 09/19/2023 18: 11 Final quality acceptance per All prior inspection and work performed by	10 Final Acceptance No No No No APPLY FINAL SUPPLIER ACCEPTANCE XXXXXX 09/10/2023 09:11 APPLY FINAL QUALITY ACCEPTANCE XXXXXX 09/10/2023 15:19 REMOVE FINAL QUALITY ACCEPTANCE XXXXXX 09/11/2023 07:16 Damaged rivets are not acceptable and need to be removed and replaced per REMOVE FINAL SUPPLIER ACCEPTANCE XXXXXX 09/11/2023 07:17 Damaged rivets are not acceptable and need to be removed and replaced per APPLY FINAL SUPPLIER ACCEPTANCE XXXXXX 09/19/2023 15:07 Rivets removed and replaced, now are per requirements APPLY FINAL QUALITY ACCEPTANCE XXXXXX 09/19/2023 18:11 Final quality acceptance per AII prior inspection and work performed by	Step Narrative Links Exceptions Acceptance


Date/	Time	01/10/2024 09:45:50 By : XXXXXXXXXX		i:50 By: XXXXXXXXX	Order K	ECV:	СОМ	
ACC	POS/WL	Line	CVN	Order ID	Re	Order Title	Н	Page
941	1/UAB	8789	1D762	145-8789-RGEN-RSHK-001NC	0	UNAUTHORIZED REWORK	N	3

APPLY FINAL OUALITY ACCEPTANCE
XXXXXX 09/19/2023 18: 11
Final quality acceptance per
XXXXX 09/19/2023 18: 11
Final quality acceptance per
XXXXXX 09/19/2023 18: 11
Final quality acceptance per
XXXXX 09/19/2023 18: 11
Final quality acceptance per
XXXXXX 09/19/2023 18: 11
Final quality acceptance per
XXXXXX 09/19/2023 18: 10/19/2024 18: 10/19/


		ATTA	CHMENTS		
ATTACHMENT ID	TASK ADDED	Rev	EXP CNTRL	ATTACH TYPE	ATTACHMENT AUTHOR
1.jpg		0	СОМ	Graphic	




Date/	Time	01/10	/2024 09:45	5:50 By: XXXXXXXXXX Orde	er Key+Campus: 99605292 01/10/2024 09:45:50		
ACC	POS/WL	Line	CVN	Order ID	Order Title	Н	Page
941	1/UAB	8789	1D762	145-8789-RGEN-RSHK-001NC	UNAUTHORIZED REWORK	N	4







Date/	Time	01/10	/2024 09:45	5:50 By: XXXXXXXXXX Orde	er Key+Campus: 99605292 01/10/2024 09:45:50		
ACC	POS/WL	Line	CVN	Order ID	Order Title	HF	Page
941	1/UAB	8789	1D762	145-8789-RGEN-RSHK-001NC	UNAUTHORIZED REWORK	N:	7
341	I/OAB	0703	10702	145-0703-NGEN-NOTIN-00114C	ONAO ITIONIZED NEWORK	IN	



Date/	Time	01/10	/2024 09:4	5:50 By: XXXXXXXXXX Orde	er Key+Campus: 99605292 01/10/2024 09:45:50		
ACC	POS/WL	Line	CVN	Order ID	Order Title	Н	Page
941	1/UAB	8789	1D762	145-8789-RGEN-RSHK-001NC	UNAUTHORIZED REWORK	N	8



Date/	Time	01/10	/2024 09:45	5:50 By: XXXXXXXXXX Orde	er Key+Campus: 99605292 01/10/2024 09:45:50		
ACC	POS/WL	Line	CVN	Order ID	Order Title	H	Page
941	1/UAB	8789	1D762	145-8789-RGEN-RSHK-001NC	UNAUTHORIZED REWORK	N	9



Date/Time		01/10/2024 09:45:5		5:50 By: XXXXXXXXXX Orde	er Key+Campus: 99605292 01/10/2024 09:45:50					
	ACC	POS/WL	Line	CVN	Order ID	Order Title	Н	Pag	е	
	941	1/UAB	8789	1D762	145-8789-RGEN-RSHK-001NC	UNAUTHORIZED REWORK	N	10	LP	