

INSPECTION REPORT

Inspector's Name Hirsch, Robert J.		Inspector's Signature			Inspector's ID No. [REDACTED]	Report No. 144	Date yy mm dd 2017 08 03						
Railroad/Company Name & Address CSX TRANSPORTATION Meyersdale PA				R/C R	Division SYSTEM	RR/Co. Representative (Receipt Acknowledged) Name John Porter Title Roadmaster Email Signature _____							
From: City HYNDMAN		Codes 3850	Destination City & County			Codes	From Latitude						
State PA		42	City HYNDMAN			3850	From Longitude						
County BEDFORD		C009	County BEDFORD			C009	To Latitude						
Mile Post: From BF0194.30 To BF0193.50				Inspection Point			To Longitude						
Activity Code:	MTW	RWP											
Units:	2	1											
Sub Units:	0	2											
Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
1										N	N	0	
Description - [** Comment to Railroad/Company **] FRA, NTSB, PAPUC, AND CSX REPRESENTATIVES RECORDED TRACK NOTES AND WALKED TRACK WESTAND EAST OF WHERE THE TRAIN DERAILED FROM MP BF 194.3 TO MP BF 193.5. THERE WERE NO DEFECTS NOTED PER UNITS INSPECTED.													
Violation Recommended				<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		Latitude:			Longitude:				
Written Notification to FRA of Remedial Action is:				<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional		Railroad Action Code		Date(mm/dd/yyyy):		[REDACTED]		Comments on back?	

Source Code A	File Number	ID's of Accompanying Inspector(s) [REDACTED] [REDACTED]
------------------	-------------	--