

Attention: One or more violations have been cited on this report.

DEPARTMENT OF TRANSPORTATION
FEDERAL RAILROAD ADMINISTRATION (FRA)

INSPECTION REPORT

OMB Approval No.: 2130-0509

Inspector's Name Keltz, Randy			Inspector's Signature				Inspector's ID No. 47943	Report No. 5	Date yy mm dd 2023 02 24				
Railroad/Company Name & Address GATX 233 S. Wacker Drive Chicago IL 60606					R/C C	Division	RR/Co. Representative (Receipt Acknowledged) Name Terry Heidkamp Title Vice President, Government and Email [REDACTED] Signature _____						
From: City CHICAGO		Codes 1670	Destination City & County				Codes	From Latitude					
State IL		17	City					From Longitude					
County COOK		C031	County					To Latitude					
Mile Post: From To			Inspection Point EAST PALESTINE, OH					To Longitude					
Activity Code:	ORI												
Units:	1												
Sub Units:	1												
Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
1				180	0517	A				N	N	1	ORI
Description EACH OWNER OF A SPECIFICATION TANK CAR MUST RETAIN THE CERTIFICATE OF CONSTRUCTION (AAR FORM 4-2) AND RELATED PAPERS CERTIFYING THAT THE MANUFACTURE OF THE SPECIFICATION TANK CAR IDENTIFIED IN THE DOCUMENTS IS IN ACCORDANCE WITH THE APPLICABLE SPECIFICATION. Found one DOT105A300W specification tank car involved in the East Palestine, OH trail derailment that did not match it's design approval. GATX 95098.													
Seal Applied			Seal Removed			Hazard Class			UN/NA ID				
Violation Recommended <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No						Latitude:			Longitude:				
Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional						Railroad Action Code			Date(mm/dd/yyyy):			Comments on back?	
Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
2										N	N	0	
Description - [** Comment to Railroad/Company **] Be advised by receipt of this report that the FRA is recommending violations for items # 1 of this report.													
Seal Applied			Seal Removed			Hazard Class			UN/NA ID				
Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No						Latitude:			Longitude:				
Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional						Railroad Action Code			Date(mm/dd/yyyy):			Comments on back?	

Attention: One or more violations have been cited on this report.

DEPARTMENT OF TRANSPORTATION
FEDERAL RAILROAD ADMINISTRATION (FRA)

INSPECTION REPORT

OMB Approval No.: 2130-0509

Inspector's Name Keltz, Randy			Inspector's Signature				Inspector's ID No. 47943	Report No. 4	Date yy mm dd 2023 02 24				
Railroad/Company Name & Address OXY VINYL 14555 Dallas PKWY. Dallas TX 75254					R/C C	Division	RR/Co. Representative (Receipt Acknowledged) Name Chris Rodrigues Title MANAGER TRANSPORTATION COMPLIA Email [REDACTED] Signature _____						
From: City DALLAS		Codes 1730	Destination City & County				Codes	From Latitude					
State TX		48	City					From Longitude					
County COLLIN		C085	County					To Latitude					
Mile Post: From To			Inspection Point EAST PALESTINE, OH				To Longitude						
Activity Code:	ORI												
Units:	3												
Sub Units:	3												
Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
1				180	0517	A				N	N	1	ORI
Description EACH OWNER OF A SPECIFICATION TANK CAR MUST RETAIN THE CERTIFICATE OF CONSTRUCTION (AAR FORM 4-2) AND RELATED PAPERS CERTIFYING THAT THE MANUFACTURE OF THE SPECIFICATION TANK CAR IDENTIFIED IN THE DOCUMENTS IS IN ACCORDANCE WITH THE APPLICABLE SPECIFICATION. Found three DOT105A300W specification tanks cars involved in the East Palestine, OH trail derailment that did not match their design approval. OCPX 80179, 80235, 80370.													
Seal Applied		Seal Removed			Hazard Class			UN/NA ID					
Violation Recommended <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No				Latitude:				Longitude:					
Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional				Railroad Action Code		Date(mm/dd/yyyy):		Comments on back?					
Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
2										N	N	0	
Description - [** Comment to Railroad/Company **] Be advised by receipt of this report that the FRA is recommending violations for items # 1 of this report.													
Seal Applied		Seal Removed			Hazard Class			UN/NA ID					
Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No				Latitude:				Longitude:					
Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional				Railroad Action Code		Date(mm/dd/yyyy):		Comments on back?					

Attention: One or more violations have been cited on this report.

DEPARTMENT OF TRANSPORTATION
FEDERAL RAILROAD ADMINISTRATION (FRA)

INSPECTION REPORT

OMB Approval No.: 2130-0509

Inspector's Name Keltz, Randy			Inspector's Signature			Inspector's ID No. 47943	Report No. 3	Date yy mm dd 2023 02 24						
Railroad/Company Name & Address OXY VINYL 14555 Dallas PKWY. Dallas TX 75254					R/C C	Division	RR/Co. Representative (Receipt Acknowledged) Name Chris Rodrigues Title MANAGER TRANSPORTATION COMPLIA Email [REDACTED] Signature _____							
From: City DALLAS		Codes 1730	Destination City & County				Codes	From Latitude						
State TX		48	City					From Longitude						
County COLLIN		C085	County					To Latitude						
Mile Post: From To			Inspection Point EAST PALESTINE, OH					To Longitude						
Activity Code:	TCT													
Units:	5													
Sub Units:	0													
Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code	
1				173	0031	A1				N	N	1	TCT	
Description SPECIFICATIONS AND PACKAGING REQUIREMENTS FOR THIS SUBCHAPTER. Found five DOT105A300W specification tanks cars involved in the East Palestine, OH trail derailment that were offered into transportation by Oxy Vinyls and did not match their design approval. OCPX 80179, 80235, 80370, GATX 95098 and TILX 402025.														
Seal Applied		Seal Removed			Hazard Class			UN/NA ID						
Violation Recommended <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No					Latitude:				Longitude:					
Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional					Railroad Action Code			Date(mm/dd/yyyy):		Comments on back?				
Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code	
2										N	N	0		
Description - [** Comment to Railroad/Company **] Be advised by receipt of this report that the FRA is recommending violations for items # 1 of this report.														
Seal Applied		Seal Removed			Hazard Class			UN/NA ID						
Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No					Latitude:				Longitude:					
Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional					Railroad Action Code			Date(mm/dd/yyyy):		Comments on back?				

Attention: One or more violations have been cited on this report.

DEPARTMENT OF TRANSPORTATION
FEDERAL RAILROAD ADMINISTRATION (FRA)

INSPECTION REPORT

OMB Approval No.: 2130-0509

Inspector's Name Keltz, Randy			Inspector's Signature				Inspector's ID No. 47943	Report No. 6	Date yy mm dd 2023 02 24				
Railroad/Company Name & Address TRINITY RAIL 14221 N Dallas Pkwy Suite 1100 Dallas TX 75254					R/C C	Division	RR/Co. Representative (Receipt Acknowledged) Name Chase Greene Title VP, Fleet Maintenance Email [REDACTED] Signature _____						
From: City DALLAS		Codes 1730	Destination City & County				Codes	From Latitude					
State TX		48	City					From Longitude					
County COLLIN		C085	County					To Latitude					
Mile Post: From To			Inspection Point EAST PALESTINE, OH				To Longitude						
Activity Code:	ORI												
Units:	1												
Sub Units:	1												
Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
1				180	0517	A				N	N	1	ORI
Description EACH OWNER OF A SPECIFICATION TANK CAR MUST RETAIN THE CERTIFICATE OF CONSTRUCTION (AAR FORM 4-2) AND RELATED PAPERS CERTIFYING THAT THE MANUFACTURE OF THE SPECIFICATION TANK CAR IDENTIFIED IN THE DOCUMENTS IS IN ACCORDANCE WITH THE APPLICABLE SPECIFICATION. Found one DOT105A300W specification tank car involved in the East Palestine, OH trail derailment that did not match it's design approval. TILX 402025.													
Seal Applied			Seal Removed			Hazard Class			UN/NA ID				
Violation Recommended <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No						Latitude:			Longitude:				
Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional						Railroad Action Code			Date(mm/dd/yyyy):		Comments on back?		
Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
2										N	N	0	
Description - [** Comment to Railroad/Company **] Be advised by receipt of this report that the FRA is recommending violations for items # 1 of this report.													
Seal Applied			Seal Removed			Hazard Class			UN/NA ID				
Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No						Latitude:			Longitude:				
Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional						Railroad Action Code			Date(mm/dd/yyyy):		Comments on back?		