

## Thursday, Feb. 22, 2018-3515 Durango Dr. (Structure Fire Reported)

- **10:21 a.m.**-Fire Reported (Spanish Translation-reported by individual residing in home. Caller reported that his kitchen was on fire and that he had exited the structure)
- 10:38-(Electric Utility requested to respond to the scene)  
  
10:27-10:29 Engine 35, Truck 43 and Battalion Chief 7 arrive on location. Engine 35 officer size up includes that there was fire showing on the Alpha (front) side of the house.
- 10:58 Primary search complete (Initial search for victims)
- 11:00 Secondary search complete (more thorough search for victims)
- 11:40 Gas utility notified to respond to the scene
- 12:02 Fire declared under control (Out taps)

## Incident Detail Report

Data Source: **Data Warehouse**  
 Incident Status: **Closed**  
 Incident number: **2018048587**  
 Case Numbers:  
 Incident Date: **2/22/2018 10:21:32**  
 Report Generated: **2/27/2018 15:15:21**

**Incident Information**

<b>Incident Type:</b>	STRUCTURE FIRE A(WORKING)	<b>Alarm Level:</b>	1
<b>Priority:</b>	Emergency	<b>Problem:</b>	99 - Structure Fire Working
<b>Determinant:</b>		<b>Agency:</b>	Fire
<b>Base Response#:</b>	02222018-0066173	<b>Jurisdiction:</b>	Dallas Fire
<b>Confirmation#:</b>		<b>Division:</b>	Dallas Fire
<b>Taken By:</b>	CALDWELL, JOHN L	<b>Battalion:</b>	Dallas Fire
<b>Response Area:</b>	DAL	<b>Response Plan:</b>	*DFR-A BOX(WORKING)
<b>Disposition:</b>		<b>Command Ch:</b>	
<b>Cancel Reason:</b>		<b>Primary TAC:</b>	
<b>Incident Status:</b>	Closed	<b>Secondary TAC:</b>	
<b>Certification:</b>		<b>Delay Reason (if any):</b>	
<b>Longitude:</b>	96861065	<b>Latitude:</b>	32867277

**Incident Location**

<b>Location Name:</b>	
<b>Address:</b>	3515 Durango Dr
<b>Apartment:</b>	
<b>Building:</b>	
<b>City, State, Zip:</b>	Dallas TX 75220
<b>County:</b>	DALLAS
<b>Location Type:</b>	
<b>Cross Street:</b>	LARGA DR/EL CENTRO DR
<b>Map Reference:</b>	23-V

**Call Receipt**

<b>Caller Name:</b>	T-MOBILE
<b>Method Received:</b>	Telephone
<b>Caller Type:</b>	
<b>Call Back Phone:</b>	(214) 511-6809
<b>Caller Location:</b>	WIRELESS

**Time Stamps**

Description	Date	Time	User	Elapsed Times	Description	Time
Phone Pickup	2/22/2018	10:21:32				
1st Key Stroke	2/22/2018	10:21:37			Received to In Queue	00:00:28
In Waiting Queue	2/22/2018	10:22:00			Call Taking	00:01:39
Call Taking Complete	2/22/2018	10:23:11	CALDWELL, JOHN L		In Queue to 1st Assign	00:00:02
1st Unit Assigned	2/22/2018	10:22:02			Call Received to 1st Assign	00:00:30
1st Unit Enroute	2/22/2018	10:22:08			Assigned to 1st Enroute	00:00:06.4
1st Unit Arrived	2/22/2018	10:25:40			Enroute to 1st Arrived	00:03:32.2
Closed	2/22/2018	13:17:39	Mobile2		Incident Duration	02:56:07


**Resources Assigned**

Unit	Flag	Assigned	Disposition	Enroute	Staged	Arrived	Delay	Complete	Odm.	Odm.	Cancel Reason
							At Patient Avail		Enroute	Arrived	
EN35	Y	10:22:02		10:22:53		10:26:34		13:17:39			
EN43	N	10:22:02		10:22:08		10:27:09		13:17:33			
EN30	N	10:22:02		10:22:37		10:29:23		13:07:06			
TR43	N	10:22:02		10:22:46		10:25:40		13:14:14			
TR41	N	10:22:02		10:23:17		10:30:12		13:14:43			
BC07	N	10:22:02		10:23:57		10:27:27		12:32:32			
BC06	N	10:22:02		10:22:10		10:34:20		11:25:35			
RE43	N	10:29:04		10:29:09		10:29:12		12:12:45			
685	N	10:31:37		10:31:58		10:47:29		11:45:23			
684	N	10:31:43		10:32:02		10:47:12		11:36:07			
EN41	N	10:42:37		10:44:03		10:51:22		13:14:25			
RE30	N	10:45:27		10:46:39		10:51:54		11:54:24			
821	N	10:57:02		10:57:08		11:17:16		11:53:27			

**Personnel Assigned**

Unit	Name
------	------

EN35  
 EN43  
 EN30  
 TR43  
 TR41  
 BC07  
 BC06  
 RE43  
 684  
 EN41  
 RE30



**Pre-Scheduled Information**

**No Pre-Scheduled Information**

**Transports**

Unit	Location/Address	City	Patient	Mode	Protocol	Mileage	Depart	Arrived	Complete
				Priority 3	Code 1	Start/End/Total			
RE43	PARKLAND HOSP/5200 HARRY HINES BLVD	Dallas				0.0/ 0.0/ 0.0	11:00:01	11:10:58	12:12:45

**Transport Legs**

**No Transports Information**

Comments

Date	Time	User	Type	Conf.	Comments
2/22/2018	10:21:32	SYS	Response		[1] No Lat/lon received.
2/22/2018	10:22:05	PAGINGSERICE	Response		[2] Paging Groups Notified:1-11 (98) GROUP
2/22/2018	10:22:20	012443	Response		[3] KITCHEN ON FIRE
2/22/2018	10:28:54	PAGINGSERICE	Response		[4] Paging Groups Notified:1-11 (99) GROUP
2/22/2018	10:28:58	101117	Response		[5] Multi-Agency Police Incident #: 18-0321632
2/22/2018	10:28:59	101117	Response		[6] [Page] Problem changed from 98 - Structure Fire Reported to 99 - Structure Fire Working [Shared]
2/22/2018	10:29:06	PAGINGSERICE	Response		[7] Paging Groups Notified:1-11 (99) GROUP [Shared]
2/22/2018	10:38:54	033101	Response		[8] ONCOR TICKET: T3483153 [Shared]
2/22/2018	10:42:39	PAGINGSERICE	Response		[9] Paging Groups Notified:1-11 (99) GROUP [Shared]
2/22/2018	10:45:28	PAGINGSERICE	Response		[10] Paging Groups Notified:1-11 (99) GROUP [Shared]
2/22/2018	11:10:35	Vilalba, Roberto J	Response		[11] BWC. [Shared]
2/22/2018	11:11:05	Harris, James A	Response		[12] NO BWC-4920 [Shared]
2/22/2018	11:35:07	033101	Response		[13] RED CROSS HAS 5 MIN ETA [Shared]
2/22/2018	11:35:33	Clayton, Thomas J	Response		[14] NO BWC BY 6153 [Shared]
2/22/2018	11:40:43	055396	Response		[15] red croos contact information: grisldai portillo 972 900 5965 [Shared]

Address Changes

No Address Changes

Priority Changes

No Priority Changes

Alarm Level Changes

Date	Time	User	Change to Alarm
2/22/2018	10:22:02	AD	1
2/22/2018	10:29:04	WHO	1
2/22/2018	10:42:37	WHO	1
2/22/2018	10:45:27	WHO	1

Activity Log

Date	Time	Radio	Activity	Location	Log Entry	User
2/22/2018	10:21:45		Sector Change		From Sector No Sector to Sector 660	012443
2/22/2018	10:22:00		Incident in Waiting Queue			
2/22/2018	10:22:00		ANI/ALI Statistics		INT Insert:Feb 22 2018 10:21:32 / INT SendNP:Feb 22 2018 10:21:31 / WS RecvNP:Feb 22 2018 10:21:32 / WS Process:Feb 22 2018 10:22:00	012443
2/22/2018	10:22:00		Incident Priority Change		Incident priority changed from <none> to Emergency	012443
2/22/2018	10:22:00		Waiting Pending Incident Time Warning		Waiting Pending Incident Time Warning timer expired	
2/22/2018	10:22:02	EN35	Assgn	3515 Durango Dr	Response Number (02222018-0066173)	AUTODISPATCH
2/22/2018	10:22:02	TR41	Assgn	3515 Durango Dr	Response Number (02222018-0066177)	AUTODISPATCH
2/22/2018	10:22:02	EN43	Assgn	3515 Durango Dr	Response Number (02222018-0066174)	AUTODISPATCH
2/22/2018	10:22:02	TR43	Assgn	3515 Durango Dr	Response Number (02222018-0066176)	AUTODISPATCH
2/22/2018	10:22:02	EN30	Assgn	3515 Durango Dr	Response Number (02222018-0066175)	AUTODISPATCH
2/22/2018	10:22:02	BC06	Assgn	3515 Durango Dr	Response Number (02222018-0066179)	AUTODISPATCH
2/22/2018	10:22:02	BC07	Assgn	3515 Durango Dr	Response Number (02222018-0066178)	AUTODISPATCH
2/22/2018	10:22:02		Incident Timer Clear		Incident Timer Cleared	
2/22/2018	10:22:03		Automatic Dispatch		Automatic Dispatch Successful for DYNAMIC- *DFR-A BOX(REPORTED) - Alarm level 1	AUTODISPATCH
2/22/2018	10:22:08	EN43	Enr	3515 Durango Dr	Responding From = WALNUT HILL LNUNNAMED STREET	EN43
2/22/2018	10:22:10	BC06	Enr	3515 Durango Dr	Responding From = N BECKLEY AVEICLOSED DALLAS FT WORTH SERV N	BC06
2/22/2018	10:22:37	EN30	Enr	3515 Durango Dr	Responding From = ZODIAC LNDAIRY MILK LN	EN30
2/22/2018	10:22:42	BC06	Route Deviation	N BECKLEY AVEYORKTOWN ST	Unit BC06 deviated from original driving directions route	BC06
2/22/2018	10:22:46	TR43	Enr	3515 Durango Dr	Responding From = LOMBARDY LNABERNATHY AVE	TR43
2/22/2018	10:22:47		Read Comment		Comment for Incident 197 was Marked as Read.	012443
2/22/2018	10:22:53	EN35	Enr	3515 Durango Dr	Responding From = WALNUT HILL LNUNNAMED STREET	EN35
2/22/2018	10:23:00		Remove Waiting Pending Incident Warning		Removing Waiting Pending Incident Time Warning timer expired	
2/22/2018	10:23:11		UserAction		User clicked Ext/Save	012443
2/22/2018	10:23:17	TR41	Enr	3515 Durango Dr	Responding From = BERKSHIRE LNDOUGLAS AVE	TR41
2/22/2018	10:23:57	BC07	Enr	3515 Durango Dr	Responding From = WALNUT HILL LNUNNAMED STREET	BC07
2/22/2018	10:25:40	TR43	At Scene	3515 Durango Dr		TR43
2/22/2018	10:26:34	EN35	At Scene	3515 Durango Dr		EN35
2/22/2018	10:27:09	EN43	At Scene	3515 Durango Dr		EN43
2/22/2018	10:27:27	BC07	At Scene	3515 Durango Dr		BC07
2/22/2018	10:28:54		MultiAgencyResponse		A Change in the Problem from 98 - Structure Fire Reported to 99 - Structure Fire Working has resulted in the recommendation of the following additional agencies Police Generated Inc: Police Inc#18-0321632	101117
2/22/2018	10:28:58		MultiAgencyResponse		The following additional Agencies have been sent because of a Problem/Nature change:Police	101117
2/22/2018	10:28:59		Problem Nature		ID # 30955197 A Change in the Problem Nature change from 98 - Structure Fire	101117

2/22/2018	10:28:59		Read Comment		Reported to 99 - Structure Fire Working Comment for Incident 197 was Marked as Read.	100758
2/22/2018	10:29:01		Reconfigure Response		The following unit(s) is (are) recommended for assignment: EN43 (00:00:04),EN35 (00:00:05),EN30 (00:00:37),TR43 (00:00:02),TR41 (00:01:23),BC07 (00:00:06),BC06 (00:07:14),RE43 (00:00:06) Incident 197 was Marked as Read. Response Number (02222018-0066185) Responding From = LARGA DR	101117
2/22/2018	10:29:01		Read Incident			
2/22/2018	10:29:04	RE43	Assgn	3515 Durango Dr		
2/22/2018	10:29:09	RE43	Enr	3515 Durango Dr		
2/22/2018	10:29:12	RE43	At Scene	3515 Durango Dr		
2/22/2018	10:29:23	EN30	At Scene	3515 Durango Dr		
2/22/2018	10:30:12	TR41	At Scene	3515 Durango Dr		
2/22/2018	10:31:37	EN35	Unit Backed up	3515 Durango Dr	Backed up with 685 - Response Priority	101117
2/22/2018	10:31:37	685	Assgn	3515 Durango Dr	Response Number (02222018-0066187)	101117
2/22/2018	10:31:43	EN35	Unit Backed up	3515 Durango Dr	Backed up with 684 - Response Priority	101117
2/22/2018	10:31:43	684	Assgn	3515 Durango Dr	Response Number (02222018-0066188)	101117
2/22/2018	10:31:58	685	Enr	3515 Durango Dr	Responding From = N CENTRAL EXPY NBWN CENTRAL ACRD NB	685
2/22/2018	10:32:02	684	Enr	3515 Durango Dr	Responding From = N CENTRAL ACRD NBWOODALL RODGERS RAMP WB	684
2/22/2018	10:34:20	BC06	At Scene	3515 Durango Dr		BC06
2/22/2018	10:36:28		Read Comment		Comment for Incident 197 was Marked as Read.	033101
2/22/2018	10:38:59		UserAction		User clicked Exit/Save	033101
2/22/2018	10:42:30		UserAction		User selected Add Additional Resources from PowerLine	101117
2/22/2018	10:42:33		VisiCAD Recommendation		EN41: 00:07:37, EN02: 00:07:37, EN01: 00:10:52, EN24: 00:11:24, EN55: 00:11:27, User Accepted EN41	101117
2/22/2018	10:42:35		UserAction		The following unit(s) is (are) recommended for assignment: EN41 (00:07:37)	101117
2/22/2018	10:42:35		Add Resources		Response Number (02222018-0066207)	101117
2/22/2018	10:42:37	EN41	Assgn	3515 Durango Dr	Responding From = NORTHAVEN	EN41
2/22/2018	10:44:03	EN41	Enr	3515 Durango Dr	RDWIDWAY RD	
2/22/2018	10:45:16		UserAction		User selected Add Additional Resources from PowerLine	101117
2/22/2018	10:45:18		VisiCAD Recommendation		RE30: 00:06:57, RE01: 00:12:09, RE20: 00:12:55, RE18: 00:13:35, RE04: 00:14:02, User Accepted RE30	101117
2/22/2018	10:45:20		UserAction		The following unit(s) is (are) recommended for assignment: RE30 (00:06:57)	101117
2/22/2018	10:45:20		Add Resources		RE01: 00:12:09, RE20: 00:12:55, RE18: 00:13:35, RE04: 00:14:02, RE45: 00:14:35, Response Number (02222018-0066208)	101117
2/22/2018	10:45:23		VisiCAD Recommendation		Responding From = ZODIAC LNDAIRY MILK LN	RE30
2/22/2018	10:45:27	RE30	Assgn	3515 Durango Dr		
2/22/2018	10:46:39	RE30	Enr	3515 Durango Dr		
2/22/2018	10:47:12	684	At Scene	3515 Durango Dr		684
2/22/2018	10:47:29	685	At Scene	3515 Durango Dr		685
2/22/2018	10:51:22	EN41	At Scene	3515 Durango Dr		EN41
2/22/2018	10:51:54	RE30	At Scene	3515 Durango Dr		RE30
2/22/2018	10:56:56		Read Comment		Comment for Incident 197 was Marked as Read.	033101
2/22/2018	10:57:01		UserAction		User clicked Exit/Save	033101
2/22/2018	10:57:02	EN35	Unit Backed up	3515 Durango Dr	Backed up with 821 - Response Priority	101117
2/22/2018	10:57:02	821	Assgn	3515 Durango Dr	Response Number (02222018-0066223)	101117
2/22/2018	10:57:08	821	Enr	3515 Durango Dr	Responding From = STA 18	101117
2/22/2018	10:57:39		UserAction		User clicked Exit/Save	033101
2/22/2018	10:58:14		UserAction		User clicked Exit/Save	033101
2/22/2018	11:00:01	RE43	To Fac	5200 HARRY HINES BLVD [PARKLAND HOSP]	Transport Priority - Priority 3; Protocol - Code 1	RE43
2/22/2018	11:00:52		UserAction		User clicked Exit/Save	101117
2/22/2018	11:10:58	RE43	At Fac	5200 HARRY HINES BLVD [PARKLAND HOSP]		RE43
2/22/2018	11:17:16	821	At Scene	3515 Durango Dr		101117
2/22/2018	11:18:02		Read Comment		Comment for Incident 197 was Marked as Read.	101117
2/22/2018	11:18:46		UserAction		User clicked Exit/Save	101117
2/22/2018	11:24:05		UserAction		User clicked Exit/Save	101097
2/22/2018	11:25:35	BC06	Clear	3515 Durango Dr		BC06
2/22/2018	11:32:39		UserAction		User clicked Exit/Save	101117
2/22/2018	11:35:09		UserAction		User clicked Exit/Save	033101
2/22/2018	11:36:07	684	Clear	3515 Durango Dr		684
2/22/2018	11:38:56		Read Comment		Comment for Incident 197 was Marked as Read.	055396
2/22/2018	11:39:00		Load Times		Depart Scene Time: 11:00:01, Arrive Destination Time: 11:10:58	055396
2/22/2018	11:39:28		UserAction		User clicked Exit/Save	101117
2/22/2018	11:41:52		UserAction		User clicked Exit/Save	055396
2/22/2018	11:45:23	685	Clear	3515 Durango Dr		685
2/22/2018	11:47:10		Read Comment		Comment for Incident 197 was Marked as Read.	101117
2/22/2018	11:47:14		Load Times		Depart Scene Time: 11:00:01, Arrive Destination Time: 11:10:58	101117
2/22/2018	11:47:28		UserAction		User clicked Exit/Save	101117
2/22/2018	11:53:27	821	Clear	3515 Durango Dr		101117
2/22/2018	11:54:24	RE30	Clear	3515 Durango Dr		RE30
2/22/2018	12:02:49		UserAction		User clicked Exit/Save	101117
2/22/2018	12:10:59		Incident Late		Active incident marked as late	

2/22/2018	12:12:45	RE43	Clear	3515 Durango Dr				
2/22/2018	12:12:45		Incident Timer Clear	3515 Durango Dr				RE43
2/22/2018	12:28:18		UserAction			Incident Late Timer cleared for 2018048587		Mobile2
2/22/2018	12:32:32	BC07	Clear	3515 Durango Dr		User dicked Exit/Save		101862
2/22/2018	13:07:06	EN30	Clear	3515 Durango Dr				BC07
2/22/2018	13:14:14	TR43	Clear	3515 Durango Dr				EN30
2/22/2018	13:14:25	EN41	Clear	3515 Durango Dr				TR43
2/22/2018	13:14:43	TR41	Clear	3515 Durango Dr				EN41
2/22/2018	13:17:33	EN43	Clear	3515 Durango Dr				TR41
2/22/2018	13:17:39	EN35	Clear	3515 Durango Dr				EN43
2/22/2018	13:17:40	EN35	Response Closed	3515 Durango Dr			Response Disposition:	EN35

Edit Log

Date	Time	Field	Changed From	Changed To	Reason	Table	Workstation	User
2/22/2018	10:21:32	Address	(Blank)	WIRELESS	New Entry	Response_Master_Incident	CADDFRF284B012443	
2/22/2018	10:21:32	Call_Back_Phone		(214) 511-6809	(Response Viewer)	Response_Master_Incident	CADDFRF284B012443	
2/22/2018	10:21:43	Address	(Blank)	3515 DUR	New Entry	Response_Master_Incident	CADDFRF284B012443	
2/22/2018	10:21:45	Longitude	0	96861065	Entry Verified	Response_Master_Incident	CADDFRF284B012443	
2/22/2018	10:21:45	Latitude	0	32867277	Entry Verified	Response_Master_Incident	CADDFRF284B012443	
2/22/2018	10:21:45	City		Dallas	Updated City	Response_Master_Incident	CADDFRF284B012443	
2/22/2018	10:21:45	Address	3515 DUR	3515 DURANGO DR	Entry Verified	Response_Master_Incident	CADDFRF284B012443	
2/22/2018	10:21:45	ResponsePlanType	0	0	(Response Viewer)	Response_Master_Incident	CADDFRF284B012443	
2/22/2018	10:21:45	Response_Area		DAL	(Response Viewer)	Response_Master_Incident	CADDFRF284B012443	
2/22/2018	10:21:45	Battalion		Dallas Fire	(Response Viewer)	Response_Master_Incident	CADDFRF284B012443	
2/22/2018	10:21:45	Division		Dallas Fire	(Response Viewer)	Response_Master_Incident	CADDFRF284B012443	
2/22/2018	10:21:45	Jurisdiction		Dallas Fire	(Response Viewer)	Response_Master_Incident	CADDFRF284B012443	
2/22/2018	10:22:00	Priority_Number	0	1		Response_Master_Incident	CADDFRF284B012443	
2/22/2018	10:22:00	Priority_Description		Emergency		Response_Master_Incident	CADDFRF284B012443	
2/22/2018	10:22:00	Problem		98 - Structure Fire Reported	(Response Viewer)	Response_Master_Incident	CADDFRF284B012443	
2/22/2018	10:22:00	Pickup_Map_Info		23-V		Response_Transports	CADDFRF284B012443	
2/22/2018	10:22:00	Map_Info		23-V		Response_Master_Incident	CADDFRF284B012443	
2/22/2018	10:22:00	Caller_Building		350001	Polygon Lookup	Response_Master_Incident	CADDFRF284B012443	
2/22/2018	10:22:04	MethodOfCallRcvd		Telephone	(Response Viewer)	Response_Master_Incident	CADDFRF284B012443	
2/22/2018	10:22:47	Read Comment	False	True	(Response Viewer)	Response_Master_Incident	CADDFRF284B012443	
2/22/2018	10:28:54	Response_Plan	*DFR-A BOX (REPORTED)	*DFR-A BOX (WORKING)	USCR EN35 99 (POWERLINE WINDOW)0	Response_Master_Incident	CADDFRF283B101117	
2/22/2018	10:28:54	RespReconfigState	0	1	Response reconfigure needed	Response_Master_Incident	CADDFRF283B101117	
2/22/2018	10:28:54	Incident_Type	STRUCTURE FIRE (REPORTED)	ASTRUCTURE FIRE (WORKING)	AUSCR EN35 99 (POWERLINE WINDOW)0	Response_Master_Incident	CADDFRF283B101117	
2/22/2018	10:28:54	Problem	98 - Structure Fire Reported	99 - Structure Fire Working	USCR EN35 99 (POWERLINE WINDOW)0	Response_Master_Incident	CADDFRF283B101117	
2/22/2018	10:28:59	Read Comment	False	True	(Comment Notification Window)	Response_Master_Incident	CAD911CT364 100758	
2/22/2018	10:28:59	Read Comment	False	True	(Comment Notification Window)	Response_Master_Incident	CADDFRF284B012443	
2/22/2018	10:28:59	Read Comment	False	True	(Comment Notification Window)	Response_Master_Incident	CAD911CT367 122119	
2/22/2018	10:28:59	Read Comment	False	True	(Comment Notification Window)	Response_Master_Incident	CAD911CT355 122742	
2/22/2018	10:28:59	Read Comment	False	True	(Comment Notification Window)	Response_Master_Incident	CAD911CT311 106177	
2/22/2018	10:28:59	Read Comment	False	True	(Comment Notification Window)	Response_Master_Incident	CAD911CT339 110346	
2/22/2018	10:28:59	Read Comment	False	True	(Comment Notification Window)	Response_Master_Incident	CAD911CT346 115647	
2/22/2018	10:28:59	Read Comment	False	True	(Comment Notification Window)	Response_Master_Incident	CAD911CT312 085032	
2/22/2018	10:28:59	Read Comment	False	True	(Comment Notification Window)	Response_Master_Incident	CAD911CT342 115898	
2/22/2018	10:29:00	Read Comment	False	True	(Comment Notification Window)	Response_Master_Incident	APCAD105 DFRAPIUSER	
2/22/2018	10:29:00	Read Comment	False	True	(Comment Notification Window)	Response_Master_Incident	CADDFRF287B101862	
2/22/2018	10:29:00	Read Comment	False	True	(Comment Notification Window)	Response_Master_Incident	CAD911CT357 120522	

2/22/2018	10:29:00	Read Comment	False	True	Window) (Comment Notification Window)	Response_Master_Incident CAD911CT356 121758
2/22/2018	10:29:00	Read Comment	False	True	(Comment Notification Window)	Response_Master_Incident CADDFRF280B033101
2/22/2018	10:29:00	Read Comment	False	True	(Comment Notification Window)	Response_Master_Incident CADDFRF288B110568
2/22/2018	10:29:00	Read Comment	False	True	(Comment Notification Window)	Response_Master_Incident CAD911CT347 046518
2/22/2018	10:29:01	Read Call	False	True	(Launch Initial Assign)	Response_Master_Incident CADDFRF283B101117
2/22/2018	10:29:01	Read Comment	False	True	(Comment Notification Window)	Response_Master_Incident CAD911CT338 116762
2/22/2018	10:36:28	Read Comment	False	True	(Response Viewer)	Response_Master_Incident CADDFRF280B033101
2/22/2018	10:38:56	Date_Time		Feb 22 2018 10:38:56	*Notified - Electric Utility	Response_User_TimeStam CADDFRF280B033101 ps
2/22/2018	10:56:56	Read Comment	False	True	(Response Viewer)	Response_Master_Incident CADDFRF280B033101
2/22/2018	10:58:09	Date_Time		Feb 22 2018 10:58:09	**Primary Search Complete	Response_User_TimeStam CADDFRF283B101117 ps
2/22/2018	11:00:49	Date_Time		Feb 22 2018 11:00:49	**Secondary Seach Complete	Response_User_TimeStam CADDFRF283B101117 ps
2/22/2018	11:18:02	Read Comment	False	True	(Response Viewer)	Response_Master_Incident CADDFRF283B101117
2/22/2018	11:32:11	Field_Data		2 ADULT AND 2 CHILDREN	RED CROSS PAGE	Response_User_Data_FieldCADDFRF283B101117 s
2/22/2018	11:38:56	Read Comment	False	True	(Response Viewer)	Response_Master_Incident CADDFRF285B055396
2/22/2018	11:40:56	Date_Time		Feb 22 2018 11:40:56	*Notified - Gas Utility	Response_User_TimeStam CADDFRF285B055396 ps
2/22/2018	11:47:10	Read Comment	False	True	(Response Viewer)	Response_Master_Incident CADDFRF283B101117
2/22/2018	12:02:46	Date_Time		Feb 22 2018 12:02:46	**Out Taps	Response_User_TimeStam CADDFRF283B101117 ps

Custom Time Stamps

Description

- \*Notified - Electric Utility
- \*\*Primary Search Complete
- \*\*Secondary Seach Complete
- \*Notified - Gas Utility
- \*\*Out Taps

Date	Time	User
2/22/2018	10:38:56	033101
2/22/2018	10:58:09	101117
2/22/2018	11:00:49	101117
2/22/2018	11:40:56	055396
2/22/2018	12:02:46	101117

Custom Data Fields

Description

RED CROSS PAGE

Data	User
2 ADULT AND 2 CHILDREN	101117

Attachments

No Attachment

# FIRE INVESTIGATION REPORT

DALLAS FIRE-RESCUE DEPARTMENT  
Fire Investigation and Explosive Ordinance Disposal Division

1551 Baylor Street #500  
Dallas, Texas 75226  
Phone Number (214) 670-4312  
Fax Number (214) 670-4650

COPY

Council District: 02
Census Tract: 098012
Zip Code: 75220

Date: 02 22 2018	Time of Alarm: 10:21	District/Shift: 07 B	Mapsc0: 23-V
Incident Number: 2018048587		Investigator (s): Price, Freeman, Gardner, Boyd	
Address: 3515 Durango Dr			
Apartment / Suite Number:	Exposure:	Same Building:	
Business Name:			

Property Owner: <span style="background-color: black; color: black;">[REDACTED]</span>	Rep:
Occupant: <span style="background-color: black; color: black;">[REDACTED]</span>	Rep:

### Type

Structure <input checked="" type="checkbox"/>	1-Story Wood frame Dwelling	Construction Type V
Non-Structure <input type="checkbox"/>		
Criminal Attempt <input type="checkbox"/>	Terroristic Threat <input type="checkbox"/>	False Alarm <input type="checkbox"/>
Injury <input checked="" type="checkbox"/>	Number of injuries 01	Death <input type="checkbox"/> Number of deaths
Multiple Alarm	2-11    3-11    4-11    5-11    6-11    7-11	Out Taps 12:02
Vehicle <input type="checkbox"/>	Year    Make    Model	State/License Number    VIN
Classification <u>UNDETERMINED</u>		

### Fire Loss Information

	Building / Vehicle	Contents
Loss Estimate	127,870	20,000
Estimated Value	127,870	20,000
Insurance Company		
Description		Comments
Right of Entry/Chain of Custody	Exigent Circumstances	
Gas	Yes	
Electric	Yes	
DFR Notified	wireless caller	
First Responder	EN35	

Assigned     FBR Entered     NFIRS Entered     Completed     Sup. Review \_\_\_\_\_

## FIRE INVESTIGATION REPORT

INCIDENT # 2018048587

Evidence: No	Photos: Yes	Supplement: No
Previous Fires: No	Drug Involved: No	Homeless: No

Sprinklers: N/A	Type: Choose One:  Activated: Choose One:	Operational: Yes <input type="checkbox"/> No <input type="checkbox"/> N/A <input checked="" type="checkbox"/>
Fire Alarm System: Yes <input type="checkbox"/> No <input type="checkbox"/> Unk. <input checked="" type="checkbox"/>	Type:	# of Heads
How many: (including non-working)		# of working smoke alarms:
Operational: Yes <input type="checkbox"/> No <input type="checkbox"/> Unk. <input checked="" type="checkbox"/> N/A <input type="checkbox"/>	Location: 3515 Durango Dr	
Number of occupants at home at time of fire: 01	Ages of occupants: 35	
Did the smoke detector warn occupants? Yes <input type="checkbox"/> No <input type="checkbox"/> Unk. <input checked="" type="checkbox"/> N/A <input type="checkbox"/>	Did the smoke detector aid in escape? Yes <input type="checkbox"/> No <input type="checkbox"/> Unk. <input checked="" type="checkbox"/> N/A <input type="checkbox"/>	
Exits Obstructed: Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Unk. <input type="checkbox"/> N/A <input type="checkbox"/> If Yes, How?		
Burglar Bars: Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Installed Correctly? Yes <input type="checkbox"/> No <input type="checkbox"/> N/A <input type="checkbox"/>		

**Narrative:**

Responding Dallas Fire-Rescue Engine 35, reported "a lot of fire showing" from the Charlie side of the structure upon arrival at the listed location. Firefighters began offensive suppression operations and called 684 685 for investigation. Upon investigators arrival, firefighters were actively ventilating and suppressing the fire. Investigators began a systematic survey of the exterior of the structure. Investigator 684 took photographs while awaiting approval to begin the interior survey. The interior survey started on the alpha side of the structure at the front door and progressed in a counterclockwise pattern, from the area of least burned to the most burned, and concluded in the kitchen area.

Investigator 685 interviewed the homeowner who stated that he was home alone at the time of the fire boiling water on the stove-top when he noticed that the flames from the burner appeared to be growing red and out of control. The burner flared and as a result, the homeowner suffered 2nd degree burns to his right arm and leg when he attempted to extinguish the fire. The homeowner was transported to Parkland Hospital by Rescue 43 for treatment.

A neighbor voluntarily provided a statement that she has been experiencing issues with her gas service lately. She stated that she contacted the gas company on February 19, 2018 to ask if there were any problems in the neighborhood. She stated that the representative she spoke to told her there were no problems with the gas service in her neighborhood and that everything was normal.

Based on the homeowner's statements, witness interviews, and interview of the first arriving suppression crew, investigators concluded that the fire originated in the kitchen, on or adjacent to the stove. The fire traveled vertically and into the attic space, igniting, the nearby combustible cabinets and surrounding structural members causing significant fire and smoke damage resulting in a total loss. Based on the homeowner's statement, witness interviews, an interview of the first suppression crew, and fire development, this fire is listed as undetermined because all accidental causes could not be eliminated.



Follow up 02-28-2018

A follow up was done today to take day time photographs and assess the structural integrity of the exterior. The integrity of the exterior structure did not appear to be compromised. As a result of the day time photographs, there is severe charring in the attic space in the room adjacent to the kitchen. This section of charring did not adequately communicate with the surrounding charring in the attic space. This area was beneath the junction of the roof line and the wooden ceiling members within the attic space.

Per a phone conversation with the homeowner by our senior fire prevention officer Spanish translator, he stated to her, that he saw the flames circling around the pot and he went to turn the burner off and all he remembers is being thrown backwards. The homeowner will provide a written statement to corroborate the phone conversation. The fire classification will remain undetermined at this time.

**SIGNIFICANT FIRE INCIDENT REPORT**

**DALLAS FIRE-RESCUE DEPARTMENT**

**FIRE INVESTIGATION & E.O.D.**

**(214) 670-4312 FAX: (214) 670-4650**

Date: 02/22/2018 Alarm Times: 1<sup>st</sup> 10:21 2<sup>th</sup> 3<sup>th</sup> 4<sup>th</sup> 5<sup>th</sup> 6<sup>th</sup> 7<sup>th</sup> Out Taps 12:02

DFR #: 2018048587 Location: 3515 Durango Dr

Investigator: Freeman, Price, EG,

Type of Incident / Description of Property: 1-Story Wood Frame Dwelling

Name of Business or Property:

Owner / Occupant: [REDACTED]

Cause of the Fire: Undetermined

Fire Loss: Building: 127,870

Content: 20,000

Total: 147,870

Departmental Resources: Fire Fighting Equipment (Companies): 13

Firefighters: 33

	Yes	No	Unk	
Smoke Detectors?	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	If yes, type
Installed Correctly?	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	If no, explain
Operational?	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	If no, explain
Warned Occupants?	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	If no, explain
Aided Escape?	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	If no, explain
Sprinkler System?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Operational? Yes <input type="checkbox"/> No <input type="checkbox"/> Unk. <input type="checkbox"/>
Additional Information?	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	

**Description of Incident:**

Structure fire of a 1-story wood frame dwelling with single occupant homeowner injured during the incident. The homeowner stated that he was using the stove-top to boil water when the fire began to grow out of control. He stated that it flared up when he attempted to turn the burner down. Homeowner transported to Parkland Hospital via Rescue 43. Suppression crews extinguished the fire and allowed for a systematic interior survey. Investigators observed severe fire damage in and around the stove area in the kitchen. Photographs were taken and witness statements were obtained. A neighbor voluntarily provided a statement that she notified the gas company of the flames from her stove glowing red. She was told by a representative that everything was normal in her neighborhood.

Injuries/Deaths Yes  No  Unk.  If Yes, continue on second page

This release authorized by \_\_\_\_\_

**DALLAS FIRE-RESCUE DEPARTMENT  
FIRE INVESTIGATION & EXPLOSIVE ORDNANCE DISPOSAL DIVISION  
INVESTIGATIVE SUPPLEMENT**

INCIDENT NUMBER 2018048587

**WITNESS INFORMATION**

NAME [REDACTED]		STATEMENT YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>	
ADDRESS 3515 Durango Dr		HOME PHONE [REDACTED]	WORK PHONE
DATE OF BIRTH [REDACTED]	RACE [REDACTED]	SEX [REDACTED]	EMPLOYMENT
SUMMARY Homeowner was home at time of the fire			

NAME [REDACTED]		STATEMENT YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>	
ADDRESS 9621 Larga Dr		HOME PHONE [REDACTED]	WORK PHONE
DATE OF BIRTH [REDACTED]	RACE [REDACTED]	SEX [REDACTED]	EMPLOYMENT
SUMMARY [REDACTED] voluntarily provided a statement about [REDACTED] residence concerning [REDACTED] gas issue.			

NAME		STATEMENT YES <input type="checkbox"/> NO <input type="checkbox"/>	
ADDRESS		HOME PHONE	WORK PHONE
DATE OF BIRTH	RACE	SEX	EMPLOYMENT
SUMMARY			

**SUSPECT INFORMATION**

NAME		ALIAS	
ADDRESS			
DATE OF BIRTH	RACE	SEX	WARRANT #
CHARGES FILED			
JAILED FOR INVESTIGATION		CHARGES FILED	GRAND JURY V
CONVICTED	SENTENCE	DATE SENTENCED	
<b>JUVENILES ONLY</b>	RELEASE TO PARENT Select	JUVENILE AUTHORITY Select	YOUTH SERVICE Select
	JUVENILE COUNSELING Select	OTHER wireless caller	
FATHER:		MOTHER:	
TELEPHONE:		SCHOOL:	

NAME		ALIAS	
ADDRESS			
DATE OF BIRTH	RACE	SEX	WARRANT #
CHARGES FILED			
JAILED FOR INVESTIGATION		CHARGES FILED	GRAND JURY Select One:
CONVICTED	SENTENCE	DATE SENTENCED	
<b>JUVENILES ONLY</b>	RELEASE TO PARENT Select	JUVENILE AUTHORITY Select	YOUTH SERVICE Select
	JUVENILE COUNSELING Select	OTHER	
FATHER:		MOTHER:	
TELEPHONE:		SCHOOL:	

**INJURIES / DEATHS**

Name	C / F	Injury Type or Fatality	Transported by and taken where Pronounced where and time
[REDACTED]	<input checked="" type="checkbox"/> / <input type="checkbox"/>	2nd degree burns	RE43 to Parkland Hosp-11:00AM
_____	<input type="checkbox"/> / <input type="checkbox"/>	_____	_____
_____	<input type="checkbox"/> / <input type="checkbox"/>	_____	_____
_____	<input type="checkbox"/> / <input type="checkbox"/>	_____	_____
_____	<input type="checkbox"/> / <input type="checkbox"/>	_____	_____
_____	<input type="checkbox"/> / <input type="checkbox"/>	_____	_____
_____	<input type="checkbox"/> / <input type="checkbox"/>	_____	_____
_____	<input type="checkbox"/> / <input type="checkbox"/>	_____	_____
_____	<input type="checkbox"/> / <input type="checkbox"/>	_____	_____
_____	<input type="checkbox"/> / <input type="checkbox"/>	_____	_____

Can names be released? <sup>No</sup>

This release authorized by \_\_\_\_\_