



Tied

Squeeze 4" PL HP  
main N/O service  
181-183 Parker  
Ave

Dig-in

2nd bell hole -  
No squeeze  
attempt - pipe  
never  
exposed

V-367

V-190

V-3406

V-315

V-315 tied  
into 2"

V-3489

V-3486

1st bell hole -  
No squeeze  
attempt - pipe  
never  
exposed