

From: [Gordon Robert \(Joe\)](#)
To: [Hall Robert](#); [Hiller Michael](#); [Bachmeier Michael](#); [Frigo Ryan](#)
Subject: Fwd: National Steel Intercept Definition 8101
Date: Wednesday, March 8, 2023 9:06:05 PM
Attachments: [image003.png](#)
[image004.png](#)
[image005.png](#)

See below the NS intercept:

Stop car loaded or empty. All wheel sets must be replaced with new wheel sets.

These are the National Steel Car company cars like those from Springfield, OH.

Joe Gordon WSO-CSM
Railroad Branch Chief
(202) 841-5537

From: Rhine Don (Joey) <don.rhine@ntsb.gov>
Sent: Wednesday, March 8, 2023 8:34 PM
To: Gordon Robert (Joe) <robert.gordon@ntsb.gov>
Subject: FW: National Steel Intercept Definition 8101

From: [REDACTED]
Sent: Wednesday, March 8, 2023 11:18 AM
To: Rhine Don (Joey) <don.rhine@ntsb.gov>
Subject: FW: National Steel Intercept Definition 8101

[CAUTION] This email originated from outside of the organization. Do not click any links or open attachments unless you recognize the sender and know the content is safe.


Joey,

Below is the intercept issued:

Jason

From: Pennington, Randall E. <Randy.Pennington@nscorp.com>
Sent: Wednesday, March 8, 2023 2:07 PM
Subject: FW: National Steel Intercept Definition

Here's what the National Steel Intercept 8101 now says. Email below shows the original version.



Intercept NS-8101 Help Message

STOP CAR LOADED OR EMPTY. ALL WHEEL SETS MUST BE REPLACED WITH NEW WHEEL SETS.

From: Pennington, Randall E.
Sent: Tuesday, March 7, 2023 10:12 PM
Subject: RE: National Steel Intercept Definition

Intercept 8101 has been added to 517 cars out of 675 within the target range of cars. The margin consists of cars that do not exist or they are in pre-registered status in Umler. The system will not allow me to apply an Intercept to pre-registered cars.

Here's what the Intercept looks like in EAM.

NS162390

Current Track: N21

Arrival Train: DA02nu07

Next Train:

INTERCEPT(S) BO REASON(S) CAR LOCATION WAYBILL CAR DETAILS CAR MOVE RESTRICTIONS SCABT

| Intercepts | Priority | Description |
|------------|----------|---|
| NS-8101 | 09 | NATIONAL STEEL NEW CAR WHEEL INSPECTION |

Intercept Help Messages

Car Mark: NS162390

Intercept NS-8101 Help Message

STOP CAR LOADED OR EMPTY. INSPECT EACH WHEEL LOCATION AT THE AXLE AND WHEEL HUB INTERFACE. IF ANY LATERAL MOVEMENT OF THE WHEEL PLATE IS IDENTIFIED, WHEEL SET MUST BE REPLACED AND QUARANTINED. NOTIFY MANAGER CAR MAINTENANCE.

Randy