

NO. 38148

GENERAL TRACK BULLETIN

March 02 , 2021

To H BARLAC1 02A BNSF 8156

at BARSTOW CA .VIRTUAL

A total of 145 items are included in this bulletin, consisting of:

53 Form A/B/C Bulletin Restriction(s)	92 TCM Restriction(s)
18 Form A(s)	0 High Wide Restriction(s)
8 Form B(s)	0 Train Message(s)
27 Form C(s)	

High Wide Restrictions are included on the following trains only:

NONE

0 High Wide Restrictions affecting all trains are included.

OK 16:15:33 Dispatcher KDF

\*\*\*\*\*

General Track Bulletin # 38148 contains

Subdivision	From Location / Milepost	To Location / Milepost
MOJAVE	VALLEY JCT. 749.0	BORON 784.0
NEEDLES	EAST NEWBERRY 725.7	BARSTOW 745.8
CAJON	BARSTOW 0.0	MP 81.3 81.3
LUCERNE VALLEY	MP 29.2 29.2	HESPERIA 0.0
SAN BERNARDINO	MP 0.0 0.0	CP WEST REDONDO 143.2
SAN DIEGO	NATIONAL CITY 273.1	FULLERTON JCT. 165.4

\*\* Before operating on territory not listed, crew must contact train dispatcher to determine if any additional restrictions are needed per timetable special instructions.

\*\* If address is not shown correctly on General Track Bulletin address, contact the train dispatcher and correct before operating on main track.

\*\* Crew members must check the date and 'OK' time on this General Track Bulletin and if the General Track Bulletin is over four (4) hours old, contact train dispatcher and determine if General Track Bulletin is valid.

\*\*\*\*\*

Most current:

SYSTEM	Gen Order No 115	02/25/21	Gen Notice No 214	03/02/21
CALIFORNIA	Gen Order No 76	03/02/21	Gen Notice No 368	01/26/21

Safety Topic

-----

Employee Fouling Tracks/S-13.1.3 (C)

The definition of Fouling Track is the placement of an individual in such proximity to a track that the individual could be struck by a moving train or on-track equipment. Fouling track is acceptable ONLY when duties require and if proper safeguards are in place. When approaching a nonpublic crossing in a vehicle or off-track equipment, do so at a right angle for optimal viewing of potential approaching movements, stop before crossing unless foul of a previously crossed track, and yield to traffic before crossing, except when within mechanical servicing/repair buildings or within an intermodal facility, unless designated by signage. Whether walking or driving, expect

the movement of trains, locomotives, cars or other equipment at any time, on any track and in either direction.

Employees must always be alert and expect the movement of trains, engines, cars or other moveable equipment at any time, on any track and in either direction. Before fouling any track, employees have an individual responsibility to determine it is safe to do so. If the track is occupied by rail equipment, employees must ensure appropriate protection has been provided for the task to be performed.

As outlined in S-13.1.3 subpart C - Do not walk between rails or foul the track except when duties require and safeguards are utilized. Use extra precaution during bad weather and when visibility is limited or impaired. PLEASE VISIT BNSF CONNECT FOR MORE INFORMATION CONCERNING THIS WEEK'S SAFETY TOPIC ON EMPLOYEE FOULING TRACKS.

Special Message

-----  
None.

Train Messages

-----  
None.

Item No	Restrnr Number	Form	Restrictions for ALL Subdivisions
1	57857	C	<p>BNSF IS CURRENTLY UPDATING OUR LOCOMOTIVE FLEET WITH A NEW DISTRIBUTED POWER (DP) SYSTEM CALLED LXA. THIS UPGRADED SYSTEM HAS COMBINED THE DP/HOT RADIO CIRCUIT BREAKER TOGETHER. PLEASE ENSURE THE DP RADIO BREAKER LOCATED ON THE ENGINE CONTROL PANEL IS LEFT IN THE CLOSED (ON) POSITION ON ALL LOCOMOTIVES. IF YOU CANNOT ESTABLISH COMMUNICATION WITH AN ETD IN A CONVENTIONAL TRAIN PLEASE CHECK THE BREAKER TO ENSURE IT IS CLOSED (ON).</p> <p>Issued On: 12-10-19</p>
2	57948	C	<p>UNTIL FURTHER NOTICE, TRAINS OPERATING WITH AN ENGINEER, CONDUCTOR AND BRAKEMAN, THE BRAKEMAN IS EXEMPT FROM GCOR 1.30 AND MAY RIDE THE SECOND LOCOMOTIVE IN THE CONSIST, IF AVAILABLE.</p> <p>Issued On: 03-20-20</p>
3	58096	C	<p>WHILE USING THE MOBILE TRAIN REPORTING (MTR) APPLICATION ON THE RAILROAD-SUPPLIED ELECTRONIC DEVICE (IPAD) FOR WORK ORDERS PLEASE REFER TO THE PDF VERSION OF THE WORK ORDER UNLESS YOU ARE REPORTING WORK.</p> <p>WHILE USING THE MTR APPLICATION, CREWS MUST REFER TO THE PDF VERSION OF THE WORK ORDER FOR LOCOMOTIVE ISOLATION AND THROTTLE INSTRUCTIONS.</p> <p>THE FUNCTIONALITY TO REPORT CHANGES TO LOCOMOTIVE CONFIGURATION IN RUN OR ISO STATUS IS NOT FULLY FUNCTIONAL AT THIS TIME ON THE MTR APPLICATION, THEREFORE CREWS MUST CONTINUE TO CALL VTR TO REPORT ANY CHANGES FROM THEIR WORK ORDERS</p> <p>Issued On: 09-01-20</p>
4	58260	C	<p>WHEN THE PTC DISPLAY DEPICTS AN APPROACH INDICATION (YELLOW TRACK LINE), FOLLOWED BY A GRAY TRACK LINE STARTING AT THE NEXT GOVERNING SIGNAL, REPORT THE CONDITION TO THE PTC DESK.</p> <p>THIS CONDITION IS RELATED TO A PTC DISPLAY ANOMALY THAT MUST BE IDENTIFIED FOR CORRECTION.</p> <p>CREWS MUST CONTINUE TO OBSERVE SIGNAL ASPECTS DISPLAYED IN THE FIELD AND COMPLY WITH THEIR INDICATION.</p> <p>FOR TRAINS OPERATING WITH PTC/TO INTERFACE MODE, THE PLANNED SPEED SHOWN ON TRIP OPTIMIZER MAY DISPLAY TRACK SPEED. HOWEVER, THE SYSTEM WILL PROHIBIT AUTO CONTROL BEYOND AN APPROACH SIGNAL AS DESIGNED.</p> <p>REPORTING IS NOT REQUIRED FOR THE FOLLOWING CONDITIONS:</p> <ul style="list-style-type: none"> <li>-GRAY TRACK LINES BEYOND RED HASH (STOP TARGET)</li> <li>-WHEN OPERATING AT RESTRICTED SPEED (YELLOW HASH) AND TRAIN IS GREATER THAN 3000' FROM THE NEXT GOVERNING SIGNAL, OR</li> <li>-IF THE GRAY TRACK LINE REPRESENTS A NON-PTC ENFORCED TRACK.</li> </ul> <p>Issued On: 02-12-21</p>

Item No	Restr Number	Form	Restrictions for MULTIPLE Subdivisions
---------	--------------	------	--

5 58242 C Subdivisions affected:  
NEEDLES

BUTTE, ANGORA, BRUSH, PIKES PEAK, PUEBLO, BOISE CITY,  
HEREFORD, CLOVIS, GALLUP, SELIGMAN AND NEEDLES

TRAIN D EDGBAR1 06 WILL OPERATE WITH 25 DIC LOCOMOTIVES WITHIN  
A 2X1 DP CONFIGURATION FROM EDMONT, SD TO BARSTOW, CA.  
TRAIN WILL BE RESTRICTED TO A MAXIMUM AUTHORIZED SPEED OF 45  
MPH. MAIN RESERVOIR AND BRAKE PIPE WILL BE THE ONLY  
CONNECTIONS BETWEEN EACH LOCOMOTIVE WITHIN THE 25 UNIT DIC  
CONSIST. THEREFORE INDEPENDENT BRAKES WILL NOT BE OPERATIVE  
ON THE DIC LOCOMOTIVES, HOWEVER THE LEAD AND REMOTE DP CONSIST  
(2X1) WILL OPERATE AS NORMAL. ENGINEERS MUST UTILIZE DYNAMIC  
BRAKING TO THE GREATEST EXTENT POSSIBLE TO SLOW AND CONTROL  
SPEED OVER THEIR TERRITORIES MINIMIZING THE USE OF BRAKE PIPE  
REDUCTIONS. TRAIN CHECKS WHEN STOPPED ARE STILL REQUIRED.

WHEN INITIALIZING PTC, USE THE FOLLOWING TO VERIFY CONSIST  
INFORMATION:

LOADS: (# OF DIC LOCOS)  
TONNAGE: (# OF DIC LOCO X 210 TONS)  
LENGTH: (# OF DIC LOCOS + POWER X 73 FEET)  
AXLES: (# OF AXLES ON DIC LOCOS)

IF CONSIST UPDATE IS RECEIVED EN-ROUTE, IGNORE THE UPDATE AND  
CONTINUE WITH THE CONSIST INFO THAT WAS INPUT AT  
INITIALIZATION. DO NOT REVIEW THE UPDATE AS ACCEPTING WILL  
OVERWRITE THE MANUAL UPDATE THAT WAS INPUT.

Issued On: 02-06-21

6 58259 C Subdivisions affected:  
CAJON NEEDLES

EFFECTIVE 2/15/21 AT 0001 CT, ATS IS RETIRED ON PTC  
SUBDIVISIONS LISTED. FOR APPROXIMATELY 90 YEARS, ATS HAS  
SERVED AMTK, BNSF, AND PREDECESSOR AT&SF RWY BY ALLOWING  
EQUIPPED-TRAINS TO OPERATE UP TO 90 MPH.

ONCE ATS IS RETIRED, PASSENGER TRAINS OPERATING WITHOUT THE  
PTC SYSTEM IN AN "ACTIVE" STATE ARE RESTRICTED TO 79 MPH.  
DURING THE REMOVAL PERIOD, ENGINEERS OF ATS-EQUIPPED TRAINS  
MAY BE REQUIRED TO ACKNOWLEDGE ATS ALERTS AS IF THE SYSTEM  
WERE IN SERVICE. TRAIN DISPATCHER NOTIFICATION OF CONDITIONS  
RELATED TO ATS IS NOT REQUIRED.

Issued On: 02-12-21

Item Restr'n Form | Restrictions for MULTIPLE Subdivisions (continued)  
 No Number |

7 58268 C Subdivisions affected:  
 CAJON LUCERNE VALLEY MOJAVE  
 NEEDLES SAN BERNARDINO SAN DIEGO

CALIFORNIA DIVISION TIMETABLE NO. 5 IS IN EFFECT 0800,  
 WEDNESDAY, MARCH 10, 2021. EMPLOYEES GOVERNED BY THESE  
 TIMETABLES AND INSTRUCTIONS MUST OBTAIN A COPY BEFORE THE  
 EFFECTIVE DATE AND TIME.  
 Issued On: 02-26-21

| End of Restrictions for MULTIPLE Subdivisions

Item Restr'n Form | Restrictions for MOJAVE Subdivision  
 No Number |

Track flag at MP 750.6 See Restr'n 2872 on CAJON SUBDIV

8 9188 A MP To MP PSGR FRT Track(s)  
 764.6 764.7 40 MPH 40 MPH MAIN TRACK  
 Track flags not displayed

9 4897 A MP To MP PSGR FRT Track(s)  
 772.4 772.7 30 MPH 30 MPH SIDING

10 1282 A MP To MP PSGR FRT Track(s)  
 783.0 783.3 NA 60 MPH MAIN TRACK

| End of Restrictions for MOJAVE Subdivision

Item Restr'n Form | Restrictions for NEEDLES Subdivision  
 No Number |

11 9043 A MP To MP PSGR FRT Track(s)  
 737.3 738.0 10 MPH 10 MPH UP MAIN 1  
 CROSSOVER  
 Track flags not displayed

Comment:AFFECTS CROSSOVER MOVEMENT UP MAIN 1 TO BNSF MAIN 1

12 2805 C EAST END NEBO MAINLINE HAND THROW SWITCH CLIC#7411 TAGGED OUT  
 OF SERVICE ACCOUNT FRA INSPECTION  
 Issued On: 03-02-21

| End of Restrictions for NEEDLES Subdivision

Item No	Restr Number	Form	Restrictions for CAJON Subdivision					Track(s)
13	5945	A	MP	To MP	PSGR	FRT		
			0.2	0.6	15 MPH	NA	AMTRAK SIDING	
			Track flags not displayed					
			Comment:WILL ONLY AFFECT AMTRAK PASSENGER PASS 1.					
14	2872	B	MP	To MP	From Z Day Date		Until Z Day Date	
			1.0	8.0	0400 P WED 03/03		1500 P WED 03/03	
					Track(s)			MAIN 1 MAIN 2 MAIN 3 MAIN 4 CAJON CNT TRK CROSSOVER INSPECTION TRK MOJAVE CNT TRK NO DEPARTURE TRK SO DEPARTURE TRK YD ENTRY LEAD
			Yellow/Red flag at MP: 0.0		Yellow/Red flag at MP:			
			Foreman:MAESTAS		Gang:TP06			Stop Required
			Yellow/Red flag on MOJAVE subdiv at MP 750.6					
			Comment:RADIO CHANNEL: 65					
15	2770	A	MP	To MP	PSGR	FRT	Track(s)	
			2.0	2.4	30 MPH	30 MPH	MAIN 3	
			Track flags not displayed					
16	2775	A	MP	To MP	PSGR	FRT	Track(s)	
			2.3	3.8	30 MPH	30 MPH	MAIN 1	
			Track flags not displayed					
17	4171	A	MP	To MP	PSGR	FRT	Track(s)	
			2.3	2.4	15 MPH	15 MPH	INSPECTION TRK	
			Track flags not displayed					
18	2543	A	MP	To MP	PSGR	FRT	Track(s)	
			2.3	2.6	50 MPH	50 MPH	MAIN 3	
			Track flags not displayed					

Item Restrtn Form | Restrictions for CAJON Subdivision (continued)  
 No Number |

-----  
 19 2101 A MP To MP PSGR FRT Track(s)  
 -----  
 2.4 2.5 10 MPH 10 MPH INSPECTION TRK  
 Track flags not displayed  
 -----

20 7689 C HOT BEARING DETECTOR MAIN 2 AT MP 8.2 IS TEMPORARY OUT OF  
 SERVICE ACCOUNT REPAIRS.  
 Issued On: 10-22-20  
 -----

21 7132 A MP To MP PSGR FRT Track(s)  
 -----  
 21.0 21.2 NA 60 MPH MAIN 2  
 -----

22 2666 A MP To MP PSGR FRT Track(s)  
 -----  
 26.9 27.0 10 MPH 10 MPH MAIN 2  
 Track flags not displayed  
 -----

-----

23 2486 B MP To MP From Z Day Date Until Z Day Date  
 -----  
 33.4 34.6 0600 P TUE 03/02 1600 P TUE 03/02  
 -----

Track(s) MAIN 1  
 MAIN 2  
 CROSSOVER

Foreman:PRESCOTT Gang:0400 Stop Required

Comment:RADIO CHANNEL: 72

-----

24 2852 B MP To MP From Z Day Date Until Z Day Date  
 -----  
 33.4 34.6 0600 P WED 03/03 1600 P WED 03/03  
 -----

Track(s) MAIN 1  
 MAIN 2  
 CROSSOVER

Foreman:PRESCOTT Gang:0400 Stop Required

Comment:RADIO CHANNEL: 72

-----

25 6912 C THE FOLLOWING INSTRUCTIONS APPLY TO WESTBOUND FREIGHT TRAINS  
 RE-INITIALIZING PTC BETWEEN MP 56.6 AND MP 78 (INCLUDES RELIEF  
 CREWS):  
 1. VERIFY DEPARTURE TEST IS NOT REQUIRED ("DEPART" SCREEN FLAG  
 NOT PRESENT).

Item Restrtn Form | Restrictions for CAJON Subdivision (continued)  
 No Number |

NOTE: IF DEPARTURE TEST IS REQUIRED, DO NOT ATTEMPT TO INITIALIZE PTC UNLESS CONDITIONS ALLOW THE AIR BRAKE SYSTEM TO BE FULLY RECHARGED. CREWS OF SUCH TRAINS SHOULD STOP AND INITIALIZE AT FIRST PRACTICAL LOCATION WHERE TRAIN BRAKES CAN BE FULLY RECHARGED BEYOND MP 78, AS DIRECTED BY TRAIN DISPATCHER.

2. INITIALIZE PTC AS USUAL, AND SELECT "UNMAPPED TRACK".
3. ONCE REAR-END OF TRAIN IS PAST MP 78, REDUCE SPEED TO BELOW 19 MPH, THEN SELECT TRACK TO TRANSITION TO ACTIVE STATE.
4. OPERATE WITH PTC ACTIVE OVER THE REMAINDER OF YOUR ROUTE.

Issued On: 04-17-20

-----

Item No	Restrtn Number	Form	MP	To MP	From Z Day Date	Until Z Day Date
26	2853	B	56.0	58.0	0600 P WED 03/03	1400 P WED 03/03

Track(s) MAIN 3

Foreman:BOINSKI Gang:2020 Stop Required

Comment:RADIO CHANNEL: 72

-----

Track flag at MP 79.3 See Restrtn 2854 on SAN BERNARDINO SUBDIV

Track flag at MP 79.3 See Restrtn 2636 on SAN BERNARDINO SUBDIV

Track flag at MP 79.3 See Restrtn 2563 on SAN BERNARDINO SUBDIV

27 8178 C EFFECTIVE 1630 PT ON SUNDAY OCTOBER 25, 2020; AT CP 7TH STREET, THE WBCS AND EBCS GROUND MOUNTED SIGNALS FOR MT1 AND MT2 WILL BE REMOVED FROM SERVICE AND WILL BE REPLACED BY A CANTILEVER MAST.

Issued On: 10-25-20

=====  
 | End of Restrictions for CAJON Subdivision  
 =====

Item Restrtn Form | Restrictions for LUCERNE VALLEY Subdivision  
 No Number |

No restrictions in effect for the territory on LUCERNE VALLEY subdiv between MP 29.2 MP 29.2 and HESPERIA MP 0.0

=====  
 | End of Restrictions for LUCERNE VALLEY Subdivision  
 =====



Item Restr'n Form | Restrictions for SAN BERNARDINO Subdivision  
 No Number |  
 -\*- -\*- -\*- | -\*-

28 2563 B MP To MP From Z Day Date Until Z Day Date  
 -----  
 0.0 0.2 0600 P TUE 03/02 1600 P TUE 03/02

Track(s) MAIN 1  
 MAIN 2  
 MAIN 3

Foreman:VASQUEZ Gang:1 Stop Required  
 Yellow/Red flag on CAJON subdiv at MP 79.3

Comment:RADIO CHANNEL: 72  
 SHORT YELLOW RED AND RED FLAG MP 0.2 METROLINK CONNECT  
 OR

-\*- -\*- -\*- | -\*-

29 2636 B MP To MP From Z Day Date Until Z Day Date  
 -----  
 0.0 0.2 1900 P TUE 03/02 0430 P WED 03/03

Track(s) MAIN 1  
 MAIN 2  
 MAIN 3

Foreman:RIVERA Gang:007 Stop Required  
 Yellow/Red flag on CAJON subdiv at MP 79.3

Comment:RESTRICTION EXTENDS BEYOND 2359 - REFER TO EFFECTIVE  
 TIMES AND DATES  
 RADIO CHANNEL: 72  
 SHORT YELLOW RED AND RED FLAGS 0.2 METROLINK CONNECTOR  
 RADIO CHANNEL 72

-\*- -\*- -\*- | -\*-

Item No	Restr Number	Form	Restrictions for SAN BERNARDINO Subdivision (continued)				
---	---	---	-----				
30	2854	B	MP	To MP	From Z Day Date	Until Z Day Date	
			0.0	0.2	0600 P WED 03/03	1600 P WED 03/03	
			Track(s) MAIN 1 MAIN 2 MAIN 3				
			Foreman:VASQUEZ                      Gang:1                      Stop Required Yellow/Red flag on CAJON subdiv at MP      79.3				
			Comment:RADIO CHANNEL: 72 SHORT YELLOW RED FLAG AND RED FLAF MP 0.2 METROLINK CO NNECTOR				
---	---	---	-----				
31	1122	A	MP	To MP	PSGR	FRT	Track(s)
			1.3	1.5	NA	25 MPH	MAIN 2
			Yellow flag at MP:                      0.5                      Yellow flag at MP:				
32	2659	A	MP	To MP	PSGR	FRT	Track(s)
			12.6	12.8	50 MPH	NA	MAIN 1
			Track flags not displayed				
33	1371	A	MP	To MP	PSGR	FRT	Track(s)
			16.0	16.3	NA	40 MPH	MAIN 2
			Track flags not displayed				
34	6216	C	BRIDGE WALKWAYS OUT OF SERVICE AT MP 30.2 ON SOUTHSIDE OF MT3 AND BETWEEN MT2 AND MT3. Issued On: 10-17-19				
35	1819	A	MP	To MP	PSGR	FRT	Track(s)
			165.2	164.7	50 MPH	NA	MAIN 3
			Track flags not displayed				
36	9968	A	MP	To MP	PSGR	FRT	Track(s)
			154.7	154.6	30 MPH	25 MPH	CROSSOVER
			Comment:MIDDLE WEST CROSSOVER MAIN 1 TO MAIN 2				
37	1069	C	DETECTOR AT MP 154.3 IS OUT OF SERVICE ON MAIN 2 ONLY. Issued On: 02-22-21				
---	---	---	-----				

```

Item Restrn Form | Restrictions for SAN BERNARDINO Subdivision (continued)
No Number |
-----|-----
38 2711 B MP To MP From Z Day Date Until Z Day Date
-----|-----
152.0 150.0 2100 P TUE 03/02 0200 P WED 03/03

Track(s) MAIN 1
MAIN 2
MAIN 3

```

Foreman:NORWOOD Gang:10647 Stop Required

Comment:RESTRICTION EXTENDS BEYOND 2359 - REFER TO EFFECTIVE  
TIMES AND DATES

RADIO CHANNEL: 36

FORM B WILL EXTEND PAST 2359

```

39 1566 A MP To MP PSGR FRT Track(s)
-----|-----
148.8 148.6 50 MPH NA MAIN 1
Track flags not displayed

```

```

40 6215 C BRIDGE WALKWAYS ARE OUT OF SERVICE MP 143.5 - 143.7
Issued On: 10-17-19

```

=====  
| End of Restrictions for SAN BERNARDINO Subdivision  
=====

```

Item Restrn Form | Restrictions for SAN DIEGO Subdivision
No Number |
-----|-----

```

```

41 6957 C AUTOMATIC CROSSING WARNING DEVICE FALSE OR PARTIAL ACTIVATION
AT MP 270.74 NATIONAL L STEEL SHIP DOT 026893.

```

STOP AND PROTECT MOVEMENT UNLESS DEVICES ARE SEEN TO BE  
WORKING OR OTHERWISE INSTRUCTED.

PROCEED PER RULE 6.32.2 PROCEDURE 2.

Issued On: 10-20-20

```

42 6394 C AUTOMATIC CROSSING WARNING DEVICE FALSE OR PARTIAL ACTIVATION
AT MP 274.74 TIDELANDS AVE. DOT#026125A

```

STOP AND PROTECT MOVEMENT UNLESS DEVICES ARE SEEN TO BE  
WORKING OR OTHERWISE INSTRUCTED.

PROCEED PER RULE 6.32.2 PROCEDURE 2.

Issued On: 10-17-20

```

43 4383 C AUTOMATIC CROSSING WARNING DEVICE FALSE OR PARTIAL ACTIVATION
AT MP 271.04/ 32ND STREET DOT#026894P

```

Item No	Restr Number	Form	Restrictions for SAN DIEGO Subdivision (continued)
			STOP AND PROTECT MOVEMENT, UNLESS DEVICES ARE SEEN TO BE WORKING OR OTHERWISE INSTRUCTED.  PROCEED PER RULE 6.32.2, PROCEDURE 2 Issued On: 06-08-20
44	2215	C	CROSSING WARNING NOTIFICATION SAN DIEGO SUB DOT 026900R BOX 2- AUTOMATIC CROSSING WARNING DEVICE FALSE OR PARTIAL ACTIVATION AT MP 272.32 HARBOR DRIVE. STOP AND PROTECT MOVEMENT, UNLESS DEVICES ARE SEEN TO BE WORKING OR OTHERWISE INSTRUCTED. PROCEED PER RULE 6.32.2, PROCEDURE 2. Issued On: 07-28-20
45	4380	C	AUTOMATIC CROSSING WARNING DEVICE FALSE OR PARTIAL ACTIVATION AT MP 272.84 19TH ST WEST  STOP AND PROTECT MOVEMENT, UNLESS DEVICES ARE SEEN TO BE WORKING OR OTHERWISE INSTRUCTED. PROCEED PER RULE 6.32.2, PROCEDURE 2 Issued On: 08-04-20
46	7840	C	AUTOMATIC CROSSING WARNING DEVICE FALSE OR PARTIAL ACTIVATION AT MP 272.44 CIVIC CENTER DR DOT 026901X  STOP AND PROTECT MOVEMENT, UNLESS DEVICES ARE SEEN TO BE WORKING OR OTHERWISE INSTRUCTED. PROCEED PER RULE 6.32.2, PROCEDURE 2 Issued On: 02-05-21
47	5552	C	AUTOMATIC CROSSING WARNING DEVICE FALSE OR PARTIAL ACTIVATION AT MP 272.1 W 8TH ST  STOP AND PROTECT MOVEMENT, UNLESS DEVICES ARE SEEN TO BE WORKING OR OTHERWISE INSTRUCTED. PROCEED PER RULE 6.32.2, PROCEDURE 2 Issued On: 06-11-20
48	4541	C	CROSSING WARNING NOTIFICATION  BOX 2 AUTOMATIC CROSSING WARNING DEVICE FALSE OR PARTIAL ACTIVATION AT MP 270.43 28TH STREET SOUTH. DOT#026890M STOP AND PROTECT MOVEMENT, UNLESS DEVICES ARE SEEN TO BE WORKING OR OTHERWISE INSTRUCTED.  PROCEED PER RULE 6.32.2, PROCEDURE 2. Issued On: 05-10-20
49	5704	C	AUTOMATIC CROSSING WARNING DEVICE FALSE OR PARTIAL ACTIVATION AT MP 270.22 HARBOR DR  STOP AND PROTECT MOVEMENT, UNLESS DEVICES ARE SEEN TO BE WORKING OR OTHERWISE INSTRUCTED. PROCEED PER RULE 6.32.2, PROCEDURE 2 Issued On: 05-13-20

Item No	Restr Number	Form	Restrictions for SAN DIEGO Subdivision (continued)
50	6385	C	AUTOMATIC CROSSING WARNING DEVICE FALSE OR PARTIAL ACTIVATION AT MP 269.85 SAMPSON ST  STOP AND PROTECT MOVEMENT, UNLESS DEVICES ARE SEEN TO BE WORKING OR OTHERWISE INSTRUCTED. PROCEED PER RULE 6.32.2, PROCEDURE 2 Issued On: 05-16-20
51	8898	C	AT WEST END OF KELCO, MP 269.90 BELT AVE. CROSSING DO NOT RIDE SIDES OF CARS DUE TO CLOSE CLEARANCE BETWEEN FLASHER POLE AND SOUTH SIDE OF MAIN TRACK. Issued On: 09-22-20
52	9279	C	PER FOREMAN LENTE MAIN TRACK OOS FROM MP 268.644 - MP 268.968 Issued On: 12-15-20
53	2136	C	BOX 2 AUTOMATIC CROSSING WARNING DEVICE FALSE OR PARTIAL ACTIVATION AT MP 180.7 ARMSTRONG AVE DOT#026718S STOP AND PROTECT MOVEMENT, UNLESS DEVICES ARE SEEN TO BE WORKING OR OTHERWISE INSTRUCTED. PROCEED PER RULE 6.32.2, PROCEDURE 2. Issued On: 11-06-19
			End of Restrictions for SAN DIEGO Subdivision

Item No	Restr Number	Form	TCM Restrictions for MOJAVE Subdivision	
54	60124	TCM	Between: MP 772.0 CLIC 6521 IS OUT OF SERVICE DUE TO TIGHT GAGE. Estimated Removal Date: 05-31-21 Placed by: MALONE	and: MP 774.0 On: 03-02-21
55	60123	TCM	Between: MP 772.0 WATCH FOOTING JIM GREY SET OUT TRACK ONLY ACCESSIBLE FROM WEST END DUE TO FROG MISSING AT EAST END. Estimated Removal Date: 05-31-21 Placed by: T. UTU	and: MP 774.0 On: 03-02-21
56	60121	TCM	Between: MP 772.0 WATCH YOUR FOOTING AROUND SWITCH EAST END OF SETOUT TRACK AT JIM GREY ACCOUNT FROG BEING REMOVED. Estimated Removal Date: 05-22-21 Placed by: MALONE	and: MP 774.0 On: 03-02-21
57	60125	TCM	Between: JIM GREY WATCH YOU FOOTING MP 777.8 NORTH SIDE DUE TO RAIL IN WALKWAY. Estimated Removal Date: 05-31-21 Placed by: MARCUM	and: BORON On: 03-02-21
58	60127	TCM	Between: MP 777.3 WATCH FOOTING AT MP 777.4 DUE TO EXPOSED CONSTRUCTION PIPE. MARKED WITH ORANGE CONES AND BARRICADES. Estimated Removal Date: 05-31-21 Placed by: ALVAREZ	and: MP 777.5 On: 03-02-21

| End of TCM Restrictions for MOJAVE Subdivision

Item No	Restr Number	Form	TCM Restrictions for NEEDLES Subdivision	
59	67853	TCM	Between: EAST NEWBERRY NORTH NEWBERRY SPUR TRACK CLIC 7261 OUT OF SERVICE TIGHT GAUGE Estimated Removal Date: 03-31-21 Placed by: FOREMAN MALONE	and: WEST NEWBERRY On: 01-14-20
60	64942	TCM	Between: MP 725.7 SET OUT TRACK NEEDLES SUB CLIC 7200-72610 OUT OF SERVICE DUE TO BROKEN RAILS Estimated Removal Date: 03-31-21 Placed by: STEWART	and: MP 727.2 On: 10-08-19
61	67854	TCM	Between: MP 726.5 CLIC 7277 WEST IS OUT OF SERVICE DUE TO FROG REMOVED Estimated Removal Date: 04-30-21 Placed by: ANSON	and: MP 726.7 On: 01-14-20

| End of TCM Restrictions for NEEDLES Subdivision

Item No	Restr Number	Form	TCM Restrictions for CAJON Subdivision	
62	69529	TCM	Between: MP 0.0	and: MP 5.7 WATCH YOUR FOOTING MP 0.0-5.7 ALL MAINS DUE TO NEW RAIL TIES LAID OUT Estimated Removal Date: 12-31-21 Placed by: MAESTAS On: 02-07-21
63	69526	TCM	Between: BARSTOW	and: EAST D YARD CLIC 0143 (AMTK 2) WATCH YOU FOOTING FOR TIES IN WALKWAY FOR 2021 CAPITOL WORK Estimated Removal Date: 11-30-21 Placed by: EACRET On: 02-07-21
64	60969	TCM	Between: EAST D YARD	and: WEST D YARD EAST END INSPECTION LEAD DO NOT EXCEED 10 MPH DUE TO FRA DEFECT Estimated Removal Date: 12-31-21 Placed by: TS RILEY On: 04-17-20
65	67852	TCM	Between: EAST D YARD	and: WEST D YARD CLIC 1449E SWITCH IS OUT OF SERVICE DUE TO TRACK CONDITION Estimated Removal Date: 03-26-21 Placed by: SANCHEZ On: 01-14-20
66	69656	TCM	Between: MP 1.0	and: MP 2.3 WATCH YOUR FOOTING BETWEEN MAIN 2 AND MAIN 3 BETWEEN MP 1.0 AND MP 2.3 DUE TO DOWNED FENCE. Estimated Removal Date: 06-30-21 Placed by: GILMORE On: 02-11-21
67	65072	TCM	Between: MP 1.0	and: MP 2.0 WATCH YOUR FOOTING AT THE EAST AND WEST END OF ALL BOWL TRACK 1401-1448 NEAR THE SKATE AND TANGENT RETARDERS DUE TO SIGNAL EQUIPMENT ADJACENT TO THE RETARDERS. Estimated Removal Date: 01-29-21 Placed by: SOTO On: 09-01-20
68	69544	TCM	Between: WEST D YARD	and: LUGO WATCH YOUR FOOTING ON MAIN 1 AND MAIN 2 MP 5.7 TO MP 39.1 ACCOUNT TIES IN THE WALKWAY FOR 2021 CAPITAL WORK. Estimated Removal Date: 07-31-21 Placed by: ROBLES On: 02-08-21
69	67175	TCM	Between: LENWOOD	and: KEENBROOK WATCH FOOTING BETWEEN MP 9.0-67.0 ON CAJON SUB. RAIL IN WALKWAY FOR 2021 RAIL RELAY PROJECTS. Estimated Removal Date: 12-31-21 Placed by: EACRET On: 11-03-20
70	67676	TCM	Between: MP 33.4	and: MP 34.6 WATCH YOUR FOOTING BETWEEN MP 33.4 AND 34.6 ALL MAINS DUE TO CONSTRUCTION ZONE. Estimated Removal Date: 09-30-21 Placed by: MONTOYA On: 01-09-20

Item No	Restr Number	Form	TCM Restrictions for CAJON Subdivision (continued)	
71	60597	TCM	Between: MARTINEZ	and: CAJON WATCH YOUR FOOTING FOR RAIL IN THE WALKWAY AT MP53.0 TO MP62.0 Estimated Removal Date: 10-30-21 Placed by: EACRET On: 04-07-20
72	66222	TCM	At: MARTINEZ	TRACK 8328 WEST 700 FT OOS DUE TO FRA DEFECTS. Estimated Removal Date: 12-31-21 Placed by: ROBLES On: 11-14-19
73	69759	TCM	At: SILVERWOOD	WATCH FOOTING AT SILVERWOOD ACCOUNT SCRAP RAIL OFF THE MAIN 1 SIDE AT THE EDGE OF THE BALLAST. Estimated Removal Date: 02-28-21 Placed by: BACKHAUS On: 02-16-21
74	63452	TCM	Between: SILVERWOOD	and: WALKER WATCH YOUR FOOTING OFF THE NORTH SIDE OF MAIN 1 AT MP58.8 BRIDGE DUE TO ROCK IN THE WALKWAY Estimated Removal Date: 12-30-21 Placed by: BACKHAUS On: 07-08-20
75	67923	TCM	Between: MP 58.0	and: MP 58.3 WATCH YOUR FOOTING ACCOUNT RAIL IN THE WALKWAY ON BOTH FIELD SIDES OF MAIN 1 AND MAIN 2 AND ALSO THE WALKWAY BETWEEN THE RAILS Estimated Removal Date: 12-11-21 Placed by: BENITO ROBLES On: 12-01-20
76	64773	TCM	Between: MP 64.0	and: MP 66.0 ON MAIN TRACK THREE AT MP 65.25 NO WALKWAY ON FIELD SIDE OF M3 DUE TO HOLE RETAINING BARRIER/HAND RAIL. Estimated Removal Date: 09-30-21 Placed by: ANSON On: 08-24-20
77	60598	TCM	Between: MP 72.0	and: MP 80.7 WATCH FOOTING DUE TO TIES ON WALKWAY Estimated Removal Date: 10-30-21 Placed by: EACRET On: 04-07-20
78	60596	TCM	Between: BASELINE	and: MP 81.3 WATCH YOUR FOOTING FOR RAIL IN THE WALKWAY AT MP80.0 TO MP81.3 Estimated Removal Date: 10-30-21 Placed by: EACRET On: 04-07-20
79	65830	TCM	Between: MP 80.3	and: MP 80.7 WATCH YOUR FOOTING FROM MP 80.4- MP 80.6 DUE TO OPEN TRANCHES ALONG THE RIDE OF WAY AND IN BETWEEN ALL MAIN TRACKS Estimated Removal Date: 09-30-20 Placed by: TEDROW On: 09-23-20



Item Restrtn Form | TCM Restrictions for CAJON Subdivision  
 No Number | (continued)

80 66351 TCM Between: MP 81.1 and: MP 81.2  
 ON THE REDLANDS INDUSTRIAL SPUR FROM MP0.0 TO MP9.5  
 WALKING CONDITIONS ARE UNEVEN DUE TO CONTINUAL CONSTRUCTION  
 MAIN LINE AND INDUSTRY TRACKS  
 Estimated Removal Date: 04-30-21  
 Placed by: POLITO On: 10-08-20

| End of TCM Restrictions for CAJON Subdivision

Item Restrtn Form | TCM Restrictions for LUCERNE VALLEY Subdivision  
 No Number |

81 67296 TCM Between: MP 20.0 and: MP 19.0  
 WATCH YOUR FOOTING BETWEEN MP19.0 TO MP20.0 DUE TO RAIL IN  
 THE WALKWAY  
 Estimated Removal Date: 06-30-21  
 Placed by: TRAVIS EACRET On: 11-06-20

| End of TCM Restrictions for LUCERNE VALLEY Subdivision

Item Restrtn Form | TCM Restrictions for SAN BERNARDINO Subdivision  
 No Number |

82 67224 TCM Between: MP 0.0 and: EAST B YARD  
 AT THE WEST END OF THE A YARD WATCH FOOTING AROUND TRACKS  
 0224 AND 0225 ACCOUNT OPEN TRENCH.  
 Estimated Removal Date: 12-31-20  
 Placed by: SANCHEZ On: 11-04-20

83 60728 TCM Between: MP 0.0 and: MP 2.0  
 IN SAN BERNARDINO YARD TRACKS 0227 0226 0217 AND 0216  
 WATCH YOUR FOOTING AROUND DERAILS AND NEW CONSTRUCTION.  
 Estimated Removal Date: 12-31-20  
 Placed by: SANCHEZ On: 04-11-20

84 69716 TCM Between: MP 0.3 and: MP 1.1  
 IN THE SAN BERNARDINO YARD WATCHING YOU FOOTING BETWEEN  
 THE  
 RUNAROUND AND THE FUELING SHED, ACCOUNT SINK HOLE CAUSING  
 UNEVEN WALKING SURFACE.  
 Estimated Removal Date: 03-31-21  
 Placed by: THOMAS POLITO On: 02-15-21

Item Restrtn Form | TCM Restrictions for SAN BERNARDINO Subdivision  
 No Number | (continued)

-----  
 85 67349 TCM Between: SAN BERNARDINO and: RANA  
 AT SAN BERNARDINO YARD, WHILE CONSTRUCTION IS OCCURRING  
 AROUND THE NEW BULL SWITCH, PLEASE WATCH FOOTING AND WALKING  
 CONDITIONS ON EAST AND WEST SIDE OF CROSSOVER. WATCH WHERE  
 YOU ARE STEPPING WHEN ASCENDING AND DESCENDING OFF CARS/  
 LOCOMOTIVES.  
 Estimated Removal Date: 12-31-20  
 Placed by: POLITO On: 11-09-20  
 -----

86 63979 TCM Between: SAN BERNARDINO and: RANA  
 WATCH YOUR FOOTING ACCOUNT UNEVEN SURFACES BETWEEN MAIN  
 TRACKS FROM MP 1.1 TO 1.5  
 Estimated Removal Date: 12-29-20  
 Placed by: ARMENDAREZ On: 07-27-20  
 -----

87 63573 TCM Between: SAN BERNARDINO and: RANA  
 AT MP 81.520, SOUTH SIDE AND EAST END OF TRACK 221, WATCH  
 YOUR FOOTING DUE TO UNEVEN WALKWAY  
 Estimated Removal Date: 12-28-20  
 Placed by: VASQUEZ On: 07-13-20  
 -----

88 60595 TCM Between: MP 1.0 and: MP 3.0  
 BETWEEN MP 1.0 AND MP 3.0 WATCH FOOTING ACCOUNT RAILROAD  
 TIES ON MAIN 3 AND THE GM LEAD.  
 Estimated Removal Date: 12-18-21  
 Placed by: EACRET On: 04-07-20  
 -----

89 63079 TCM At: WEST COLTON  
 SANJAC JOBS TRAVERSING THE UP CONNECTOR ON THE PERRIS  
 VALLEY SUB CLOSE CLEARANCES AT INDUSTRY DOCKS, DO NOT RIDE  
 CARS INTO INDUSTRY'S AND THE RUNAROUND LOCATED AT MP 4.3  
 ALONG WITH WEEDS/DEBRIS NEAR THE WALKWAYS.  
 Estimated Removal Date: 11-30-21  
 Placed by: TM ARENAS On: 06-24-20  
 -----

90 60826 TCM Between: MAY and: PRADO DAM  
 AUTOMATIC CROSSING WARNING DEVICE ACTIVATION FAILURE OR  
 SYSTEM DISABLED AT:  
 MP 27.50, RINCON RD (NOT ON MAIN TRACK)  
 STOP AND PROTECT MOVEMENT EVEN IF DEVICES ARE SEEN TO BE  
 WORKING. PROCEED PER RULE 6.32.2, PROCEDURE 1  
  
 DOT #026548A  
 Estimated Removal Date: 04-30-21  
 Placed by: ORCHARD On: 04-14-20  
 -----

Item No	Restr Number	Form	TCM Restrictions for SAN BERNARDINO Subdivision (continued)	
91	66914	TCM	<p>At: PORPHYRY            CROSSING WARNING NOTIFICATION - SUB. SAN BERNARDINO            (X) BOX 2            AUTOMATIC CROSSING WARNING DEVICE FALSE OR PARTIAL            ACTIVATION            AT MP 0.36 SIXTH STREET EAST            STOP AND PROTECT MOVEMENT, UNLESS DEVICES ARE SEEN TO BE            WORKING OR OTHERWISE INSTRUCTED.            PROTECT CROSSING PER RULE 6.32.2, PROCEDURE 2.            DOT#027403S            Estimated Removal Date: 10-31-20            Placed by: SIGNAL CALL DESK                      On: 10-26-20</p>	
92	69174	TCM	<p>Between: ATWOOD    and: FULLERTON JCT            **BACK TRACK KIMBERLY CLARK LEAD**             AUTOMATIC CROSSING WARNING DEVICE FALSE OR PARTIAL            ACTIVATION AT MP 167.3 STATE COLLEGE BLVD DOT 026686N             STOP AND PROTECT MOVEMENT UNLESS DEVICES ARE SEEN TO BE            WORKING OR OTHERWISE INSTRUCTED. PROCEED PER RULE 6.32.2            PROCEDURE 2.            Estimated Removal Date: 12-31-21            Placed by: SIGNAL    On: 01-25-21</p>	
93	67963	TCM	<p>Between: ATWOOD    and: FULLERTON JCT            AUTOMATIC CROSSING WARNING DEVICE FALSE OR PARTIAL            ACTIVATION            AT MP 166.69 RAYMOND AVE DOT 026671Y            KC LEAD ONLY            STOP AND PROTECT MOVEMENT, UNLESS DEVICES ARE SEEN TO BE             WORKING OR OTHERWISE INSTRUCTED.            PROCEED PER RULE 6.32.2, PROCEDURE 2            Estimated Removal Date: 12-31-20            Placed by: SIGNAL    On: 12-02-20</p>	
94	66936	TCM	<p>Between: ATWOOD    and: FULLERTON            **BACK TRACK KIMBERLY CLARK LEAD**             AUTOMATIC CROSSING WARNING DEVICE FALSE OR PARTIAL            ACTIVATION AT MP 166.8 ACACIA AVE DOT 026684A             STOP AND PROTECT MOVEMENT UNLESS DEVICES ARE SEEN TO BE            WORKING OR OTHERWISE INSTRUCTED. PROCEED PER RULE 6.32.2            PROCEDURE 2.            Estimated Removal Date: 12-31-20            Placed by: SIGNAL DESK    On: 10-27-20</p>	

Item No	Restr Number	Form	TCM Restrictions for SAN BERNARDINO Subdivision (continued)
95	61520	TCM	<p>Between: ATWOOD and: FULLERTON  ** BACK TRACK KIMBERLY CLARK LEAD**</p> <p>BOX 2 AUTOMATIC CROSSING WARNING DEVICE FALSE OR PARTIAL  ACTIVATION AT MP 166.2 RAYMOND AVE DOT# 026679D  STOP AND PROTECT MOVEMENT, UNLESS DEVICES ARE SEEN TO BE  WORKING OR OTHERWISE INSTRUCTED. PROCEED PER RULE 6.32.2,  PROCEDURE 2.  Estimated Removal Date: 12-31-20  Placed by: SIGNAL CALL DESK On: 05-04-20</p>
96	64759	TCM	<p>Between: MP 160.8 and: MP 160.6  AUTOMATIC CROSSING WARNING DEVICE FALSE OR PARTIAL  ACTIVATION  AT MP 160.7 LAMONT ST</p> <p>STOP AND PROTECT MOVEMENT, UNLESS DEVICES ARE SEEN TO BE  WORKING OR OTHERWISE INSTRUCTED.  PROCEED PER RULE 6.32.2, PROCEDURE 2  Estimated Removal Date: 08-23-20  Placed by: SIGNAL On: 08-23-20</p>
97	63909	TCM	<p>Between: MP 160.4 and: MP 160.2  AUTOMATIC CROSSING WARNING DEVICE FALSE OR PARTIAL  ACTIVATION  AT MP 160.3 KNOTT AVE</p> <p>STOP AND PROTECT MOVEMENT, UNLESS DEVICES ARE SEEN TO BE  WORKING OR OTHERWISE INSTRUCTED.  PROCEED PER RULE 6.32.2, PROCEDURE 2  Estimated Removal Date: 07-25-20  Placed by: SIGNAL On: 07-24-20</p>
98	69433	TCM	<p>Between: BUENA PARK and: VALLEY VIEW  **BACK TRACK NOT AFFECTING MAIN TRACK**  AUTOMATIC CROSSING WARNING DEVICE FALSE OR PARTIAL  ACTIVATION AT MP 161.30 DOLLY AVE. DOT#027860Y  STOP AND PROTECT MOVEMENT, UNLESS DEVICES ARE SEEN TO BE  WORKING OR OTHERWISE INSTRUCTED.  PROCEED PER RULE 6.32.2, PROCEDURE 2  Estimated Removal Date: 02-28-21  Placed by: SOC On: 02-03-21</p>

Item No	Restr Number	Form	TCM Restrictions for SAN BERNARDINO Subdivision (continued)
99	68551	TCM	Between: BUENA PARK and: NORWALK CROSSING WARNING NOTIFICATION - SUB. SAN BERNARDINO (X) BOX 2 AUTOMATIC CROSSING WARNING DEVICE FALSE OR PARTIAL ACTIVATION AT MP 158.1 BORATE ST DOT 02781L STOP AND PROTECT MOVEMENT, UNLESS DEVICES ARE SEEN TO BE WORKING OR OTHERWISE INSTRUCTED. PROTECT CROSSING PER RULE 6.32.2, PROCEDURE 2. Estimated Removal Date: 12-31-20 Placed by: SIGNAL CALL DESK On: 12-29-20
100	69017	TCM	Between: MP 160.0 and: MP 158.0 WATCH YOUR FOOTING AROUND ALL BALLOON TRACKS AT LA MIRADA AND LA PALMA YARDS DUE TO TIES PLACED ALONG SIDE TRACKS FOR TIE RENEWAL PROJECT. Estimated Removal Date: 12-31-21 Placed by: BARNER On: 01-19-21
101	69650	TCM	AT: MP 159.0 ***BACK TRACK ONLY-NOT AFFECTING MAIN TRACK *** AUTOMATIC CROSSING WARNING DEVICE FALSE OR PARTIAL ACTIVATION AT MP 159.0 CANARY AVENUE, DOT#027841U STOP AND PROTECT MOVEMENT, UNLESS DEVICES ARE SEEN TO BE WORKING OR OTHERWISE INSTRUCTED. PROCEED PER RULE 6.32.2, PROCEDURE 2 Estimated Removal Date: 02-28-21 Placed by: SOC On: 02-11-21
102	66905	TCM	Between: VALLEY VIEW and: NORWALK **BACK TRACK NOT ON MAIN LINE** AUTOMATIC CROSSING WARNING DEVICE FALSE OR PARTIAL ACTIVATION AT MP 157.6 CARMENITA RD. DOT 027836X. STOP AND PROTECT MOVEMENT UNLESS DEVICES ARE SEEN TO BE WORKING OR OTHERWISE INSTRUCTED. PROCEED PER RULE 6.32.2 PROCEDURE 2. Estimated Removal Date: 12-31-20 Placed by: SIGNAL DESK On: 10-26-20
103	67241	TCM	AT: MP 158.0 AUTOMATIC CROSSING WARNING DEVICE ACTIVATION FAILURE OR DISABLED AT MP 158.0 BORATE STREET DOT 027838L STOP AND PROTECT MOVEMENT EVEN IF DEVICES ARE SEEN TO BE WORKING. PROCEED PER RULE 6.32.2, PROCEDURE 1. ***THIS DOES NOT AFFECT MAIN TRACK*** Estimated Removal Date: 11-30-20 Placed by: SOC On: 11-05-20

Item No	Restr Number	Form	TCM Restrictions for SAN BERNARDINO Subdivision (continued)
104	60862	TCM	Between: SANTA FE SPRINGS and: EASTERN AVE. ** BACK TRACK NOT ON MAIN LINE** BOX 2 AUTOMATIC CROSSING WARNING DEVICE FALSE OR PARTIAL ACTIVATION AT MP 150.08 / WASHINGTON BLVD E DOT#027765D STOP AND PROTECT MOVEMENT, UNLESS DEVICES ARE SEEN TO BE WORKING OR OTHERWISE INSTRUCTED. PROCEED PER RULE 6.32.2, PROCEDURE 2. Estimated Removal Date: 12-31-20 Placed by: SIGNAL CALL DESK On: 04-15-20
105	67979	TCM	Between: MP 154.0 and: MP 153.9 ***BACK TRACK ONLY-NOT AFFECTING MAIN TRACK*** AUTOMATIC CROSSING WARNING DEVICE ACTIVATION FAILURE OR DISABLED AT MP 153.99 LOS NIETOS RD. STOP AND PROTECT MOVEMENT EVEN IF DEVICES ARE SEEN TO BE WORKING. PROCEED PER RULE 6.32.2, PROCEDURE 1. Estimated Removal Date: 12-31-20 Placed by: SM WILLIS On: 12-03-20
106	68825	TCM	Between: MP 150.0 and: MP 148.0 WATCH YOUR FOOTING UNEVEN WALKWAYS DUE TO TP46 TIE GANG WORK. HOLES AND OPEN TIE CRIBS. ON THE NORTH VAIL LEAD TRACKS (A LEAD, B LEAD AND C LEAD) BEGINNING AT MP 148.7. Estimated Removal Date: 02-28-21 Placed by: ARMENDARIZ On: 01-13-21
107	68846	TCM	Between: MP 149.9 and: MP 149.8 ***DOES NOT AFFECT MAIN TRACK*** AUTOMATIC CROSSING WARNING DEVICE ACTIVATION FAILURE OR DISABLED AT MP 149.87 WASHINGTON BLVD. C-LEAD ONLY DOT#027764W STOP AND PROTECT MOVEMENT EVEN IF DEVICES ARE SEEN TO BE WORKING. PROCEED PER RULE 6.32.2, PROCEDURE 1. Estimated Removal Date: 01-31-21 Placed by: SM BRADY On: 01-14-21
108	68997	TCM	Between: BANDINI and: EASTERN AVE. DO NOT RIDE CARS ON THE NORTH SIDE OF LOSANG 5480, WEST STORAGE TRACK. FENCE IS LEANING TOWARDS TRACK. Estimated Removal Date: 03-01-21 Placed by: FILL On: 01-19-21
109	68830	TCM	Between: BANDINI and: COMMERCE MP 147.56 LINE SEGMENT 7600 TRACK LOSANG 5252. CARS NEED TO BE SPOTTED AT LEAST 25 FEET FROM WHEEL STOPS AT PREMIER FOODS DUE TO BROKEN WHEEL STOP. Estimated Removal Date: 03-01-21 Placed by: LA MIRADA TM On: 01-14-21

Item Restrtn Form | TCM Restrictions for SAN BERNARDINO Subdivision  
 No Number | (continued)

-----  
 110 68535 TCM | Between: BANDINI and: EASTERN AVE.  
 \*\*BACK TRACK NOT ON MAIN LINE\*\*  
 DOT 027765D  
 BOX 1  
 AUTOMATIC CROSSING WARNING DEVICE ACTIVATION FAILURE OR  
 DIASABLED AT MP 149.15 WASHINGTON BLVD STOP AND PROTECT  
 MOVEMENT EVEN IF DEVICES ARE SEEN TO BE WORKING. PROCEED  
 PER RULE 6.32.1 PROCEDURE 1  
 Estimated Removal Date: 12-31-20  
 Placed by: YOUKHANA On: 12-28-20  
 -----

-----  
 111 68533 TCM | Between: BANDINI and: COMMERCE  
 \*\*\*BACK TRACK ONLY-NOT AFFECTING MAIN TRACK\*\*\*  
 AUTOMATIC CROSSING WARNING DEVICE ACTIVATION FAILURE OR  
 DISABLED AT MP 149.15 WASHINGTON BLVD B LEAD.  
 STOP AND PROTECT MOVEMENT EVEN IF DEVICES ARE SEEN TO BE  
 WORKING. PROCEED PER RULE 6.32.2, PROCEDURE 1.  
 Estimated Removal Date: 12-31-20  
 Placed by: SM YOUKHANA On: 12-28-20  
 -----

-----  
 112 66103 TCM | Between: BANDINI and: EASTERN AVE.  
 WATCH YOUR FOOTING THROUGHOUT THE ENTIRE COMMERCE DSF  
 DUE TO CONSTRUCTION.  
 Estimated Removal Date: 12-31-20  
 Placed by: YOUKHANA On: 10-02-20  
 -----

-----  
 113 62687 TCM | Between: BANDINI and: EASTERN AVE.  
 \*\* BACK TRACK NOT ON MAIN LINE \*\*  
 AUTOMATIC CROSSING WARNING DEVICE FALSE OR PARTIAL  
 ACTIVATION  
 AT MP 150.10 WASHINGTON BLVD. DOT 027766K  
  
 STOP AND PROTECT MOVEMENT, UNLESS DEVICES ARE SEEN TO BE  
  
 WORKING OR OTHERWISE INSTRUCTED.  
 PROCEED PER RULE 6.32.2, PROCEDURE 2  
 Estimated Removal Date: 11-30-20  
 Placed by: SOC On: 06-11-20  
 -----

-----  
 114 60835 TCM | Between: BANDINI and: COMMERCE  
 A NEW COMMERCE DSF DERAIL IS INSTALLED AND OPERATIONAL  
 APPROXIMATELY 600 FT WEST OF THE EXISTING WEST DSF DERAIL  
 ON TRACK 4700.  
 Estimated Removal Date: 12-31-21  
 Placed by: DAVIS On: 04-14-20  
 -----

Item No	Restr Number	Form	TCM Restrictions for SAN BERNARDINO Subdivision (continued)
115	68853	TCM	Between: MP 149.5 and: MP 149.4 ***DOES NOT AFFECT MAIN TRACK*** AUTOMATIC CROSSING WARNING DEVICE ACTIVATION FAILURE OR DISABLED AT MP 149.49 MALT AVE DOT#027763P STOP AND PROTECT MOVEMENT EVEN IF DEVICES ARE SEEN TO BE WORKING. PROCEED PER RULE 6.32.2, PROCEDURE 1. Estimated Removal Date: 01-31-21 Placed by: SM MC FARLIN On: 01-14-21
116	68789	TCM	Between: MP 149.0 and: MP 148.6 LINE SEGMENT 7600 BETWEEN MP 148.6 AND MP 149.0 ON THE NORTH VAIL A, B AND C LEADS WATCH YOUR FOOTING DUE TO CONSTRUCTION, TIES ARE ON THE WALKWAYS ON ALL LEADS. Estimated Removal Date: 12-31-21 Placed by: WILLIAMS On: 01-12-21
117	69907	TCM	At: COMMERCE INDUSTRY LEAD AT COMMERCE MP 147.1 TO MP 147.9. BOTH SIDES OF THE TRACK BE ON THE LOOKOUT FOR MOW MATERIALS, UNEVEN WALKING SURFACES AND DISTURBED WALKWAYS. Estimated Removal Date: 03-30-21 Placed by: DERIEUX On: 02-22-21
118	68777	TCM	Between: COMMERCE and: EASTERN AVE. WATCH YOUR FOOTING ON THE INDUSTRY TRACK FROM EASTERN AVE TO THE WESTEND OF COMMERCE ACCOUNT TIES ON THE RIGHT OF WAY Estimated Removal Date: 10-31-21 Placed by: JESSE MENDEZ On: 01-11-21
119	65666	TCM	Between: MP 148.0 and: MP 146.0 BETWEEN CONTOL SIGNALS AT EASTERN AVE. FIELD SIDE OF MAIN 3 WATCH YOUR FOOTING DUE TO SIGNAL CONSTRUCTION. Estimated Removal Date: 09-30-20 Placed by: SM YOUKHANA On: 09-18-20
120	69436	TCM	Between: MP 147.4 and: MP 147.2 WATCH FOOTING OFF RIGHT AWAY OF MAIN TRACK 3 Estimated Removal Date: 04-03-21 Placed by: NEWSOM On: 02-03-21
121	68778	TCM	Between: EASTERN AVE. and: EAST HOBART WATCH YOUR FOOTING ON SETOUT TRACK FROM 710 FREEWAY MP 146.5 TO EASTERN AVE ACCOUNT TIES ON THE RIGHT OF WAY Estimated Removal Date: 10-31-21 Placed by: JESSE MENDEZ On: 01-11-21
122	66618	TCM	Between: EAST HOBART and: HOBART M1 BETWEEN HOBART AND EAST HOBART, SWITCH 145EW IS OUT OF SERVICE. SIGNAL DEPARTMENT LOCKS APPLIED. Estimated Removal Date: 10-31-20 Placed by: AGUILAR On: 10-17-20



Item Restrnr Form | TCM Restrictions for SAN BERNARDINO Subdivision  
 No Number | (continued)

-----  
 123 60966 TCM Between: EAST HOBART and: WEST HOBART  
 WATCH FOOTING ACCOUNT RAILS BETWEEN SET OUT TRACK AND BUGGY  
 0 AT HOBART.  
 Estimated Removal Date: 12-31-21  
 Placed by: UTU On: 04-17-20  
 -----

124 64188 TCM At: HOBART  
 UNTIL FURTHER NOTICE; BE ON THE LOOKOUT FOR POSSIBLE LIVE  
 FLAGMAN PROTECTING 6TH STREET BRIDGE PROJECT MP 141.6.  
 TEMPORARY  
 CONSTRUCTION CROSSING AT THIS LOCATION. CROSSING IS PROTECT  
 BY  
 DERAILS ON BOTH SIDES WHICH ARE LOCKED ON RAIL WITH MOW  
 LOCKS. THIS AFFECTS YARD TRACKS 1802, 1803, 1804, AND 1805.  
 UPON APPROACH CONTACT BNSF EIC ON CHANNEL 47 WHO WILL JOB  
 BRIEF WITH THE CONSTRUCTION AND TRAIN CREW TO MAKE SAFE  
 MOVEMENT THROUGH THE CONSTRUCTION AREA.  
 IF UPON APPROACH DERAILS AND FLAGS ARE FOUND TO BE DOWN AND  
 LOCKED OFF RAIL, AND NO EIC CONTACT MADE; OK TO PROCEED  
 WITH SWITCHING.  
 Estimated Removal Date: 12-31-21  
 Placed by: AP TREVIZO On: 09-18-19  
 -----

125 63613 TCM At: HOBART  
 UNTIL FURTHER NOTICE CUT AND CLEAR THE CONSTRUCTION CROSSIN  
 FOR 6TH STREET BRIDGE PROJECT AT MP 141.6. THE TEMPORARY  
 CONSTRUCTION CROSSING MUST BE CLEARED AT THIS LOCATION WITH  
 THE CUT OF CARS BEHIND THE DERAILS ON BOTH SIDES OF THE  
 CROSSING.  
 THIS AFFECTS YARD TRACKS 1801, 1802, 1803 AND 1804.  
 Estimated Removal Date: 07-04-21  
 Placed by: TREVIZO On: 08-30-19  
 -----

126 68354 TCM At: HOBART  
 AT FIRST STREET YARD; DO NOT WALK ON THE NORTH OR EAST SIDE  
 OF TRACK 1802 BETWEEN MP 141.3 AND MP 141.6 ACCOUNT 6TH ST.  
 BRIDGE CONSTRUCTION. TEMPORARY FALSEWORK, BEAMS AND BRIDGE  
 SUPPORTS BEING ERECTED BETWEEN METROLINK MAIN 4 AND BNSF  
 YARD TRACK 1802 IN THIS AREA.  
 Estimated Removal Date: 12-31-21  
 Placed by: TREVIZO On: 07-12-18  
 -----

| End of TCM Restrictions for SAN BERNARDINO Subdivision  
 =====

Item Restrnr Form | TCM Restrictions for SAN DIEGO Subdivision  
 No Number |

Item No	Restr Number	Form	TCM Restrictions for SAN DIEGO Subdivision (continued)
127	69181	TCM	<p>Between: NATIONAL CITY and: FULLERTON JCT.            ***KIMBERLY CLARK LEAD***</p> <p>AUTOMATIC CROSSING WARNING DEVICE ACTIVATION FAILURE OR DISABLED AT MP 168.2 MELROSE AVE.            STOP AND PROTECT MOVEMENT EVEN IF DEVICES ARE SEEN TO BE WORKING.            PROCEED PER FULE 6.32.2 PROCEDURE 1.</p> <p>DOT# 026689.            Estimated Removal Date: 12-31-21            Placed by: ANGULO On: 01-26-21</p>
128	69151	TCM	<p>Between: NATIONAL CITY and: SAN DIEGO            NEAR MP 271 CLIC 7839, 32ND STREET RUN AROUND, IS OUT OF SERVICE DUE TO OVERGROWN VEGETATION, TRASH/DEBRIS, AND HOMELESS ENCAMPMENT</p> <p>Estimated Removal Date: 07-31-21            Placed by: FOREMAN 331 On: 01-25-21</p>
129	68644	TCM	<p>At: NATIONAL CITY            ***IRVINE INDUSTRIAL COMPLEX***            BOX (1)</p> <p>AUTOMATIC CROSSING WARNING DEVICE ACTIVATION FAILURE OR DISABLED AT MP 177.90 EDINGER AVE. DOT#026707E            STOP AND PROTECT MOVEMENT EVEN IF DEVICES ARE SEEN TO BE WORKING</p> <p>Estimated Removal Date: 01-25-21            Placed by: LUNA On: 01-04-21</p>
130	68567	TCM	<p>Between: NATIONAL CITY and: SAN DIEGO            AT SAN DIEGO YARD THE WEST END OF TRACKS 9831W, 9832W AND 9833W SWITCHES ARE OUT OF SERVICE DUE TO DERAILMENT. THESE TRACKS ARE ALSO OUT OF SERVICE AT THE WEST END AT THE CLEARANCE POINTS.</p> <p>Estimated Removal Date: 07-31-21            Placed by: TM DANLEY On: 12-30-20</p>
131	67802	TCM	<p>Between: NATIONAL CITY and: FULLERTON JCT.            WATCH YOUR FOOTING FOR OTM AND SWITCHES ON THE GROUND FROM MP 268.6 TO MP 269.1 ON THE RIGHT OF WAY</p> <p>Estimated Removal Date: 07-31-21            Placed by: LENTI On: 11-25-20</p>

Item No	Restr Number	Form	TCM Restrictions for SAN DIEGO Subdivision (continued)
132	67720	TCM	<p>Between: NATIONAL CITY and: FULLERTON JCT.            ***IRVINE INDUSTRIAL COMPLEX***            BOX (1)            AUTOMATIC CROSSING WARNING DEVICE ACTIVATION FAILURE OR            DISABLED AT            MP 179.6 REDHILL DOT#026715W            MP 179.30 DYRE RD DOT #0267114U            MP 179.15 CARNEGIE AVE DOT #026728X            MP 178.8 WARNER AVE DOT# 026710M            STOP AND PROTECT MOVEMENT EVEN IF DEVICES ARE SEEN TO BE            WORKING. PROCEED PER RULE 6.32.2, PROCEDURE 1.            Estimated Removal Date: 11-24-20            Placed by: MOLINAR On: 11-23-20</p>
133	67408	TCM	<p>Between: NATIONAL CITY and: FULLERTON JCT.            ***IRVINE INDUSTRIAL COMPLEX***            AUTOMATIC CROSSING WARNING DEVICE ACTIVATION FAILURE OR            DISABLED AT MP 181.0 MC GAW AVE            STOP AND PROTECT MOVEMENT EVEN IF DEVICES ARE SEEN TO BE            WORKING. PROCEED PER RULE 6.32.2, PROCEDURE 1.            DOT 026720T            Estimated Removal Date: 11-30-20            Placed by: SM MOLINAR On: 11-11-20</p>
134	67354	TCM	<p>Between: NATIONAL CITY and: FULLERTON JCT.            WATCH YOUR FOOTING FOR A HOLE IN THE GROUND ON THE BRIDGE            AT MP 269.076 ON THE RIGHT OF WAY.            Estimated Removal Date: 03-31-21            Placed by: LENTI On: 11-09-20</p>
135	67244	TCM	<p>Between: NATIONAL CITY and: FULLERTON JCT.            ***IRVINE INDUSTRIAL COMPLEX***            AUTOMATIC CROSSING WARNING DEVICE ACTIVATION FAILURE OR            DISABLED AT MP 181.2 VAN KARMAN AVE DOT 026721A            STOP AND PROTECT MOVEMENT EVEN IF DEVICES ARE SEEN TO BE            WORKING. PROCEED PER RULE 6.32.2, PROCEDURE 1.            Estimated Removal Date: 11-30-20            Placed by: SM MOLINAR On: 11-05-20</p>
136	64672	TCM	<p>Between: NATIONAL CITY and: FULLERTON JCT.            IRVINE INDUSTRIAL COMPLEX             AUTOMATIC CROSSING WARNING DEVICE FALSE OR            PARTIAL            ACTIVATION            AT MP 178.3 VALENCIA AVE             STOP AND PROTECT MOVEMENT, UNLESS DEVICES ARE SEEN TO BE            WORKING OR OTHERWISE INSTRUCTED.            PROCEED PER RULE 6.32.2, PROCEDURE 2            Estimated Removal Date: 08-20-20            Placed by: SIGNAL On: 08-19-20</p>

Item No	Restr Number	Form	TCM Restrictions for SAN DIEGO Subdivision (continued)
137	64453	TCM	<p>At: NATIONAL CITY  AUTOMATIC CROSSING WARNING DEVICE FALSE OR PARTIAL  ACTIVATION  AT MP 273.2 BAY MARINA DR (SPUR TRACK ONLY)</p> <p>STOP AND PROTECT MOVEMENT, UNLESS DEVICES ARE SEEN TO BE  WORKING OR OTHERWISE INSTRUCTED.  PROCEED PER RULE 6.32.2, PROCEDURE 2  Estimated Removal Date: 08-13-20  Placed by: SIGNAL On: 08-12-20</p>
138	69653	TCM	<p>Between: NATIONAL CITY and: FULLERTON JCT.  ***IRVINE INDUSTRIAL COMPLEX***  BOX (1)  AUTOMATIC CROSSING WARNING DEVICE ACTIVATION FAILURE OR  DISABLED AT MP 179.34 MCGAW AVE. DT#026722G.  STOP AND PROTECT MOVEMENT EVEN IF DEVICES ARE SEEN TO BE  WORKING.  Estimated Removal Date: 12-31-20  Placed by: SIGNAL CALL DESK On: 03-10-20</p>
139	67993	TCM	<p>AT: MP 268.9  AT MP 268.9 TRACK 9801 WB WHISTLE BOARD MISSING  Estimated Removal Date: 01-07-21  Placed by: FRMN LENTI On: 12-03-20</p>
140	60967	TCM	<p>Between: MP 268.1 and: MP 267.6  WATCH YOUR FOOTING ON MAIN TRACK FROM MP 267.6-267.6 DUE TO  RIBBON RAIL LAID ON EACH SIDE OF TRACK.  Estimated Removal Date: 12-31-21  Placed by: VANADESTINE On: 04-17-20</p>
141	66484	TCM	<p>At: SAN DIEGO  AT THE MIRAMAR COMPLEX, CLOSE CLEARANCE ON TRACK 5001  BETWEEN CARROLL CANYON ROAD (DOT# 026959F) AND PRODUCTION  AVENUE (DOT# 026956K).  Estimated Removal Date: 01-13-21  Placed by: W NARRON On: 10-13-20</p>
142	60440	TCM	<p>Between: SAN DIEGO and: FULLERTON JCT.  BOX 2 AUTOMATIC CROSSING WARNING DEVICE FALSE OR PARTIAL  ACTIVATION MP 166.8 ACACIA AVE. STOP AND PROTECT MOVEMENT,  UNLESS DEVICES ARE SEEN TO BE WORKING OR OTHERWISE  INSTRUCTED. PROCEED PER RULE 6.32.2 PROCEDURE 2. KIMBERLY  CLARK LEAD ONLY</p> <p>DOT 026684A  Estimated Removal Date: 07-31-20  Placed by: DS 15 On: 04-02-20</p>

Item No	Restr Number	Form	TCM Restrictions for SAN DIEGO Subdivision (continued)
143	69012	TCM	<p>Between: MP 165.5 and: MP 165.4  ON KIMBERLY CLARK LEAD ONLY  AUTOMATIC CROSSING WARNING DEVICE FALSE OR PARTIAL  ACTIVATION AT MP 167.3 STATE COLLEGE BLVD. DOT#026686N  STOP AND PROTECT MOVEMENT, UNLESS DEVICES ARE SEEN TO BE  WORKING OR OTHERWISE INSTRUCTED.  PROCEED PER RULE 6.32.2, PROCEDURE 2.  Estimated Removal Date: 01-31-21  Placed by: SOC On: 01-19-21</p>
144	64665	TCM	<p>AT: MP 165.5  ***** AT IRVINE INDUSTRIAL COMPLEX *****  AUTOMATIC CROSSING WARNING DEVICE ACTIVATION FAILURE OR  DISABLED AT MP 180.2 ARMSTRONG,  STOP AND PROTECT MOVEMENT EVEN IF DEVICES ARE SEEN TO BE  WORKING. PROCEED PER RULE 6.32.2, PROCEDURE 1.  DOT# 026718S  Estimated Removal Date: 12-31-20  Placed by: SIGNAL DESK On: 08-19-20</p>
145	60707	TCM	<p>Between: MP 165.5 and: MP 165.4  ON THE KIMBERLY CLARK LEAD ONLY  BOX (1) AUTOMATIC CROSSING WARNING DEVICE ACTIVATION  FAILURE OR DISABLED AT MP 167.77 KIMBERLY STREET  STOP AND PROTECT MOVEMENT EVEN IF DEVICES ARE SEEN TO BE  WORKING. PROCEED PER RULE 6.32.2, PROCEDURE 1  DOT# 026068M  Estimated Removal Date: 01-31-21  Placed by: SM FELI On: 04-10-20</p>
			End of TCM Restrictions for SAN DIEGO Subdivision

LOCOMOTIVE SAFETY MESSAGES

LOCOMOTIVE	SAFETY MESSAGE
BNSF 8156	No Safety Message for this Locomotive
BNSF 6240	No Safety Message for this Locomotive
BNSF 7226	No Safety Message for this Locomotive
BNSF 7760	No Safety Message for this Locomotive
BNSF 3751	No Safety Message for this Locomotive