


National Transportation Safety Board Investigative Hearing

Norfolk Southern Railway general merchandise freight train 32N derailment with subsequent hazardous material release and fires, in East Palestine, Ohio, on February 3, 2023



Agency / Organization

NTSB

Title


NTSB Materials Laboratory gasket photographs GATX95098 pressure plate and OCPX80235 pressure relief device


Docket ID: DCA23HR001

NTSB Materials Laboratory photographs of recovered gasket materials.

1. GATX95098 pressure plate gasket, recovered from East Palestine, Ohio tank car staging area on February 22, 2023.







2. OCPX80235 pressure relief device gasket, recovered during valve tear down at TrinityRail Car Repair, 2850 Peden Rd., Saginaw, Texas, March 15, 2023.

