



**Survival Factors Attachment-
Incident Commander Report**

**Reed, PA
RRD22LR003**

(4 pages)



Halifax Fire Department
 Station: **029**
 Shifts Or Platoon: **2 - 0800-1600**

Location: S River RD Reed (Township of) PA 17032 North of Mountain Road	Incident Type: 357 - Extrication of victim(s) from machinery
Lat/Long: N 41° 7' 42.6" W 76° 53' 21.04"	EMSID: FDID: 22029 Incident #: 2021-0012184 Exposure ID: 62953423 Incident Date: 12/08/2021 Dispatch Run #: 21-238
Zone: 29-5 - Reed Twp (East Shore) Location Type: 5 - Adjacent to Population Density: Rural Cross Street, Directions or National Grid: North of Mountain Road	

Report Completed by:	Neiter, Timothy	ID: 29012	Date: 12/13/2021
Report Reviewed by:	Not Reviewed		
Report Printed by:	Neiter, Timothy	ID: 29012	Date: 12/13/2021 Time: 09:41

Aid Given or Received:	Mutual aid received	Primary action taken:	78 - Control traffic
Total # of apparatus on call:	4	Total # of personnel on call:	11

Special Studies	
COVID 19 was a factor in this incident.	No, COVID 19 was not a factor.

Neighboring Agencies
Agency Name: Halifax EMS Agency ID: Co13 Agency Type: EMS Mutual Aid
Agency Name: Life Team EMS Agency ID: Co6 Agency Type: EMS Mutual Aid
Agency Name: PA State Police (PSP) Agency ID: PSP Agency Type: Law
Agency Name: Rescue fire Company- Susquehanna Township Agency ID: 22037 Agency Type: Fire
Agency Name: Williamstown EMS Agency ID: Co24EMS Agency Type: EMS Mutual Aid

NARRATIVE (1)**Narrative Title:** n/a**Narrative Author:** Neiter, Timothy**Narrative Date:** 12/13/2021 09:38:19**Narrative Apparatus ID:** n/a**Narrative:**

Dispatched for Traumatic Injuries. Chief 29 en route advised that patient was trapped under a piece of railroad equipment. Chief 29 requested Rescue 37 to be added. Chief on board utility. Was advised to use access road south of incident past railroad bridge to access scene. AOS to find railroad maintenance crew working to rescue patient. Observed patient pinned under railroad equipment (see picture attached - equipment on left). Patient was in 'ball' face down between railroad tracks under equipment. Railroad crew stated that patient was under equipment for at least 15 minutes and unknown whether he was breathing. Patient was not moving or making any sounds. Railroad crew was using crane (on right side of attached picture) to lift equipment off of patient. Within approx 1 minute of my arrival, equipment had been lifted and maintenance crew pulled patient from under equipment south until patient cleared equipment. EMS 24 and EMS chief 13 had arrived on scene and began CPR.

Fire Police advised to shut down S River Road at Mountain Road and Brubaker road.

Engine 29-1 aos and i advised to park on South River Road in area of incident and place ladder over guard rail to access. Crew assisted with providing CPR. R37 aos and placed in service. Medic Stilo arrived, assessed and called for signal 12. Observed patient had head wounds, left leg wound in area of ankle.

PSP asked roadway keep closed for investigation. U 29-1 and FP 29 closed road and detoured traffic to Mountain Road from South and Brubaker Road from North. U 29 driven by FF Gros reassigned to assist with traffic control at intersection of Mountain Road/Brubaker Road.


Units from EMS 24, Lifeteam, EMS 13, R37, PSP, OSHA and Federal Railroad Admin on scene.No incidents to report.

APPARATUS

Unit	E29-1	Unit	U29
Type:	Engine	Type:	Support apparatus, other
Use:	Suppression	Use:	Other
Response Mode:	Lights and Sirens	Response Mode:	Lights and Sirens
# of People	5	# of People	1
Alarm	12 /08/2021 11:25:00	Alarm	12 /08/2021 11:25:00
Dispatched	12 /08/2021 11:25:00	Dispatched	12 /08/2021 11:25:00
Enroute	12 /08/2021 11:35:00	Enroute	12 /08/2021 11:29:00
Arrived	12 /08/2021 11:41:00	Arrived	12 /08/2021 11:32:00
Cancelled	-- / -- / -- -- : -- : --	Cancelled	-- / -- / -- -- : -- : --
Cleared Scene	12 /08/2021 14:47:00	Cleared Scene	12 /08/2021 14:47:00
In Quarters	-- / -- / -- -- : -- : --	In Quarters	-- / -- / -- -- : -- : --
In Service	12 /08/2021 14:47:00	In Service	12 /08/2021 14:47:00
Unit	U29-1	Unit	FP29
Type:	Support apparatus, other	Type:	Other apparatus/resource
Use:	Other	Use:	Other
Response Mode:	No Lights or Sirens	Response Mode:	Lights and Sirens
# of People	2	# of People	1
Alarm	12 /08/2021 11:25:00	Alarm	12 /08/2021 11:25:00
Dispatched	12 /08/2021 11:47:00	Dispatched	12 /08/2021 11:35:00
Enroute	12 /08/2021 11:47:00	Enroute	12 /08/2021 11:35:00
Arrived	12 /08/2021 11:51:00	Arrived	12 /08/2021 11:41:00
Cancelled	-- / -- / -- -- : -- : --	Cancelled	-- / -- / -- -- : -- : --
Cleared Scene	12 /08/2021 14:47:00	Cleared Scene	12 /08/2021 14:47:00
In Quarters	-- / -- / -- -- : -- : --	In Quarters	-- / -- / -- -- : -- : --
In Service	12 /08/2021 14:47:00	In Service	12 /08/2021 14:47:00
Number Of People not on apparatus: 2			

PEOPLE -- PERSON 1			
Is Owner	False	Business Name	
Telephone Number		Involvement	Patient
Name	Helbert K Parker	Date of Birth	
Address	Kingsport, TN 37664-5818		

CUSTOM FIELDS FORM
County Dispatch Code
If applicable - Pin, Job, Search
Alarm Level

INCIDENT IMAGES


PERSONNEL ON CALL			
Name	Personnel Rank	Role(s)	Apparatus
Boyer, Austin	Firefighter		Other
Culhane, Patrick	Probationary		U29-1
Gros, Daniel	Firefighter		E29-1
Herrold, Matthew	Assistant Chief	58 - Drive / Operate apparatus or vehicle	E29-1
Lower, Diane	Lt. Fire Police		FP29
Neiter, Timothy	Chief	58 - Drive / Operate apparatus or vehicle, 81 - Incident command	U29
Pottiger, Cody	Firefighter		E29-1
Pottiger, Nathan	Firefighter		E29-1
Pottiger, Robert	Firefighter	58 - Drive / Operate apparatus or vehicle	U29-1
Pottiger, Thomas	Assistant Chief		E29-1
Warfel, Sherm	Lieutenant		Other