

Photo 1 – main wreckage, front view (FAA)



Photo 2 – throttle cable disconnected, bolt and nut missing (FAA)