



Photo 1 – View of nose gear bent aft



Photo 2 –View of airplane inverted on runway showing structural damage to fuselage.