

From: [Kyle Duncan](#)
To: [Flaherty David](#); [REDACTED]
Cc: [REDACTED]; [Michael Madsen](#)
Subject: RE: Kodiak Enterprise - Fire Control Plans
Date: Thursday, July 20, 2023 10:50:53 AM

[CAUTION] This email originated from outside of the organization. Do not click any links or open attachments unless you recognize the sender and know the content is safe.

Good morning David. Answers to your questions below. Let me know if you need any clarification.

1. There were no smoke or heat detectors in the dry stores room.
 - a. I believe there was one smoke detector in the dry stores room, though I cannot guarantee this.
2. There were no smoke or heat detectors in the deck locker located above the dry stores room.
 - a. As far as I know this is correct.
3. The control panel for the fire detection system was only located on the bridge.
 - a. The fire and smoke sensors were all tied in to the ships main alarm system. There were control panels in the following locations: Bridge, Engine Control Room, Watermaker room, and Refrigeration room.
4. The control panel for the fire detection system had a wireless notification system, but it did not notify the designated personnel the night of the fire.
 - a. Correct. I can confirm that the wireless notifications system was working as late as March 31st. I have an email generated from that system when it was triggered due to smoke from hotwork activities in the bow thruster space. It did not send out any notifications the night of the fire. I can't be certain why.
5. The control panel for the fire detection system had an audible alarm, but it was not connected to the vessel's general alarm or other internal communication systems on the vessel.
 - a. Correct. The ships alarm system, of which the fire detection equipment was part of, was not tied in to the general alarm. There were strobes and audible alarms dedicated to that system, but it did not cross over to the general alarm.

Please contact vendor with PO.

Thanks,
-Kyle

From: Flaherty David [REDACTED] >
Sent: Thursday, July 20, 2023 5:02 AM
To: Kyle Duncan [REDACTED] LT USCG SEC PUGET
SND (USA) [REDACTED]
Cc: [REDACTED]
Subject: Kodiak Enterprise - Fire Control Plans
Importance: High

HI

Hope all is well.

I just want to confirm the following about the vessels fire detection and notification system:

1. There were no smoke or heat detectors in the dry stores room.
2. There were no smoke or heat detectors in the deck locker located above the dry stores room.
3. The control panel for the fire detection system was only located on the bridge.
4. The control panel for the fire detection system had a wireless notification system, but it did not notify the designated personnel the night of the fire.
5. The control panel for the fire detection system had an audible alarm, but it was not connected to the vessel's general alarm or other internal communication systems on the vessel.

Please let me know if you have any questions concerning this.

Thanks & Take Care

Captain David M. Flaherty
Senior Marine Engineer,
Major Investigations, Office of Marine Safety
National Transportation Safety Board

CONFIDENTIALITY NOTICE - THIS E-MAIL TRANSMISSION MAY CONTAIN INFORMATION THAT IS PRIVILEGED, CONFIDENTIAL, PROPRIETARY, SUBJECT TO COPYRIGHT, AND/OR EXEMPT FROM DISCLOSURE UNDER APPLICABLE LAW. IT IS FOR THE USE OF INTENDED RECIPIENTS ONLY. If you are not an intended recipient of this message, please notify the original sender immediately by forwarding what you received and then delete all copies of the correspondence and attachments from your computer system. Any use, distribution, or disclosure of this message by unintended recipients is not authorized and may be unlawful.

CONFIDENTIALITY NOTICE

The information in this message is intended only for the addressee or the addressee's authorized agent. The message may contain information that is privileged, confidential, or otherwise exempt from disclosure. If the reader of this message is not the intended recipient or the recipient's authorized agent, then you are notified that any dissemination, distribution or copying of this message is prohibited. If you have received this message in error, please reply to the sender and then delete the message.