	Kodiak Enterprise 1104 Master Worklist Spring 2023			
	Repair Project Tacoma			
Labor Code Ex:	Arrival 3/24/23 Depart			
KOD 61.40011	C=crew V=vendor Y=yard PP=postpone OPS=operations CXL=cancelled			ated 04/10/23
Vessel Abbv. CC abbv.Mat Grp	Material Group / GL # 612006 / Cost Center	Budget	Assign	Status
KOD 00.xxxxx	Cost Center CATCHING - nets, trawl gear, pots, blocks, stern gate/rol	ler		
40003	Electrical			
	Naust System Inspection		v	5%
40006	Equipment			
	Inspect / Repair all winch brakes		cy	30%
	Need to remove PMW Adjuster screw on brake band to free up for proper adjustment		y	50%
	Rebuild 6 main winch level wind roller		y	50%
	Need to Inspect Brakes and clean all 3 Cod End winches and Both Gilsons Clean & Inspest brk.		c	
	Need 2 level wind roller made out of stainless steel for 3rd wire winch.		y	10%
	Net Helix 1280, headrope is broken under the kite. Foot chain is twisting up, replace 3 strand bars off the foot chain, check the backend 4inch		у	
	Send 80 ton trawl blocks in to to be serviced/rebuilt.		cv	10%
	Replace port main winch air brake		у	50%
KOD 60.xxxxx	Cost Center MANUFACTURING - factory / production			
0300	Pipes, Valves & Fittings			
	Inspect/repair all factory overboard through hull piping (ABS required)		V	10%
	Repair hot water line leak above lab. Copper/PEX.		y	
	Install flow switch on discharge of Factory SW Supply Pumps		yc	
	Replace Factory Saltwater piping in Watermaker space in bilge		у	
40003	Electrical			
	Refurbish communication beacon for offload emergency stops in the freezer hold.		c	
	Refurbish electrical box for offload system at the boxilator.		V	PP
	Refurbish all freezer hold conveyor/stanchion oulet internals.		cv	PP
	Continue light replacement with LED sticks.		cv	
	New Computer for plate freezers HMI.			
40006	Equipment			
	Refurbish cod table.		c	
40011	Hydraulics			
	Send out one main factory hydraulic pump for refurbish.		cv	
	Inspect/repair hydraulic hoses and fittings.		yv	
	1 Hydraulic clean up at motor/Estop bypass.		v	

40015	Production		
10012	Inspect/repair fish sorter bearings.	c	25%
	Inspect fish oil decanter and clarifier. Alfa Laval Bobby Jensen.	v	10%
	Inspect/repair case up strappers.	c	
	Replace #4 Baader 54 skinner with Baader 52 skinner.	cv	90%
	Inspect/replace fwd bearing on Alfa Laval 438. Does not accept grease.	v	10%
	Inspect/repair extruders and metering hoppers.	c	
50001	Services		
	Pressure wash/sanitize freezer hold.	v	
KOD 61.xxxxx	Cost Center - FACILITY - house, galley, bunks, heads - non prod	uction	
0300	Pipes, Valves & Fittings		
	Retrofit 01 shower valves	c	
	Repair section of 3" Fire Main Line 02 level stair well overhead going into Electrician shop	у	100%
40002	Construction Supplies & Services		
	Re cover bench cushion in deck shack and captains chair in the wheelhouse.	v	
	Replace floor in bathroom in room 02-18 (Night Deck Boss room).	v	
	Replace floor in bathroom rooms 01-05 and 01-04 (Deckhands room)	v	
	Refinish all wood window frames and Seals in Wheel House	V	PP
	Replace vinyl flooring in 1st Eng. Stateroom, deck is rusted	V	
	Repair lavatory cabinet in 01-12.	V	
	Repair 01 companionway head deck. This gets a lot of use and needs an overhaul badly	V	
	New floors Deck Shack and Head	V	
40003	Electrical		
	Trouble Shoot Inspect Chloropac High Voltage Output slowly increasing?	cv	100%
40006	Equipment		
	Research 02 Port hot water space exhaust fan, area needs more airflow through hallway.	yv	
40009	Galley		
	Exhaust trunk from surimi area port fwd has leak into galley area. Sour smell under galley cupboards. (Also smells in 02-4 & 02-3 State Rooms)	v	10%
	Repair pex tubing in galley overhead - can't find leak	y	CXL
	1 Service Dishwasher (Hobart)	v	25%
	Service Ovens (Lang)	v	
	Service / Replace Coffee machine (Harbor Foods)	v	
	Service Beverage Machine (Harbor Foods)	v	
	Service Chemical Dispensers (Wesmar)	v	
	Domestic Freezer & Chiller - Pressure test and find leaks in evaporator/piping	v	100%
40020	Safety		
	Repair stair landing in breakroom.	у	10%

50001	Services		
	Bring in vendor to tune-up oil fire boiler / Weld studs and replace gaskets	v	
	Inspect and repair feed water leak at stack boiler connection - done last season	у	100%
	Eddy current testing of stack tube boiler	v	PP
Day of	1 Repair Blow Down Overboard line for Waster Heat Boiler	У	20%
KOD 62.xxxxx	Cost Center POWER & PROPULSION		
0300	Pipes, Valves & Fittings		
	Replace steering directional control valves	v	10%
	Inspect all M.E. Copper Nickel cooling water piping on Heat exchangers Replace as Needed	y	e
40004	Engines & Generators		
	Re-route crankcase exhaust for #2 AUX	У	,
	Replace Port & STBD ME's exhaust bellows, heat shields and refractory on exhaust, Tune up engines (Fairbanks Morse)	c	v 10%
	Clean all three generators	v	
Day of	1 Repair exhaust bellows leaks on both 3512B's	V	75%
Within 3 Days	Tune up/safeties/air gap insp on all aux	v	10%
	Align Bow Thruster Engine to drive shaft for tunnel	V	y
KOD 63.xxxxx	Cost Center REFRIGERATION / RSW	,	
0300	Pipes, Valves & Fittings		
	Remove R-22 condensers send out for cleaning & inspection, add additional plates before hake	У	50%
	Replace S/W Piping & R-22 piping at both Condensers, rotten	У	50%
	Repair Freon piping leak on suction line	У	100%
	Replace failed frequency drive on # 2 compressor	c ·	v 40%
40006	Equipment		
	Install new oil rectifying valve	y	V PP
	Service all compressors to include oil and filters	С	
KOD 64.xxxxx	Cost Center MARINE -hull & tanks, engineering, deck, wheel	house	
0300	Pipes, Valves & Fittings		
	Replace broken 5" Seachest valve for Factory Hake Pump	DO	CI
	Need to replace 1" Nipples on Port & STBD M/E Shaft Seal Cooling lines (Heavier Schedule)	c	100%
	Remove and Repair/Replace #1 AUX Duplex Strainer 5" Hayward (Frozen on one side)	C	
	Replace split sounding pipe in freshwater tank	У	100%
Within 3 days	1 Repair or replace fire main piping O.B. in ER	У	100%
40001	Chemicals & Paint		
	Prep / paint all bulkheads in Fishhold including shafts.	v	PP

40003	Electrical		
	1 GMDSS upgrade to Felcom 18-Kelly	v	50%
	Ships Satellite phone is not functioning correctly, change out satellite dome	yv	75%
	Service Sonar replace motor and limit switches	cv	
40006	Equipment		
	1 Engine room air supply trunks need to be cleaned out and painted	v	
	Inspect all supply and exhaust fans - repair if necessary	С	
	Case Marine to Lay Up R.O.	v	100%
	Case Marine to replace section of bowl filter shoot line	v	
	Anchors don't suck up tight	у	
	Anchor windlass Replace rusty hoses and fittings including vent for gearbox	v	10%
	Skiff Tarp doesn't fit. New skiff cover needed.	v	100%
	Have Evoqua down to go through Chloropac used cells keep for spares	v	10%
40011	Hydraulics		
	Port midship crane has leak in telescope hydraulics. Replace one lifting ram with proper size.	v	50%
Day of	Replace Port Crane Boom cylinder	v	50%
40014	Marine		
	Repair leaking portlights in rooms 02-18, 01-05, 01-04	y	10%
	Repair Doubler plate on Stern Ramp, Crack across the bottom	DC	I
	Inspect stbd fwd cutter pump sump steel	у	100%
	Inspect / Repair hole in deck at port side fwd Fishhold	y	20%
	Inspect / Find water leak penetrating #6 STBD Fuel Oil Tank - no leaks	у	100%
	Inspect / Find water leak penetrating STBD Fuel Oil Tank (Day Tank)	у	100%
Day of	1 Repair #2 STBD Fuel Oil Tank in Bow Thruster Room (Leak at bottom of Bulkhead)	у	30%
Day of	Repair bulkheads around watertight doors in to wheelhouse crawl space	у	40%
Day of	Repair tank vent pipe threads on deck	у	90%
40018	Rentals		
40020	Safety		
	Scramble Ladder (Get with Katie to replace them)	С	
	Add Camera surveillance to the steering flat.	IT	
	ABS Prep	yc	
	2 new scramble ladder (Katie Knifong).	c	
	Inspect life rafts (Katie Knifong).	V	
	Aux #2 3512B Inframe Overhaul #700785		
700785	Inframe overhaul Stbd 3512B	V	Fall
	Aux #3 3512B Inframe Overhaul #700786	,	
700786	Inframe overhaul Port 3512B	V	Fall
	Furuno FAR2228 Radar #700672		