

12 Months Locomotive Failure Repair History for BNSF 8487

Last Retrieval At: 2023-10-25|09:54

WO Typ	Open		Defect		Qualifier		Action
	Date	Station	JCD	Description	CD	Description	
DF 9	8/10/2023	FTWORT		Communication loss ;		Wipu	Duplicate
	Due Comment : 08/10/2023 08:00:54 CST (S_BAT_MAM) Witronix not ification: BNSF 8487						
	81123	FTWORT					
DF 9	8/3/2023	GRAJUP	F018	No Output ;			Repaired
	Due Comment : 08/03/2023 15:00:50 CST (X_XI_MAMHTTP) DITCH LIG HT ENGINEERS SIDE						
	80623	DENVER				Replace	
	Comment : DITCH LIGHT ENGINEERS SIDE J Vasquez Replaced di tch light August 6 2023 05:09						
DF 9	7/30/2023	FTWORT		Communication loss ;		Wipu	Duplicate
	Due Comment : 07/30/2023 10:00:52 CST (S_BAT_MAM) Witronix not ification: BNSF 8487						
	73023	FTWORT					
DF 9	7/17/2023	FTWORT		Communication loss ;		Wipu	Duplicate
	Due Comment : 07/17/2023 00:46:09 CST (S_BAT_MAM) Witronix not ification: BNSF 8487						
	71723	FTWORT					
DF 9	6/6/2023	FTWORT		Communication loss ;		Wipu	Duplicate
	Due Comment : 06/06/2023 23:15:41 CST (S_BAT_MAM) Witronix not ification: BNSF 8487						
	70623	FTWORT					
DF 9	5/26/2023	GRAJUP	F004	No Output ;		Crossing Bell Assy	Duplicate
	Due Comment : 05/26/2023 02:13:20 CST (X_XI_MAMHTTP) BELL SWIT CH NEEDS TO BE ADJUSTED . DOES NOT ALWAYS TURN T HE BELL OFF 05/26/2023 05:57:24 CST (B119958) CI osing the Notification due to change in Defect L evel. Notification 100016232870 is created with changed Defect Level						
	52623	GRAJUP					
DF 8	5/26/2023	GRIZUP	F004	Electrical Failure ;		Crossing Bell Assy	Repaired
	Due Comment : 05/26/2023 05:57:23 CST (B119958) defect adjuste d. UPRR CREW REPORTED CROSSING BELL IS STUCK ON. meo 05/26/2023 02:13:20 CST (X_XI_MAMHT P) BELL SWITCH NEEDS TO B E ADJUSTED . DOES NOT ALWAYS TURN THE BELL OFF						
	52623	DENVER				Repair	
	Comment : BELL SWITCH NEEDS TO BE ADJUSTED . DOES J Vasque z replaced bell relay May 26 2023 21:42						
DF 8	5/22/2023	BESHOA	F004	Electrical Failure ; General - Text Requi		Crossing Bell Assy	Repaired
	Due Comment : 05/22/2023 03:01:06 CST (B178233) radio, crew re ported crossing bell will not shut off, button d oes not seem stuck.....MEO						
	52223	DENVER					
	Comment : radio, crew reported crossing bell will K Kopas switch is just a bit funky. You need to slightly pull on lever when turning it off. May 22 2023 14:31						
DF 9	5/11/2023	FTWORT		29 No Communication with D;		DVR	Duplicate
	Due Comment : 05/11/2023 21:00:27 CST (S_BAT_MAM) Witronix not ification: BNSF 8487						
	52623	FTWORT					
DF 9	5/10/2023	DENVER		28 Defective subsystem unk;		DVR	
	Due Comment : 05/10/2023 21:35:48 CST (B654783) RADIO: Reporte d having a LDARS System malfunction message on s creen for camera....MEO						
DF 2	3/15/2023	FTWORT	F009	Empty ;		Expansion Tank	Repaired
	Due Comment : 03/15/2023 01:45:58 CST Jake Brown (B178530) CAD - Per PC AMLU Central BNSF 8487 - Can you add a defect to it? Dumped its water, dead and drained d.....MEO ----- 03/15/2023 02:20:26 CST Paul Lee (C84806 7) Send downloads to BNSF.techsupport@progressra il.com for detailed workscope.						
	31823	ALLINE					
	Comment : CAD - Per PC AMLU Central BNSF 8487 - C C Crabr ee Replaced #9 HLP March 18 2023 15:12						
DF R	2/18/2023	ATLAGA		43 DVR Limited: No Control;		Event Recorder	Repaired
	Due Comment : 02/18/2023 08:31:05 CST Robert Balinger (B0098 1) no control system data is being recorded. Ple ase inspect comm path from the control system to the ER. Verify repair by cabling int o the PVR web gui prior to release. ----- 02/22/2023 21:45:55 CST Mechanical batch ID (S_BAT_MAM) Duplicate symptom reported ----- 02/22/2023 23:46:00 CST ----- 0 2/22/2023 22:00:49 CST Mechanical batch ID (S_BA T_MAM) Duplicate symptom reported ----- 02/22/2023 22:15:53 C ST Mechanical batch ID (S_BAT_MAM) Duplicate sym ptom reported ----- 02/22/2023 22:30:42 CST Mechanical batch ID (S_BAT_MAM) Duplicate symptom reported ----- 02/22/2023 23:00:47 CST Mechanical batch ID (S_BAT_MAM) Duplicate sym ptom reporte d ----- 02/22/2023 23:15:40 CST Mechanical batch ID (S_BAT_MAM) Duplicate symptom reported ----- 02/22/2023 23:30:58 CST M echanical batch ID (S_BAT_MAM) Duplicate symptom reported ----- 02/22/2023 23:46:00 CST Mechanical batch ID (S_BAT_MAM) Duplicate symptom reported ----- 02/23/2023 00:00: 43 CST Mechanical batch ID (S_BAT_MAM) Duplicate symptom reported ----- 02/23/2023 00:15:50 CST Mechanical ba tch ID (S_BAT_MAM) Duplicate symptom reported ----- 02/23/2023 00:31:04 CST Mechanical batch ID (S_BAT_MAM) D uplicate symptom reported ----- 02/23/2023 00:45:48 CST Mecha nical batch ID (S_BAT_MAM) Duplicate symptom reported ----- 02/23/2023 01:00:53 CST Mechanical batch ID (S_BA T_MAM) Duplicate symptom reported ----- 02/23/2023 01:15:45 C ST Mechanical batch ID (S_BAT_MAM) Duplicate sym ptom reported ----- 02/23/2023 01:30:41 CST Mechanical batch ID (S_BAT_MAM) Duplicate symptom reported ----- 02/23/2023 01 :45:51 CST Mechanical batch ID (S_BAT_MAM) Dupli cate symptom reported ----- 02/23/2023 02:00:54 CST Mechanical batch ID (S_BAT_MAM) Duplicate symptom reporte d ----- 02/23 /2023 02:15:51 CST Mechanical batch ID (S_BAT_MAM) Duplicate symptom reported ----- 02/23/2023 02:30:39 CST M echanical batch ID (S_BAT_MAM) Duplicate symptom reported ----- 02/23/2023 02:45:47 CST Mechanical batch ID (S_BAT_MAM) Duplicate symptom reported ----- 02/23/2023 03:00: 52 CST Mechanical batch ID (S_BAT_MAM) Duplicate symptom reported ----- 02/23/2023 03:15:45 CST Mechanical ba tch ID (S_BAT_MAM) Duplicate symptom reported -- ----- 02/23/202 3 03:30:39 CST Mechanical batch ID (S_BAT_MAM) D uplicate symptom reported ----- 02/23/2023 03:45:37 CST Mecha nical batch ID (S_BAT_MAM) Duplicate sym ptom reported ----- 0 2/23/2023 04:00:44 CST Mechanical batch ID (S_BA T_MAM) Duplicate symptom reported ----- 02/23/2023 04:15:40 C ST Mechanical batch ID (S_BAT_MAM) Duplicate sym ptom reported ----- 02/23/2023 04 :45:42 CST Mechanical batch ID (S_BAT_MAM) Dupli cate symptom reported ----- 02/23/2023 05:00:49 CST Mechanical batch ID (S_BAT_MAM) Duplicate symptom reporte d ----- 02/23 /2023 05:15:40 CST Mechanical batch ID (S_BAT_MAM) Duplicate symptom reported ----- 02/23/2023 05:30:48 CST M echanical batch ID (S_BAT_MAM) Duplicate symptom reported ----- 02/23/2023 05:45:37 CST Mechanical batch ID (S_BAT_MAM) Duplicate symptom reported ----- 02/23/2023 06:00: 42 CST Mechanical batch ID (S_BAT_MAM) Duplicate symptom reported ----- 02/23/2023 06:15:37 CST Mechanical ba tch ID (S_BAT_MAM) Duplicate symptom reported -- ----- 02/23/202 3 06:30:46 CST Mechanical batch ID (S_BAT_MAM) D uplicate symptom reported ----- 02/23/2023 07:00:57 CST Mechanical batch ID (S_BA T_MAM) Duplicate symptom reported ----- 02/23/2023 07:15:52 C ST Mechanical batch ID (S_BAT_MAM) Duplicate sym ptom reported ----- 02/23/2023 07:30:37 CST Mechanical batch ID (S_BAT_MAM) Duplicate symptom reported ----- 02/23/2023 07:45:38 CST Mechanical batch ID (S_BAT_MAM) Dupli cate symptom reported ----- 02/23/2023 08:01:08 CST Mecha nical batch ID (S_BAT_MAM) Duplicate symptom reporte d ----- 02/23 /2023 08:15:37 CST Mechanical batch ID (S_BAT_MAM) Duplicate symptom reported ----- 02/23/2023 08:30:39 CST M echanical batch ID (S_BAT_MAM) Duplicate symptom reported ----- 02/23/2023 08:45:46 CST Mechanical batch ID (S_BAT_MAM) Duplicate symptom reported ----- 02/23/2023 09:00: 50 CST Mechanical batch ID (S_BAT_MAM) Duplicate symptom reported ----- 02/23/2023 09:15:40 CST Mechanical ba tch ID (S_BAT_MAM) Duplicate symptom reported ----- 02/23/2023 09:30:55 CST Mechanical batch ID (S_BAT_MAM) D uplicate symptom reported ----- 0 2/23/2023 09:45:39 CST Mecha nical batch ID (S_BAT_MAM) Duplicate symptom reported ----- 02/23/2023 10:00:41 CST Mechanical batch ID (S_BA T_MAM) Duplicate symptom reported ----- 02/23/2023 10:15:49 C ST Mechanical batch ID (S_BAT_MAM) Duplicate sym ptom reported ----- 02/23/2023 10:30:40 CST Mechanical batch ID (S_BAT_MAM) Duplicate symptom reported ----- 02/23/2023 10 :47:55 CST Mechanical batch ID (S_BAT_MAM) Dupli cate symptom reported ----- 02/23/2023 11:00:53 CST Mechanical batch ID (S_BAT_MAM) Duplicate sym ptom reporte d -----						
	31823	ALLINE					

	Comment :	ER is not recording control system F Benga no fa ults on power view. EMD said everything communic ating March 17 2023 14:49 _____		
DF 8	2/13/2023 LINCNE	F004	No Output ;	Toilet (VTR) Repaired
	Due Comment :	02/13/2023 11:25:43 CST Steven Salisbury (B16957 5) toilet handle broke, do not use as leader		
	31823 ALLINE			
	Comment :	toilet inop - handle broke O Escamilla Complete March 18 2023 07:53 _____		
DF 9	12/12/2022 TRINCO	F004	;	Toilet (VTR) Repaired
	Due Comment :	12/12/2022 12:58:18 CST Interface B302604 TRINC O CAB CONDITION DEFECT REPORTED BY CREW Trouble Code: TOILET		
	121322 ALLINE			
	Comment :	CAB CONDITION DEFECT REPORTED BY CREW AD D Kozal LABORER SERVICED December 13 2022 09:30 _____		
DF 9	12/9/2022 ALLINE	F013	Internal Water Leak ;	Repaired
	Due Comment :	12/09/2022 09:29:18 CST Interface At next shopp ing - TS04 correct water leak ----- 12/30/2022 11:04:37 CST I nterface Duplicate symptom reported At next sho pping - TS04 correct water leak		
	31823 ALLINE			
	Comment :	At next shopping - TS04 correct water le C Crabt ree Complete March 18 2023 15:12 _____		