Williams Shaun

From: Sent: To: Cc: Subject: Attachments: McAtee Nancy Tuesday, December 14, 2021 4:16 PM Williams Shaun Budinski Michael Email report-CEN21FA198 (Annunciator panel) Danville AR SPARE M 1.jpg; Danville AR SPARE M 2.jpg

Shaun,

The annunciator panel for the accident aircraft was submitted to the Materials Laboratory for examination. The panel contained 12 individual annunciators. Each annunciator contained two (2) bulbs. The individual annunciator lights were removed from the panel and x-rayed to determine the status of the filaments inside each of the bulbs. One (1) annunciator light displayed hot filament stretch in both bulbs-SPARE (Position M). Photographs of the two bulbs are attached to this email.

If you have any questions, please let me know.

Nancy B McAtee Senior Chemist RE-30




Photo 1: Spare Bulb M2




Photo 2: Spare Bulb M1