

6 Oct. 2019

Champion 7GCBA, N9512S, SN: 21

TACH: 1302.0, TTAF: 1302.0

Inspected aircraft in accordance with Champion maintenance and inspection procedures. Lubed all controls and bell cranks. Replaced rod end fittings on right and left aileron control rod ends. Replaced Whelan beacon assembly on belly of fuselage. Replaced bushings in front and rear control sticks. Installed new Airtex ELT-345 with remote switch and antenna kit. Inspected ELT and checked in accordance with FAR 91-207 (d) and was found to be operational. ELT battery due: Aug. 2026. Repaired front seat. Installed Aero Fabricators Inc. Champion 7 series toe brake rudder conversion kit, refer to 337. Fabricated new rudder floor plates. Installed new brake caliper bleeder fittings on right and left brake calipers.

Patrick Yancey IA, A&P [REDACTED]