

Make Beech Model 95B55 Serial No./No. TC-1407

Tach Reading 3568.40 Date 12-1-21 Annual Inspection

completed this date to include: Open inspection plates for inspection and lubrication of pulleys, cables, bellcranks and attach points performed retraction tests and operated satisfactory Installed aft retract rod hem bearing for nose gear part # ADNEL6-317 and Re rig nose gear to set proper tension. Adjusted left main striker clearance to .011 and checked rigging Installed new seat rollers on pilots seat and copilot's part # 118641. Installed new O-rings in left brake caliper and bleed brake Installed missing Wilky plugs on bottom of both wings. Removed and reinstalled right 3 in one gauge after overhauled by Air parts of Lock Haven

**NORTHWEST AVIATION
MAINTENANCE, INC.**

1705 East Main Street • Griffith, IN 46319
Telephone: (219) 922-2632 • 800-247-7070

W.O. #



Authorized Signature

Grid area at the bottom of the page.

TACH
TIME

TODAYS
FLIGHT

TIME IN
SERVICE

ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)

Make Beech Model 951355 Serial No./No. TC-1407

Tach Reading	3568.40	Date	12-1-21	Annual Inspection
part # 96-380016 see 8130-3 for details on overhaul.				
Installed Beechcraft Kit 58-4003-1 for the rear two				
seats. c.w. AD 76-07-12 on Bendix ignition switches by				
function testing. c.w AD 2007-08-08 By Inspection and				
lubrication of uplock rollers. c.w FAR 91.207D By				
Inspection. I certify that this Aircraft was inspected				
in accordance with an Annual Inspection and was				
determined to be in an Airworthy condition this date.				

**NORTHWEST AVIATION
MAINTENANCE, INC.**

1705 East Main Street • Griffith, IN 46319
Telephone: (219) 922-2632 • 800-247-7070


