

MAINTENANCE RECORD

A/C REG#

INSPECTION, REPAIRS & REPLACEMENT

COMPLETE ENTRIES, DRAW A DIAGONAL LINE THROUGH ANY
UNUSED LINES IN DATE AND TIME COLUMNS.

SIGNATURE

10/20/2021 N210JB A/C S/N: K992 HOBBS 105.4 ACTT: 2156.6 ENG S/N: L-1188-31 ENG TT: 1338.5 ENG TSO: 114.6

Performed 100hr/Annual inspection. Complied with AD 2001-17-17 on main rotor grips PN: 47-120-135-5 SN: SR00854 and SN: SR00842 with TT: 114.6, NDT performed by Apex Inspections WO: 8766 no relevant indications noted, next due at ACTT 2456.6. Installed Repaired Main Rotor Blades PN: 47-110-120-50 SN: 3925 and SN: 3926 see 337 dated 15 Oct 2019 for repair work. Installed new lower aft elevator cable PN: NAS303R25-1055. Installed Serviceable Oil Drain Valve PN: 49F9798-21. Stringed, static balanced and performed Dynamic track and balance Main Rotor System. All work performed IAW Bell and Lycoming Installation, Maintenance and Overhaul Manuals.

MAINTENANCE RELEASE:

The Aircraft, Airframe, Aircraft Engine, Appliance, or Component identified was repaired/inspected/overhauled in accordance with current regulations of the Federal Aviation Administration and is approved for return to service. Pertinent details of this repair are on file at this agency under work order 4112 Dated: 10/20/2021.

Signed: Michael Johnson

Scott's Helicopter Service, Inc.
CRS# CUHR150S